

182

ASS. REC. BY:

REF: CS/FCI18017431/ Accts n2
Special Instruction

Surveyor: Adrian
CWS

ASSIGNMENT (Office)

From (Person): Eileen Lee

of FCI

Date/Time: 25/9/18 @ 3:10pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKL 5797H

Insured: SHC 8678G

at Workshop m/s: MCS Garage

Tel: 12700917

of 10 Keki Bkt Road 2 # 03-25

Policy No:

Claim No: D18006980 MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 21/09/18

CA / REV / REP. / REV 24 HRS

1wp

26/9/18 @ After 11 am
H.O.D. Endorsement:

Date/Time: 3:18pm @ 25/9/18

Person Contacted: Hendrick

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL 5797H - NA / INC18017284 / 24 DOA: 21/9/18
	SHC 8678G - NA / INC18017284 / 24 DOA: 21/9/18

REF: FCI

ASSIGNMENT

From: _____ Date: 26/9/18

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL 5797H

at Workshop m/s: MCS Garage

of: 10 kaki Bkt Rd 2 # 03-25

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SKL5797H Yr Regn: 2013 / Nov

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Jetta C.C. 1390

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 88267 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW2221620M0S1174

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18
R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Cap

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 26/09/18

Survey held at MCS.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/10	TP 1st Cap. Adrian confirmed US \$1900 and 3 days with repairer. (Red. GI 87, 762)

RECEIVED 25 DEC 2018

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: TP

Lump Sum / L.B.I. (\$ 1900)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: 160

Transportation: 50

S - RS: SI 50

Photos: 23

Others: _____

TOTAL: 283



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18017431/Ard3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 25-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8678G	Veh. Inspected	SKL 5797H
Policy No.		Coverage (\$)	0.00
Claim No.	D18006980MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	25/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Engine No.	HIDDEN	Accident Date	21/09/2018	Inspection Date	26/09/2018
Survey held at	MCS GARAGE 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE SINGAPORE 417868				

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MOTOR SURVEY ASSIGNMENT

Date	24-09-2018	Our Ref No. D18006980MFSH
Accident Date	21-09-2018	Claim Type. Third Party
Insured Vehicle	SHC8678G	Third Party Vehicle. SKL5797H
Survey Location	10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE	
Contact Person.	MR KENDRICK	
Contact No.	92700917/ 92700917	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MCS GARAGE	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2445B
Vehicle Details	
Vehicle No.:	SKL5797H
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1622G5
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	CAXB83839
Chassis No.:	WVWZZZ16ZDM051174
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$18,867.00
Original Registration Date:	28 Nov 2013
First Registration Date:	28 Nov 2013
Transfer Count:	2
Actual ARF Paid:	\$8,867.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2023
PARF Rebate Amount:	\$6,206.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$76,889.00
COE Rebate Amount:	\$37,867.00
Total Rebate Amount:	\$44,073.00

The information contained herein is correct as at 24 Dec 2018

OK

MCS Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868
 Tel: 9270 0917 / 6538 4322

TP 1st Comp.
 Janice.

Vehicle number: SKL5797H

Vehicle Made & Model: VOLKSWAGEN JETTA

Qty	Nett Items	Amount \$
1	Rear bumper <i>defound</i>	1,230.71 ✓
1	Rear bumper difusser <i>ut</i>	570.30 ✓
2	Rear bumper reflectors - L/R @ 89.95 <i>new</i>	179.90 +
1	Rear bumper CTR guide <i>new</i>	145.50 +
2	Rear bumper side guides - L/R @ 65.50	131.00 +
2	Rear bumper side retainers - L/R @ 68.55 <i>new</i>	137.10 +
1	Rear bumper reinforcement	530.17 +
1	Rear boot lid	1,430.71 +
1	Rear boot logo	128.40 x
1	Rear boot emblem "JETTA" <i>def</i>	68.55 +
1	Rear boot emblem "TSI" <i>new</i>	55.80 +
2	Rear boot lamps - L/R @ 211.60	423.20 +
1	Rear boot inner lock	260.50 +
1	Rear end panel	935.50 +
1	Rear taillamp - LH	391.55 +
Sub-total		6,618.89
Less 10%		661.89
Total List		5,957.00

Handwritten notes: 1801.01, 1620.50, 200

Special Nett Items

1 set	Rear Reverse sensor <i>Dangd</i>	280.00 <i>200</i>
Total Special Nett		280.00

Labour Charges

To check rear electrical wiring	50.00 <i>30</i>
To remove, refix interior upholstery to facilitate repair works	120.00 +
To remove, refix rear reverse sensor	80.00 <i>50</i>
To respray painting & etc	800.00 <i>250</i>
Panel beating, cut, weld, remove & replacing above parts	800.00 <i>250</i>
Total Labour	1,850.00

Consultants hence notify
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE PARTS & LABOUR GRAND TOTAL \$

Acknowledged by Repairer
 Signature:
 Date:

Handwritten notes:
 Total: 2400.50
 4/5: 1.9K
 03 Days
 1.9K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18017431/Acd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-12-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8678G	Veh. Inspected	SKL 5797H
Policy No.		Coverage (\$)	0.00
Claim No.	D18006980MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	25/09/2018
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN JETTA	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WWWZZZ16ZDM051174	Colour	BLACK
Odometer	88267	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/09/2018	Inspection Date	26/09/2018
Survey held at	MCS GARAGE 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE SINGAPORE 417868		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 5797H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	DEFORMED	1,230.71	1,230.71
1	REAR BUMPER DIFUSSER (N)	CUT	570.30	570.30
2	REAR BUMPER REFLECTORS-L/R @\$89.95 (N)	NOT NECESSARY	179.90	-
1	REAR BUMPER CTR GUIDE (N)	NOT NECESSARY	145.50	-
2	REAR BUMPER SIDE GUIDES-L/R @\$65.50 (N)	NOT NECESSARY	131.00	-
2	REAR BUMPER SIDE RETAINERS-L/R @\$68.55 (N)	NOT NECESSARY	137.10	-
1	REAR BUMPER REINFORCEMENT (N)	NOT NECESSARY	530.17	-
1	REAR BOOT LID (N)	NOT NECESSARY	1,430.71	-
1	REAR BOOT LOGO (N)	NOT NECESSARY	128.40	-
1	REAR BOOT EMBLEM "JETTA" (N)	NOT NECESSARY	68.55	-
1	REAR BOOT EMBLEM "TSI" (N)	NOT NECESSARY	55.80	-
2	REAR BOOT LAMPS-L/R @\$211.60 (N)	NOT NECESSARY	423.20	-
1	REAR BOOT INNER LOCK (N)	NOT NECESSARY	260.50	-
1	REAR END PANEL (N)	NOT NECESSARY	935.50	-
1	REAR TAILLAMP-LH (N)	NOT NECESSARY	391.55	-
	LESS 10% DISCOUNT		-661.89	-180.10
			5,957.00	1,620.91
SPECIAL NETT ITEMS				
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			280.00	200.00
LABOUR				
	TO CHECK REAR ELECTRICAL WIRING.		50.00	30.00
	TO REMOVE,REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIR WORKS.	NOT NECESSARY	120.00	-
	TO REMOVE,REFIX REAR REVERSE SENSOR.		80.00	50.00
	TO RESPRAY PAINTING & ETC.		800.00	250.00
	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS.		800.00	250.00
			1,850.00	580.00
GRAND TOTAL			8,087.00	2,400.91



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00
---	--	--	----------

Report Ref No. CS/FCI18017431/Acd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.