

ASS. REC BY: Meiimen REF: CS3/AXA18001787/Grb³²-1

ASSIGNMENT (Office)

From: Wong Wee Fu To: AXA Date/Time: 25/09/2018

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 1994S Insured: SHB 9926P

at Workshop with: Twincar Automotive Tel: 68420051

at: Blk 2 Kaki Bukit # 01-17/18

Policy No: P1680520 Claim No: C0468884

Sum Insured: _____ Excess: _____

Make of Veh: _____ DOA: 25/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 9:27am @ 30/11/18 Person Contacted: Melody Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLC 1994S - NA/DA/18001650/13</u>
	<u>SHB 9926P - NA/DA/18001650/13</u>
	<u>Dismantle Part: 31.01.2018</u>
	<u>After repair: 02.02.2018</u>

240318 529pm Email to Ernest Jay from Meiimen

Submit L/s \$7850 @ 7 days
Red: \$10,350.00, 571.

Submit paper survey
* Report submitted by email.

RECEIVED 02 OCT 2018

Repair days 7

TCM
lim
26/9/18

27/9/2018

PRS
Karl.

AXA

30/01/18

SLC1994S

20 Nov 2009

0

SLC 1994S
Twincor Automotive
Blk 2, kaki Blk # 01-17/18

Toyota Lexus RX450H 3456
Black
135714

JTJBC11A402015860

0

0

0

235/60 R18
"

NEX EN

66

66

30-01-18
3pm

w/s Twincor.

0



RECEIVED 20 MAR 2010

24032018

PRS

Catherine Chong (LKK Auto)

From: WONG Wee Fu <weefu.wong@axa.com.sg>
Sent: Tuesday, 25 September, 2018 1:23 PM
To: sur@lkkauto.com; assignments@lkkauto.com
Subject: Paper RI. CS3/AXA18001787/GBS2. TP VEH SLC1994S.C0468884
Attachments: TP surveyor rpt.pdf

Hi Lkk,

Please assist with Paper RI.

Believed that you have already inspected vehicle post repairs.

Thanks

Wee Fu

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: Weefu.wong@axa.com.sg

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

**Contact us at**

Hotline: (65) 6532 2888

E-mail: CustomerService@DirectAsia.com

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act")

Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore)

Road Transport Act, 1987 (Malaysia)

Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Certificate No.	: MT/00432241
Type of Coverage / Driver Plan	: Car Comprehensive (Value Plus Plan)
1) Vehicle Registration No.	: SLC1994S
Chassis No.	: JTJBC11A402015860
2) Name of Policy Holder	: LAU, KOK SENG
3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	: 20/11/2017 00:00
4) Date/Time of Expiry of Insurance	: 19/11/2018 23:59
5) Persons or Classes of Persons Entitled to Drive	
(a) The Insured	
(b) Any named person under the policy who is driving on the Insured's order or with his permission.	
(c) Any authorised person, provided such person is aged 30 and above and holds a valid driving licence of 2 years or more, who is driving on the Insured's order or with his permission	
The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.	
6) Limitations as to use*	
Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business.	
*Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.	

Sum Insured	: Market Value
Own Damage Excess	: S\$ 1,000.00 (before any applicable GST)
Windscreen Excess	: S\$ 100.00 (before any applicable GST)
Choice of workshop	: DirectAsia approved workshops
Finance company / Hire Purchase	: TOKYO CENTURY LEASING (SINGAPORE) PTE LTD
Main driver	: LAU, KOK SENG
Named driver	: None

Important Note: This policy does not cover drivers below the age of 30 and drivers who hold a valid driving licence of less than 2 years with the exception of the named drivers above.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Direct Asia Insurance (Singapore) Pte. Ltd.

Issued on: 16/11/2017

Edip Okur
Chief Underwriting Officer

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LAU KOK SENG
11 ANCHORVALE CRESCENT #10-02
SINGAPORE 544649

Contact : 97989978

TAX INVOICE

Date : 04/09/2018
Date in : 26/01/2018
Vehicle Num. : SLC1994S
Make/Model : TOYOTA LEXUS RX450H-2009
Chassis/Eng# : JTJBC11A402015860/2GRJ166835
Accident Date : 25/01/2018
Claim No : CLM13998
Reference : JAN-24/2018
Policy No. : MT/00432241 (19/11/2018)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0513-18-TCA DATED 27/08/2018
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$
18,200.00

E. & O.E.	Sub S\$:	18,200.00
Add GST (7 %) S\$:		1,274.00
Total Amount S\$:		19,474.00



for TWINCAR AUTOMOTIVE PTE LTD

TWINCAR RENTAL

Business Registration Number : 53092815M

Blk 2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 68420051 Fax : 67410510 email: sales@n51.com.sg

Invoice To :

LAU KOK SENG
11 ANCHORVALE CRESCENT
#10-02
SINGAPORE 544649

INVOICE

Invoice No. 13-2094

Date 5/2/2018

		Hirer's Car No.	VHA No.	Terms
		SLC1994S	71578	CASH
No. of Day	Description	Per Day	Amount (\$\$)	
10	Car Rental from the period of 26/01/2018 to 05/02/2018. Vehicle no. SLL9720R Singapore Dollars One Thousand Six Hundred Only	160.00	1,600.00	
		Total	\$1,600.00	

TWINCAR RENTAL



Authorised Signature



TWINCAR RENTAL

Kaki Bukit Autohub @ 2 Kaki Bukit Ave. 2 #01-18
Singapore 417921 Tel: 6744 0510 / 6842 0051

Tc
SLG19945

VHA No: 71578

ROC NO: 53092815M

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR Name: (as in I/C) <u>LAM KOK SENG</u> NRIC/PASSPORT No: <u>S 7902005 B</u> Address (Res): <u>11 ANCHORVALE CRESCENT</u> <u>#10-02 S(54969)</u> Name & Address of Employer: _____ Occupation: _____ Driving Exp: _____ Driving Licence No: <u>S7902005B</u> D/L Type: Local / International Pass Date: <u>11/01/1979</u> Date of Birth: <u>06/07/1978</u> Tel: (O) _____ (R) _____ HP <u>97989978</u>		Vehicle No: <u>SLL 9720 R</u> Replace Veh No: _____ Mileage Out: _____ Mileage Out: _____ Make & Model: <u>Toyota Harrier</u> Auto / Manual Group: _____ OUT: Date <u>26/11/18</u> Time: <u>15.50 HRS</u> HIRE/PERIOD EXPIRY _____ NON-WAIVER EXCESS: \$ _____																																																		
ADDITIONAL DRIVER'S PARTICULARS Name: (as in I/C) _____ NRIC/PASSPORT No: _____ Address (Res): _____ Driving Licence No: _____ D/L Type: Local / International Pass Date: _____ Date of Birth: _____ Occupation: _____ Driving Exp: _____		<table border="1"> <thead> <tr> <th colspan="4">CHARGES</th> </tr> </thead> <tbody> <tr> <td>Daily @ \$</td> <td><u>160</u></td> <td>per day</td> <td><u>10</u></td> </tr> <tr> <td>Weekly @ \$</td> <td></td> <td>per week</td> <td></td> </tr> <tr> <td>Monthly @ \$</td> <td></td> <td>per month</td> <td></td> </tr> <tr> <td>Hours @ \$</td> <td></td> <td>per hour</td> <td></td> </tr> <tr> <td>Others @ \$</td> <td></td> <td></td> <td></td> </tr> <tr> <td>CDW @ \$</td> <td></td> <td>per day/month</td> <td></td> </tr> <tr> <td>PAI @ \$</td> <td></td> <td>per day/month</td> <td></td> </tr> <tr> <td colspan="4">Delivery Service</td> </tr> <tr> <td colspan="4" style="text-align: right;">SUB-TOTAL \$</td> </tr> </tbody> </table>		CHARGES				Daily @ \$	<u>160</u>	per day	<u>10</u>	Weekly @ \$		per week		Monthly @ \$		per month		Hours @ \$		per hour		Others @ \$				CDW @ \$		per day/month		PAI @ \$		per day/month		Delivery Service				SUB-TOTAL \$												
CHARGES																																																				
Daily @ \$	<u>160</u>	per day	<u>10</u>																																																	
Weekly @ \$		per week																																																		
Monthly @ \$		per month																																																		
Hours @ \$		per hour																																																		
Others @ \$																																																				
CDW @ \$		per day/month																																																		
PAI @ \$		per day/month																																																		
Delivery Service																																																				
SUB-TOTAL \$																																																				
VEHICLE CHECKLIST D - DENTS S - SCRATCHES A - ACCIDENTS 		<table border="1"> <thead> <tr> <th colspan="7">PETROL LEVEL</th> </tr> </thead> <tbody> <tr> <td>Out</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> <td></td> </tr> <tr> <td>In</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> <td></td> </tr> <tr> <td colspan="7">EXTENSION</td> </tr> <tr> <td colspan="7">Collection Service</td> </tr> <tr> <td colspan="7">Misc.</td> </tr> <tr> <td colspan="7" style="text-align: right;">TOTAL CHARGE \$</td> </tr> </tbody> </table>		PETROL LEVEL							Out	E	1/4	1/2	3/4	F		In	E	1/4	1/2	3/4	F		EXTENSION							Collection Service							Misc.							TOTAL CHARGE \$						
PETROL LEVEL																																																				
Out	E	1/4	1/2	3/4	F																																															
In	E	1/4	1/2	3/4	F																																															
EXTENSION																																																				
Collection Service																																																				
Misc.																																																				
TOTAL CHARGE \$																																																				
ACCESSORIES CHECK <input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> S/Tyre <input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> Hub Caps <input type="checkbox"/> Radio / Cass <input type="checkbox"/> CD <input type="checkbox"/> Cartridges		Rented out by: _____ Hirer's Signature <u>Sey</u> Addition Driver's Signature _____																																																		

I have read and agree to the terms & condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given TWINCAR RENTAL in connection with this Agreement is true.

* IMPORTANT

- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY TWINCAR RENTAL.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO TWINCAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
05/02/2018	11:50 HRS				<u>Sey</u>

1 Kaki Bukit Avenue 6
#01-55 AutoBay @ Kaki Bukit
Singapore 417883
Tel: 9015 8686 (Ah Boon)

No. _____

Date: 06/11/18

Sold to:

SLC 1994.S

[illegible]

Issued by: _____

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173; Fax : 645 36131.

Report No: 0513-18-TCA

27 August 2018

Lau Kok Seng
11 Anchorvale Crescent #10-02
Singapore 544649

INVOICE No. 0513-18-TCA


Vehicle No. SLC1994S

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$1,090.00
Total amount payable		<u>\$1,090.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0513-18-TCA

27 August 2018

ACCIDENT VEHICLE SURVEY REPORT

Lau Kok Seng
11 Anchorvale Crescent #10-02
Singapore 544649

VEHICLE INFORMATION:

Vehicle Reg No.:	SLC1994S	Odometer:	135714km
Make & Model:	Toyota Lexus RX450H	Colour:	Black
Chassis number:	JTBC11A402015860	Date of accident:	25/01/2018
Year of Regn.:	20/11/2009	Date inspected:	29/01/2018
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	05/02/2018

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	4mm/Nexen	4mm/Nexen	235/60R18
Rear:	4mm/Nexen	4mm/Nexen	235/60R18

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
CENTER EXHAUST GASKET	1	necessary	18.50	18.50 NEC XNN
CENTER EXHAUST RUBBER MOUNTING	4	distorted	155.60	155.60 SVCX
CENTER EXHAUST SILENCER	1	bent	1,850.30	1,850.30 SVCX
REAR BUMPER	1	squashed	752.40	752.40 DD ✓
REAR BUMPER CORNER BRACKET L/R	2	bent	283.40	283.40 BT ✓
REAR BUMPER INNER SPONGE	1	deformed	281.50	✓ 281.50 CUT ✓
REAR BUMPER LOWER COVER	1	deformed	261.60	✓ 261.60 BT ✓
REAR BUMPER REFLECTOR L/R	2	fractured	363.80	181.90 363.80 CUT ✓
REAR BUMPER REINFORCEMENT	1	bent	591.60	591.60 BT ✓
REAR BUMPER SIDE LOWER BRACKET L/R	2	bent	197.00	197.00 BT ✓
REAR BUMPER SIDE RETAINER L/R	2	necessary	264.50	264.50 NEC ✓
REAR END PANEL	1	buckled	717.40	717.40 BT ✓
REAR END PANEL ANTENNA SENSOR	1	shorted	319.30	319.30 SCR XNN
REAR END PANEL INNER TOP GARNISH	1	fractured	289.90	289.90 CRA ✓
REAR END PANEL INNER TOP GARNISH CHROME L/R	2	deformed	230.60	230.60 CRA XNN
REAR EXHAUST GASKET	1	necessary	61.10	61.10 NEC ✓
REAR EXHAUST RUBBER MOUNTING	2	distorted	127.80	127.80 SVCX DIS ✓
REAR EXHAUST SILENCER BOX	1	bent	781.85	781.85 SVCX DD ✓
REAR SPARE TYRE INNER TOP UPHOLSTERY COVER	1	deformed	535.20	535.20 CUT XNN
REAR TAILGATE	1	buckled	1,217.40	1,217.40 R X
REAR TAILGATE 'LEXUS' EMBLEM	1	necessary	61.75	61.75
REAR TAILGATE 'LOGO' EMBLEM	1	necessary	61.90	61.90
REAR TAILGATE 'RX450H' EMBLEM	1	necessary	65.50	65.50
REAR TAILGATE CHROME MOULDING	1	fractured	458.30	458.30 CRA XNN
REAR TAILGATE DAMPER L/R	2	bent	2,028.60	2,028.60 SVCX
REAR TAILGATE HINGES L/R	2	bent	354.80	354.80 SVCX
REAR TAILGATE INNER CLOSE BUTTON SWITCH	1	shorted	218.30	218.30 SVCX
REAR TAILGATE INNER LUGGAGE COVER L/R	2	L-fractured	870.40	435.00 CRA XNN
REAR TAILGATE INNER PULL GARNISH	1	reuse	195.20	0.00
RR TAILGATE INNER SIDE UPHOLSTERY TRIM GARNISH L/R	2	reuse	470.40	0.00
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	1	fractured	585.10	585.10 CRA XNN
REAR TAILGATE MECHANISM LOCK	1	bent	581.95	581.95 BT ✓
REAR TAILGATE MECHANISM LOCK COVER	1	warped	95.80	95.80 BT ✓
REAR TAILGATE MECHANISM LOCK MOTOR	1	shorted	385.10	385.10 SVCX
REAR TAILGATE OPENER BUTTON SENSOR	1	shorted	195.80	195.80 SVCX
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	2	necessary	87.50	87.50 NEC ✓
REAR TAILGATE REFLECTOR L/R	2	fractured	579.80	579.80 CRA ✓
REAR TAILGATE SENSOR L/R	2	shorted	396.60	396.60 SCR XNN
REAR TAILGATE WEATHER STRIP	1	deformed	372.85	372.85 CUT ✓
REAR TAILGATE WINDSCREEN MOULDING	1	necessary	181.25	181.25 NNX
REAR TAILLAMP BACK RUBBER GASKET L/R	2	necessary	57.20	57.20 NEC ✓

PAR Automotive Consultancy**REAR TAILLAMP L/R**

	2	fractured	1,205.40	1,205.40	CRA ✓
	Subtotal before discount		S\$ 18,810.25	S\$ 17,709.25	
Percentage discount	10%	and 10%	S\$ 1,881.03	S\$ 1,770.93	
	Sub-total 1		S\$ 16,929.23	S\$ 15,938.33	
REAR BUMPER CLIPS - SET	1	necessary	50.00	50.00	} NEC ✓
REAR BUMPER LOWER COVER CLIPS - SET	1	necessary	50.00	50.00	
REAR BUMPER REVERSE SENSOR - SET	1	shorted	650.00	650.00	SCR ✓
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	30.00	30.00	} NEC ✓
REAR FENDER INNER SHIELD CLIPS L/R - SET	2	necessary	60.00	60.00	
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	2	necessary	100.00	100.00	
REAR TAILGATE CHROME MOULDING CLIPS - SET	1	necessary	30.00	30.00	
REAR TAILGATE INNER LUGGAGE COVER CLIPS L/R - SET	2	necessary	60.00	60.00	} NEC ✓
REAR TAILGATE INNER SIDE UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	2	necessary	60.00	60.00	
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	2	necessary	100.00	100.00	} NEC ✓
REAR TAILGATE REVERSE CAMERA	1	shorted	800.00	800.00	
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100.00	NNX
REAR TAILLAMP CLIPS - SET	1	necessary	30.00	30.00	NECV
	Subtotal before discount		S\$ 2,120.00	S\$ 2,120.00	
	Sub-total 2		S\$ 2,120.00	S\$ 2,120.00	
	Parts-total		S\$ 19,049.23	S\$ 18,058.33	

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	100.00	50.00 80.00	
To remove, reinstall tailgate windscreen	300.00	150.00 80.00	
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	150.00	60.00	
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,900.00	600.00 1,500.00	+300 = 900
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	250.00	80.00 200.00	
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,700.00	600.00 1,250.00	+200 = 800
To apply anti-rust chemical on repaired and replaced panel.	120.00	60.00 90.00	
	Labour Total	S\$ 4,520.00	S\$ 3,330.00
	Parts & Labour Total	S\$ 23,569.23	S\$ 21,388.33

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 18,200.00
and the recommended number of working days for the repairs is within 10 day(s).

B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

Repair days 7

TGlim
Wim
26/9/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 1994S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	CENTER EXHAUST GASKET	NOT NECESSARY	18.50	-
4	CENTER EXHAUST RUBBER MOUNTING	SERVICEABLE	155.60	-
1	CENTER EXHAUST SILENCER	SERVICEABLE	1,850.30	-
1	REAR BUMPER	DENTED	752.40	752.40
2	REAR BUMPER CORNER BRACKET L/R	BENT	283.40	283.40
1	REAR BUMPER INNER SPONGE	CUT	281.50	281.50
1	REAR BUMPER LOWER COVER	BENT	261.60	261.60
2	REAR BUMPER REFLECTOR L/R	CUT 1PC ONLY	363.80	181.90
1	REAR BUMPER REINFORCEMENT	BENT	591.60	591.60
2	REAR BUMPER SIDE LOWER BRACKET L/R	BENT	197.00	197.00
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	264.50	264.50
1	REAR END PANEL	BENT	717.40	717.40
1	REAR END PANEL ANTENNA SENSOR	NOT NECESSARY	319.30	-
1	REAR END PANEL TOP GARNISH	CRACKED	289.90	289.90
2	REAR END PANEL TOP GARNISH CHROME L/R	NOT NECESSARY	230.60	-
1	REAR EXHAUST GASKET	NECESSARY	61.10	61.10
2	REAR EXHAUST RUBBER MOUNTING	DISTORTED	127.80	127.80
1	REAR EXHAUST SILENCER BOX	DENTED	781.85	781.85
1	REAR SPARE TYRE INNER TOP UPHOLSTERY COVER	NOT NECESSARY	535.20	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,217.40	-
1	REAR TAILGATE 'LEXUS' EMBLEM	NECESSARY	61.75	61.75
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	61.90	61.90
1	REAR TAILGATE 'RX450H' EMBLEM	NECESSARY	65.50	65.50
1	REAR TAILGATE CHROME MOULDING	NOT NECESSARY	458.30	-
2	REAR TAILGATE DAMPER L/R	SERVICEABLE	2,028.60	-
2	REAR TAILGATE HINGES L/R	SERVICEABLE	354.80	-
1	REAR TAILGATE INNER CLOSE BUTTON SWITCH	SERVICEABLE	218.30	-
2	REAR TAILGATE INNER LUGGAGE COVER L/R	NOT NECESSARY	870.40	-
1	REAR TAILGATE INNER PULL GARNISH	REUSE	195.20	-
2	RR TAILGATE INNER SIDE UPHOLSTERY TRIM GARNISH L/R	REUSE	470.40	-

Report Ref No. CS3/AXA18001787/Grbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	NOT NECESSARY	585.10	-
1	REAR TAILGATE MECHANISM LOCK	BENT	581.95	581.95
1	REAR TAILGATE MECHANISM LOCK COVER	BENT	95.80	95.80
1	REAR TAILGATE MECHANISM LOCK MOTOR	SERVICEABLE	385.10	-
1	REAR TAILGATE OPENER BUTTON SENSOR	SERVICEABLE	195.80	-
2	REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	NECESSARY	87.50	87.50
2	REAR TAILGATE REFLECTOR L/R	CRACKED	579.80	579.80
2	REAR TAILGATE SENSOR L/R	NOT NECESSARY	396.60	-
1	REAR TAILGATE WEATHERSTRIP	CUT	372.85	372.85
1	REAR TAILGATE WINDSCREEN MOULDING	NOT NECESSARY	181.25	-
2	REAR TAILLAMP BACK RUBBER GASKET L/R	NECESSARY	57.20	57.20
2	REAR TAILLAMP L/R	CRACKED	1,205.40	1,205.40
	LESS 10% DISCOUNT		-1,881.02	-796.16
			16,929.23	7,165.44
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	40.00
1	SET REAR BUMPER LOWER COVER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SCRATCHED	650.00	350.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	25.00
2	SET REAR FENDER INNER SHIELD CLIPS L/R (SN)	NECESSARY	60.00	40.00
2	SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R (SN)	NOT NECESSARY	100.00	-
1	SET REAR TAILGATE CHROME MOULDING CLIPS (SN)	NECESSARY	30.00	20.00
2	SET REAR TAILGATE INNER LUGGAGE COVER CLIPS L/R (SN)	NECESSARY	60.00	40.00
2	SET REAR TAILGATE INNER SIDE UPHOLSTERY TRIM GARNISH CLIPS L/R (SN)	NECESSARY	60.00	40.00
2	SET REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS (SN)	NECESSARY	100.00	50.00
1	REAR TAILGATE REVERSE CAMERA (SN)	SERVICEABLE	800.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REAR TAILLAMP CLIPS (SN)	NECESSARY	30.00	30.00
			2,120.00	665.00

Report Ref No. CS3/AXA18001787/Grbs2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		100.00	50.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		300.00	80.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		150.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,900.00	900.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		250.00	80.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE BAOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR TAILGATE.		1,700.00	800.00
	TO APPLY ANTI-RUST CHEMICAL ON REPIRED AND REPLACED PANEL.		120.00	60.00
			4,520.00	2,030.00
	GRAND TOTAL		23,569.23	9,860.44
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,850.00

Report Ref No. CS3/AXA18001787/Grbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.