

ASS. REC. BY:

REF: CS/FCI18017436 / Dgd3/12

Special Instruction:

Surveyor:

Brynn

ASSIGNMENT (Office)

(WS)

From (Person):

Eileen Lee

of

FCI

Date/Time:

25/9/18 @ 2.57pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 7986S

Insured:

SH 3188E

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

AMK Autopoint #01-05

Policy No:

Claim No:

018007007MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/04/18

CA / REV / REP. / REV 24 HRS (wp)

26/09/18 @

H.O.D. Endorsement:

Date/Time:

2.58pm @ 25/9/18

Person Contacted:

Lynn

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SH 7986S - CS/FCI18013255 / R/d 3e2
	SH 3188E - X.
03/10/18 @ 2.13pm	revised to Eileen Lee by email.

DoA: 19/7/18

REF:

ASSIGNMENT

COE Sept 2021

From: _____ Date: _____
 Unlimited Cost
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Est. of Market Value:

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs: 10 8 days Res: Yes or No


Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 7986 S Yr Regn: 2013 / Sept
 Type: M/Gar / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover /
 Truck / Trailer or
 Make: Mercedes Benz E 220 cc 2143
 Colour: White A/C, Insured / Std / HI / HA
 Sp. Branding: 579687 T/Audio, Insured / Std / HI / HA
 Eng/No: 65192431508051
 ChNo: WDD2120022A758683
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brakes: Good / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rin / STD A/Rin or
 Tyre Size: F: 205/60 R16
 R: ———



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake

Front Rear
 R/Del. 6 mm R/Del. 6 mm
 L/Del. 6 mm L/Del. 6 mm
 D.O.A. 21/09/2019 D.O.I. 25/09/2019
 Survey held at Chuppi AMIC

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 16/10/18 First Capital SH 3188E
 given 2/5 13000/- wtu 10 days
 (Red & 7444.54, 36%)

RECEIVED 16 OCT 2018

Date/Time, Fee Paid to:

1) 16/10 typist

Date/Time, Fee Return to:

2)

☐ Prel. Report
☐ Final Report

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Weekend (\$)

Report Format: TP

Lump Sum / I.D.A. (%) 13000

Survey Fee:

Transportation:

Phone:

Others:

17/10/18

10x15=150

170+150

50

50+50

114

584

MOTOR SURVEY ASSIGNMENT

Date	24-09-2018	Our Ref No. D18007007MFSH
Accident Date	21-09-2018	Claim Type. Third Party
Insured Vehicle	SH3188E	Third Party Vehicle. SH7986S
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	MS LYNN OR MS IRENE AT 65425119 OR 6542 7162	
Contact No.	65425119/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 3 October 2018 2:13 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007007MFSH/1
Attachments: CSFCI18017436Dqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SH 7986S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 25 September 2018 3:03 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007007MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 26/09/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 25 September 2018 2:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007007MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007007MFSH
Our Ref: CS/FCI18017436/Dqd3

Date: 03 October 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SH 7986S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/09/2018 at the premises of M/s CHUNNI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 20,444.54 .
Revised Estimate Amount	: S\$ 16,151.94 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the o/s front portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SH 7986S

DATE : 24.09.2018

MAKE :

TEL : 6542 5119

MODEL : MERCEDES

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bumper Assy, Frt <i>Replaced</i>			\$ 1,890.50	✓
	Bumper Bracket, Frt/RH <i>Hole</i>			\$ 95.00	X
	Head Lamp Assy (RH) <i>broken</i>			\$ 2,380.00	✓
	Head Lamp Bracket (RH) <i>broken</i>			\$ 300.00	✓
	Fender, Frt/RH <i>Replaced</i>			\$ 996.08	✓
	Fender Splashshield, Frt/RH (Front) <i>deformed</i>			\$ 257.00	✓
	Wheel Rim, RH <i>Crack</i>			\$ 1,250.00	✓
	Tyre 205/60R16 Yokohama, RH <i>new</i>			\$ 480.00	X
	Wheel Hub Bearing, Frt, RH <i>new</i>			\$ 1,250.00	✓
	S/Absorber, Front RH <i>distorted</i>			\$ 944.00	✓
	Strut, Frt/RH <i>new</i>			\$ 604.00	X
	Steering Knuckle Arm, Frt/RH <i>distorted</i>			\$ 1,119.00	✓
	Lower Arm Assy, Frt/RH <i>distorted</i>			\$ 661.05	✓
	Lower Arm Bolt <i>NA</i>			\$ 55.00	X
	Top Arm Assy, Frt/RH <i>distorted</i>			\$ 479.15	✓
	Torsion Bar Rod, Frt/RH <i>distorted</i>			\$ 105.60	✓
	Torsion Bar Frt/RH <i>distorted</i>			\$ 405.00	✓
	P/Steering Gear Assy <i>new</i>			\$ 7,167.00	X
			19204.38		
			17283.94		
	SUB TOTAL			\$ 20,438.38	
	LESS 10%			\$ 2,043.84	
	DISCOUNTED TOTAL			\$ 18,394.54	
	Labour Charge				
	Panel Beating			\$ 600.00	400/-
	Spray Painting Charge			\$ 500.00	400/-
	Wiring Charge			\$ 50.00	NA
	Towing Charges			\$ 50.00	NA
	Tuff Kote			\$ 50.00	NA
	Remove/Refix Undercarriage (FRT)			\$ 200.00	150/-
	FRT Wheel Alignment			\$ 120.00	60/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	NA
			1010.00		
	26/09/2018 e 0908hrs TOTAL LABOUR			\$ 2,050.00	
	Not Antimal				
	L/Sum 10 days			\$ 20,444.54	
	ryan LKK Auto			18293.94	
			L/S	13000/-	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					part prices too high

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SH 7986 S

Technician:

Mileage: 579687

Time Printed 26.9.18 10:02 AM

Mercedes-Benz 212 (E) Sedan Steel

Front : Left

Actual	BEFORE	Specified Range
0°19'		-1°07' -0°27'
6°24'		-5°30' 15°30'
0°07'		-0°21' 55°14'
16°27'		
16°46'		
		-2°19' -1°19'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-15°11'		-1°07' -0°27'
6°29'		-5°30' 15°30'
-22°05'		-0°21' 55°14'
28°06'		
12°55'		
		-2°19' -1°19'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
15°30'		-0°20' 0°20'
-0°05'		-1°30' 1°30'
-11°39'		
-21°58'		-0°41'

Rear : Left

Actual	BEFORE	Specified Range
-1°27'		-1°32' -0°32'
-0°35'		-0°05' 0°25'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°28'		-1°32' -0°32'
0°51'		-0°05' 0°25'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°02'		-0°30' 0°30'
0°16'		0°05' 0°35'
-0°43'		-0°15' 0°15'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18017436/Dqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 3188E	Veh. Inspected	SH 7986S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007007MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	25/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E220	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD2120022A758683	Colour	WHITE	
Odometer	579687	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2018	Inspection Date	26/09/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7986S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER ASSY,FRT	DENTED	1,890.50	1,890.50
1	BUMPER BRACKET,FRT/RH	NOT NECESSARY	95.00	-
1	HEAD LAMP ASSY (RH)	BROKEN	2,380.00	2,380.00
1	HEAD LAMP BRACKET (RH)	BENT	300.00	300.00
1	FENDER,FRT/RH	DENTED	996.08	996.08
1	FENDER SPLASHSHIELD,FRT/RH (FRONT)	DEFORMED	257.00	257.00
1	WHEEL RIM,RH	CUT	1,250.00	1,250.00
1	TYRE 205/60R16 YOKOHAMA,RH	SERVICEABLE	480.00	-
1	WHEEL HUB BEARING,;FRT,RH	DAMAGED	1,250.00	1,250.00
1	S/ABSORBER FRONT RH	DISTORTED	944.00	944.00
1	STRUR,FRT/RH	NOT NECESSARY	604.00	-
1	STEERING KNUCKLE ARM,FRT/RH	DISTORTED	1,119.00	1,119.00
1	LOWER ARM ASSY,FRT/RH	DISTORTED	661.05	661.05
1	LOWER ARM BOLT	NOT NECESSARY	55.00	-
1	TOP ARM ASSY,FRT/RH	DISTORTED	479.15	479.15
1	TORSION BAR ROD,FRT/RH	DISTORTED	105.60	105.60
1	TORSION BAR FRT/RH	DISTORTED	405.00	405.00
1	P/STEERING GEAR ASSY	DAMAGED	7,167.00	7,167.00
	LESS 10% DISCOUNT		-2,043.84	-1,920.44
			18,394.54	17,283.94
LABOUR				
	PANEL BEATING.		600.00	400.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TOWING CHARGES.	NOT NECESSARY	50.00	-
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			2,050.00	1,010.00

Report Ref No. CS/FCI18017436/Dqd3n2



GRAND TOTAL		20,444.54	18,293.94
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,000.00

Report Ref No. CS/FCI18017436/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.