

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 286Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT O/S DOOR (CONSISTENT)	BUCKLED	1,760.00	1,760.00
1	FRONT O/S DOOR RUBBER (CONSISTENT)	SERVICEABLE	275.00	-
1	FRONT O/S DOOR INNER LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	245.00	-
1	FRONT O/S DOOR OUTER HANDLE (CONSISTENT)	DISTORTED	155.00	155.00
1	FRONT O/S DOOR GLASS REGULATOR GEAR (CONSISTENT)	DISTORTED	340.00	340.00
1	FRONT O/S DOOR OUTER MOULDING (CONSISTENT)	SERVICEABLE	127.00	-
1	FRONT O/S DOOR LOWER GARNISH (CONSISTENT)	BUCKLED	182.00	182.00
2	FRONT O/S DOOR HINGE @\$188.00 (CONSISTENT)	BENT	376.00	376.00
1	FRONT O/S DOOR CHECKER (CONSISTENT)	SERVICEABLE	122.00	-
1	FRONT O/S DOOR PROTECTOR (CONSISTENT)	NECESSARY	95.00	95.00
	LESS 15% DISCOUNT		-551.55	-436.20
			3,125.45	2,471.80
	SPECIAL NETT ITEMS			
1	FRONT O/S DOOR COMPANY LOGO (CONSISTENT)(SN)	NECESSARY	180.00	120.00
			180.00	120.00
	<u>LABOUR</u>			
	TO PUTTY AND SPRAY REPLACED PARTS.		500.00	320.00
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT O/S DOOR INNER LOCK.		400.00	250.00
			900.00	570.00
	GRAND TOTAL		4,205.45	3,161.80

RECOMMENDED COST OF LUMP SUM REPAIRS		2,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM18017451/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser