

1012 TP / A & A  
25/9/18 - 4301

**Ah Lim Motor Company**  
**10 Ang Mo Kio Industrial**  
**Park 2A**  
**#01-09 AMK Autopoint**  
**Singapore 568047**

SURVEYOR COPY

**Claim Reference:**  
**Assessment Number: AH000935**  
**Version: AHLIM001/1**  
**Date Calculated: 21/09/2018 08:10**

**Full Report - V1**  
**Registration: SGW2384A**  
**Printed: 21/09/2018 15:11**

### Summary Information

|                       |                              |                            |     |
|-----------------------|------------------------------|----------------------------|-----|
| <b>Claim</b>          |                              |                            |     |
| Location:             | Singapore (SG)               | Currency:                  | SGD |
| Printed by:           | Ahlim ahlim                  | Date of Incident:          |     |
| Authorisation Status: | Interim                      | Able to Authorise Repairs: | TBA |
| Work Provider:        | AXA Insurance S'pore Pte Ltd | Repairs Authorised:        | TBA |
| Claim Reference:      | 3rd party                    | Estimated Repair Time:     |     |
| Policy Number:        |                              | Quote Due Date:            |     |
| Other Reference:      |                              | Actual Repair Days:        |     |
| Third Party:          |                              | Parts Ordered Date:        |     |
| Insured Amount:       |                              | Hire Car Start:            |     |
| Under Warranty:       |                              | Hire Car End:              |     |
| Warranty Expired:     |                              | Vehicle Collected:         |     |

### Vehicle Details

|                     |                   |                    |                     |
|---------------------|-------------------|--------------------|---------------------|
| <b>Vehicle</b>      |                   | <b>Model Specs</b> |                     |
| Manufacturer:       | SUZUKI            | FRONT DRIVE        | 5-DOOR              |
| Model:              | SX4               | TWO COAT METALLIC  | PREPARE OFF VEHICLE |
| Sub Model:          | GL                |                    |                     |
| Model Sheet Number: | R50 05            |                    |                     |
| Registration:       | SGW2384A          |                    |                     |
| Registration Month: | July              |                    |                     |
| Registration Year:  | 2007              |                    |                     |
| VIN Number:         | JSAGYA21S00107324 |                    |                     |
| Manufacture Year:   | 2007              |                    |                     |
| Odometer:           | Not Known         |                    |                     |
| Colour:             |                   |                    |                     |
| Engine Number:      | M16A1267434       |                    |                     |
| Fuel Level:         | %                 |                    |                     |

### Vehicle Condition

|                         |                               |            |
|-------------------------|-------------------------------|------------|
| <b>Vehicle Status</b>   |                               |            |
| Pre-Accident Condition: | Severity of Impact:           |            |
| Steering:               | Vehicle Status on Inspection: |            |
|                         | Date of Inspection:           | 21/09/2018 |
| Brakes Pedal Travel:    |                               |            |
| Place of Inspection:    |                               |            |
| Pre-Accident Damage:    |                               |            |
| Tyres Condition:        | Tread Depth RHF:              |            |
| Tread Depth LHF:        | Tread Depth RHR:              |            |
| Tread Depth LHR:        | Direction of Impact:          |            |
| Damage Areas:           |                               |            |

# Ah Lim Motor Company

Claim Reference:

Assessment Number: AH000935



Version: AHLIM001/1

Date Calculated: 21/09/2018 08:10

Full Report - V1

Registration: SGW2384A

Printed: 21/09/2018 15:11



## Addresses

## Cost Summary

|                      |            |        |
|----------------------|------------|--------|
| Total Labour         | \$639.00   | 594    |
| Total Paint/Material | \$139.00   | =      |
| Total Parts          | \$466.90   | =      |
| Excess:              | TBA        |        |
| Grand Total Exc GST: | \$1,244.90 |        |
| 7 % GST:             | \$87.14    |        |
| Grand Total Inc GST: | \$1,332.04 | 1199.9 |

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$45.00/HR

### Repair /

### Guide Number Repair Details

|           |                                       |
|-----------|---------------------------------------|
| HP01R0)   | R + R RIGHT REAR WHEEL                |
| 689)      | R + R RIGHT REAR WHEEL ARCH COVER     |
| NO NUMBER | DETACH + REFIT L/WHEELARCH TRIM       |
| 677       | R + R LEFT TAILLAMP                   |
| 677       | R + R RIGHT TAILLAMP                  |
| 661)      | R + R REAR BUMPER                     |
| 501       | RENEW REAR BUMPER                     |
| NO NUMBER | R + R RIGHT REAR OUTER BUMPER BRACKET |
| 1782      | REPAIR R/R DOOR                       |
| 3482      | REPAIR R/R SIDE PANEL CPL             |

| WU       | Cost Price (\$) |
|----------|-----------------|
| 1.0      | 4.50 ✓          |
| 2.0      | 9.00 ✓          |
| 1.0      | 4.50 ✓          |
| 1.0      | 4.50 ✓          |
| 1.0      | 4.50 ✓          |
| 2.0      | 9.00 ✓          |
| 5.0      | 22.50 ✓         |
| 1.0      | 4.50 ✓          |
| 10.0*    | 45.00 ✓         |
| 30.0* 20 | 135.00 90       |

### LABOUR COST

|                                      |
|--------------------------------------|
| Total Work Units                     |
| Corrosion Protection External Labour |
| Corrosion Protection Internal Labour |
| Sub Total                            |
| Paint Labour                         |
| Total Labour                         |

|         |                 |
|---------|-----------------|
| 54.0    |                 |
| 0.0HRS  | 0.00            |
| 0.0HRS  | 0.00            |
| 5.4HRS  | \$243.00 198.00 |
| 8.8HRS  | \$396.00 594    |
| 14.2HRS | \$639.00        |

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

### Guide Number Description

|      |   |
|------|---|
|      | - TWO COAT METALLIC                     |
|      | - PREPARE OFF VEHICLE                   |
| 2581 | REAR BUMPER REPAIR PAINT PLASTIC        |
| 1782 | R/R DOOR REPAIR PAINTING >50%           |
| 3482 | R/R SIDE PANEL CPL REPAIR PAINTING >50% |

| WU   | Cost Price (\$) |
|------|-----------------|
| 16.0 |                 |
| 21.0 |                 |
| 18.0 |                 |

### LABOUR COST - PAINT

|                               |
|-------------------------------|
| TIME(PAINT)                   |
| Preparation Main Work Plastic |

|        |
|--------|
| 55.0 ✓ |
| 8.0 ✓  |



# Ah Lim Motor Company

Claim Reference:

Assessment Number: AH000935

Version: AHLIM001/1

Date Calculated: 21/09/2018 08:10

Full Report - V1

Registration: SGW2384A

Printed: 21/09/2018 15:11

|                                    |        |                   |
|------------------------------------|--------|-------------------|
| Preparation Main Work Metal        | 25.0   |                   |
| Preparation Work Multi Layer Paint | 0.0    |                   |
| Total Work Units (10WU/HR)         | 88.0   |                   |
| Total Paintwork Labour             | 8.8HRS | \$396.00          |
| <b>MATERIAL COST - PAINT</b>       |        | <b>Cost Price</b> |
| Repair Painting                    |        | \$44.64           |
| Repair Painting Plastic            |        | \$53.06           |
| Material-Const Main Work Plastic   |        | \$12.70           |
| Total Excluding Pearlescent Uplift |        | \$139.00          |
| Pearlescent Uplift @ 0.0%          |        | \$0.00            |
| Total Paint Material Cost          |        | \$139.00          |

## PARTS

| Guide No.     | Qty | Description          | Part Number        | Supplier | Bet. | Price (\$)      |
|---------------|-----|----------------------|--------------------|----------|------|-----------------|
| 2581          | 1   | REAR BUMPER          | 7181180J00799      |          | 0%   | 370.00*         |
| 2620          | 1   | R/R OUT BUMPER BRKT  | 7182180J00000      |          | 0%   | 16.00*          |
| 2650          | 1   | REAR BUMPER MNTG KIT | USE SINGLE PARTS   |          | 0%   | 20.00*          |
| f: OEM Parts  |     |                      | Sub Total          |          |      | \$406.00        |
| g: Original   |     |                      | Mark Up From Cost  | (15 %)   |      | \$60.90         |
| h: Secondhand |     |                      | <b>Total Parts</b> |          |      | <b>\$466.90</b> |
| p: Parallel   |     |                      |                    |          |      |                 |
| x: Exchange   |     |                      |                    |          |      |                 |

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Total Extras

\$0.00

## Final Calculation

|                                   |          |                                |
|-----------------------------------|----------|--------------------------------|
| <b>Total Parts</b>                |          | \$466.90                       |
| <b>Labour</b>                     |          |                                |
| Total Panel/Mechanical            | \$243.00 |                                |
| Total Paintwork                   | \$396.00 |                                |
| <b>Total Labour</b>               |          | <del>\$639.00</del> 594.00     |
| <b>Total Paint/Material Costs</b> |          | \$139.00                       |
| <b>Grand Total Excludes GST</b>   |          | <del>\$1,244.90</del> 1,194.90 |
| GST @ 7 %                         |          | \$87.14                        |
| <b>Grand Total Includes GST</b>   |          | <b>\$1,332.04</b>              |

## Assessment Notes

3 Days.  
 Part by part.  
 before paint photos.  
 En. Qiap - 82880282  
 25/9/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: