Charn's Customcraft 1010 Bukit Merah Lane 3 Singapore 159724

Claim Reference: THIRD PARTY Assessment Number: CC000017

Version: CHARNCUS/1

Date Calculated: 21/09/2018 04:21

Full Report - V1 Registration: SLR6778M

Printed: 21/09/2018 11:22

PREPARE OFF VEHICLE

Summary Information

Claim

Location: Singapore (SG) Currency: SGD

Printed by: Sharon Lee Date of Incident:

Authorisation Status: Interim Able to Authorise Repairs: TBA Work Provider: AXA Insurance S'pore Pte Repairs Authorised: TBA

Ltd

Claim Reference: THIRD PARTY Estimated Repair Time:

Policy Number:
Other Reference:
Actual Repair Days:
Third Party:
Parts Ordered Date:
Insured Amount:
Under Warranty:
Warranty Expired:
Hire Car End:
Vehicle Collected:

Vehicle Details

Vehicle Model Specs

Manufacturer:HYUNDAIFROM 05/2016AIR CONDITIONINGModel:TucsonWINDSCREEN HEATEDTOUCHSCREENSub Model:BASE MODELFOG LAMPSADAPTIVE HEADLAMPS

Model Sheet Number: 3046 01 LED TAILLAMPS HEADLAMP WASHERS
Registration: SLR6778M RAIN SENSOR 1.6 LTR 130 KW

TWO COAT METALLIC

Registration Month: CRUISE CONTROL WHEELS 7J X 18 ALLOY Registration Year: PRODUCTION CZECH REP STARTER BUTTON

Odometer: Not Known

Colour: Engine Number:

Vehicle Status

VIN Number:

Englis Number.

Fuel Level: %

Vehicle Condition

Pre-Accident Condition: Severity of Impact:

Steering: Vehicle Status on

Inspection:

Brakes Pedal Travel: Date of Inspection: 21/09/2018

Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth RHF: Tread Depth RHR: Damage Areas: Tread Depth RHR: Direction of Impact:


Charn's Customcraft


Claim Reference: THIRD PARTY Assessment Number: CC000017

Version: CHARNCUS/1

Date Calculated: 21/09/2018 04:21

Full Report - V1 **Registration: SLR6778M** Printed: 21/09/2018 11:22





Addresses

Cost	Su	mm	ary
------	----	----	-----

Total Labour	\$738.00
Total Paint/Material	\$174.05
Total Parts	\$787.75
Total of Additional Costs	\$280.00
Excess:	TBA
Grand Total Exc GST:	\$1,979.80
7 % GST:	\$138.59
Grand Total Inc GST:	\$2,118.39

Repair Information

1 4	ĸ	HIK

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR **Price/Dent = \$45.00/HR**

Repair /			, ,
Guide Numb	er Repair Details	WU	Cost Price (\$)
86611R00	RENEW REAR LOWER BUMPER (REMOVED)	8.0	36.00
86630R00)	R + R REAR BUMPER CARRIER	2.0	9.00
NN	REAR BUMPER R&R / NEW PARTS	20.0*	90.00
2931	REPAIR BOOTLID/TAILGATE	10.0*	45.00
2986	REPAIR BOOT/T-GATE MOULDING	10.0*	45.00
3941	REPAIR REAR PANEL	10.0*	45.00
LA	BOUR COST		

Total Work Units	60.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	6.0HRS	\$270.00
Paint Labour	10.4HRS	\$468.00
Total Labour	16.4HRS	\$738.00

PAINT WO	RK Time Basis	10 WU = 1 HR. Price	e = \$45.00/HR
Guide Num	ber Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
2583	REAR BUMPER NEW PART PAINT K1R	10.0	
2986	BOOT/T-GATE MOULDINGREPAIR PAINT PLASTIC	11.0	
2931	BOOTLID/TAILGATE REPAIR PAINTING >50%	31.0	
3941	REAR PANEL REPAIR PAINTING >50%	19.0	
L	ABOUR COST - PAINT		
	TIME(PAINT)	71.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	

Charn's Customcraft

Claim Reference: THIRD PARTY Full Report - V1 Assessment Number: CC000017 Registration: SLR6778M

Version: CHARNCUS/1 Printed: 21/09/2018 11:22

Date Calculated: 21/09/2018 04:21

Total Work Units (10WU/HR)	104.0	
Total Paintwork Labour	10.4HRS	\$468.00
MATERIAL COST - PAINT		Cost Price
New Part Painting - Plastic K1R		\$45.76
Material-Constant Main Work Metal		\$28.60
Repair Painting		\$67.55
Repair Painting Plastic		\$19.44
Material-Const Main Work Plastic		\$12.70
Total Excluding Pearlescent Uplift		\$174.05
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$174.05

PARTS

					Price Valid	: 01/06/2015
Guide N	lo.Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	EMBLEM 'S'	Renew		0%	10.00*
1000	1	EMBLEM 'TURBO'	Renew		0%	40.00*
2585	1	LOWER REAR BUMPER	86612D7000		0%	190.00*
2583	1	REAR BUMPER	86611D7000		0%	260.00*
2640	1	REAR BUMPER SUPPORT	86631D7000		0%	165.00 *
1000	1	TUCSON EMBLEM	Renew		0%	20.00*
f: OEM I	Parts		Sub Total			\$685.00
g: Origii	nal		Mark Up Fr	rom Cost	(15 %)	\$102.75
h: Seco	ndhand		Total Part	ts		\$787.75
n: Daral	اما					-

p: Parallel x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REVERSE SEN CTR LHSPECIA	ALIST 0%	\$140.00
REVERSE SEN CTR SPECIA	ALIST	\$140.00
RH		
	Total Extras	\$280.00

Final Calculation		
Total Parts		\$787.75
Labour		
Total Panel/Mechanical	\$270.00	
Total Paintwork	\$468.00	
Total Labour		\$738.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$280.00	
Total of Additional Costs		\$280.00
Total Paint/Material Costs		\$174.05
Grand Total Excludes GST		\$1,979.80

Assessment Notes

GST @ 7 %

Grand Total Includes GST

\$138.59

\$2,118.39

Charn's Customcraft

Claim Reference: THIRD PARTY Assessment Number: CC000017

Version: CHARNCUS/1

Date Calculated: 21/09/2018 04:21

CC000017 Registration: SLR6778M Printed: 21/09/2018 11:22 09/2018 04:21

Full Report - V1