



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDV8886U

Ms Ong Geok Lan, Landy

16 Ang Mo Kio Central 3
#12-25
Singapore 567748

Vehicle & Document Information

WIP No 27087
Reg No/Reg Date SDV8886U / 11/02/2015
Date In/Mileage 26/09/2018 / 52719
Chassis No WDD2050402R038594
Engine No 27491030318343
Make/Model MB/MB C 180 SEDAN (W205) *AVANTGARDE / A
Colour/Trim 028 890 Cavansit B1/ 041 115 Pebble

Account No	Terms	Date/Time Printed	CSE	Operator					
CS100001	Cash	30/11/2018/ 18:00		356 / Vincent Seah					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
M BPNSUN POLICY NO/ACC DATE : GA056815/1 // 22.09.18 TOW IN/EXCESS : 23.09.18 // \$500 DATE IN/DATE SURVEY: 23.09.18// 26.09.18 TAUFIKH=LKK 14:00PM BY/AUTHORIZED ON : TAUFIKH=LKK // 26.09.18									
S BPNTOW ACCIDENT TOWING FROM 16 ANG MO KIO CENTRAL 3 TO PLSC USING KING DOLLEY W0: 153757								150.00	
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT							0.10	380.00	
A BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT								120.00	
S BPNSUB SUPPLY 1 PC NO PLATE								60.00	
A BPILAB DISASSEMBLE AND REPLACE ON FRONT BUMPER, BONNET, RH/LHF FENDER , FRONT SUPPORT PANEL								3840.00	
A BPIRES RESPRAY ON FRONT BUMPER, RH/LH FRONT FENDER , BONNET								2400.00	
X BPNEXC INSURANCE EXCESS								-500.00	
X FRONT BUMPER					1.00	1506.37	00.00	1506.37	
X FRONT BUMPER CENTRE CHROME MOULDING					1.00	172.64	00.00	172.64	
X FRONT BUMPER LOWER GRILLE					1.00	120.86	00.00	120.86	
X LICENSE PLATE MOLDING					1.00	120.86	00.00	120.86	
X LHF FOGLAMP COVER					1.00	75.40	00.00	75.40	
X LEFT FOGLAMP BOTTOM ORNAMENTAL MOLDING					1.00	54.36	00.00	54.36	
X TOP LEFT FOGLAMP ORNAMENTAL MOLDING					1.00	65.23	00.00	65.23	
X LEFT BASIC MOUNTING FOR BUMPER					1.00	68.53	00.00	68.53	
X RIGHT BASIC MOUNTING FOR BUMPER					1.00	68.53	00.00	68.53	
X BOTTOM BASIC MOUNTING FOR BUMPER					1.00	102.80	00.00	102.80	

Confirmed & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDV8886U

Ms Ong Geok Lan, Landy

16 Ang Mo Kio Central 3
#12-25
Singapore 567748

Vehicle & Document Information

WIP No **27087**
Reg No/Reg Date **SDV8886U / 11/02/2015**
Date In/Mileage **26/09/2018 / 52719**
Chassis No **WDD2050402R038594**
Engine No **27491030318343**
Make/Model **MB/MB C 180 SEDAN (W205) *AVANTGARDE / A**
Colour/Trim **028 890 Cavansit Bl/ 041 115 Pebble**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	30/11/2018/ 18:00		356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X TOP BASIC MOUNTING FOR BUMPER	1.00	63.42	00.00	63.42
X IMPACT ABSORBER	1.00	149.56	00.00	149.56
X PRESSURE SENSOR	1.00	182.62	00.00	182.62
X SEALING FRONT END	1.00	23.59	00.00	23.59
X HOOD	1.00	1999.27	00.00	1999.27
X COMPANY SIGN	1.00	78.83	00.00	78.83
X AIR DUCT	1.00	125.66	00.00	125.66
X RAD. PROTECTIVE GRILLE	1.00	130.01	00.00	130.01
X RADIATOR GRILLE BEAM	1.00	205.32	00.00	205.32
X TOP LEFT ORNAMENTAL MOLDING	1.00	60.43	00.00	60.43
X BOTTOM LEFT ORNAMENTAL MOLDING	1.00	74.70	00.00	74.70
X TOP RIGHT ORNAMENTAL MOLDING	1.00	60.43	00.00	60.43
X BOTTOM RIGHT ORNAMENTAL MOLDING	1.00	74.70	00.00	74.70
X STAR BEAM	1.00	72.06	00.00	72.06
X MERCEDES STAR	1.00	130.65	00.00	130.65
X CROSS MEMBER	1.00	407.90	00.00	407.90
X FRONT SUPPORT CONSOLE	1.00	202.17	00.00	202.17
X LEFT HEADLAMP UNIT	1.00	3126.25	00.00	3126.25
X RIGHT HEADLAMP UNIT	1.00	3126.25	00.00	3126.25
X FRONT SUPPORT PANEL	1.00	691.68	00.00	691.68
X BOTTOM AIR DUCT SEGMENT	1.00	167.52	00.00	167.52
X ELECTRICAL WIRING HARNESS	1.00	128.55	00.00	128.55
X DISTANCE SENSOR	1.00	172.07	00.00	172.07
X SPACER RING	2.00	6.42	00.00	12.84
X COVER F ENGINE COMP. BM	1.00	181.26	00.00	181.26
X DISTANCE SENSOR	1.00	172.07	00.00	172.07
X [STR] REFRIGERANT CONDENSER	1.00	1428.90	00.00	1428.90
X FIXTURE	1.00	21.11	00.00	21.11

Finalization

Confirmed & accepted by

Nett **22,075.40**
7% GST on **22075.40** **1545.28**

Total Payable **23,620.68**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-0500111-X

TAX INVOICE

Invoice Name & Address				Owner Name & Vehicle Info			
AXA INSURANCE PTE LTD				Cust No/Name	/Ong Geok Lan, Landy		
MOTOR CLAIM DEPARTMENT				Reg No/Reg Date	SDV8886U / 11/02/2015		
8 SHENTON WAY #24-01				Date In/Mileage	26/09/2018/ 52719		
SINGAPORE 068811				Chassis No	WDD2050402R038594		
Contact No				Engine No	27491030318343		
				Make/Model	MB/HB C 180 SEDAN (W205) "AVANTGARDE / A		
				Colour/Trim	028 890 Cavansit B1/ 041 115 Pebble		
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No	
CSI00001	Cash	14/12/2018/ 09:52	VS	356 / Vincent Seah	27087	28148840	
Description of Goods / Services					Qty	Unit Price S\$	Amount S\$
							F.O.C.
3PNSUN							
POLICY NO/ACC DATE : GA056815/1 // 22.09.18							
TOW IN/EXCESS : 23.09.18 // \$500							
DATE IN/DATE SURVEY: 23.09.18// 26.09.18 TAUFIKH=LKK 14:00PM							
BY/AUTHORIZED ON : TAUFIKH=LKK // 26.09.18							150.00
S BPNTOW							
ACCIDENT TOWING FROM 16 ANG MO KIO CENTRAL 3 TO PLSC							
USING KING DOLLEY							
WO: 153757							0.10 380.00
A BPILAB							
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO							
IDENTIFICATION STANDARD. NETT							120.00
A BPILAB							
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT							60.00
S BPNSUB							
SUPPLY 1 PC NO PLATE							3840.00
A BPILAB							
DISASSEMBLE AND REPLACE ON FRONT BUMPER, BONNET, RH/LHF FENDER,							
FRONT SUPPORT PANEL							2400.00
A BPIRES							
RESPRAY ON FRONT BUMPER, RH/LH FRONT FENDER, BONNET							-500.00
X BPNEXC							
INSURANCE EXCESS							1506.37
				1.00	1506.37		1506.37
X FRONT BUMPER				1.00	172.64		172.64
X FRONT BUMPER CENTRE CHROME MOULDING				1.00	120.86		120.86
X FRONT BUMPER LOWER GRILLE				1.00	120.86		120.86
X LICENSE PLATE HOLDING				1.00	75.40		75.40
X LHF FOGLAMP COVER				1.00	54.36		54.36
X LEFT FOGLAMP BOTTOM ORNAMENTAL MOULDING				1.00	65.23		65.23
X TOP LEFT FOGLAMP ORNAMENTAL MOULDING				1.00	68.53		68.53
X LEFT BASIC MOUNTING FOR BUMPER				1.00	68.53		68.53
X RIGHT BASIC MOUNTING FOR BUMPER				1.00	102.80		102.80
X BOTTOM BASIC MOUNTING FOR BUMPER				1.00			

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
AXA INSURANCE PTE LTD	Cust No/Name /Ong Geok Lan, Landy
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date SDV8886U / 11/02/2015
8 SHENTON WAY #24-01	Date In/Mileage 26/09/2018/ 52719
SINGAPORE 068811	Chassis No WDD2050402R038594
Contact No	Engine No 27491030318343
	Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
	Colour/Trim 028 890 Cavansit B1/ 041 115 Pebble

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CSI00001	Cash	14/12/2018/ 09:52	VS	356 / Vincent Seah	27087	28148840

Description of Goods / Services	Qty	Unit Price S\$	Amount S\$
(TOP BASIC MOUNTING FOR BUMPER	1.00	63.42	63.42
X IMPACT ABSORBER	1.00	149.56	149.56
X PRESSURE SENSOR	1.00	182.62	182.62
X SEALING FRONT END	1.00	23.59	23.59
X HOOD	1.00	1999.27	1999.27
X COMPANY SIGN	1.00	78.83	78.83
X AIR DUCT	1.00	125.66	125.66
X RAD. PROTECTIVE GRILLE	1.00	130.01	130.01
X RADIATOR GRILLE BEAM	1.00	205.32	205.32
X TOP LEFT ORNAMENTAL MOLDING	1.00	60.43	60.43
X BOTTOM LEFT ORNAMENTAL MOLDING	1.00	74.70	74.70
X TOP RIGHT ORNAMENTAL MOLDING	1.00	60.43	60.43
X BOTTOM RIGHT ORNAMENTAL MOLDING	1.00	74.70	74.70
X STAR BEAM	1.00	72.06	72.06
X MERCEDES STAR	1.00	130.65	130.65
X CROSS MEMBER	1.00	407.90	407.90
X FRONT SUPPORT CONSOLE	1.00	202.17	202.17
X LEFT HEADLAMP UNIT	1.00	3126.25	3126.25
X RIGHT HEADLAMP UNIT	1.00	3126.25	3126.25
X FRONT SUPPORT PANEL	1.00	691.68	691.68
X BOTTOM AIR DUCT SEGMENT	1.00	167.52	167.52
X ELECTRICAL WIRING HARNESS	1.00	128.55	128.55
(DISTANCE SENSOR	1.00	172.07	172.07
.. SPACER RING	2.00	6.42	12.84
X COVER F ENGINE COMP. BM	1.00	181.26	181.26
X DISTANCE SENSOR	1.00	172.07	172.07
X [STR] REFRIGERANT CONDENSER	1.00	1428.90	1428.90
X FIXTURE	1.00	21.11	21.11

Parts	15,625.40	Nett	22,075.40
Labour	6,740.00	7% GST on	22075.40
Standard Menu	0.00		1545.28
Specialist Job	210.00	Total Payable	23,620.68
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	-500.00	Total Due	23,620.68
Total(w/o GST)	22,075.40		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

TO:

AXA

MOTOR VEHICLE CLAIM
SATISFICATION/DISCHARGE VOUCHER

NAME OF INSURED:

Eng Heok Len Lendy

MOTOR POLICY NO:

GA 056815/2

REGISTRATION NO:

SDV 88864

ACCIDENT DATE:

22/09/17

WIP NO.:

27087


REPAIRER NAME:

CYCLE & CARRIAGE INDUSTRIES PTE LTD (CCI)
MERCEDES-BENZ SERVICE CENTRE
188 PANDAN LOOP SINGAPORE 128378

I/We certify that the vehicle has been fully repaired to my entire satisfaction and the payment of CCI's charges that are claimable under the policy will be deemed as full and final settlement of my claim.

I/We hereby release CCI from all liabilities in respect of damages to my/our motor vehicle.

SIGNATURE OF INSURED:



DATE:

09/10/17



Service Request Details

Claim S8M00WMP	Document Type
Reference CS/ASM18017460/T1qc3s2	Document SubType
Loss Date September 22, 2018	Upload Documents SDV8886U INS
Request Date February 11, 2019	
Due Date December 25, 2018	
Vendor Name LKK AUTO CONSULTANTS PTE LTD (OD)	Reports & Statement GIA Report
Type of Loss Own Damage	Merimen
Services Accelerated survey and authorize	Model C180 BLUE EFFICIENCY
	SDV8886 resurvey photo.pdf

Actions

Next Step
PAST DUE: Report that your work is blocked, and modify the Expected Completion Date.

Complete Work

More

Vehicle Information

Incident Vehicle Registration #
SDV8886U

Make
MERCEDES

AXA Immediate Advice - SDV8886U (2).pdf

Forms / Claim Documents

Others

LKK AUTO CONSULTANTS PTE LTD (OD)

December 14, 2018

SDV8886 ESTIMATE.pdf

Reports & Statement

Estimate / Quotation

LKK AUTO CONSULTANTS PTE LTD (OD)

September 27, 2018

AXA Immediate Advice - SDV8886U.pdf

Reports & Statement

Others

LKK AUTO CONSULTANTS PTE LTD (OD)

September 27, 2018

Policy Schedule.pdf

<< **Service Request Details**

Claim S8M00WMMP	Actions		Add
Reference CS/ASM18017460/T1qd3s2 	Next Step PAST DUE: Report that your work is blocked, and modify the Expected Completion Date.		KHONG Lynn
Loss Date September 22, 2018	Complete Work		9/25/18 1:23 PM
Request Date February 11, 2019	More		22075.4
Due Date December 25, 2018	Vehicle Information		22075.4
Vendor Name LKK AUTO CONSULTANTS PTE LTD (OD)	Incident Vehicle Registration # SDV8886U	Open	
Type of Loss Own Damage	Make MERCEDES	Share	
Services Accelerated survey and authorize	Model C180 BLUE EFFICIENCY	Clone	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Workshop Details						
Involving	1 2014 MERCEDES C180 BLUE EFFICIENCY (SDV8886U)		Total Rebate Amount	66188		
Date of Loss	September 22, 2018		Nett Loss Amount	\$41,812.00		
Time of Loss	18.55		Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (IOD)		
Loss Description	SDV8886U (INSD) C/AW SHC5316X (TP)		Days of work completion	7		
Comment						

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SDV8886U	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	02/11/2015
Mileage	0	Age of Vehicle	3

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	Driver Details
Manufacturing Year	2014		CATEGORY
Make	MERCEDES		FNOL INFORMATION
Model	C180 BLUE EFFICIENCY		Driver Name
Type			Date of Birth
Type of Paint			Age
Chassis No	WDD2050402R038594		Occupation
Engine No	27491030318343		Education Qualification
Engine Capacity	1595 cc		Driving Experience
			Driver License #

POST SURVEY INFORMATION
mm/dd/yyyy



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Detailed Assessment		Condition of Vehicle at time of survey	
Inspection Date *	09/26/2018	General condition	Good
Total Loss	Yes No	Steering (Serviceable)	Yes No
Towing Charges	0	Footbrake (Serviceable)	Yes No
Voluntary Excess	0	Handbrake (Serviceable)	Yes No
Compulsory Excess	500	Engine Modification	Yes No
Young/Inexperienced/Unarmed Driver Excess	0	Pre-accident condition	Good
Other Excess		Tyre Condition	
Age of Tyres		Spare wheel	
Front Tyre Size	225/50R17	Rear Tyre Size	225/50R17
Front left side	DUNLOP 6mm	Rear left side	DUNLOP 6mm
Front right side	DUNLOP 6mm	Rear right side	DUNLOP 6mm

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add

Approve

Deny

Submit All

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./BTT%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
------	-------	----------	----------	------	-----------	-------------	------------------------	-----------	------------	------------	-----------	----------	-----------------	----------------	--------

Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
------	-------	-------------------------	-----------	------------	---------------	-------	-----------------	---------	--------

	1		ACCIDENT TOWING FROM 16 ANG MO KIO CENTRAL 3 TO PLSC USING KING DOLLEY.	150	0	0	Reviewing		
	2		USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.	380	0	0	Reviewing		
	3		TO REMOVE, REPLACE HEADLAMP WITH FOCUS.	120	0	0	Reviewing		
	4		REMOVE AND REPLACE RADIATOR COOLING SYSTEM, CONDENSER WITH VACUUM AND RECHARGE REFRIGERANT.	0	0	0	Reviewing		
	5		PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT.	0	0	0	Reviewing		

<< **Assessment Details**

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add Approve Cancel Submit All						
EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		8	
	2	LEFT FRONT FENDER	Reviewing	0	REPAIR	
	3	RIGHT FRONT FENDER	Reviewing	0	REPAIR	
	4	RHF FENDER OUTER LINEAR	Reviewing	0	NOT NECESSARY	
	5	FRONT BUMPER	Reviewing	1506.37	DEFORMED	
	6	FRONT BUMPER CENTRE CHROME MOULDING	Reviewing	172.64	CUT	
	7	FRONT BUMPER LOWER GRILLE	Reviewing	120.86	DEFORMED	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	 17	RHF MOUNTING RAIL	Reviewing	0	NOT NECESSARY	
	 18	TOP BASIC MOUNTING FOR BUMPER	Reviewing	63.42	DEFORMED	
	 19	IMPACT ABSORBER	Reviewing	149.56	DEFORMED	
	 20	PRESSURE SENSOR	Reviewing	182.62	MISSING	
	 21	IMPACT ABSORBER	Reviewing	0	NOT NECESSARY	
	 22	SEALING FRONT END	Reviewing	23.59	NECESSARY	
	 23	HOOD	Reviewing	1999.27	BENT	
	 24	COMPANY SIGN	Reviewing	78.83	NECESSARY	
	 25	BONNET CATCH	Reviewing	0	NOT NECESSARY	
	 26	SPRING ELEMENT	Reviewing	0	NOT NECESSARY	
	 27	RETAINING HOOK	Reviewing	0	NOT NECESSARY	
	 28	AIR DUCT	Reviewing	125.66	DEFORMED	
	 29	RAD. PROTECTIVE GRILLE	Reviewing	130.01	CRACKED	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	42	LEFT HEADLAMP UNIT	Reviewing	3126.25	CUT	
	43	RIGHT HEADLAMP UNIT	Reviewing	3126.25	CRACKED	
	44	LEFT HEADLIGHT CONTROL UNIT	Reviewing	0	NOT NECESSARY	
	45	FRONT SUPPORT PANEL	Reviewing	691.68	BENT	
	46	RADIATOR	Reviewing	0	NOT NECESSARY	
	47	BOTTOM AIR DUCT SEGMENT	Reviewing	167.52	DEFORMED	
	48	AIR DUCT FOR RADIATOR	Reviewing	0	NOT NECESSARY	
	49	TOP COLD AIR INDUCTION	Reviewing	0	NOT NECESSARY	
	50	FRONT NUMBER PLATE WITH HOUSING FRONT	Reviewing	60	MISSING	
	51	ELECTRICAL WIRING HARNESS	Reviewing	128.55	CUT	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$22,075.40		Claim Amount		\$22,075.40	
CATEGORY	ESTIMATE	REVISED AMOUNT				
Labour	\$6,890.00	\$6,890.00				
Miscellaneous	\$15,685.40	\$15,685.40				
Excess	-\$500.00	-\$500.00				

Submit for Review