

EDIT	SIR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	52	DISTANCE SENSOR	Reviewing	172.07	DISTORTED	
	53	SPACER RING	Reviewing	12.84	NECESSARY	
	54	COVER F ENGINE COMP BM	Reviewing	181.26	CRACKED	
	55	DISTANCE SENSOR	Reviewing	172.07	NOT WORKING	
	56	[STR] REFRIGERANT CONDENSER	Reviewing	1428.9	BENT	
	57	FIXTURE	Reviewing	21.11	NECESSARY	

SR		NAME	ACTION	AMOUNT	COMMENT	REMOVE
EDIT	NO					
		30	RADIATOR GRILLE BEAM	Reviewing	205.32	DISTORTED
		31	TOP LEFT ORNAMENTAL MOLDING	Reviewing	60.43	CUT
		32	BOTTOM LEFT ORNAMENTAL MOLDING	Reviewing	74.7	CUT
		33	TOP RIGHT ORNAMENTAL MOLDING	Reviewing	60.43	CUT
		34	BOTTOM RIGHT ORNAMENTAL MOLDING	Reviewing	74.7	CUT
		35	STAR BEAM	Reviewing	72.06	MISSING
		36	MERCEDES STAR	Reviewing	130.65	MISSING
		37	CROSS MEMBER	Reviewing	407.9	BENT
		38	FRONT SUPPORT CONSOLE	Reviewing	202.17	BENT
		39	LEFT BRACKET	Reviewing	0	NOT NECESSARY
		40	RIGHT BRACKET	Reviewing	0	NOT NECESSARY
		41	U-SHAPED STRIKER	Reviewing	0	NOT NECESSARY

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	8	LICENCE PLATE MOLDING	Reviewing	120.86	MISSING	
	9	LHF INNER FOGLAMP COVER	Reviewing	0	NOT NECESSARY	
	10	LHF FOGLAMP COVER	Reviewing	75.4	CUT	
	11	LEFT FOGLAMP BOTTOM ORNAMENTAL MOLDING	Reviewing	54.36	CUT	
	12	TOP LEFT FOGLAMP ORNAMENTAL MOLDING	Reviewing	65.23	CUT	
	13	LEFT BASIC MOUNTING FOR BUMPER	Reviewing	68.53	NECESSARY	
	14	RIGHT BASIC MOUNTING FOR BUMPER	Reviewing	68.53	DEFORMED	
	15	BOTTOM BASIC MOUNTING FOR BUMPER	Reviewing	102.8	DEFORMED	
	16	LHF MOUNTING RAIL	Reviewing	0	NOT NECESSARY	

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		6		TO INSPECT & CONDUCT WHEEL ALIGNMENT.	0	0	0	Reviewing		
		7		REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELBASE.	0	0	0	Reviewing		
		8		TO DISASSEMBLE AND REPLACE ON FRONT BUMPER, BONNET, RH/LHF FENDER, FRONT SUPPORT PANEL.	3840	0	0	Reviewing		
		9		RESPRAY ON FRONT BUMPER, RH/LH FRONT FENDER, BONNET.	2400	0	0	Reviewing		

CATEGORY		POLICY INFORMATION		ASSESSMENT INFORMATION		CATEGORY		FNOL INFORMATION		POST SURVEY INFORMATION	
Sum Insured		0		0		License Type					
Market Value		0		108000		License Issue Date		January 1, 1984		mm/dd/yyyy	
						License Expiration Date				mm/dd/yyyy	
						Address		16 ANG MO KIO CENTRAL 3 #12-25, 567748, Singapore			
						Address type		Personal Correspondence			
						Gender		Female			
						Marital status		Unknown			
						Identification #		S1651980D			

Service Address

...

Primary Contact/Insured

ONG GEOK LAN LANDY
16 ANG MO KIO CENTRAL 3, #12-25
GRANDEUR 8, 567748, Singapore
96818886
LANDY.PANCAKE@GMAIL.COM

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions
C&C (Pandam) OD EXCESS \$500 (unnamed)

Notes

- Messages
- Documents
- Invoices
- Assessment
- History
- Metrics

Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance
KHONG Lynn	
September 25, 2018	
ESTIMATE .pdf	
Forms / Claim Documents	
Estimate / Quotation	
KUMAR Shailendra	
September 25, 2018	
OO PRI EMAIL.pdf	
Forms / Claim Documents	
Others	
KUMAR Shailendra	
September 25, 2018	

Claim Portal

Service Address

Evidence

Photos

Primary Contact/Insured

LKK AUTO CONSULTANTS PTE LTD (OD)

ONG GEOK LAN LANDY
16 ANG MO KIO CENTRAL 3, #12-25
GRANDEUR 8, 567748, Singapore
96818886
LANDY.PANCAKE@GMAIL.COM

December 14, 2018

SDV8886 Inspection photo.pdf

Claim Handler

Evidence

Photos

KHONG Lynn
68804892
lynn.khong@axa.com.sg

December 14, 2018

LKK AUTO CONSULTANTS PTE LTD (OD)

Additional Instructions
C&C (Pandam) OD EXCESS \$500 (unnamed)

Notes

SDV8886 SUPPLEMENTARY.pdf

Reports & Statement

Estimate / Quotation

LKK AUTO CONSULTANTS PTE LTD (OD)

December 14, 2018

Messages
Documents

Invoices
Assessment

History
Metrics