


Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo




Acc cent Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE  
138 Robinson Road #07-09  
The Corporate Office  
Singapore 068906  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm**

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS

Original Report No : MOR117026498 Vehicle Registration No : SKS3438X  
Name(as shown in NRIC) : TAY BOCK HENG,ALBERT  
(\*Vehicle Driver/Vehicle Owner) (\*Please delete as appropriate  
NRIC/Passport No : S1260912D  
Address : \_\_\_\_\_  
Contact (Tel) : \_\_\_\_\_ (H/P) : 97526023  
(EMail) : \_\_\_\_\_  
Date Of Accident : 26/02/2017 Time Of Accident : 08:45  
Place Of Accident : BLK 475 MSCP CARPARK LOT NO 1  
Insurance Company : AXA Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:-

amend policy number to GA034374/1



SIGNATURE OF VEHICLE OWNER/DRIVER

DATE:

27/02/17

**Enquire Vehicle & Owner Information ( Vehicle No. SKS3438X As At 26 Feb 2017 / 07:00:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: N63-104332-17

**Current Owner Details**

Owner ID Type: Singapore NRIC  
Owner ID: S1260912D  
Owner Name: TAY BOCK HENG ALBERT  
Registered Address Type: HDB / HUDC  
Registered Block/House No.: 496D  
Registered Street Name: TAMPINES AVENUE 9  
Registered Unit No.: # 09 - 534  
Registered Building Name: -  
Registered Postal Code: 520496

**Current Vehicle Details**

Vehicle No.: SKS3438X  
Make Description/Model: TOYOTA / COROLLA ALTIS 1.6 AUTO  
Insurance Company Name: AXA INSURANCE PTE LTD



Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).  
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.  
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution  
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)  
Last updated on 17 Sep 2017 at 12:38 AM



# Thank you



Ng Ching Boon Eric has successfully logged out.

Your last login date and time was 28 Sep 2017, 17:43:06.

To return to ONE.MOTORING, please click [here](#).

For security reasons, please **CLEAR YOUR CACHE** after each session.

## Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SKS3439X -		18.19 Enquire Veh Owner Info (Others) by Law Firm	5.35	28 Sep 2017, 17:43:46

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Last updated on 17 Sep 2017 at 12:38 AM



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-17-033044  
Date of Request: 08/03/2017

Your Ref No: WALK IN MAXAM

N-51 AUTOMOTIVE PTE LTD  
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB  
SINGAPORE 417921

Dear Sir/Madam,

Your Vehicle No: GQ9226J  
Date of Accident: 26/02/2017  
Place of Accident: TAMPINES ST 43  
Involving Vehicle No: SKS3438X

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

## TAX INVOICE

Our Ref No: GR-17-033045  
Date of Request: 08/03/2017

Your Ref No: WALK IN MAXAM

N-51 AUTOMOTIVE PTE LTD  
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB  
SINGAPORE 417921

Dear Sir/Madam,

Date of Accident: 26/02/2017  
Vehicle No: GQ9226J  
Place of Accident: TAMPINES STREET 43  
Involving Vehicle No: SKS3438X

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SKS3438X	TAMPINES STREET 43	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

MEO MARINE ELECTRICAL SERVICE PTE LTD  
BLK 79 #01-2606 GEYLANG BAHRU INDUSTRIAL  
ESTATE  
SINGAPORE 339687

Contact : 62921250 98159713

## TAX INVOICE

Date : 06/09/2017  
Date in : 09/03/2017  
Vehicle Num. : GQ9226J  
Make/Model : NISSAN CABSTAR-1999  
Chassis/Eng# : JN1SF4F23Z0001721/QD32085690  
Accident Date : 26/02/2017  
Claim No : CLM13942  
Reference : MAR-23/2017  
Policy No. : 5080421580 (06/07/2017)

LUMPSUM REPAIR BILL  
AS PER SURVEYOR REPORT  
REF : CLM13942TP/N DATED 31/07/2017  
BY CARLINK CONSULTANCY

Amount S\$  
6,700.00

E. & O.E.	Sub S\$ :	6,700.00
Add GST ( 7 % )	S\$ :	469.00
Total Amount S\$ :		<u>7,169.00</u>



for N-51 AUTOMOTIVE PTE LTD



*biSAFE<sub>3</sub>*

# CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009  
Fax: 62874788 Tel: 62856178

## INVOICE

M/S Meo Marine Electrical Service Pte Ltd  
C/o Kaki Bukit Autohub  
2 Kaki Bukit Avenue 2, #01-18  
Singapore 417921

Invoice No: CLM13942TP/N

Date: 31st July 2017

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	Vehicle No: GQ 9226 J Charges for accident vehicle inspection and appraisal report, transportation, photographs & misc*** (photographs - 84 copies)			\$709.00
<b>Total:</b>				<b>\$709.00</b>

We thank you for the opportunity to serve you and assure you of our best at all times

  
PATRICK NG  
Automotive Engineer Assessor  
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"

**CARLINK CONSULTANCY**60 Hillside Drive  
Singapore 549009

Tel : 62856178

Fax : 62874788

**ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT**

Our Ref: CLM13942TP/N

<b>1 REFERENCE</b>			
Date of request	: 10th March 2017		
Requested by	: M/S Meo Marine Electrical Service Pte Ltd C/o Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-18 Singapore 417921		
Type of claim	: Third party		
Workshop	: M/S N-51 Automotive Pte Ltd Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-18 Singapore 417921		
Date of survey	: 10th March 2017		
Accident date	: 26th February 2017		
<b>2 DETAILS OF VEHICLE</b>			
Registration No.	: GQ 9226 J		
Make & Model	: Nissan Cabstar		
Date of registration	: 7th July 1999		
Engine No.	: QD32085690		
Chassis No.	: JN1SFAF23Z0001721		
Transmission	: Manual		
Colour	: Silver		
Speedometer reading	: 454771 Km		
<b>3 STATIC CHECK</b>			
Steering	: In order	Paintwork	: Good
Footbrake	: In order	Modification	: Nil
Handbrake	: In order	General condition	: Good
<b>4 TYRE CONDITION</b>			
	<u>Nearside/Make</u>	<u>Offside/Make</u>	<u>Size</u>
Front tyre	: 6mm/Dunlop	6mm/Dunlop	: 185 R14C
Rear tyre	: 6mm/Gondor	6mm/Gondor	: 155 R12C
<b>5 POINT OF IMPACT</b>			
See Annex(es) and Motor Accident Reports			
<b>6 REMARK</b>			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

Report No.

CLM13942TP/N

Vehicle No. GQ9226J

Parts and Labour Assesment**PARTS**

Description of part	Repairer's Qty	Qty	Condition	Repairer's estimate	Our adjustment	
FRONT APRON PANEL CLIPS	7	7	NECESSARY	45.50	45.50	NECV ✓
FRONT BUMPER	1	1	DISTORTED/CUT	637.20	637.20	BT ✓
FRONT BUMPER BRACKET L/R	2	1 ✓	BENT LH	772.60	270.10 772.60	BT ✓
FRONT GRILLE	1	1	BENT/CUT	286.20	286.20	BR ✓
FRONT GRILLE CLIPS	6	6	NECESSARY	39.00	39.00	NECV ✓
FRONT LH CORNER SIDE PANEL	1	1	DENTED/WARPED	480.70	480.70	DD ✓
FRONT LH CORNER SIDE PANEL SCREW CLIPS	5	5	NECESSARY	32.50	32.50	NECV ✓
FRONT LH DOOR PILLAR 'INNER'	1	0	REPAIR	501.30	0.00	
FRONT LH DOOR PILLAR 'OUTER'	1	0	REPAIR	1,272.80	0.00	
FRONT LH DOOR STEP PANEL	1	1	DISTORTED/CUT	628.10	300.00 628.10	DD ✓
FRONT LH DOOR STEP PANEL CLIPS	2	2	NECESSARY	13.00	13.00	NNX
FRONT LH HEADLAMP CLIPS	4	4	NECESSARY	26.00	26.00	} NECV
FRONT LH HEADLAMP LOWER RUBBER SEAL CLIPS	3	3	NECESSARY	19.50	19.50	
FRONT LH SIDE LAMP CLIPS	2	2	NECESSARY	13.00	13.00	} 1554.00 ✓✓✓
FRONT PANEL	1	1	DENTED/WARPED	1,742.00	1,742.00	
			Subtotal before discount	S\$ 6,509.40	S\$ 4,735.30	2449.6
Percentage discount	30% and	30%		S\$ 1,952.82	S\$ 1,420.59	
			<b>Sub-total</b>	<b>S\$ 4,556.58</b>	<b>S\$ 3,314.71</b>	1504.72
FRONT APRON PANEL	1	1	DENTED/WARPED	270.60	270.60	DD ✓
FRONT APRON PANEL 'NISSAN' EMBLEM	1	1	NECESSARY	60.30	60.30	NECV ✓
FRONT BUMPER FOGLAMP COVER L/R	2	0	SERVICEABLE	68.20	0.00	
FRONT LH CORNER SIDE PANEL RUBBER SEAL	1	1	NECESSARY	23.70	-23.70	NNX
FRONT LH DOOR STEP PANEL GARNISH	1	1	DISTORTED/CUT	48.90	-48.90	NNX
FRONT LH DOOR STEP PANEL VERTICAL GARNISH	1	1	DISTORTED/CUT	52.10	52.10	NNX
FRONT LH HEADLAMP	1	1	CRACKED	354.50	354.50	CRA ✓
FRONT LH HEADLAMP INNER PANEL	1	1	BENT	315.40	315.40	BT ✓ X R
FRONT LH HEADLAMP LOWER RUBBER SEAL	1	1	TORN	84.00	84.00	TN ✓
FRONT LH SIDE LAMP	1	1	CRACKED	160.60	160.60	CRA ✓
FRONT WINDSCREEN RUBBER MOULDING	1	0	SERVICEABLE	137.50	0.00	
FRONT WIPER GARNISH 'NISSAN' STICKER	1	1	NECESSARY	29.10	-29.10	NN X
			Subtotal before discount	S\$ 1,604.90	S\$ 1,399.20	
Percentage discount	10% and	10%		S\$ 160.49	S\$ 139.92	
			<b>Sub-total</b>	<b>S\$ 1,444.41</b>	<b>S\$ 1,259.28</b>	930

10% = 837

FRONT BUMPER CLIPS - SET	1	1	NECESSARY	30.00	30.00	NECV
FRONT BUMPER NUMBER PLATE	1	1	DENTED/BENT	25.00	<del>25.00</del>	NNX
FRONT LH HEADLAMP BULB	1	1	FAULTY	40.00	<del>40.00</del>	30
FRONT LH SIDE LAMP PARKING BULB	1	1	FAULTY	12.00	12.00	} NECV
FRONT LH SIDE LAMP SIGNAL BULB	1	1	FAULTY	12.00	12.00	
FRONT WIPER GARNISH CLIPS - SET	1	1	NECESSARY	30.00	30.00	NNX X
Subtotal before discount				<u>\$S 149.00</u>	<u>\$S 149.00</u>	
<b>Sub-total</b>				<b>\$S 149.00</b>	<b>\$S 149.00</b>	60
<b>Parts-total</b>				<b>\$S 6,149.99</b>	<b>\$S 4,722.99</b>	


**LABOUR**

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and wire for parking sensor.	180.00	<del>180.00</del>	60.00
To remove, reinstall windscreen. (to FR)	150.00	0.00	
To remove, reinstall dashboard fascia, meter reading and etc. (to FR)	280.00	<del>180.00</del>	NN X
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,500.00	<del>1,200.00</del>	600.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignment and damaged consistent to the accident.	1,750.00	<del>1,600.00</del>	200.00 500
To apply anti-rust chemical on repaired and replaced panel.	120.00	<del>100.00</del>	X NN
<b>Labour Total</b>	<b>\$S 3,980.00</b>	<b>\$S 3,180.00</b>	
<b>Parts &amp; Labour Total</b>	<b>\$S 10,129.99</b>	<b>\$S 7,902.99</b>	1200

Results of inspection of the accident vehicle are as shown above,

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : \$S 6,700.00 and the recommended number of working days for the repairs is within 8 day(s).

  
 PATRICK SURVEYOR  
 Automotive Appraiser

Repair days # 4

Tim Lim

9/10/18

3541.72  
 20%: 2850



Your Ref: 18.24757.S.CK.xy

Date: 22<sup>nd</sup> October 2018

Our Ref: CS3/AXA17004768/Gqbs2-1

**M/s AXA Insurance Pte Ltd**  
c/o: Seah Ong & Partners LLP  
36 Robinson Road  
#12-03 City House  
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GQ 9226J**  
**INSURED VEHICLE: SKS 3438X**  
**ACCIDENT DATE: 26/02/2017**

We thank you for your instruction on 25/09/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GQ 9226J from M/s CarLink Consultancy.
- b) Final Repair Bill of GQ 9226J from M/s N-51 Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles GQ 9226J and SKS 3438X.
- d) Colour damaged vehicle photographs of GQ 9226J.

Pre-Repair Inspection Date : 09/03/2017 at M/s N-51 Automotive Pte Ltd, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GQ 9226J
Make & Model	: Nissan Cabstar
Year of Registration	: 1999
Chassis Number	: JN1SFAF23Z0001721
Engine Capacity	: 3153 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GQ 9226J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
7	FRONT APRON PANEL CLIPS	NECESSARY	45.50	45.50
1	FRONT BUMPER	BENT	637.20	637.20
2	FRONT BUMPER BRACKET L/R	N/S BENT	772.60	270.00
1	FRONT GRILLE	BROKEN	286.20	286.20
6	FRONT GRILLE CLIPS	NECESSARY	39.00	39.00
1	FRONT LH CORNER SIDE PANEL	DENTED	480.70	480.70
5	FRONT LH CORNER SIDE PANEL SCREW CLIPS	NECESSARY	32.50	32.50
1	FRONT LH DOOR PILLAR 'INNER'	TO REPAIR SEE LABOUR	501.30	-
1	FRONT LH DOOR PILLAR 'OUTER'	TO REPAIR SEE LABOUR	1,272.80	-
1	FRONT LH DOOR STEP PANEL	DENTED	628.10	300.00
2	FRONT LH DOOR STEP PANEL CLIPS	NOT NECESSARY	13.00	-
4	FRONT HEADLAMP CLIPS	NECESSARY	26.00	26.00
3	FRONT LH HEADLAMP LOWER RUBBER SEAL CLIPS	NECESSARY	19.50	19.50
2	FRONT LH SIDE LAMP CLIPS	NECESSARY	13.00	13.00
1	FRONT PANEL	TO REPAIR SEE LABOUR	1,742.00	-
	LESS 30% DISCOUNT		-1,952.82	-644.88
			<b>4,556.58</b>	<b>1,504.72</b>
<b>NETT ITEMS</b>				
1	FRONT APRON PANEL (N)	DENTED	270.60	270.60
1	FRONT APRON PANEL 'NISSAN' EMBLEM (N)	NECESSARY	60.30	60.30
2	FRONT BUMPER FOGLAMP COVER L/R (N)	SERVICEABLE	68.20	-
1	FRONT LH CORNER SIDE PANEL RUBBER SEAL (N)	NOT NECESSARY	23.70	-
1	FRONT LH DOOR STEP PANEL GARNISH (N)	NOT NECESSARY	48.90	-
1	FRONT LH DOOR STEP PANEL VERTICAL GARNISH (N)	NOT NECESSARY	52.10	-
1	FRONT LH HEADLAMP (N)	CRACKED	354.50	354.50
1	FRONT LH HEADLAMP INNER PANEL (N)	TO REPAIR SEE LABOUR	315.40	-
1	FRONT LH HEADLAMP LOWER RUBBER SEAL (N)	TORN	84.00	84.00
1	FRONT LH SIDE LAMP (N)	CRACKED	160.60	160.60
1	FRONT WINDSCREEN RUBBER MOULDING (N)	SERVICEABLE	137.50	-
1	FRONT WIPER GARNISH 'NISSAN' STICKER (N)	NOT NECESSARY	29.10	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-160.49	-93.00
			1,444.41	837.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	FRONT LH HEADLAMP BULB (SN)	FAULTY	40.00	30.00
1	FRONT LH SIDE LAMP PARKING BLUB (SN)	NECESSARY	12.00	12.00
1	FRONT LH SIDE LAMP SIGNAL BULB (SN)	NECESSARY	12.00	12.00
1	SET FRONT WIPER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
			149.00	84.00
	<b><u>LABOUR</u></b>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		180.00	60.00
	TO REMOVE, REINSTALL WINDSCREEN. (TO FR)	NOT NECESSARY	150.00	-
	TO REMOVE, REINSTALL DASHBOARD FASCIA, METER READING AND ETC. (TO FR)	NOT NECESSARY	280.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	600.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR PILLAR 'INNER', FRONT LH DOOR PILLAR 'OUTER', FRONT PANEL AND FRONT LH HEADLAMP INNER PANEL.		1,750.00	500.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	120.00	-
			3,980.00	1,160.00
	<b>GRAND TOTAL</b>		<b>10,129.99</b>	<b>3,585.72</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,850.00</b>

Report Ref No. CS3/AXA17004768/Gqbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.