

ASS. REC. BY:

REF: CS/PCT-1801749 /ft d3 | ⁿ² Special Instruction:

Special instruction:

Surveyor: Xinguo Qiana ASSIGNMENT (Office)

From (Person): CWS (Karen Tan) of FCI Date/Time: 26/9/18

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No: SMC 3290P Insured: 0183 0027

at Workshop m/s Yong Sing Motor Tel: 91020025

of 10, Defu lane 8 Defu industrial estate Singapore 539315.

Policy No: _____ Claim No: D18006990 MASH

Sum Insured: _____ Excess: _____

Make of Vch. _____ D.O.A. 21/9/18
(Client's Record)

CA / REV / REP. / REV 24 HRS (WP) H.O.D. Endorsement:

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT _____

Date/Time	Action/Instruction () Estimate
-----------	---------------------------------

15

Signature

XRL

REF:

fci

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Yang Sing Motor

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC3290P

Yr Regn:

29 Jun 2018

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Attis

c.c.

1598

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

19702

T/Radio:

Insured / Std / NI / NA

Eng/No:

MR053 REH 604585099

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ Rim or

Tyre Size:

F:

205/55 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

26-09-18

Survey held at

w/s

4830pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/3/19

\$4896.25

(Red: 3800.25; 43%) confirm with Sam Lim.

RECEIVED 13 MAR 2019

Date/Time, File Pass to?



Preli. Report

1) 13/3 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum / (E.I.): (\$

4896.25

170+15

50

50+50

97

432



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006990MFSH

Date: 28/9/2018

Our Ref: CS/FCI18017497/Gtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMC 3290P

Please be informed that we had conducted the inspection of the abovementioned vehicle 26/09/2018 at the premises of M/s Yong Sing Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>6,102.00</u>
Revised Estimate Amount	: S\$ <u>4,532.50</u>
"Check" Items Amount	: S\$ <u>2,010.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Guo Qiang

Automotive Assessor

Denise Tay (LKKAUTO)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 26 September 2018 9:40 AM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006990MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 25 September 2018 4:43 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006990MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 28 September 2018 11:47 AM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006990MFSH/1
Attachments: PRELI ADVISED SMC 3290P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMC 3290P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 26 September 2018 9:40 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006990MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 25 September 2018 4:43 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006990MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Denise Tay (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Thursday, 7 February 2019 8:11 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Karen Tan'; assignments
Subject: RE: REMINDER - 2: REQUEST OF SURVEY REPORT-OUR
REF:D18006990MFSH;ACCIDENT INVOLVING SHA2796Z AND SMC3290P ON
21-09-2018

Dear Sir/Mdm,

Thank you for the email.

Dear Denise,

Kindly assist

FYNA Our Ref : CS/FCI18017497/Gtd3



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 6 February 2019 8:30 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: REMINDER - 2: REQUEST OF SURVEY REPORT-OUR REF:D18006990MFSH;ACCIDENT INVOLVING SHA2796Z
AND SMC3290P ON 21-09-2018

Dear Sir,

We received LOD from workshop/solicitor.

Please let us have the **Survey Report including Vehicle Inspection Photos & Survey Fees Invoice** asap.

Denise Tay (LKKAuto)

From: Yong Sing <yongsingmotors@gmail.com>
Sent: Wednesday, 13 March 2019 11:53 AM
To: Denise Tay (LKKAuto)
Subject: Re: Finalise for SMC3290P

Hi,

Confirm finalize amount at \$4896.25.

Part by Part repair job and 05 repair days

With Regards,

Sam Sim (Mr)

Executive

Mobile: 9182 0027 Fax: 6284 2798
53 Defu Lane 12, Singapore 539144



On Wed, 13 Mar 2019 at 11:23, Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

Dear Sam,

Can confirm the finalize amount????

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Yong Sing Repair Estimate

Vehicle Registration Number	: SMC3290P	Ref. No.	: _____
Make / Model	: TOYOTA ALTIS	Reg. Date	: _____
Chassis No	: MR053REH604585099	The damages on the vehicle are as indicated in the following diagram :	
Name of Driver	: TAY CHOR CHAI		
Date/Time of Accident	: 21/9/2018 16:00		
Type of Repair	: PART BY PART		
Mileage	: _____		
Rental Vehicle	: Yes / No		

Yong Sing estimate repair cost		Adjusted by Surveyor, if applicable
Total Labour Charges	\$ 1,800.00	\$ -
Total Spray Painting Charges	\$ 1,900.00	\$ -
Total Material Charges	\$ 4,576.50	\$ 4,576.50
Other Charges	\$ 420.00	\$ -
TOTAL	\$ 8,696.50	\$ 4,576.50

Lump Sum Repair, if any : _____

No. of Repair Days : [07] days [5] days

WORKSHOP'S Remark

SURVEYOR'S Remark

part by part.

before paint photos.

Guo Qiang - 82880282

26/9/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 4 - Spare Parts / Material Usage

Item	Parts Description	Qty	Cost Price (\$)	Disc (25%)	Final Price (\$)	Repair @ Replace (/) (Yong Sing Request)	Repair @ Replace (/) (Surveyor Recommend)
	REAR BUMPER / <i>el</i>	1	\$ / 745.00	25.00%	\$ 558.75	REPLACE (/)	/
	REAR BUMPER REINFORCEMENT / <i>BT</i>	1	\$ / 355.00	25.00%	\$ 266.25	REPLACE (/)	/
	REAR BUMPER RH RETAINER / <i>free</i>	1	\$ / 125.00	25.00%	\$ 93.75	REPLACE (/)	/
	REAR BUMPER LH RETAINER / <i>free</i>	1	\$ / 125.00	25.00%	\$ 93.75	REPLACE (/)	/
	REAR BUMPER LH SEAL X <i>NN</i>	1	\$ X 95.00	25.00%	\$ 71.25	REPLACE (/)	X
	REAR BUMPER RH SEAL X <i>NN</i>	1	\$ X 95.00	25.00%	\$ 71.25	REPLACE (/)	X
	REAR END PANEL / <i>enc</i>	1	\$ / 680.00	25.00%	\$ 510.00	REPLACE (/)	/
	REAR END LUGGAGE PANEL X <i>NN</i>	1	\$ X 960.00	25.00%	\$ 720.00	REPLACE (/)	X
	REAR END VENTILATION COVER X <i>NN</i>	1	\$ X 96.00	25.00%	\$ 72.00	REPLACE (/)	X
	REAR BOOT LID / <i>enc</i>	1	\$ / 950.00	25.00%	\$ 712.50	REPLACE (/)	/
	REAR BOOT LOCK / <i>BT</i>	1	\$ / 450.00	25.00%	\$ 337.50	REPLACE (/)	/
	REAR BOOT WEATHER STRIP / <i>twi</i>	1	\$ / 135.00	25.00%	\$ 101.25	REPLACE (/)	/
	REAR BOOT LH HINGE X <i>NN</i>	1	\$ X 96.00	25.00%	\$ 72.00	REPLACE (/)	X
	REAR BOOT RH HINGE X <i>NN</i>	1	\$ X 96.00	25.00%	\$ 72.00	REPLACE (/)	X
	REAR LUGGAGE RH TRIM X <i>NN</i>	1	\$ X 450.00	25.00%	\$ 337.50	REPLACE (/)	X
	REAR LUGGAGE LH TRIM X <i>NN</i>	1	\$ X 450.00	25.00%	\$ 337.50	REPLACE (/)	X
	REAR END PANEL GARNISH / <i>el</i>	1	\$ / 385.00	25.00%	\$ 288.75	REPLACE (/)	/
	REAR LUGGAGE BOTTOM TRIM X <i>NN</i>	1	\$ X 430.00	25.00%	\$ 322.50	REPLACE (/)	X
	REAR TAILLAMP RH <i>Q</i>	1	\$ / 560.00	25.00%	\$ 420.00	REPLACE (/)	/
	REAR TAILLAMP LH <i>Q</i>	1	\$ / 560.00	25.00%	\$ 420.00	REPLACE (/)	/
	REAR BOOTLAMP RH <i>Q</i> / <i>CRH</i>	1	\$ / 580.00	25.00%	\$ 435.00	REPLACE (/)	/
	REAR BOOTLAMP LH <i>Q</i>	1	\$ / 580.00	25.00%	\$ 435.00	REPLACE (/)	/
	REAR BUMPER REVERSE SENSOR / <i>DM</i>	1	\$ / 380.00	25.00%	\$ 285.00	REPLACE (/)	200 (SV)
TOTAL MATERIALS			\$ 6,102.00		\$ 4,575.50		

531.75 /
 327.45 /
 12.5 /
 72.5 /
 X
 X
 774.45 /
 X
 X
 781.45 /
 277.4 /
 135
 X
 X
 X
 X
 150.1 /
 X
 381.9 /
 381.9 /
 274.3 /
 274.3 /
 200 (SV)

4025
 25%: 3026.25

4896.25

2896

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO DISMANTLE AND REFIT DAMAGED ITEMS, TO PULL AND ALIGN REAR LUGGAGE, REAR END PANEL FRAME, TO CUT AND WELD OUT REAR END PANEL, LUGGAGE AND ADJUST.	\$1,800.00	600
Total Labour Cost	\$1,800.00	\$0.00

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO SPRAY PAINT REAR BUMPER.	\$350.00	200
TO SPRAY PAINT REAR END PANEL.	\$300.00	200
TO SPRAY PAINT REAR LUGGAGE PANEL.	\$300.00	200 100
TO SPRAY PAINT REAR BOOT LID.	\$350.00	200
TO SPRAY PAINT REAR LH FENDER	\$300.00	200 100
TO SPRAY PAINT REAR RH FENDER.	\$300.00	200 100
Total Spray Painting Cost	\$1,900.00	\$0.00 900

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO CONDUCT SYSTEM WIRING CHECK.	\$100.00	30
TO PROVIDE ANTI RUST COATING AFTER WELDING.	\$100.00	60
TO REMOVE AND REFIT REAR BUMPER SENSOR.	\$60.00	40
TO REFIT REAR BOOT ACCESSORIES INCLUDING LOCK AND LAMP.	\$60.00	40
TO CONDUCT WATER LEAKAGE TEST TO WELDED AREAS.	\$100.00	X NN
Total Other Costs	\$420.00	\$0.00

170



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18017497/Gtd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-03-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2796Z	Veh. Inspected	SMC 3290P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006990MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	26/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MR053REH604585099	Colour	WHITE	
Odometer	19702	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	7 mm	
L/H Front Tyre	205/55 R16	MICHELIN	7 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	7 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2018	Inspection Date	26/09/2018	
Survey held at	YONG SING MOTOR WORKS 10 DEFU LANE 8 DEFU INDUSTRIAL ESTATE SINGAPORE 539315			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 3290P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	745.00	531.75
1	REAR BUMPER REINFORCEMENT	BENT	355.00	327.45
1	REAR BUMPER RH RETAINER	NECESSARY	125.00	72.50
1	REAR BUMPER LH RETAINER	NECESSARY	125.00	72.50
1	REAR BUMPER LH SEAL	NOT NECESSARY	95.00	-
1	REAR BUMPER RH SEAL	NOT NECESSARY	95.00	-
1	REAR END PANEL	BUCKLED	680.00	374.45
1	REAR END LUGGAGE PANEL	NOT NECESSARY	960.00	-
1	REAR END VENTILATION COVER	NOT NECESSARY	96.00	-
1	REAR BOOT LID	BUCKLED	950.00	781.45
1	REAR BOOT LOCK	BENT	450.00	277.40
1	REAR BOOT WEATHER STRIP	TWISTED	135.00	135.00
1	REAR BOOT LH HINGE	NOT NECESSARY	96.00	-
1	REAR BOOT RH HINGE	NOT NECESSARY	96.00	-
1	REAR LUGGAGE RH TRIM	NOT NECESSARY	450.00	-
1	REAR LUGGAGE LH TRIM	NOT NECESSARY	450.00	-
1	REAR END PANEL GARNISH	DEFORMED	385.00	150.10
1	REAR LUGGAGE BOTTOM TRIM	NOT NECESSARY	430.00	-
1	REAR TAILLAMP RH	CRACKED	560.00	381.90
1	REAR TAILLAMP LH	CRACKED	560.00	381.90
1	REAR BOOTLAMP RH	CRACKED	580.00	274.30
1	REAR BOOTLAMP LH	CRACKED	580.00	274.30
	LESS 25% DISCOUNT		-2,249.50	-1,008.75
			6,748.50	3,026.25
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
	LESS 25% DISCOUNT		-95.00	-
			285.00	200.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE AND REFIT DAMAGED ITEMS.TO PULL AND ALIGN REAR LUGGAGE,REAR END PANEL FRAME.TO CUT AND WELD OUT REAR END PANEL LUGGAGE AND ADJUST.		1,800.00	600.00
	TO SPRAY PAINT REAR BUMPER.		350.00	200.00
	TO SPRAY PAINT REAR END PANEL.		300.00	200.00
	TO SPRAY PAINT REAR LUGGAGE PANEL.		300.00	100.00
	TO SPRAY PAINT REAR BOOT LID.		350.00	200.00
	TO SPRAY PAINT REAR LH FENDER.		300.00	100.00
	TO SPRAY PAINT REAR RH FENDER.		300.00	100.00
	TO CONDUCT SYSTEM WIRING CHECK.		100.00	30.00
	TO PROVIDE ANTI RUST COATING AFTER WELDING.		100.00	60.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		60.00	40.00
	TO REFIT REAR BOOT ACCESSORIES INCLUDING LOCK AND LAMP.		60.00	40.00
	TO CONDUCT WATER LEAKAGE TEST TO WELDED AREAS.	NOT NECESSARY	100.00	-
			4,120.00	1,670.00
	GRAND TOTAL		11,153.50	4,896.25
	RECOMMENDED COST OF REPAIRS			4,896.25

Report Ref No. CS/FCI18017497/Gtd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.