

15/92/111

INS. CASE OWNER:

Guthrie

CC 3 Agm
/AXA1801

LKK:

IDAC:

Surveyor:

Eunice

DOI:

ASSIGNMENT

KALIX

Date / Time:

25/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBE 229AS

Name of Insured:

MUNA WHISTLE VIL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

KALIX

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MOHAMMED EDDY HARMAN BIN KISHU

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBE 229AS

SHD 409P

SHD 5600K



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

trans
cab
TP

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

25/1/18
pukin

SHD 409P - x

GBE 229AS - x

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 26/1/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Kenneth

Repair Cost:

PIP

SS

21,699.88

9

days Reduction:

\$90,254.95

22

Email:

Call:

FINAL SETTLEMENT

Date/Time:

21/1/18

Confirm with:

WATKIN

Email:

Call:

Final Liability:

WATKIN

SS

100

(Agreed / Assessed)

BOLA S/N No.:

22

If NO or B 28, Ass. Lia:

100%

Repair Cost:

(WATKIN)

SS

21,638.87

12

days

x \$105.74

Loss of Rental (LOR):

SS

1268.88

(S

x 12

days)

Loss of Use (LOU):

SS

600.00

(S

50

x 12

days)

Loss of Income (LOI):

SS

600.00

(S

50

x 12

days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

[Tick only one]

GLA/LTA Search

SS

7.49

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

21,515.24

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

SS

21,515.24

Name 1:

Trans - Cab Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

-

Payee 3: (Strike if N.A.)

SS

Name 3:

-

✓ GIA

ASS. REC. BY:

REF:

AVA/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09

days

Res.:

Yes or No

Lum Sum:

1-B.1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

26/9

File pass to Catherine

P/P \$7,699.88

CRD - \$90,254.95 / 77 T.

* 9 repair days + 2 PRS + 1 Sunday = 12 days.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + R.S. \$

Fixtots

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Veh No:

SHD 409P

Yr Regn:

17, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Renault Lorion

c.c.

1995

Colour:

M-White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

228362

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 283497

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

R/Bal.

8

mm

Rear

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

23/9/18

D.O.I.

25/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& M

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC3/ASM18017520/Kfb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-09-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 2299S	Veh. Inspected	SHD 409P
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00WNA	Excess (\$)	0.00
Assign From		Assign Date	26/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/09/2018	Inspection Date	25/09/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 409P**AAD1809-222***Not Authorised**Preserving B & paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 409P

VF1ABL15AUC283497

RENAULT

LATITUDE

23.9.2018

AXA**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>B</i> 1,108.46	<i>✓</i>
2	1 BUMPER LOWER REAR	\$	<i>B</i> 768.84	<i>✓</i>
3	1 BUMPER BRACKET CTR REAR	\$	<i>D.1</i> 113.47	<i>✓</i>
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>D.1</i> 135.97	<i>✓</i>
5	1 BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99	<i>X</i>
6	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	<i>X</i>
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	<i>X</i>
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	<i>X</i>
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	<i>X</i>
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52	<i>✓</i>
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	<i>X</i>
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>B</i> 225.95	<i>✓</i>
13	1 BOOT REAR	\$	<i>B</i> 2,872.68	<i>✓</i>
14	1 BOOT FINISHER	\$	<i>CM</i> 470.06	<i>✓</i>
15	1 BOOT WHEATERSTRIP	\$	<i>D.1/R</i> 323.05	<i>✓</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	<i>✓</i>
17	1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	<i>✓</i>
18	1 BOOT BADGE 'RENAULT'	\$	<i>RM</i> 225.36	<i>✓</i>
19	1 BOOT BADGE	\$	<i>RM</i> 225.36	<i>✓</i>
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	<i>X</i>
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	<i>X</i>
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	<i>X</i>
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	<i>X</i>
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	<i>X</i>
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	<i>X</i>
26	1 BOOT LOCK	\$	<i>RM</i> 202.67	<i>✓</i>
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	<i>X</i>
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	<i>X</i>
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1809-222

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 409P

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45	X
32	1 FENDER PANEL REAR LH	\$	R	3,299.13	X
33	1 WHEELARCH REAR LH	\$	SL	543.47	X
34	1 FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45	X
35	1 FENDER PANEL REAR RH	\$	R	3,299.13	X
36	1 WHEELARCH REAR RH	\$	SL	543.47	X
37	1 TAILLAMP RH	\$	CN	552.55	✓
38	1 TAILLAMP PANEL RH	\$	R	986.70	—
39	1 TAILLAMP LH	\$	CN	552.55	✓
40	1 TAILLAMP PANEL LH	\$	R	986.70	X
41	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	nd	404.56	✓
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
44	1 SPARE WHEEL PANEL TRIM	\$	Return	612.21	✓
45	1 EXHAUST REAR	\$	R	7,489.05	—
46	1 EXHAUST CAP REAR	\$	R	230.49	—
47	1 FUEL FLAP L70Y	\$	SL	343.57	} X
48	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	
49	1 CHASSIS PANEL REAR LH L70Y	\$	R	3,766.43	
50	1 KUCKLE ARM REAR LH	\$	SL	736.67	
51	1 BRAKE DISC REAR L70Y	\$	SL	525.91	
52	1 WHEEL HUB NUT L70Y	\$	SL	51.11	
53	1 WHEEL HUB CAP L70Y	\$	SL	57.82	
54	1 ABS SENSOR REAR LH	\$	SL	255.75	
55	1 REAR AXLE L70Y	\$	SL	4,167.03	
56	1 AXLE ARM LH	\$	SL	117.22	
57	1 LOWER ARM REAR LH	\$	SL	905.99	} X
58	1 ABSORBER REAR	\$	SL	389.75	
59	1 STABILIZER BAR REAR LH	\$	SL	604.65	
60	1 BRAKE CALIPER REAR LH	\$	SL	1,300.67	
61	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	✓
62	1 BUMPER COVER FRT	\$	Bu	1,259.42	✓
63	1 BUMPER SPOILER FRT	\$	SL	181.75	X
64	1 BUMPER ABSORBER FRT	\$		394.68	X NN
65	1 BUMPER RETAINER FRT LH	\$	NT	151.41	✓
66	1 BUMPER SUPPORT FRT	\$	SL	123.88	X
67	1 BUMPER RETAINER FRT RH	\$	SL	150.77	X

Trans-cab Auto Services Pte Ltd

AAD1809-222

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 409P

68	1 BUMPER SUPPORT FRT	\$	Sn	123.88	X
69	1 BUMPER UNDERTRAY FRT	\$	Sn	472.83	X
70	1 BUMPER GRILLE LOWER FRT	\$	Sn	266.80	X
71	1 BUMPER FOG LAMP GRILLE LH	\$	Sn	207.21	X
72	1 BUMPER FOG LAMP GRILLE RH	\$	Sn	207.21	X
73	1 BUMPER BEAM FRT	\$		914.08	2 Suc
74	1 TOW COVER FRT	\$	Sn	28.61	X
75	1 RADIATOR GRILLE	\$	mgcm	1,707.78	✓
76	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	na	225.36	✓
77	1 RADIATOR GRILLE FRAME	\$	cmf	1,353.75	✓
78	1 FRAME FULL SUPPORT PANEL	\$	cmf	615.90	✓
79	1 FRAME FULL SUPPORT BRACKET	\$	R	89.79	} X
80	1 FRONT BRACE PANEL	\$	R	177.22	
81	1 HORN	\$	Sn	314.17	
82	1 HORN BRACKET	\$	R	40.45	
83	1 HEADLAMP LH	\$	Sn	1,184.43	
84	1 HEADLAMP RH	\$	Sn	1,184.43	
85	1 HEADLAMP PANEL FRT LH	\$	R	152.15	
86	1 HEADLAMP PANEL FRT RH	\$	R	152.15	
87	1 BONNET	\$	R	1,941.63	
88	1 BONNET INSULATOR	\$	Sn	405.73	
89	1 BONNET STRUT LH	\$	Sn	88.61	
90	1 BONNET STRUT RH	\$	Sn	88.61	
91	1 BONNET HINGE LH	\$	R	348.31	
92	1 BONNET HINGE RH	\$	R	348.31	
93	1 BONNET LOCK	\$	R	305.48	
94	1 BONNET CABLE	\$	Sn	119.19	
95	1 BONNET CABLE COVER	\$	Sn	161.03	
96	1 BONNET SEAL OUTER	\$	Sn	92.36	
97	1 BONNET SEAL INNER	\$	Sn	157.28	
98	1 FENDER PANEL FRT LH	\$	R	783.83	
99	1 WHEELARCH FRT LH	\$	Sn	278.84	
100	1 FENDER BRACKET LOWER LH	\$	Sn	15.79	
101	1 FENDER INSULATOR LH	\$	Sn R	130.84	
102	1 FENDER INSULATOR RH	\$	Sn	130.84	
103	1 AIR CLEANER LOWER	\$	Sn	271.26	
104	1 AIR CLEANER HOSE	\$	Sn	76.14	
105	1 BASE BATTERY TRAY	\$	Sn	363.40	

Trans-cab Auto Services Pte Ltd

AAD1809-222

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 409P

106	1 AIR CLEANER BOX	\$	S\$ 464.20
107	1 TURBO DUCT	\$	S\$ 1,027.80
108	1 A/C HEATER VALVE	\$	S\$ 484.50
109	1 SUBFRAME OUTER FRT	\$	S\$ 2,652.45
110	1 SUBFRAME BRACKET OUTER LH	\$	S\$ 92.36
111	1 ENGINE UNDERTRAY	\$	S\$ 564.98
112	1 A/C CONDENSER	\$	S\$ 2,020.37
113	1 A/C CONDENSER GARNISH LH UPPER	\$	S\$ 39.67
114	1 A/C CONDENSER GARNISH RH UPPER	\$	S\$ 39.67
115	1 A/C CONDENSER GARNISH LH	\$	S\$ 58.81
116	1 A/C CONDENSER GARNISH RH	\$	S\$ 59.60
117	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	S\$ 208.39
118	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	S\$ 658.72
119	1 A/C PIPE COMPRESSOR	\$	S\$ 334.29
120	1 A/C PIPE	\$	S\$ 658.72
121	1 A/C COMPRESSOR	\$	S\$ 2,684.61
122	1 AIR COOLER	\$	S\$ 792.60
123	1 AIR INTERCOOLER HOSE (LONG)	\$	S\$ 1,014.13
124	1 AIR INTERCOOLER HOSE (Short)	\$	S\$ 375.14
125	1 TRANSMISSION COOLER	\$	S\$ 1,219.30
126	1 TRANSMISSION COOLER PAD	\$	S\$ 17.96
127	1 RADIATOR	\$	S\$ 1,202.20
128	2 RADIATOR STUD UPPER	\$	S\$ 14.41
129	2 RADIATOR BUSH UPPER	\$	S\$ 50.12
130	2 RADIATOR MTG LOWER	\$	S\$ 55.85
131	1 RADIATOR FAN COWLING	\$	S\$ 820.54
132	1 RADIATOR FAN MOTOR LH	\$	S\$ 967.36
133	1 RADIATOR FAN MOTOR RH	\$	S\$ 1,479.46
134	1 RADIATOR TANK	\$	S\$ 324.62
135	1 RADIATOR HOSE UPPER	\$	S\$ 240.56
136	1 RADIATOR HOSE LOWER	\$	S\$ 491.18
137	1 RADIATOR TANK HOSE	\$	S\$ 61.18

TOTAL	\$	100,263.67
10%	\$	10,026.37
	\$	90,237.31

Trans-cab Auto Services Pte Ltd

AAD1809-222

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 409P

Special Nett

1 1SET PARKING AID	\$	Short	700.00	600.00
2 1SET REAR BUMPER CLIP	\$	na	66.00	—
3 1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5 1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7 1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	na	66.00	—
10 1 EXHAUST MOUNTING REAR	\$	Sh	17.82	X
11 1SET BOOT FINISHER CLIP	\$	na	24.20	X
12 1 BOOT STICKER "Trans-cab"	\$	na	30.00	—
13 1 BOOT STICKER "6555-3333"	\$	na	30.00	—
14 1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
18 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
19 1 TAILLAMP CLIP RH	\$	na	5.00	—
20 1 TAILLAMP CLIP LH	\$	na	5.00	—
21 2 REAR WINDSCREEN SELANT	\$	na	80.00	X
22 1 WINDSCREEN MOULDING	\$	na	100.00	X
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sh	385.00	X
25 1 SPARE TYRE	\$	Sh	330.00	X
26 1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	X
27 1SET BUMPER CLIP FRT	\$	na	66.00	—
28 1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	} X
29 1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
30 1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
31 1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
32 1 TOW COVER FRT	\$	Sh	14.50	
33 1SET RADIATOR GRILLE SCREW	\$	na	16.00	}
34 1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	
35 1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
36 2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	

Trans-cab Auto Services Pte Ltd**AAD1809-222**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 409P

37	1 LEFT REAR TYRE	\$	Sn 330.00 X
38	1 LEFT REAR TYRE RIM	\$	Sn 380.00 X
39	2 FRAME FULL SUPPORT PANEL STUD	\$	Sn 30.00 X
40	1 Windscreen moulding	\$	nn 100.00 X
41	1SET Front licence plate with holder	\$	Bn 80.00 45sn

TOTAL \$ 3,497.52**TOTAL PARTS \$ 93,734.83****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	9,000.00 1300l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00 1320l
To Rust-Proofing Of The Affected Areas.	\$	170.00 60l
To reinstall rear bumper parking sensor.	\$	170.00 60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 60l
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 } 80l
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 } 100l
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1809-222

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 409P

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X
Towing Fees.	\$	120.00	501
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
To rust-proofing of the affected areas.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	501
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To lift-up engine with gear box and refit.	\$	nn 440.00	X

Trans-cab Auto Services Pte Ltd

AAD1809-222

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 409P

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	X
To remove and refit air bag system and reset.	\$	480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	100%
To replace, refix and top up coolant for radiator	\$	170.00	50%
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	50%
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X

TOTAL \$ 24,220.00**Over All Total \$ 117,954.83****(PART-BY-PART)****Repair Days****30 DAYS****9 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9/24/2018

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD409P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Sep 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003348
Chassis No.:	VF1ABL15AUC283497
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Nov 2016
First Registration Date:	14 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Nov 2024
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	13 Nov 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$41,313.00
COE Rebate Amount:	\$31,698.00
Total Rebate Amount:	\$46,696.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Sep 2018

OK



Service Request Details

Claim

S8M00WNA

Reference

None 

Loss Date

September 23, 2018

Request Date

September 27, 2018

Trans - Cab.

Due Date

October 4, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHA409P

Make

TPVD RENAULT

Model

LATITUDE 2.0

Service Address

...

Primary Contact/Insured

NINJA LOGISTICS PTE LTD

30 JALAN KILANG BARAT, KEWALRAM HOUSE, 159363, Singapore

sahmiaziz@ninjvan.sg

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 26/09/2018

Survey Details:

Date of loss	23-Sep-18
Date of appointment	26-Sep-18
Date of survey	25-Sep-18
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHD 409P
Make and Model	RENAULT LATITUDE 2.0L DCI AUTO D/AB 4DR
Date of registration	14/11/2016
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 117,954.83
------------------	---------------

Proposed/Revised repair cost:

Parts	\$ 24,429.88
Check items (estimate)	\$ -
Labour	\$ 3,270.00
Total	\$ 27,699.88
Lump Sum(if applicable)	\$ -

Number of days for repair	9
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

09 RECOMMENDED REPAIR DAYS + 2 PRS + 1 SUNDAY = 12 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 29,638.87	W/GST
Loss of use	\$ -	
Loss of rental	\$ 1,268.88	12days x \$105.74
Loss of income	\$ 600.00	12days x \$50
LTA search fees	\$ 7.49	
Others	\$ -	
Proposed Total	\$ 31,515.24	



<MANDATE IA> - S8M00WNA {ACCIDENT INVOLVING
GBE 2299S(OI) / SHD 409P(TP) / OTHERS ON
23/09/2018}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S28(OI LAST) - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$31,515.24 (CLAIMING LOR & LOI). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply



Re:<MANDATE IA> - S8M00WNA {ACCIDENT
INVOLVING GBE 2299S(OI) / SHD 409P(TP) / OTHERS
ON 23/09/2018}

Type

🔗 Question

Message

Please proceed

Reply

Cecilia

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1809-222

Your Ref : SJD5604K (FR), GBE2299S(RR)

Date : 08.August 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

**ACCIDENT INVOLVING SHD0409P AND SJD5604K (FR), GBE2299S(RR) ON 23/09/18
10:20 PM ALONG SIN MING AVE TOWARDS MARYMOUNT**

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	29,638.87
2.	Loss of Rental for <u>17</u> days @ \$ <u>105.79</u> per day	\$	1,268.88
3.	Loss of Income for <u>12</u> days @ \$ <u>50</u> per day	\$	600.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	31,515.24

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666**Fax:** 6287 7764**Co. Reg. No.:** 201019626G**GST Reg. No.:** 201019626G**Tax Invoice / Debit Note**

TO: AXA INSURANCE PTE LTD 8 SHENTON WAY,#27-01 AXA TOWER 068811 SINGAPORE ATTENTION:	INVOICE NO. : INV1812-493 DATE : 31. December 2018 REFERENCE NO : AAD1809-222 TERMS : DUE DATE : 31. December 2018 PAGE : 1
---	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHD0409P;DOA 23.09.18(PART-BY-PART-18)	1	29,638.87	29,638.87

Total SGD Excl. GST : 27,699.88**7% GST :** 1,938.99**Total SGD Incl. GST :** 29,638.87****** TWENTY NINE THOUSAND SIX HUNDRED THIRTY EIGHT AND EIGHTY SEVEN SGD ONLY ******

1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"

2) Please quote our Invoice Number during payment.

3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.

4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.**THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC3/ASM18017520/Kgb3s2	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 18-10-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	GBE 2299S	Veh. Inspected
			SHD 409P
	Policy No.	P1671150	Coverage (\$)
			0.00
	Claim No.	S8M00WNA	Excess (\$)
			0.00
	Assign From		Assign Date
			25/09/2018
2. Vehicle Particulars & Condition			
	Make & Model	RENAULT LATITUDE (A)	c.c
			1995
	Engine No.	HIDDEN	Year of Reg.
			2016
	Chassis No.	VF1ABL15AUC283497	Colour
			METALIC WHITE / RED
	Odometer	228362	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			NIL
	General	GOOD	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	215/60 R16	GITI
			8 mm
	L/H Front Tyre	215/60 R16	GITI
			8 mm
	R/H Rear Tyre	215/60 R16	GITI
			7 mm
	L/H Rear Tyre	215/60 R16	GITI
			7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	23/09/2018	Inspection Date
			25/09/2018
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD	
		NO.2 ANG MO KIO ST 63	
		SINGAPORE 569111	
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.			
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 9

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 409P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR (CONSISTENT)	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	BENT	768.84	768.84
1	BUMPER BRACKET CTR REAR (CONSISTENT)	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	DISTORTED	135.97	135.97
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH (CONSISTENT)	CRACKED	43.61	43.61
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR (CONSISTENT)	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	BENT	225.95	225.95
1	BOOT REAR (CONSISTENT)	BENT	2,872.68	2,872.68
1	BOOT FINISHER (CONSISTENT)	CRACKED	470.06	470.06
1	BOOT WEATHERSTRIP (CONSISTENT)	DISTORTED / DENTED	323.05	323.05
1	BOOT REFLECTOR LAMP LH (CONSISTENT)	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH (CONSISTENT)	CRACKED	493.35	493.35
1	BOOT BADGE 'RENAULT' (CONSISTENT)	NECESSARY	225.36	225.36
1	BOOT BADGE (CONSISTENT)	NECESSARY	225.36	225.36
1	BOOT STRUT LH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT STRUT RH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM (CONSISTENT)	SERVICEABLE	586.45	-
1	BOOT SWITCH (CONSISTENT)	SERVICEABLE	168.13	-
1	BOOT LOCK (CONSISTENT)	DENTED	202.67	202.67
1	BOOT LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	74.40	-

Report Ref No. CC3/ASM18017520/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP (CONSISTENT)	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG (CONSISTENT)	SERVICEABLE	221.81	-
1	DOOR PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
1	FENDER PANEL INNER TRIM REAR LH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH (CONSISTENT)	SERVICEABLE	543.47	-
1	TAILLAMP RH (CONSISTENT)	CRACKED	552.55	552.55
1	TAILLAMP PANEL RH (CONSISTENT)	BENT	986.70	986.70
1	TAILLAMP LH (CONSISTENT)	CRACKED	552.55	552.55
1	TAILLAMP PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL) (CONSISTENT)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	DENTED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM (CONSISTENT)	DEFORMED	612.21	612.21
1	EXHAUST REAR (CONSISTENT)	BENT	7,489.05	7,489.05
1	EXHAUST CAP REAR (CONSISTENT)	BENT	230.49	230.49
1	FUEL FLAP L70Y (CONSISTENT)	SERVICEABLE	343.57	-
1	WHEEL HOUSING PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	4,682.09	-
1	CHASSIS PANEL REAR LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	3,766.43	-
1	KNUCKLE ARM REAR LH (CONSISTENT)	SERVICEABLE	736.67	-
1	BRAKE DISC REAR L70Y (CONSISTENT)	SERVICEABLE	525.91	-
1	WHEEL HUB NUT L70Y (CONSISTENT)	SERVICEABLE	51.11	-
1	WHEEL HUB CAP L70Y (CONSISTENT)	SERVICEABLE	57.82	-
1	ABS SENSOR REAR LH (CONSISTENT)	SERVICEABLE	255.75	-
1	REAR AXLE L70Y (CONSISTENT)	SERVICEABLE	4,167.03	-

Report Ref No. CC3/ASM18017520/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AXLE ARM LH (CONSISTENT)	SERVICEABLE	117.22	-
1	LOWER ARM REAR LH (CONSISTENT)	SERVICEABLE	905.99	-
1	ABSORBER REAR (CONSISTENT)	SERVICEABLE	389.75	-
1	STABILIZER BAR REAR LH (CONSISTENT)	SERVICEABLE	604.65	-
1	BRAKE CALIPER REAR LH (CONSISTENT)	SERVICEABLE	1,300.67	-
1	WHEEL HOUSING PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	4,682.09	-
1	BUMPER COVER FRT (CONSISTENT)	BUCKLED	1,259.42	1,259.42
1	BUMPER SPOILER FRT (CONSISTENT)	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT (CONSISTENT)	NOT NECESSARY	394.68	-
1	BUMPER RETAINER FRT LH (CONSISTENT)	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH (CONSISTENT)	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT (CONSISTENT)	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT (CONSISTENT)	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT (CONSISTENT)	SERVICEABLE	914.08	-
1	TOW COVER FRT (CONSISTENT)	SERVICEABLE	28.61	-
1	RADIATOR GRILLE (CONSISTENT)	MTG CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT' (CONSISTENT)	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME (CONSISTENT)	CRACKED	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL (CONSISTENT)	CRACKED	615.90	615.90
1	FRAME FULL SUPPORT BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	177.22	-
1	HORN (CONSISTENT)	SERVICEABLE	314.17	-
1	HORN BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP RH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-

Report Ref No. CC3/ASM18017520/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEADLAMP PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR (CONSISTENT)	SERVICEABLE	405.73	-
1	BONNET STRUT LH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET STRUT RH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE (CONSISTENT)	SERVICEABLE	119.19	-
1	BONNET CABLE COVER (CONSISTENT)	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER (CONSISTENT)	SERVICEABLE	92.36	-
1	BONNET SEAL INNER (CONSISTENT)	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH (CONSISTENT)	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH (CONSISTENT)	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH (CONSISTENT)	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH (CONSISTENT)	SERVICEABLE	130.84	-
1	AIR CLEANER LOWER (CONSISTENT)	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE (CONSISTENT)	SERVICEABLE	76.14	-
1	BASE BATTERY TRAY	SERVICEABLE	363.40	-
1	AIR CLEANER BOX (CONSISTENT)	SERVICEABLE	464.20	-
1	TURBO DUCT (CONSISTENT)	SERVICEABLE	1,027.80	-
1	A/C HEAT VALVE (CONSISTENT)	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT (CONSISTENT)	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH (CONSISTENT)	TO REPAIR SEE LABOUR	92.36	-
1	ENGINE UNDERTRAY (CONSISTENT)	SERVICEABLE	564.98	-
1	A/C CONDENSER (CONSISTENT)	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER (CONSISTENT)	SERVICEABLE	39.67	-

Report Ref No. CC3/ASM18017520/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C CONDENSER GARNISH RH UPPER (CONSISTENT)	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH (CONSISTENT)	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH (CONSISTENT)	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR (CONSISTENT)	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE (CONSISTENT)	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR (CONSISTENT)	SERVICEABLE	334.29	-
1	A/C PIPE (CONSISTENT)	SERVICEABLE	658.72	-
1	A/C COMPRESSOR (CONSISTENT)	SERVICEABLE	2,684.61	-
1	AIR COOLER (CONSISTENT)	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG) (CONSISTENT)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT) (CONSISTENT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER (CONSISTENT)	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD (CONSISTENT)	SERVICEABLE	17.96	-
1	RADIATOR (CONSISTENT)	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER (CONSISTENT)	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER (CONSISTENT)	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER (CONSISTENT)	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING (CONSISTENT)	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH (CONSISTENT)	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH (CONSISTENT)	SERVICEABLE	1,479.46	-
1	RADIATOR TANK (CONSISTENT)	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER (CONSISTENT)	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER (CONSISTENT)	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE (CONSISTENT)	SERVICEABLE	61.18	-
	LESS 10% DISCOUNT		-10,026.36	-2,609.32
			90,237.31	23,483.88
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN) (CONSISTENT)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-

Report Ref No. CC3/ASM18017520/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER RETAINER RH CLIP RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN) (CONSISTENT)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN) (CONSISTENT)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN) (CONSISTENT)	NECESSARY	5.00	5.00
1	TAILLAMP CLIP LH (SN) (CONSISTENT)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN) (CONSISTENT)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN) (CONSISTENT)	SERVICEABLE	330.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN) (CONSISTENT)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN) (CONSISTENT)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN) (CONSISTENT)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN) (CONSISTENT)	NOT NECESSARY	69.00	-

Report Ref No. CC3/ASM18017520/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRAME FULL SUPPORT PANEL CLIP (SN) (CONSISTENT)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	LEFT REAR TYRE (SN) (CONSISTENT)	SERVICEABLE	330.00	-
1	LEFT REAR TYRE RIM (SN) (CONSISTENT)	SERVICEABLE	380.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN) (CONSISTENT)	SERVICEABLE	30.00	-
1	WINSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN) (CONSISTENT)	BENT	80.00	45.00
			3,497.52	946.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		9,000.00	1,300.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK CATCH, DOOR PANEL REAR LH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, TAILLAMP PANEL LH, SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), WHEEL HOUSING PANEL REAR LH, CHASSIS PANEL REAR LH L70Y, FRAME FULL SUPPORT BRACKET, FRONT BRACE PANEL, HORN BRACKET, HEADLAMP PANEL FRT LH, } HEADLAMP PANEL FRT RH, BONNET, BONNET HINGE LH, BONNET HINGE RH, BONNET LOCK, FENDER PANEL FRT LH AND SUBFRAME BRACKET OUTER LH. }		7,500.00	1,320.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE. }		170.00	80.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }		170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	100.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHEMNT AND PERFORM WATER SEEPAGE TEST. }		170.00	-

Report Ref No. CC3/ASM18017520/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHEMNT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHEMNT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.		170.00	50.00

Report Ref No. CC3/ASM18017520/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 9 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			24,220.00	3,270.00
GRAND TOTAL			117,954.83	27,699.88
RECOMMENDED COST OF REPAIRS				27,699.88

Report Ref No. CC3/ASM18017520/Kgb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.