



Your Ref : S8M0173L

Date: 03rd February 2020

Our Ref : CC4/ASM18017521/R1pa3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Saw Theng

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHC 7570P
ACCIDENT ON 19/09/2018 INSURED VEHICLE GBE 9385E**

Instruction was received to inspect the vehicle Reg. No. SHC 7570P. The inspection was conducted on 25/09/2018 at the premises of M/s Ding Auto Pte Ltd, 31 Corporation Road Singapore 649806.

The following vehicle information was recorded:

Registration Number	: SHC 7570P
Make/Model	: Hyundai Sonata 2.0
Year of Registration	: 2010
Body Colour	: Yellow
Chassis Number	: KMHET41VMAA796048
Engine Capacity	: 1991 cc
Speedometer Reading	: 674626 km

The vehicle sustained damages at the rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“uneconomical Total Loss”**.

Book Value	S\$	9,950.26
Less: LTA Reimbursement Value (RV)	(S\$	9,678.00)
Nett Liability	S\$	272.26

Vehicle Inspected By:

MRB

MOHD. RASUL BIN MOHD YUNUS

AMSOE, AMIRTE, AMSAE-A, M. MATAI

Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.