

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG18017529/KEA3Q2**Date:** 24/04/2020**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100433888

**Claimant Vehicle No :** SJL5046D **Insured Vehicle No :** SKW1760G

Date of Loss: 23/09/2018 Nature of Claim: TP Claim No: 4943873341SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJL5046D**

Make &amp; Model: SUBARU IMPREZA 5D, 1.5 R AWD (A)

Engine No: EL15D407506

Reg. Date: 28/11/2008 (Man. Year: 2008)

Chassis No: JF1GH3KS58G017717

Colour: Metallic Silver

Odometer: 142535 km

Engine Capacity: 1498 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>2,318.00</b>		
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>2,318.00</b>	<b>-2,318.00</b>	
<b>+ Medical Costs (S\$)</b>		215.05		
<b>+ Car Rental (23.0 x S\$100.00/day) (S\$)</b>		2,300.00		
<b>+ Other Costs (S\$)</b>		120.00		
<b>Nett Liability (S\$)</b>		<b>4,953.05</b>		

**INSPECTION**

Date of Assignment: 26/09/2018

Date Inspected: 26/09/2018 Inspected At:

S & H Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive #07-02, Sin Ming  
AutoCity  
Singapore 575722

Estimated Period of Repair: 0.0 days

**Adjuster:** KENNETH KONG

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$9,000.00

LTA REIMBURSEMENT VALUE (RV) : \$6,682.00

NETT VALUE : \$2,318.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

## REPAIR DETAILS

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**