



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2008084
INV Date 02/12/2020
Reference CC4/EQI18017536/Ups3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SLL 5487R
Insured Veh. SKP 365H
Claim No.
Policy No. DMPPHQ18-005538
Accident Date 25/09/2018
Inspection Date 26/09/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18017536/Ups3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 02-12-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKP 365H	Veh. Inspected	SLL 5487R
	Policy No.	DMPPHQ18-005538	Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	JOEL GOH	Assign Date	26/09/2018
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6BM42A8G0346042	Colour	GREY
	Odometer	25428	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	TOYO	8 mm
	L/H Front Tyre	205/60 R16	TOYO	8 mm
	R/H Rear Tyre	205/60 R16	TOYO	8 mm
	L/H Rear Tyre	205/60 R16	TOYO	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/09/2018	Inspection Date	26/09/2018
	Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 5487R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEEP CUT	1,031.70	1,031.70
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	351.00	-
1	FRONT BUMPER FOG LAMP COVER WITH CHROME	SCRATCHED	149.20	149.20
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	568.40	-
1	FRONT BUMPER SIDE RETAINER	BENT	42.50	18.70
1	FRONT BUMPER SIDE LAMP	NOT NECESSARY	315.00	-
1	FRONT BUMPER RUBBER SEAL	NOT NECESSARY	112.00	-
1	FRONT FENDER-R/H	TO REPAIR SEE LABOUR	550.00	-
1	FRONT FENDER INNER SHIELD	TORN	175.00	175.00
1	FRONT DOOR-R/H	TO REPAIR SEE LABOUR	1,061.50	-
1	FRONT DOOR CHECKER	NOT NECESSARY	46.80	-
2	FRONT DOOR HINGES	NOT NECESSARY	74.00	-
1	FRONT DOOR INNER BOARD	NOT NECESSARY	951.60	-
1	FRONT DOOR LOCK	NOT NECESSARY	313.00	-
1	FRONT DOOR REGULATOR	NOT NECESSARY	419.10	-
1	FRONT DOOR REGULATOR MOTOR	NOT NECESSARY	250.00	-
1	FRONT DOOR RUBBER	NOT NECESSARY	89.00	-
1	FRONT DOOR SIDE MIRROR ASSY	DAMAGED	685.00	455.10
1	FRONT WHEEL RIM-R/H	TO REPAIR SEE LABOUR	1,022.20	-
1	FRONT WHEEL HUB	NOT NECESSARY	185.80	-
1	FRONT WHEEL BEARING	NOT NECESSARY	146.00	-
1	FRONT SHOCK ABSORBER	NOT NECESSARY	381.00	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	349.50	-
1	FRONT LOWER ARM	NOT NECESSARY	516.70	-
1	FRONT DRIVE SHAFT-R/H	NOT NECESSARY	1,168.60	-
	LESS 20% DISCOUNT		-2,190.92	-365.94
			8,763.68	1,463.76

Report Ref No. CC4/EQI18017536/Ups3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	50.00	50.00
1	FRONT TYRE (SN)	NOT NECESSARY	350.00	-
			450.00	100.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.		80.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	NOT NECESSARY	450.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
	TO REMOVE, REPLACE DOOR DAMAGED PARTS AND TRANSFER ALL FITTINGS.	NOT NECESSARY	200.00	-
	TO APPLY UNDERCOATING.	NOT NECESSARY	200.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER-R/H, FRONT DOOR-R/H AND FRONT WHEEL RIM -R/H.		1,600.00	500.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,500.00	800.00
			4,210.00	1,320.00
GRAND TOTAL			13,423.68	2,883.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CC4/EQ118017536/Ups3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 5487R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 5487R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 5487R

RE-INSPECTION

