



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 26.09.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2911S TOYOTA VELLFIRE (2012)

To Supply

1) 1pc	Rear bumper	\$	1,785.00 <i>de</i>
2) 1set	Rear bumper clip	\$	30.00 <i>ne</i>
3) 1pc	Rear bumper right side retainer	\$	130.00 <i>ne</i>
4) 1pc	Rear right bumper tow hook cover	\$	59.80 <i>de</i>
5) 1pc	Tail gate	\$	2,200.00 <i>bt</i>
6) 1pc	Tail gate "Vellfire" emblem	\$	80.00 <i>ne</i>
7) 1pc	Tail gate "Toyota" logo	\$	90.00 <i>ne</i>
8) 1pc	Tail gate "Hybrid Synergy Drive" emblem	\$	60.00 <i>ne</i>
9) 1pc	Tail gate "E-Four" emblem	\$	70.00 <i>ne</i>
10) 1pc	Tail gate weatherstrip	\$	282.00 <i>cut</i>
11) 1pc	Tail gate lamp	\$	326.80 ?
12) 1pc	Right tail lamp lower panel	\$	278.50 <i>de</i>
13) 1pc	Reverse lamp	\$	240.90 <i>cut</i>
14) 1pc	Rear end panel	\$	804.10 <i>Rp</i>
15) 1pc	Rear end panel top garnish	\$	400.00 <i>de</i>
16) 1set	Rear end panel top garnish clip	\$	30.00 <i>ne</i>
17) 1pc	Rear bumper center right parking sensor (Genuine)	\$	290.00 <i>cut</i>
18) 1pc	Rear bumper center left parking sensor (Genuine)	\$	290.00 ?
19) 1pc	Rear bumper center right parking sensor cover (Genuine)	\$	25.00 <i>cut</i>
20) 1pc	Rear bumper center left parking sensor cover (Genuine)	\$	25.00 ?

Sub total parts	\$	7,497.10
Less: 25% discount	\$	1,874.27
	\$	5,622.83

To Supply S.Nett Parts

1) 1pc	"Prime Taxi" sticker	\$	55.00 <i>del</i>
2) 1set	Rear glass seal	\$	245.10 <i>del</i>
3) 1tube	Rear glass sealant	\$	45.00 <i>del</i>

Sub total S.Nett Parts \$ 345.10

L/charges

1) Towing charges (Using King-dolley)	\$	80.00 ✓
2) To tuff kote	\$	100.00 <i>30</i>
3) To remove & refit rear glass	\$	120.00 ✓
4) To remove & refit center reverse sensor & sensor, reset reverse sensor light. Check wiring	\$	60.00 <i>30</i>
5) To transfer tail gate trim cover, handle, glass & mechanism part.	\$	120.00 <i>60</i>
6) To cut / welding rear end panel, knock / repair floor panel. Remove rear bumper, tail gate, tail gate lamp & etc. Replace the above parts. Align & adjust rear bumper and tail gate.	\$	1,000.00 <i>700</i>
7) To putty, respray painting rear bumper, end panel, tail gate inlet & outer, floor panel, tow hook cover & reverse sensor cover in pearl white. To polish	\$	1,200.00 <i>700</i>

Sub total L/charges \$ 2,680.00
Estimated Grand total \$ 8,647.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
WP
26/9/18 Ekan
5 days
Resay after repair.
sure @ islands.com