



Case Details

Case Reference Number : TAX/09/18/2102

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : AXA Insurance
Singapore Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-3852-ID

Accident Date and Time : 22/09/2018 12:00 AM

Vehicle Registration Number : SHC4479R

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 50

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
			Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	1	0	Repair
One Time Key In			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	BT Replace
One Time Key In			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	CRA Replace
One Time Key In			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	0	0	? Check
One Time Key In			HOOD PANEL	1	748.10	748.10	25.00	561.08	Replace	1	0	XR Repair
One Time Key In			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	0	0	X SVL Not Given
One Time Key In			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	X N1 Not Given
One Time Key In			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	X SVL Not Given
Standard		6505517	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	CRA Replace
Standard VM		6505515	SUPPORT, FR BUMPER RH	1	68.76	68.76	25.00	51.57	Replace	0	0	? Check
Standard		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	X SVL Not Given
One Time Key In			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	SCR Replace
Total Spare Part Cost								2,892.08		Surveyor Total	1,239.18	
Lump Sum Discount (%)								20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost								2,313.66		Final Sur Total	991.34	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH PORTION FRONT	676.00	400	
Total:		676.00	400.00	


Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO RESPRAY FRONT LOWER GRILLE	180.00	0	NN
3	TO REPSRAY FRONT HOOD	378.00	200	
4	TO RESPRAY FRONT FENDER RH	378.00	0	NN
Total:		1,314.00	400.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	0	NN
3	TO REPLACE SUNDRY PARTS	100.00	0	NN
Total:		328.44	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,313.66	991.34
Total Labour Cost	676.00	400.00
Total Spray Painting	1,314.00	400.00
Other	328.44	20.00
Overall Total	4,632.10	1,811.34
Lump Sum Repair Option		☒
Lump Sum Total	0.00	1,800.00
Surveyor Approved Amount		1,800.00
No of Repair Days*	5	3
Remarks	-	LUMP SUM 3 DAYS AFTER REPAIR PHOTO
Surveyor Name		Naz
Signature		
Survey Date	27/09/2018	