




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18017585/Gea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Date : 09-09-2020	
			Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	YP 7561X	<b>Veh. Inspected</b>	SJT 3909K	
<b>Policy No.</b>	P2006928	<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	S8M00WSE	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>		<b>Assign Date</b>	27/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	MERCEDES BENZ C180K	<b>c.c</b>	1796	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2008	
<b>Chassis No.</b>	WDD2040462A108346	<b>Colour</b>	BLACK	
<b>Odometer</b>	123215	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM	
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>	225/45 R17	DAYTON	6 mm	
<b>L/H Front Tyre</b>	225/45 R17	DAYTON	6 mm	
<b>R/H Rear Tyre</b>	225/45 R17	DAYTON	6 mm	
<b>L/H Rear Tyre</b>	225/45 R17	DAYTON	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
<b>Accident Date</b>	23/09/2018	<b>Inspection Date</b>	27/09/2018	
<b>Survey held at</b>	MEGA SWIFT AUTO 176 SIN MING DRVIE #05-11 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		