



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLQ 9352 L
 Make & Model : TOYOTA PRIUS
 Chassis No : ZVW508031139

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH rear door / BT	1	\$1,181.75	✓	
2	RH rear door hinge top X	1	\$78.34	X	
3	RH rear door hinge bottom X	1	\$78.34	X	
4	RH rear door lock X	1	\$411.70	X	
5	RH rear door checker X	1	\$156.79	X	
6	RH rear door weatherstip X	1	\$178.40	X	
7	RHR door glass outer moulding X	1	\$111.61	X	
8	RHR power window motor X	1	\$511.69	X	
9	RHR power window regulator X	1	\$177.64	X	
10	RH side skirt / cut	1	\$721.50	? 379.6	/
11	RH side skirt clip / nb ^c	10	\$50.00	/	
12	RH rear fender X but repair	1	\$881.60	? X	
13	RH rear fender undershield X	1	\$92.30	X	
14	RH rear fender undershield clip X rec	10	\$30.00	X	
15	RH rear rim / cut	1	\$1,555.10	? 300(SN)	/
16	Rear bumper / cut	1	\$497.50	395.6	/
17	Rear bumper clip / rec	10	\$40.00	/	
18	Rear bumper lower garnish RH X repair	1	\$149.70	X	
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2046.95
 25% : 1538.21



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLQ 9352 L Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (RHR FENDER,RHR DOOR,RHF DOOR) RH SIDE SKIRT , REAR BUMPER)	\$1,200.00	800. 600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (RHR FENDER,RHR DOOR,RHF DOOR) RH SIDE SKIRT , REAR BUMPER)	\$1,200.00	1000
3	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	60
4	To remove & refit inner seat & upholstery to assist work load.	\$250.00	60
5	To check wiring	\$50.00	30
6	To tuff coat	\$100.00	60
7	To remove & refit reverse sensor to assit work load	\$120.00	40
			1850

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Company Reg No. 200005485N / GST No. 20-0005485-N

3685.21
5 Days.