



Case Details

Case Reference Number : TAX/09/18/2098

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : American Home Assurance Company

Type of Repair : Accident Repair

Estimation ID : EST-3850-ID

Accident Date and Time : 21/09/2018 02:45 AM

Vehicle Registration Number : SHC4877A

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 10

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			
					List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair	▼
One Time Key In			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	0	0	X nn	Not Given ▼
One Time Key In			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	0	0	X nn	Not Given ▼
One Time Key In			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	0	0	X nn	Not Given ▼
One Time Key In			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	X nn	Not Given ▼
One Time Key In			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	X s v l	Not Given ▼
One Time Key In			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	X s v l	Not Given ▼
One Time Key In			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	/ DEF	Replace ▼
One Time Key In			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	0	0	X s v l	Not Given ▼
One Time Key In			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	/ n l	Replace ▼
One Time Key In			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	0	0	X s v l	Not Given ▼
One Time Key In			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	0	0	X nn	Not Given ▼

Total Spare Part Cost	2,858.15	Surveyor Total	131.10
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	2,858.15	Final Sur Total	131.10

SMRT Recommendation									Surveyor Approval				
BOM Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	0	0	Not Given	
One Time Key In			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Given	
One Time Key In			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Given	
One Time Key In			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Given	
One Time Key In			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Given	
One Time Key In			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Given	
Total Spare Part Cost								2,858.15		Surveyor Total	131.10		
Lump Sum Discount (%)								0.00		Lump Sum Dis (%)	0		
Final Spare Part Cost								2,858.15		Final Sur Total	131.10		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	845.00	300	
Total:		845.00	300.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	NN
Total:		558.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	NN
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	NN
4	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	NN
5	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	NN
Total:		700.00	20.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	TO WASH AND VACUUM	60.00	0	NN
7	TO REPLACE SUNDRY PARTS	100.00	0	NN
Total:		700.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,858.15	131.10
Total Labour Cost	845.00	300.00
Total Spray Painting	558.00	200.00
Other	700.00	20.00
Overall Total	4,961.15	651.10
Lump Sum Repair Option		
Lump Sum Total	0.00	651.10
Surveyor Approved Amount		651.10
No of Repair Days*	5	2
Remarks	-	Surveyor Remarks
Surveyor Name		Naz
Signature		
Survey Date	27/09/2018	Save Clear

NAZ LKK
27/9/18
P/P
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: