

22/03/2002

ASS. REC. BY:

REF: CS/EGI18017652/Usb/12

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Yee pei Li of EGI

Date/Time: 1/10/18 @ 1:16pm

check with marcus just follow

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: GBG 3385J Insured: GBD 675H

at Workshop n/s Fastech Auto Tel: 6746 5405

of 1 kaki Bkt Ave G # 01-46

Policy No: Claim No: GBD 675H / SL / pl

Sum Insured: Excess:

Make of Veh: D.O.A. 27/09/18
(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 1:55pm @ 1/10/18 Person Contacted: Nancy Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
01/10/18	@ 16:32 p.m. revert pending estimate from repairer to Pei Li via email.

(08/11/13) wef

ASS. REC. BY: Morcas

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 636 33857at Workshop m/s Lf.

of _____

Insured: 630 67511

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 576

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

60003

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 636 33857 Yr Regn: 7.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)Make: Toyota hiace Dxc.c 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 30081 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH 2010224666

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/80 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 27/9/18 D.O.I. 28/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ATA 27672 net 2932819/11/18 confirmed 2/3 \$21,000 with Alu.19/11/18 Confirmed 4/5 \$21,000/- @ 16 days with Morcas
(\$21,285.87 Red - 50%)

RECEIVED 19 NOV 2018

Date/Time, File Pass to?

1) 17/11/18Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 16Resurvey No. of Trip: 3Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

350

Report Format :

Lump Sum / I.B.I: (\$ 21,000/- 4/5)

ERGO

Date: 01.10.2018
Our Reference: GBD 675H/SL/pl
Your Reference: GBG 3385J

Sent via Fax

or

Email

nancy.lam@fastechauto.com.sg

To: FASTECH AUTO PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBG 3385J
Insured's Vehicle: GBD 675H
Date Of Accident: 27.09.2018


We acknowledge receipt of your request for PRS on: 28.09.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK Auto Consultants Pte Ltd

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:			<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 1 October 2018 4:32 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: 'SUR'; 'Nivitha (LKK Auto)'; assignments@lkkauto.com
Subject: RE: GBD675H / TP : GBG3385J/LKK / DOA : 27/09/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle GBG 3385J on 28/09/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 1 October 2018 1:54 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments@lkkauto.com
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: GBD675H / TP : GBG3385J/LKK / DOA : 27/09/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Monday, 1 October 2018 1:46 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>
Subject: OI : GBD675H / TP : GBG3385J/LKK / DOA : 27/09/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 1 October 2018 1:46 PM
To: 'admin-d@lkkauto.com'
Cc: SUR (sur@lkkauto.com)
Subject: OI : GBD675H / TP : GBG3385J/LKK / DOA : 27/09/2018
Attachments: GBD675H - SAS.pdf; GBG3385J - SAS.pdf; GBG3385J - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : LINA @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 6000B

Vehicle Details

Vehicle No.: GBG3385J

Vehicle to be Exported: No

Intended Deregistration Date: 28 Sep 2018

Vehicle Make: TOYOTA

Vehicle Model: HIACE DX 3.0 MANUAL

Primary Colour: Silver

Manufacturing Year: 2017

Engine No.: 1KD2719086

Chassis No.: KDH2010224666

Maximum Power Output: -

Open Market Value: \$33,390.00

Original Registration Date: 22 Jul 2017

First Registration Date: 22 Jul 2017

Transfer Count: 0

Actual ARF Paid: \$1,670.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 21 Jul 2027

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$31,403.00

COE Rebate Amount: \$27,672.00

Total Rebate Amount: \$27,672.00

The information contained herein is correct as at 28 Sep 2018

OK

Date of Accident : 27/9/18 Accident Time: 2.17 (24-HR-Format)
Accident Place : Exit 17 Toward AYE City
Vehicle. No. (Car Plate No.) : G B G 3385J Make/Model: Toyota Hiace
Insurance Company : NTUC Policy No: _____
Owner or Company Name /IC No. : Ming Kee egg supplies / 499160008
Owner or Company Contact No. : _____ Owner's Hp _____ Company Tel _____
DRIVER'S Name / IC No. : Seah Jia Hwa, Mums / 59500981F
DRIVER'S Date Of Birth : 6/1/1995 DRIVER'S License Pass Date 2/1/2015
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____
DRIVER'S Address : Blk 108 Jalan Bukit Merah #02-1780
DRIVER'S Contact No./ Alt No. : 1) 93633792 2) 5160108
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): 1 Driver

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle. No: G B D 675H (ergo)

Vehicle. No: _____

Vehicle Make/Model: _____

Vehicle Make/Model: _____

Name Driver: _____

Name Driver: _____

IC No. Driver/Contact: _____

IC No. Driver/Contact: _____

*** NEW - Passenger's name & gender:**

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorised
Nale
28/9/18
4/5 \$21,000/-
16dy.

VEHICLE NO: GBG 3385J

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN
1 PCS	REAR WINDSCREEN RUBBER
1 PCS	REAR WINDSCREEN WIPER ARM
1 PCS	REAR WINDSCREEN WIPER MOTOR
1 PCS	REAR WINDSCREEN WIPE BLADE
1 PCS	TAILGATE 2/30.10
1 PCS	TAILGATE REAR LOGO
1 PCS	TAILGATE 'HIACE' STICKER
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE LOCK STRIKER
2 PCS	TAILGATE DEMPERS @\$188.10
1 PCS	TAILGATE INNER TRIM BOARD
1 SET	TAILGATE INNER TRIM BOARD CLIPS
1 PCS	TAILGATE OUTER HANDLE
1 PCS	TAILGATE WEATHER STRIP
1 PCS	REAR BUMPER
2 PCS	REAR BUMPER SIDE HOLDRES @\$30.50
1 SET	REAR BUMPER CLIPS
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP PLATE
2 PCS	REAR BODY PANELS @\$1885.10
2 PCS	REAR TAILLAMP HOUSING PANELS @\$466.50
2 PCS	REAR TAILLAMP INNER PANELS @\$485.10
2 PCS	TAILLAMPS @\$305.10
1 PCS	FUEL TANK
1 PCS	REAR END PANEL INNER
1 PCS	REAR FLOOR PANEL
1 PCS	REAR BUMPER BEAM
1 PCS	REAR SPARE TYRE BRACKET
1 PCS	REAR SPARE TYRE BRACKET HOOK
1 PCS	REAR EXHAUST
2 PCS	TAILLAMP LOWER GARNISHS @\$105.00
1 PCS	TAILGATE '1250 KG' STICKER
1 PCS	REAR STOP PANEL
1 PCS	TAILGATE OUTER LOCK COVER
1 PCS	REAR FLOOR PANEL TOP CARPET
1 PCS	BONNET
1 PCS	BONNET LOCK
1 PCS	BONNET LOGO

Shatterfnd	\$1,250.10	—
ns	\$299.30	X
11	\$285.40	X
11	\$466.10	X
11	\$105.30	X
Body DO	\$2485.10	—
Ren	\$48.50	—
Ren	\$38.50	—
tailgorn	\$209.10	—
11	\$66.50	X
11	\$376.20	X
unqd/Torn	\$465.10	—
Ren	\$50.00	—
Body/CR	\$285.30	—
twi	\$292.50	—
Dis	\$485.10	—
Ren	\$61.00	—
Ren	\$50.00	—
Body DO	\$622.10	—
Body	\$233.50	—
n/s Body DO of R	\$3,770.20	1PC
n/s Body DO	\$933.00	1PC
R	\$970.20	X
n/s crn	\$610.20	1PC
11	\$850.00	X
Body DO	\$850.00	—
R	\$1,480.10	X
ns	\$205.30	X
Ref	\$322.10	—
11	\$66.50	X
11	\$1,022.30	X
n/s twi	\$210.00	1PC
Ren	\$62.00	—
Ref	\$166.50	—
Dis	\$105.10	—
unqd/Torn	\$665.10	—
DO/Ref	\$866.10	—
twi	\$88.90	—
Ren	\$58.50	—

25%

21476.8

12186.9

2 PCS	BONNET HINGES @\$66.50	11	\$133.00	X
1 PCS	FRONT CORNER PANEL N/S	DP	\$366.50	
1 PCS	FRONT GRILLE TOP	Cut/trim	\$487.65	
1 PCS	FRONT GRILLE CENTRE	Cut	\$675.10	
1 PCS	FRONT BUMPER	11	\$671.10	
1 PCS	FRONT BUMPER TOW COVER	11	\$25.00	X
1 PCS	FRONT BUMPER CENTRE GRILLE	Toon	\$162.65	
1 PCS	FRONT BUMPER TOP BEAM	Best	\$189.60	
1 PCS	FRONT BUMPER REINFORCEMENT	Best	\$650.10	
2 PCS	FRONT BUMPER REINFORCEMENT STAYS @\$155.00	M/S	\$310.00	120
2 PCS	FRONT BUMPER SIDE HOLDERS @\$106.50	M/S	\$213.00	120
2 PCS	HEADLAMP ASSY 'HID' @\$2950.00	Che	\$5,900.00	
1 PCS	FRONT DOOR N/S	11	\$1,766.10	X
1 PCS	FRONT DOOR MIRROR N/S	Page	\$620.10	
1 PCS	FRONT SUPPORT PANEL	Best/trim	\$766.28	
1 PCS	FRONT WIRE HARNESS N/S	Che	\$580.10	
1 PCS	AIR CON CONDENSER	Best/trim	\$1,431.90	
1 PCS	AIR CON DISCHARGE PIPE	11	\$365.20	X
1 PCS	AIR CON SUCTION PIPE	11	\$289.65	X
1 PCS	AIR CON LIQUID PIPE	11	\$266.10	X
1 PCS	AIR CON FAN MOTOR	11	\$681.50	X
1 PCS	RADIATOR	Best	\$2,110.60	
1 PCS	RADIATOR FAN MOTOR	11	\$688.10	X
1 PCS	WASHER TANK	11	\$182.60	
1 PCS	RADIATOR SUB TANK	11	\$199.10	X
S.NETT				
1 PCS	FRONT LICENCE PLATE W/HOLDER	Best	\$50.00	40
1 BOT	RADIATOR COOLANT	rec	\$50.00	
1 PCS	FRONT DOOR 'ROC' STICKER N/S	rec	\$50.00	30
1 PCS	REAR WINDSCREEN SEALANT	rec	\$50.00	40
1 PCS	TAILGATE 70 KM/H STCIKER	rec	\$20.00	10
1 SET	REAR REVERSE CAMERA	shook	\$400.00	300
1 SET	REAR view video cam	shook	\$280.00	
1 Set	REAR licence plate w/holder	Best	\$50.00	40
1 SET	REAR WOODEN BOARD	Page	\$900.00	800
2 PCS	REAR FENDER TOP INNER BOARD (REPLACED GLASS)	o/s rec	\$450.00	200
1 SET	REAR FLOOR PANEL INSULATOR	rec	\$300.00	120
LABOUR CHRAGES:				
	TOWING CHARGE		\$120.00	50
	TO CHECK WIRING		\$80.00	30
	TO DISMANTLE & REPLACING REVERSE camera		\$80.00	50
	TO DISMANTLE & REPLACING REAR WINDSCREEN		\$150.00	120
	TO TRANSFER TAILGATE MECHANISM		\$120.00	60
	TO CLEAN UP REAR EGGS STAIN, WASH ETCS		\$380.00	100
	TO SPRAY RUST PROOFING		\$300.00	120
	TO DISMENTLE & REFIX FUEL TANK	11	\$120.00	X

TO REFILL AIR CON GAS
TO TANSFER FRONT DOOR MECHANISM
TO MOUNT VEHICLE ON CAR O-LINER
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED
REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$150.00 /00
11 \$100.00 X
11 \$380.00 X
\$3,800.00 2200

\$3000.00-1600

TOTAL

52587.83
42,285.87

4430




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18017652/Usbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 28-11-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 675H	Veh. Inspected	GBG 3385J	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBD675H/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	01/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE DX (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KDH2010224666	Colour	SILVER	
Odometer	30081	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	DUNLOP	6 mm	
L/H Front Tyre	195/80 R15	DUNLOP	6 mm	
R/H Rear Tyre	195/80 R15	DUNLOP	6 mm	
L/H Rear Tyre	195/80 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2018	Inspection Date	28/09/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 3385J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN	SHATTERED	1,250.10	1,250.10
1	REAR WINDSCREEN RUBBER	NO SUCH PARTS	299.30	-
1	REAR WINDSCREEN WIPER ARM	NOT NECESSARY	285.40	-
1	REAR WINDSCREEN WIPER MOTOR	NOT NECESSARY	466.10	-
1	REAR WINDSCREEN WIPER BLADE	NOT NECESSARY	105.30	-
1	TAILGATE	BADLY DENTED	2,485.10	2,150.10
1	TAILGATE REAR LOGO	NECESSARY	48.50	48.50
1	TAILGATE "HIACE" STICKER	NECESSARY	38.50	38.50
1	TAILGATE INNER LOCK	TWISTED / JAMMED	209.10	209.10
1	TAILGATE LOCK STRIKER	NOT NECESSARY	66.50	-
2	TAILGATE DAMPERS @\$188.10	NOT NECESSARY	376.20	-
1	TAILGATE INNER TRIM BOARD	WARPED / TORN	465.10	465.10
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE OUTER HANDLE	BENT / CRACKED	285.30	285.30
1	TAILGATE WEATHER STRIP	TWISTED	292.50	292.50
1	REAR BUMPER	DISTORTED	485.10	485.10
2	REAR BUMPER SIDE HOLDERS @\$30.50	BENT	61.00	61.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	BADLY DENTED	622.10	622.10
1	REAR END PANEL TOP PLATE	BENT	233.50	233.50
2	REAR BODY PANELS @\$1885.10	N/S BADLY DENTED / O/S TO REPAIR SEE LABOUR	3,770.20	1,885.10
2	REAR TAILLAMP HOUSING PANELS @\$466.50	N/S BADLY DENTED	933.00	466.50
2	REAR TAILLAMP INNER PANELS @\$485.10	TO REPAIR SEE LABOUR	970.20	-
2	TAILLAMPS @\$305.10	N/S CRACKED	610.20	305.10
1	FUEL TANK	NOT NECESSARY	850.00	-
1	REAR END PANEL INNER	BADLY DENTED	850.00	850.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,480.10	-

Report Ref No. CS/EGI18017652/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER BEAM	NO SUCH PARTS	205.30	-
1	REAR SPARE TYRE BRACKET	BENT	322.10	322.10
1	REAR SPARE TYRE BRACKET HOOK	NOT NECESSARY	66.50	-
1	REAR EXHAUST	NOT NECESSARY	1,022.30	-
2	TAILLAMP LOWER GARNISHS @\$105.00	N/S TWISTED	210.00	105.00
1	TAILGATE "1250KG" STICKER	NECESSARY	62.00	62.00
1	REAR STOP PANEL	BENT	166.50	166.50
1	TAILGATE OUTER LOCK COVER	DISTORTED	105.10	105.10
1	REAR FLOOR PANEL TOP CARPET	DAMAGED / TORN	665.10	665.10
1	BONNET	DENTED / BENT	866.10	866.10
1	BONNET LOCK	TWISTED	88.90	88.90
1	BONNET LOGO	NECESSARY	58.50	58.50
2	BONNET HINGES @\$66.50	NOT NECESSARY	133.00	-
1	FRONT CORNER PANEL N/S	DENTED	366.50	366.50
1	FRONT GRILLE TOP	TWISTED / CUT	487.65	487.65
1	FRONT GRILLE CENTRE	CUT	675.10	675.10
1	FRONT BUMPER	DISTORTED	671.10	671.10
1	FRONT BUMPER TOW COVER	NOT NECESSARY	25.00	-
1	FRONT BUMPER CENTRE GRILLE	TORN	162.65	162.65
1	FRONT BUMPER TOP BEAM	BENT	189.60	189.60
1	FRONT BUMPER REINFORCEMENT	BENT	650.10	650.10
2	FRONT BUMPER REINFORCEMENT STAYS @\$155.00	N/S DENTED	310.00	155.00
2	FRONT BUMPER SIDE HOLDERS @\$106.50	N/S CRACKED	213.00	106.50
2	HEADLAMP ASSY "HID" @\$2950.00	CRACKED	5,900.00	5,360.00
1	FRONT DOOR N/S	TO REPAIR SEE LABOUR	1,766.10	-
1	FRONT DOOR MIRROR N/S	DAMAGED	620.10	620.10
1	FRONT SUPPORT PANEL	BENT / TWISTED	766.28	766.28
1	FRONT WIRE HARNESS N/S	CRACKED	580.10	580.10
1	AIR CON CONDENSER	BENT / PUNCTURE	1,431.90	1,431.90
1	AIR CON DISCHARGE PIPE	NOT NECESSARY	365.20	-
1	AIR CON SUCTION PIPE	NOT NECESSARY	289.65	-
1	AIR CON LIQUID PIPE	NOT NECESSARY	266.10	-

Report Ref No. CS/EGI18017652/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON FAN MOTOR	NOT NECESSARY	681.50	-
1	RADIATOR	BENT / PUNCTURE	2,110.60	2,095.10
1	RADIATOR FAN MOTOR	NOT NECESSARY	688.10	-
1	WASHER TANK	DEFORMED	182.60	182.60
1	RADIATOR SUB TANK	NOT NECESSARY	199.10	-
	LESS 25% DISCOUNT		-	-6,671.80
			41,207.83	20,015.38
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	BOT RADIATOR COOLANT (SN)	NECESSARY	50.00	50.00
1	FRONT DOOR "ROC" STICKER N/S (SN)	NECESSARY	50.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	TAILGATE 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED	400.00	300.00
1	SET REAR VIEW VIDEO CAM (SN)	SHORTED	280.00	280.00
1	SET REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	SET REAR WOODEN BOARD (SN)	DAMAGED	900.00	800.00
2	REAR FENDER TOP INNER BOARD (REPLACED GLASS) (SN)	O/S NECESSARY	450.00	200.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	300.00	120.00
			2,600.00	1,910.00
	<u>LABOUR</u>			
	TOWING CHARGE.		120.00	50.00
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE CAMERA.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		120.00	60.00
	TO CLEAN UP REAR EGGS STAIN,WASH ETCS.		380.00	100.00
	TO SPRAY RUST PROOFING.		300.00	120.00
	TO DISMANTLE & REFIX FUEL TANK.	NOT NECESSARY	120.00	-
	TO REFILL AIR CON GAS.		150.00	100.00
	TO TRANSFER FRONT DOOR MECHANISM.	NOT NECESSARY	100.00	-
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-

Report Ref No. CS/EGI18017652/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED REPLACING PARTS, INCLUSIVE OF THE REPAIR OF O/S REAR BODY PANELS, REAR TAILLAMP INNER PANELS, REAR FLOOR PANEL AND FRONT DOOR N/S.		3,800.00	2,200.00
	TO PUTTY & SPRAY PAINTING.		3,000.00	1,600.00
			8,780.00	4,430.00
GRAND TOTAL			52,587.83	26,355.38
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				21,000.00

Report Ref No. CS/EGI18017652/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.