

108.11.13

Surveyor:

NAZ

REF:

NS/INC18017660/NAH22

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

CB 6864M

Policy No.

506819 7521 - 03 170118 - 16012019

Claims No.

MT/1012820-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMB 15204

Yr Regn: 20 Nov 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAN A22

C.C 10, S18

Colour

MULTI COLOURED

A/C: Insured / Std / NI / NA

Sp. Reading

(BATT FLAT)

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WMAA 22229E7002309

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70 R 22.5

R:

11 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GY (F), FREN 2A (R)

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/9/18

D.O.I.

27/9/18

Survey held at

SMRT WOODLANDS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SMB 15204 - NS/INC16005311 / Kth3n2

DA: 120316 JNL

L/S

CB 6864M - NA/INC18017660/24

DA: 210918

21/11/17 FINALIZED Lump sum REPAIR \$6150.00 / 3 DAYS
(Red: 369.80: 12%)

RECEIVED 23 JAN 2019

22/7/2019

Date/Time, File Pass to?

☐ : Preli. Report

1) 23/11/17 Tuptst

☒ : Final Report

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I.: (\$ 6150/-)

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp

(\$)

☐ : Interview

(\$)

☐ : Tech. Invs

(\$)

☐ : Weekend

(\$)

S + RS. SI

Photos

Others

TOTAL

160

160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18017660/Ntb				
73 BRAS BASAH ROAD		Date: 28-09-2018		
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Code: INC4		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	CB 6864M	Veh. Inspected	SMB 1520U	
Policy No.	50681197521-03	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/09/2018	Inspection Date	27/09/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="21/09/2018 14:14"/>
Vehicle No.(For Motor)	<input type="text" value="CB6864M"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5068197521-03		LU CHEET PHANG	S1817411A	GPC	drivo CLASSIC	SKP6334H	SKP6334H	17/01/2018	16/01/2019

Denise Tay (LKKAuto)

From: mtreg <mtreg@income.com.sg>
Sent: Tuesday, 22 January 2019 1:13 PM
To: Denise Tay (LKKAuto)
Subject: FW: REQUEST CLAIM NUMBER

Hi,

All claims created.

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Tuesday, January 22, 2019 8:44 AM
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST CLAIM NUMBER

TP Claims against NTUC Income: Follow-Through Survey

Date : 22/1/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentativ
1	MT/1012820-002	SMRT BUS	SMB 1520U	CB 6864M	21/9/2018	13:35	\$ 7,019.80	\$
2	MT/1024579-002	COMFORT TRANSPORTATION PTE LTD	SHD 4374D	SJF 9635J	19/12/2018	18:00	\$ 4,379.40	\$
3	MT/1019716-002	SMRT BUS	SMB 203S	SJM 3280B	12/11/2018	17:30	\$ 4,627.63	\$

Claim received from LKK Auto

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/09/2018 14:16
Date Of Accident	21/09/2018 13:35
Exact Location Of Accident	MARSILING RISE - BS: 46199 (BLK120)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB1520U
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	MAN
Model	MAN A22
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	

Driver

Name of Driver	WONG CHIN HAW
Work Permit No	G2151974Q
Date Of Birth	16/02/1985
Occupation	OUTDOOR
Date Of Driving Pass	03/08/2015
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address NO ADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 45

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I WAS ABOUT TO MOVE OFF FROM THE BUS STOP 46199 (BLK 120) WHEN A PTE BUS ENCROACHED INTO MY LANE AND SIDE SWIPED THE RIGHT FRONT PORTION OF MY BUS. MY BUS SUSTAINED SCRATCHES ON THE RIGHT FRONT BODY AND THE RIGHT VIEW MIRROR DISLODGED

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number CB6864M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

Denise



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/01/2019

User ID : CatherineLee

Section A - Accident Details


Registration Number	SMB1520U
Case Reference Number	BUS/09/18/7028
Registration Date	20/11/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Wong Chin Haw
Type of Accident	Side Swipe
Accident Date and Time	21/09/2018 1:38 PM
Accident Reported Date and Time	21/09/2018 2:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098097
Special Instruction to ARC, if any	
Prepared Date and Time	27/09/2018 10:19 AM
Chassis Number	VMMAA22ZZ9E7002309
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$1,060.00
Total Spray Cost	\$446.00	\$300.00
Total Spare Part Cost	\$5,049.06	\$5,049.06
Total Other Cost	\$0.00	(\$272.00)
TOTAL COST	\$6,820.06	\$6,137.06
Lump Sum Total	\$6,800.00	\$6,150.00
Number of Repair Days	3.5	3.0
Prepared / Adjusted By	Kok Khooon Goh	Naz
ARC / Surveyor Sign Off Date	27/09/2018 10:51 AM	27/09/2018 1:11 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



TOTAL - Naz



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/01/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	\$1,060.00
Total Labour	\$1,325.00	\$1,060.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$446.00	\$300.00
Total Spray Painting & Panel Beating	\$446.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$272.00)
Total Other Costs	\$0.00	(\$272.00)

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			MIRROR, VIEW FRONT, R H, MAN A22 'C' SERIES	1.00	\$1,353.00	10.00	\$1,217.70	Replace	Replace
			WINDSCREEN, FRONT, F OR MAN A22 BUS	1.00	\$5,031.80	10.00	\$4,528.62	Replace	Replace
			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
			ADHESIVE, DIRECT GLAZING	10.00	\$37.00	0.00	\$370.00	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
			STICKER IU	1.00	\$35.00	0.00	\$35.00	Replace	Replace
Total					\$6,616.80		\$6,311.32		

BR
CEL
NEL
NEL
NEL
NEL

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

PARTS \$6311.32
LABOUR \$1060.00
SPRAY 300.00
LESS LIS 20% \$6137.05

LIS TOTAL \$6150.00 13 REPAIR DAYS.

8720.80



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/09/2018

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB1520U
Case Reference Number	BUS/09/18/7068
Registration Date	20/11/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Wong Chin Haw
Type of Accident	Side Swipe
Accident Date and Time	21/09/2018 1:38 PM
Accident Reported Date and Time	21/09/2018 2:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	
Prepared Date and Time	27/09/2018 10:19 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates


Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$446.00	\$0.00
Total Spare Part Cost	\$5,014.66	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$6,785.66	\$0.00
Lump Sum Total	\$6,800.00	\$0.00
Number of Repair Days	3.5	
Prepared / Adjusted By	Kok Khooon Goh	Naz
ARC / Surveyor Sign Off Date	27/09/2018 10:51 AM	
Signature		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	1060





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/09/2018

User ID : GohKK2

Total Labour	\$1,325.00	
--------------	------------	--

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$446.00	300
Total Spray Painting & Panel Beating	\$446.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			MIRROR VIEW: FRONT, R	1.00	\$1,353.00	10.00	\$1,217.70	Replace	/ CRA
			H, MAN A22 'C' SERIES	1.00	\$5,031.80	10.00	\$4,528.62	Replace	/ CRA
			WINDSCREEN, FRONT: F	1.00	\$80.00	0.00	\$80.00	Replace	/ nlc
			OR MAN A22 BUS	10.00	\$37.00	0.00	\$370.00	Replace	/ nlc
			ACTIVATOR	1.00	\$37.00	0.00	\$37.00	Replace	/ nlc
			ADHESIVE: DIRECT	1.00	\$35.00	0.00	\$35.00	Replace	/ nlc
			GLAZING	1.00	\$35.00	0.00	\$35.00	Replace	/ nlc
			PRIMER (SIKA 206 G+P)	1.00	\$35.00	0.00	\$35.00	Replace	/ nlc
			STICKER IU	1.00	\$6,573.80		\$6,268.32		
Total									

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

NAZ LKIC
27/9/18 1030
L/S
3 DAYS
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18017660/Ntbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 23-01-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	CB 6864M	Veh. Inspected	SMB 1520U	
Policy No.	5068197521-03	Coverage (\$)	0.00	
Claim No.	MT/1012820-002	Excess (\$)	0.00	
Assign From		Assign Date	27/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAN A22	c.c	10518	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WMAA22ZZ9E7002309	Colour	MULTI COLOUR	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	GOODYEAR	6 mm	
L/H Front Tyre	275/70 R22.5	GOODYEAR	6 mm	
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm	
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2018	Inspection Date	27/09/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1520U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	MIRROR, VIEW:FRONT, RH, MAN A22 'C' SERIES	BROKEN	1,353.00	1,353.00
1	WINDSCREEN, FRONT:FOR MAN A22 BUS	CRACKED	5,031.80	5,031.80
	LESS 10% DISCOUNT		-	-638.48
			6,384.80	5,746.32
SPECIAL NETT ITEMS				
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
10	ADHESIVE:DIRECT GLAZING @\$37.00 (SN)	NECESSARY	370.00	370.00
1	PRIMER (SIKA 206 G+P) (SN)	NECESSARY	80.00	80.00
1	STICKER IU (SN)	NECESSARY	35.00	35.00
			565.00	565.00
LABOUR				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		1,325.00	1,060.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		446.00	300.00
			1,771.00	1,360.00
GRAND TOTAL			8,720.80	7,671.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				6,150.00

Report Ref No. NS/INC18017660/Ntbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.