

Surveillance

REF:

CS/FCI 18017669/R1sd3e2 0446K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBC 3433A

at Workshop m/s SNA AH TEC

of 24K 3, Pioneer Rd North #01-18

Insured: FCI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: _____

(Policy Condition)

930-Byr

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 24K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBC 3433A Yr Regn: 2011 / DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NISSAN NV200 1.5 MT c.c. 1461

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 236296 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYBAM204 0025013

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185R14C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 28/09/18

D.O.I. 20/11/18

Survey held at SNA AH TEC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S & CHAS

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/11/18	@ 16:31 p.m. revised PA to Eileen Lee via email.
09/10/19	Confirmed L/S \$ 3,700/- @ 6 days with Result. (\$ 4,711.34 Rd - 56% Re-open case for analyze before 9/10/19.
	RECEIVED 14 MAY 2019
	MV - \$ 24K
	LTA - \$ 12,167.00
	WEH - \$ 11,833.00
	file pass to typist after re-open

Date/Time, File Pass to?

11/10/19

1) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$) S + RS SI☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: 160

Transportation: 50

Photos: 61

Others: _____

TOTAL

271

Report Format :

Lump Sum / I.B.I: (\$ 3,700/- US)

14/10/19 re-open ref only, 1st doc 14/5/19

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	0446K

Vehicle Details

Vehicle No.:	GBC3433A
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	K9KF276D123851
Chassis No.:	VSKYBAM20U0025013
Maximum Power Output:	-
Open Market Value:	\$21,342.00
Original Registration Date:	30 Dec 2011
First Registration Date:	30 Dec 2011
Transfer Count:	3
Actual ARF Paid:	\$1,068.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	29 Dec 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$37,011.00
COE Rebate Amount:	\$12,167.00
Total Rebate Amount:	\$12,167.00

The information contained herein is correct as at 27 Sep 2018

OK

24,000
12,167

11,833

RE: GBC3433A - FINALISE & AFTER PAINT

Rasul (LKKAuto)

Tue 8/10/2019 3:00 PM

To: Sharon Sng <sharon@sngahtee.com>

Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Hi Sharon,

Finalised amount of \$ 3,700 / 6 days lump sum is confirmed

Best Regards,

Rasul | Assessor**LKK Auto Consultants Pte Ltd**Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Auto
Consultants
Pte Ltd*Save the Earth. Print only when necessary.*

From: Sharon Sng [mailto:sharon@sngahtee.com]**Sent:** Monday, 7 October, 2019 7:15 PM**To:** Rasul (LKKAuto)**Subject:** GBC3433A - FINALISE & AFTER PAINT

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457

TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>*-Please note that all offer/acceptance is made without prejudice.-*

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004355

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE 12/11/2018

ACCIDENT DATE : 25/09/2018

VEHICLE NO : GBC3433A

CHASSIS/ENG.NO :

VEHICLE MODEL : NISSAN NV200

CLAIM NO :

POLICY NO :

REMARK 3433 FIRST CAP TP
AGST SHC1818R

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
						SUB-TOTAL:	0.00
** NETT PRICE **							
1	1	PC	FRT BUMPER <i>DE</i>	536.10	10	482.49	482.49 ✓
2	10	PC	FRT BUMPER CLIPS <i>NE</i>	4.10	10	3.69	36.90 ✓
3	1	PC	FRT BUMPER RETAINER(RH) <i>NE</i>	24.00	10	21.60	21.60 ✓
4	1	PC	FRT BUMPER REINFORCEMENT <i>? X SUC</i>	614.90	10	553.41	553.41 X
5	1	PC	FRT FOGLAMP COVER (RH) <i>X SUC</i>	321.60	10	289.44	289.44 X
6	1	PC	FRT HEADLAMP (RH) <i>SUC</i>	446.40	10	401.76	401.76 ✓
7	1	PC	FRT HEADLAMP CLIP(RH) <i>NE</i>	5.60	10	5.04	5.04 ✓
8	1	PC	FRT HEADLAMP LOWER GARNISH(RH) <i>DE</i>	329.30	10	296.37	296.37 ✓
9	1	PC	REAR BUMPER <i>DE</i>	624.80	10	562.32	562.32 ✓
10	10	PC	REAR BUMPER CLIP <i>NE</i>	4.10	10	3.69	36.90 ✓
11	1	PC	REAR BUMPER RETAINER(LH) <i>(RH) < - NE</i>	36.00	10	32.40	32.40 ✓
12	1	PC	REAR BUMPER REFLECTOR(LH) <i>(RH) CPA</i>	55.00	10	49.50	49.50 ✓
13	1	PC	REAR BOOT NV200 STICKER <i>NE</i>	79.90	10	71.91	71.91 ✓
14	1	PC	REAR BOOT DCI STICKER <i>NE</i>	68.90	10	62.01	62.01 ✓
15	1	PC	REAR BOOT EMBLEM <i>NE</i>	145.60	10	131.04	131.04 ✓
16	1	PC	FRT LOWER ARM (RH) <i>? X SUC</i>	200.50	10	180.45	180.45 X
17	1	PC	REAR BOOT LID (RH) <i>repair</i>	1,281.10	10	1,152.99	1,152.99 R
18	1	PC	REAR BOOT LID (LH) <i>PA</i>	960.90	10	864.81	864.81 ✓
						SUB-TOTAL	5,231.34
						<i>\$3055.05</i>	

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004355

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE 12/11/2018

ACCIDENT DATE : 25/09/2018

VEHICLE NO : GBC3433A

CHASSIS/ENG.NO :

VEHICLE MODEL : NISSAN NV200

CLAIM NO :

POLICY NO :

REMARK : 3433 FIRST CAP TP
AGST SHC1818R

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** SPECIAL NETT PRICE **							
1	1	PC	REAR BUMPER REVERSE SENSOR <i>1 xsc</i>	280.00	<i>200</i>	280.00	<i>200</i> 280.00*
2	1	PC	REAR BOOT 70 KM STICKER <i>1 xsc</i>	10.00		10.00	10.00✓
3	1	PC	REAR BOOT 5 PAX STICKER <i>1 xsc</i>	10.00		10.00	10.00✓
4	1	PC	REAR NUMBER PLATE <i>1 xsc</i>	30.00		30.00	30.00✓
5	1	PC	FRT SHOCKABSORBER(RH) <i>1 xsc</i>	252.80		252.80	252.80✓
6	1	PC	FRT KNUCKLE ARM (RH) <i>1 xsc</i>	357.20		357.20	357.20✓
7	1	PC	REAR WINDSCREEN SEALANT <i>1 xsc</i>	40.00		40.00	<i>\$40</i> 80.00 ✓
SUB-TOTAL							1,020.00
** WORK LABOUR **							
TO KNOCK ,WELD, REMOVE & REPLACE ABOVE PARTS							
TO REMOVE & REFIT REAR WINDSCREEN							
TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS							
TO CHECK WIRING1							
TO DO WHEEL ALIGNMENT							
TO APPLY ANTI-RUST COAT							
LKK Auto Consultants hence notify the Repairer of the following:							
• To resurvey before/after spray painting							
• To display damaged part(s) during resurvey							
• Parts prices are subject to confirmation							
• Third party survey is on a "Without Prejudice" basis							
• No illegal modification(s) is allowed							
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company							
JOYCE Knownledged by Repairer Signature: <i>[Signature]</i> Date:							
PAGE: 2 of 2				SUB-TOTAL : SS 8,411.34			
				ADD 7% GST. SS 588.79			
				GRAND TOTAL : SS 9,000.13			

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

17/12 - 31/12
Available

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18017669/R1sd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-05-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1818R	Veh. Inspected	GBC 3433A
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18007081MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	28/09/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200 1.5L MT	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	VSKYBAM20U0025013	Colour	WHITE
Odometer	236296	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14C	FALKEN	6 mm
L/H Front Tyre	185 R14C	FALKEN	6 mm
R/H Rear Tyre	185 R14C	FALKEN	6 mm
L/H Rear Tyre	185 R14C	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/09/2018	Inspection Date	20/11/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 3433A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER (N)	DEFORMED	536.10	536.10
10	FRT BUMPER CLIPS @\$4.10 (N)	NECESSARY	41.00	41.00
1	FRT BUMPER RETAINER (RH)(N)	NECESSARY	24.00	24.00
1	FRT BUMPER REINFORCEMENT (N)	SERVICEABLE	614.90	-
1	FRT FOGLAMP COVER (RH)(N)	SERVICEABLE	321.60	-
1	FRT HEADLAMP (RH)(N)	SCRATCHED	446.40	446.40
1	FRT HEADLAMP CLIP (RH)(N)	NECESSARY	5.60	5.60
1	FRT HEADLAMP LOWER GARNISH (RH)(N)	DEFORMED	329.30	329.30
1	REAR BUMPER (N)	DEFORMED	624.80	624.80
10	REAR BUMPER CLIP @\$4.10 (N)	NECESSARY	41.00	41.00
1	REAR BUMPER RETAINER (RH)(N)	NECESSARY	36.00	36.00
1	REAR BUMPER REFLECTOR (RH)(N)	CRACKED	55.00	55.00
1	REAR BOOT NV200 STICKER (N)	NECESSARY	79.90	79.90
1	REAR BOOT DCI STICKER (N)	NECESSARY	68.90	68.90
1	REAR BOOT EMBLEM (N)	NECESSARY	145.60	145.60
1	FRT LOWER ARM (RH)(N)	SERVICEABLE	200.50	-
1	REAR BOOT LID (RH)(N)	TO REPAIR SEE LABOUR	1,281.10	-
1	REAR BOOT LID (LH)(N)	BENT	960.90	960.90
	LESS 10% DISCOUNT		-581.26	-339.45
			5,231.34	3,055.05
SPECIAL NETT ITEMS				
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	REAR BOOT 70KM STICKER (SN)	NECESSARY	10.00	10.00
1	REAR BOOT 5 PAX STICKER (SN)	NECESSARY	10.00	10.00
1	REAR NUMBER PLATE (SN)	NECESSARY	30.00	30.00
1	FRT SHOCK ABSORBER (RH)(SN)	SERVICEABLE	252.80	-
1	FRT KNUCKLE ARM (RH)(SN)	SERVICEABLE	357.20	-
2	REAR WINDSCREEN SEALANT @\$40.00 (SN)	NECESSARY (1 PC ONLY)	80.00	40.00
			1,020.00	90.00

Report Ref No. CS/FCI18017669/R1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCK,WELD,REMOVE & REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOT LID (RH).		800.00	600.00
	TO REMOVE & REFIT REAR WINDSCREEN.		200.00	100.00
	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS.		900.00	650.00
	TO CHECK WIRING.		30.00	30.00
	TO DO WHEEL ALIGNMENT.		80.00	60.00
	TO APPLY ANTI RUST COAT.		150.00	80.00
			2,160.00	1,520.00
	GRAND TOTAL		8,411.34	4,665.05

RECOMMENDED COST OF LUMP SUM REPAIRS			3,700.00
---	--	--	-----------------

Report Ref No. CS/FCI18017669/R1sd3e2

MARKET VALUE: \$24,000.00(EST)-LTA REIMBURSEMENT VALUE: \$12,167.00=NETT VALUE: \$11,833.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.