

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 02 Oct 2018

Preliminary Advice

Insured Vehicle No	: GBA4967E		
TP Vehicle No	: SFC1938B	Accident Date	: 12/09/2018
Make	: TOYOTA DYNA 100 MANUAL	Assignment Date	: 28/09/2018
Date of Inspection	: 28/09/2018	Est. Duration of Repair	: 1 day
Inspection At	: Koon Heng Motor (-) 1 Kaki Bukit Ave 6, #02-14, Autobay@Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s wing mirror portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,489.00
Revised Amount	:S\$	1,070.10
Check Items (Estimated)	:S\$	200.00
Total	:S\$	1,270.10

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.