

Surveyer

REF: C93/1PC18012187/Gsd3-1ⁿ²

Surveyer

Guo Qiang

ASSIGNMENT (Office)

Progn. (Person):

Qing li li

LPC

File of Time

28/09/2018

Estimated Cost

1414-10

$$OD(TP) / WS / TP RES / OD RES / EVA / INV / MV / CS$$

To Inspect Vehicle No.

SKF 1603S

Insured

SGR 1343B

at Workshop info

N-51 Automotive

Tel

6842005

of

2 Kaki Bukit Ave 2 # 01-18

Policy No.

Claim No.

18/18/18 VPOS 020734

Sum Incurred:

Exercises

Make of Veh

DOA 03/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endonastical

Late/True

3:56 pm ⑥ 4/7/18

Person Contacted

Melody

Vehicle IN/OUT

Date/Time

Action/Instruction	(X)	Estimate
1. Review the project schedule and identify critical path activities.		
2. Assign resources to each activity based on availability and skill set.		
3. Monitor progress regularly and update the schedule as needed.		
4. Communicate with stakeholders to ensure transparency and manage expectations.		
5. Conduct a final review and evaluation of the project outcomes.		

10/10/13

Submit L/S \$ 7,100/- @ 6 days
(\$ 5,200.00 Red - 42%)

[Signature]

10/10/2018


RECEIVED 10 OCT 2018

PRS
X22

REF: LPC

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop: N-51
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$60k
 IDAC Accident Report: Consistent? Yes or No
 GIA / PR Seen: Consistent? Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

\$5000 - \$6000

Veh No: SKF 1603S Yr Regn: 02 May 2012
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 118i CC: 1598
 Colour: black A/C: Insured / Std / NI / NA
 Sp Reading: 94770 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBA1A32060J 065751
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Ins. / Jammed / Leaked / Burnt or
 Brake: Ins. / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or
 Tyre Size: F: 225/45R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / OKO or
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 04-07-18
 Survey held at: WLS 4pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time: File Pass to?
 06/07/12
 1) Typist
 Date/Time: File Return to?

☐ : Prelim. Report
☐ : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:
 Transportation
) S + RS \$1
) Photos
) Copies

Report Format: PRS
 Lump Sum / I.B.I: (\$)

TOTAL

450

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 28 September 2018 4:29 PM
To: Shirley Hiew (LKK Auto); MT_Claim_SG
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; 'assignments'
Subject: RE: SKF1603S & SGR1343B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: 18/18/18/VP05/020734
Attachments: 20734 TP SURVEY REPORT.pdf

Dear Shirley

Attached is the TP survey report.

Please let us have your surveyor's comment and report.

Thanks,
Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, 9 July, 2018 11:41 AM
To: ONG LI LI; MT_Claim_SG
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; 'assignments'
Subject: RE: SKF1603S & SGR1343B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: 18/18/18/VP05/020734

Dear Li Li,

Refer to your assignment on 04.07.2018 at 3.28PM.

Please be informed that we have inspected the vehicle SKF 1603S on 04.07.2018 at 16.00PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Monday, 9 July 2018 9:58 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; MT_Claim_SG <mt_claim@lonpac.com>
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>; 'assignments' <assignments@lkkauto.com>

Subject: RE: SKF1603S & SGR1343B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: 18/18/18/VP05/020734

Hi Shirley

Our Claim no. 18/18/18/VP05/020734.

Please take note that our Insured has not reported the accident.

Kindly let us have your preliminary advice.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Monday, 9 July, 2018 9:27 AM
To: ONG LI LI; MT_Claim_SG
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; 'assignments'
Subject: RE: SKF1603S & SGR1343B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: to be advised

Dear Li Li,

Kindly provide us the claim no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Wednesday, 4 July 2018 3:58 PM
To: 'ONG LI LI' <long@lonpac.com>; 'assignments' <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; sur@lkkauto.com
Subject: RE: SKF1603S & SGR1343B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: to be advised

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]

Sent: Wednesday, 4 July 2018 3:28 PM

To: Chin Hui Xin <huixin@n51.com.sg>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com

Subject: RE: SKF1603S & SGR1343B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: to be advised

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Wednesday, 4 July, 2018 3:22 PM

To: MT_Claim_SG

Subject: SKF1603S & SGR1343B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Lee Meng Chuan
Blk 326 Ang Mo Kio Ave 3
#08-1992
Singapore 560326

Date : 10/08/2018

Reference No : CAS/18-08/022

General Information

Registration No. : SKF 1603S
Accident Date : 03/07/2018

Particulars of Damaged Vehicle

Colour	: Black	Make & Model	: BMW 118I
Engine Capacity	: 1598 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 94770	Engine No.	: A885J180N13B16A
Chassis No.	: WBA1A32060J065751	Steering	: In Order
Registration Date	: 02/05/2012	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	225/45R17	BRIDGESTONE	80%
L/H Front Tyre	225/45R17	BRIDGESTONE	80%
R/H Rear Tyre	225/45R17	YOKOHAMA	90%
L/H Rear Tyre	225/45R17	YOKOHAMA	90%

Inspection

Repairer : N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2, #01-18 Kaki Bukit Autohub, Singapore 417921

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$16,287.96
Revised Amount : \$12,300.00
Less Excess : -
Nett Total : \$12,300.00

Remarks

- (A) Survey was done on 04/07/2018
- (B) Re-survey was done on 05/07/2018
- (C) Re-survey after repair was done on 10/07/2018
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : SKF 1603S

Our ref : CAS/18-08/022

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS</u>					
1	1pc	Rear bumper	Dented/Deformed	1,037.90	1,037.90
2	1pc	Rear bumper center bracket	Broken	56.85	56.85
3	1pc	Rear bumper lower cover	Grazed/Deformed	225.60	225.60
4	1pc	Rear bumper reinforcement	Dented/Bent	449.40	449.40
5	24pcs	Rear bumper reverse sensor @ \$236.88	Damaged	947.52	493.76 947.52
6	24pcs	Rear bumper reverse sensor 'o' ring @ \$10.00	Necessary	40.00	20 40.00
7	24pcs	Rear bumper reverse sensor holder @ \$72.76	Necessary	291.04	145.52 291.04
8	2pcs	Rear bumper side retainer L/R @ \$69.55	Broken	139.10	139.10
9	1pc	Rear end panel 'inner'	Dented	397.45	397.45 X NN
10	1pc	Rear end panel 'outer'	Dented/Warped	497.45	497.45 X R
11	1pc	Rear end panel antenna sensor	Damaged	501.90	501.90 X NN
12	1pc	Rear end panel top garnish	Deformed	77.20	77.20 CRA
13	1pc	Rear exhaust aluminium heat shield	Warped	80.25	80.25 DIS
14	1pc	Rear exhaust gasket	Necessary	65.00	65.00 REC
15	3pcs	Rear exhaust rubber mounting @ \$31.00	Serviceable	93.00	- X NN
16	1pc	Rear exhaust silencer box	Dented	864.80	864.80
17	1pc	Rear floor panel top trim board	Dented/Broken	154.00	154.00 X NN
18	1pc	Rear tailgate	Dented/Warped	1,230.50	1,230.50
19	1pc	Rear tailgate 'logo' emblem	Damaged	80.25	80.25
20	1pc	Rear tailgate bracket	Broken	21.20	21.20 X NN
21	2pcs	Rear tailgate damper L/R @ \$133.75	Bent/Jammed	267.50	267.50 X NN
22	2pcs	Rear tailgate hinges L/R @ \$75.90	Repair	151.80	- X NN
23	1pc	Rear tailgate inner trim board	Deformed	160.50	160.50 X NN
24	1pc	Rear tailgate lock striker	Bent	55.75	55.75 X NN
25	1pc	Rear tailgate mechanism lock	Bent/Jammed	155.70	155.70
26	1pc	Rear tailgate outer lock button	Damaged	103.40	103.40 X NN
27	1pc	Rear tailgate outer lock button bracket	Broken	35.55	35.55 X NN
28	1pc	Rear tailgate weather strip	Distorted	85.00	85.00
29	1set	Rear tailgate windscreen seal –set	Necessary	595.25	595.25
30	1pc	Rear tailgate wiper motor	Damaged	390.40	390.40 X NN
31	2pcs	Rear taillamp L/R @ \$422.65	Mounting Broken	845.30	845.30
32	2pcs	Rear taillamp side garnish L/R @ \$65.70	Broken	131.40	131.40
Sub total				10,227.96	9,983.16

Constant Appraiser Services

Vehicle No : SKF 1603S

Our ref : CAS/18-08/022

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
1	1set	Rear bumper clips - set	Necessary	120.00	50 120.00
2	1set	Rear end panel top garnish clips - set	Necessary	50.00	30 50.00
3	1pc	Rear floor panel insulator mat	Not Necessary	350.00	-
4	1set	Rear tailgate inner trim board clips - set	Necessary	80.00	40 80.00
5	1pc	Rear tailgate windscreen sealant	Necessary	120.00	50 100.00
6	2sets	Rear taillamp clips L/R – set @ \$30.00	Necessary	60.00	40 60.00
		Sub total		11,007.96	10,393.16
		<u>LABOUR & MISC. CHARGES</u>			
1		To reset system after repair works		400.00	360.00
2		To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor		120.00	80.00 50
3		To remove, reinstall tailgate windscreen		300.00	150.00 120
4		To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)		160.00	100.00 80
5		To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper		1,900.00	1,600.00 700
6		To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident		180.00	100.00 70
7		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		2,100.00	1,600.00 700
8		To apply anti-rust chemical on repaired and replaced panel		120.00	90.00 40
		Grand total		16,287.96	14,473.16
Recommended cost of lump sum repair (To its pre-accident condition)					12,300.00

6 days

Constant Appraiser Services

Vehicle No : SKF 1603S

Our ref : CAS/18-08/022

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$12,300.00** on a contractual basis. Under normal circumstances, the repair period would be about **7 (Seven)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC18012187/Gsd3n2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 10-10-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGR 1343B	Veh. Inspected	SKF 1603S
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020734	Excess (\$)	0.00
Assign From	ONG LI L I	Assign Date	28/09/2018
2. Vehicle Particulars & Condition			
Make & Model	BMW 118i	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBA1A32060J065751	Colour	BLACK
Odometer	94770	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/45 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/07/2018	Inspection Date	04/07/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 1603S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED / DEFORMED	1,037.90	1,037.90
1	REAR BUMPER CENTER BRACKET	BROKEN	56.85	56.85
1	REAR BUMPER LOWER COVER	GRAZED / DEFORMED	225.60	225.60
1	REAR BUMPER REINFORCEMENT	DENTED / BENT	449.40	449.40
4	REAR BUMPER REVERSE SENSOR @\$236.88	DAMAGED (2 PCS ONLY)	947.52	473.76
4	REAR BUMPER REVERSE SENSOR "O" RING @\$10.00	NECESSARY (2 PCS ONLY)	40.00	20.00
4	REAR BUMPER REVERSE SENSOR HOLDER @\$72.76	NECESSARY (2 PCS ONLY)	291.04	145.52
2	REAR BUMPER SIDE RETAINER L/R @\$69.55	BROKEN	139.10	139.10
1	REAR END PANEL "INNER"	NOT NECESSARY	397.45	-
1	REAR END PANEL "OUTER"	TO REPAIR SEE LABOUR	497.45	-
1	REAR END PANEL ANTENNA SENSOR	NOT NECESSARY	501.90	-
1	REAR END PANEL TOP GARNISH	CRACKED	77.20	77.20
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	DISTORTED	80.25	80.25
1	REAR EXHAUST GASKET	NECESSARY	65.00	65.00
3	REAR EXHAUST RUBBER MOUNTING @\$31.00	NOT NECESSARY	93.00	-
1	REAR EXHAUST SILENCER BOX	DENTED	864.80	864.80
1	REAR FLOOR PANEL TOP TRIM BOARD	NOT NECESSARY	154.00	-
1	REAR TAILGATE	DENTED / WARPED	1,230.50	1,230.50
1	REAR TAILGATE "LOGO" EMBLEM	DAMAGED	80.25	80.25
1	REAR TAILGATE BRACKET	NOT NECESSARY	21.20	-
2	REAR TAILGATE DAMPER L/R @\$133.75	NOT NECESSARY	267.50	-
2	REAR TAILGATE HINGES L/R @\$75.90	NOT NECESSARY	151.80	-
1	REAR TAILGATE INNER TRIM BOARD	NOT NECESSARY	160.50	-
1	REAR TAILGATE LOCK STRIKER	NOT NECESSARY	55.75	-
1	REAR TAILGATE MECHANISM LOCK	BENT / JAMMED	155.70	155.70
1	REAR TAILGATE OUTER LOCK BUTTON	NOT NECESSARY	103.40	-
1	REAR TAILGATE OUTER LOCK BUTTON BRACKET	NOT NECESSARY	35.55	-

Report Ref No. CS3/LPC18012187/Gsd3n2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE WEATHER STRIP	DISTORTED	85.00	85.00
1	SET REAR TAILGATE WINDSCREEN SEAL	NECESSARY	595.25	595.25
1	REAR TAILGATE WIPER MOTOR	NOT NECESSARY	390.40	-
2	REAR TAILLAMP L/R @\$422.65	MOUNTING BROKEN	845.30	845.30
2	REAR TAILLAMP SIDE GARNISH L/R @\$65.70	BROKEN	131.40	131.40
			10,227.96	6,758.78
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	120.00	50.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR FLOOR PANEL INSULATOR MAT (SN)	NOT NECESSARY	350.00	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	80.00	40.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	120.00	50.00
2	SETS REAR TAILLAMP CLIPS L/R @\$30.00 (SN)	NECESSARY	60.00	40.00
			780.00	210.00
	LABOUR			
	TO RESET SYSTEM AFTER REPAIR WORKS.		400.00	150.00
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		120.00	50.00
	TO REMOVE,REINSTALL TAILGATE WINDSCREEN.		300.00	120.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		160.00	80.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER.		1,900.00	700.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		180.00	70.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR END PANEL "OUTER"		2,100.00	700.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00
			5,280.00	1,910.00
GRAND TOTAL			16,287.96	8,878.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,100.00

Report Ref No. CS3/LPC18012187/Gsd3n2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.