

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110

INV No. AC2006263

INV Date 11/09/2020

Reference CC3/EQI18017707/K1ea3q2

Code EQ

### **PROFESSIONAL SERVICE FEE**

Vehicle No. SHD 7105U

Insured Veh. GBF 5545G

Claim No.

Policy No. DMCPHQ18-001368

Accident Date 26/09/2018

Inspection Date 28/09/2018

| Description                    | Total  |
|--------------------------------|--------|
| Third Party Express Settlement | 400.00 |
| Subtotal                       | 400.00 |
| GST (7%)                       | 28.00  |
| Grand Total                    | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

|   | Affiliated to Federation Internationale Des Experts En Automobile   |                                       |                    |                    |  |  |  |
|---|---|---------------------------------------|--------------------|--------------------|--|--|--|
| EQ II   | Q INSURANCE COMPANY LTD Ref : CC3/EQI18017707/K1ea3q2   |                                       |                    |                    |  |  |  |
| 5 MAXWELL ROAD<br>#17-00 TOWER BLOCK<br>MND COMPLEXSINGAPORE 069110 |   | Date: 11-09-2020  Code: EQI           |                    |                    |  |  |  |
| 1.  | 1. Policy Particulars :- THIRD PARTY CLAIM  |                                       |                    |                    |  |  |  |
|   | Insured Veh.  | GBF 5545G                             | Veh. Inspected     | SHD 7105U          |  |  |  |
|   | Policy No.  | DMCPHQ18-001368                       | Coverage (\$)      | 0.00               |  |  |  |
|   | Claim No.   |                                       | Excess (\$)        | 0.00               |  |  |  |
|   | Assign From   |                                       | Assign Date        | 28/09/2018         |  |  |  |
| 2.  |   | Vehicle Partic                        | culars & Condition |                    |  |  |  |
|   | Make & Model  | HYUNDAI 140                           | c.c                | 1685               |  |  |  |
|   | Engine No.  | HIDDEN                                | Year of Reg.       | 2016               |  |  |  |
|   | Chassis No.   | KMHLB41UMGU093517                     | Colour             | BLUE               |  |  |  |
|   | Odometer  | 338601                                | Steering           | IN ORDER           |  |  |  |
|   | Brakes  | IN ORDER                              | Modification       | STANDARD ALLOY RIM |  |  |  |
|   | General   | FAIR                                  |                    |                    |  |  |  |
| 3.  |   | Conditi                               | ons of Tyres       |                    |  |  |  |
|   |   | Size                                  | Make               | Balance            |  |  |  |
|   | R/H Front Tyre  | 205/60 R16                            | CAMPEON            | 7 mm               |  |  |  |
|   | L/H Front Tyre  | 205/60 R16                            | CAMPEON            | 7 mm               |  |  |  |
|   | R/H Rear Tyre   | 205/60 R16                            | CAMPEON            | 7 mm               |  |  |  |
|   | L/H Rear Tyre   | 205/60 R16                            | CAMPEON            | 7 mm               |  |  |  |
| 4.  | T   | · · · · · · · · · · · · · · · · · · · | on of Damages      |                    |  |  |  |
|   | THE VEHICLE SU  | STAINED DAMAGES AT THE N/S            | FRONT PORTION.     |                    |  |  |  |
|   | DAMAGES SEE D   | ETAILS.                               |                    |                    |  |  |  |
| 5.  |   |                                       | Information        |                    |  |  |  |
|   | Accident Date   | 26/09/2018                            | Inspection Date    | 28/09/2018         |  |  |  |
|   | Survey held at  | COMFORTDELGRO ENGINEER                | RING PTE LTD       |                    |  |  |  |
|   |   | 59 LOYANG DRIVE<br>SINGAPORE 508969   |                    |                    |  |  |  |
| 5a.   |   | Re                                    | emarks             |                    |  |  |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                       |                    |                    |  |  |  |
| 5b.   | 5b. Estimate Days of Repair   |                                       |                    |                    |  |  |  |
|   | ESTIMATED NOR   | MAL PERIOD FOR REPAIR:                | 2 Working Days     |                    |  |  |  |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7105U

| Qty | Description of Parts  | Condition               | Estimate By Workshop (\$)) | Our Adjusted<br>(\$) |
|-----|---|-------------------------|----------------------------|----------------------|
|     | REPLACEMENT OF PARTS  |                         |                            |                      |
| 1   | HEADLAMP (LH)   | NOT NECESSARY           | 1,388.00                   | -                    |
| 1   | FRONT FENDER (LH)   | DENTED                  | 566.30                     | 566.30               |
| 1   | FRONT FENDER SHIELD (LH)  | NOT NECESSARY           | 175.90                     | -                    |
| 1   | FRONT FENDER (NPA)  | TO REPAIR SEE<br>LABOUR | -                          | -                    |
| 1   | LH WING MIRROR (NPA)  | TO REPAIR SEE<br>LABOUR | -                          | -                    |
|     | LESS 20% DISCOUNT   |                         | -426.04                    | -113.26              |
|     |   |                         | 1,704.16                   | 453.04               |
|     | <u>LABOUR</u>   |                         |                            |                      |
|     | PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER AND LH WING MIRROR. |                         | 440.00                     | 200.00               |
|     | SPRAY PAINTING CHARGE.  |                         | 500.00                     | 450.00               |
|     | TUFF KOTE.  |                         | 50.00                      | 20.00                |
|     |   |                         | 990.00                     | 670.00               |
|     | GRAND TOTAL   |                         | 2,694.16                   | 1,123.04             |

| RECOMMENDED COST OF REPAIRS |  | 1,123.04 |
|-----------------------------|--|----------|

Report Ref No. CC3/EQI18017707/K1ea3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

**Automotive Assessor** 




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No: 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 7105U

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SHD 7105U







