

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18017718/GCD3E2

Date: 11/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700052580
Claimant Vehicle No : SLS4278Y	Insured Vehicle No :	SBJ839X
Date of Loss: 20/09/2018	Nature of Claim: TP	Claim No: 9588365819SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS4278Y	Engine No:	2ZR8169729
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102065392
Reg. Date:	22/09/2017 (Man. Year: 2017)	Odometer:	80810 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/10/2018	
Date Inspected:	01/10/2018 Inspected At:	Lian Her Motors (HQ) Block 5038 Ang Mo Kio Avenue 3, #01-405 Ang Mo Kio Industrial Park 2 Singapore 569541
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE GARNISH	Broken	0.00 F	*- F
3	1		*FRT BUMPER	Cracked	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
6	1		*FRT BUMPER SPONGE	Broken	0.00 F	*- F
7	1		*FRT BUMPER GRILLE & LOWER GRILLE	Broken	0.00 F	*- F
8	1		*FRT LH BUMPER FOG LAMP COVER	Broken	0.00 F	*- F
9	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >