

ASS. REC. BY:

REF: CS/FCI18017739/ Dtd3/02

Special Instruction:

Surveyor:

Brynn

ASSIGNMENT (Office)

CWS

From (Person):

Eileen Lee

of

FCI

Date/Time: 1/10/18 @ 3:27pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 6021A

Insured:

SHC 3388B

at Workshop m/s

Chunni Motor

Tel:

65425119

of

AMK Autopoint # 01-05/06

Policy No:

Claim No:

D18 007139MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/09/18

2/10/18

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

3:48pm @ 1/10/18

Person Contacted:

Lynn

Vehicle IN/OUT


Date/Time	Action/Instruction (✓) Estimate
	SHA 6021A - X
	SHC 3388B - CC3/FCI13016488/Krk3
11/10/2018	@ 9:35am revised via email. preli advise.

ASSIGNMENT

COE June 2022

2014 June

From: _____ Date: _____
 Estimated Cost: _____
 OD / IP / WS / IP RES / OD RES / EVA / HV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 located: _____
 Policy No: _____
 Claim No: _____
 Claim Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 CIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: 8-6 days Res: Yes or No
 Lm Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No: **SHA 6021A** Yr Regn: **2014 June**
 Type: M/Gar / M/Cycle / Bus / Van / Lorry / ☒ Prime Mover /
 Truck / Trailer or
 Make: **Hyundai I40** C.C. **1685**
 Color: **Blue** A/C: Insured / Std / TH / HA
 Sp. Bonding: **457338** T/Audio: Insured / Std / TH / HA
 Eng No: **D4FDEU417594**
 Chassis: **KMHLB41UMEU053954**
 Cond: Good / ☒ Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or
 Brake: Insured / Jammed / Leaked / Burnt or
 Mod: ☒ TH / S/Rim / STD A/Rim or
 Tyre Size: F: **205/60 R16**
 R: **11**
 BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Hankook**
 Front: _____ Rear: _____
 R/Dal: **6** mm R/Dal: **6** mm
 L/Dal: **6** mm L/Dal: **6** mm
 D.O.A. **27/09/2018** D.O.I. **02/10/2018**
 Survey held at **Chunni AMK**
 Den. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or
N/S Front
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
07/11/18	First report SHC 3388B Insured 4/5 8,000 - 10,000 - 8 dys 2/12 (Red: 6166.88 : 38%)

RECEIVED 08 NOV 2018

Date/Time, File Print 107 ☐ : Prelim. Report
☒ : Final Report
 1) Bill Typist
 Date/Time, File Print 107

Days Of Repair: **8**
 Resurvey No. of Trip: **2**

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Insp (\$) ☐ : Weekend (\$)

Survey Fee: **6x15=90**
 Transportation: **170+90**
 50
 50+50
 146
556

Report Format :
 Lump Sum / L.B.E. (%) **10,000/-**



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007139MFSH

Date: 11/10/2018

Our Ref: CS/FCI18017739/Dtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 6021A

Please be informed that we had conducted the inspection of the abovementioned vehicle 11/10/2018 at the premises of M/s Chun Ni Motor and have the following to report: -

Workshop Estimate Amount	: S\$ 16,166.88
Revised Estimate Amount	: S\$ 12,628.56
"Check" Items Amount	: S\$ 0.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
N/S Front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-09-2018	Our Ref No. D18007139MFSH
Accident Date	27-09-2018	Claim Type. Third Party
Insured Vehicle	SHC3388B	Third Party Vehicle. SHA6021A
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65425119/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 11 October 2018 9:35 AM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007181MFSH/1
Attachments: PRELI ADVISED SHB 2020Z.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHB 2020Z**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 4 October 2018 10:31 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007181MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 4 October 2018 10:07 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007181MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHA 6021 A
Technician:
Mileage: 457338
Time Printed 2.10.18 10:57 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
10°07'		-3°00' 3°00'
3°49'		-0°19' 5°41'
8°58'		-1°30' 1°30'
10°50'		
20°57'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
1°51'		-3°00' 3°00'
4°02'		-0°19' 5°41'
0°00'		-1°30' 1°30'
11°28'		
13°19'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	8°16'		-3°00' 3°00'
Cross Caster	-0°13'		-3°00' 3°00'
Cross SAI	-0°39'		-3°00' 3°00'
Total Toe	8°57'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-1°38'		-3°30' 2°30'
0°16'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°55'		-3°30' 2°30'
-0°31'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	-0°42'		-3°00' 3°00'
Total Toe	-0°15'		-3°00' 3°00'
Thrust Angle	0°23'		-3°00' 3°00'

REPAIR ESTIMATE*

DATE : 28.09.2018

TEL : 6542 5119

FAX : 6542 6039

FCI

14085.70
11268.56



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18017739/Dtd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3388B	Veh. Inspected	SHA 6021A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007139MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	01/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHLB41UMEU053954	Colour	BLUE	
Odometer	457338	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	6 mm	
L/H Front Tyre	205/60 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2018	Inspection Date	02/10/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6021A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	DISTORTED	544.50	544.50
1	FRONT BUMPER SPONGE	NOT NECESSARY	99.20	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	402.10	-
1	FRONT BUMPER GRILLE (LH)	DEFORMED	41.60	41.60
1	FRONT BUMPER BRACKET TOP (LH)	BROKEN	22.40	22.40
1	FRONT BUMPER RETAINER MOUNTING	NOT NECESSARY	9.20	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (LH)	BROKEN	1,388.00	1,388.00
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER APRON PANEL (LH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (LH)	TORN	174.90	174.90
1	FRONT FENDER RETAINER	NOT NECESSARY	24.60	-
1	FRONT WHEEL RIM (LH)	BENT	325.30	325.30
1	FRONT WHEEL HUB CAP (LH)	CUT	107.10	107.10
1	FRONT WHEEL BEARING	DAMAGED	150.90	150.90
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	108.80	-
1	FRONT DRIVE SHAFT (LH)	DISTORTED	1,030.80	1,030.80
1	RACK & PINION ASSY	DAMAGED	969.60	969.60
1	STG TIE END	DISTORTED	62.60	62.60
1	STABILIZER BAR	DISTORTED	252.30	252.30
1	STABILIZER BAR BUSH (LH)	NOT NECESSARY	16.40	-
1	STABILIZER BAR LINK	DISTORTED	61.10	61.10
1	STABILIZER BRACKET	NOT NECESSARY	24.00	-
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	529.30	529.30
1	KNUCKLE ARM (LH)	DISTORTED	552.00	552.00
1	ENGINE UNDER COVER	NOT NECESSARY	334.60	-
1	ENGINE CROSSMEMBER	DISTORTED	2,094.40	2,094.40
1	ABS SENSOR	NOT NECESSARY	234.00	-
1	WIRING ENGINE	MOUNTING CRACKED	3,326.00	3,326.00

Report Ref No. CS/FC118017739/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-3,067.72	-2,817.14
			12,270.88	11,268.56
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE (LH)(SN)	SERVICEABLE	216.00	-
			216.00	-
	<u>LABOUR</u>			
	PANEL BEATING.		1,200.00	500.00
	SPRAY PAINTING CHARGE.		750.00	400.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	20.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	REMOVE/REFIX DASHBOARD.		450.00	150.00
	REMOVE/REFIX FUSE BOX.		180.00	50.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			3,680.00	1,360.00
	GRAND TOTAL		16,166.88	12,628.56
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,000.00

Report Ref No. CS/FCI18017739/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.