



Case Details

Case Reference Number : TAX/09/18/2121
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB306M

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-3888-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 25/09/2018 06:46 AM
 Vehicle Age(In Months) : 49

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval		
BOM Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair ▼
One Time Key In			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check ▼
One Time Key In			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair ▼
One Time Key In			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Given ▼
One Time Key In			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Given ▼
One Time Key In			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace ▼
One Time Key In			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace ▼
One Time Key In			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Given ▼
One Time Key In			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Not Given ▼
One Time Key In			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▼
Total Spare Part Cost								2,336.47		Surveyor Total	149.40	
Lump Sum Discount (%)								20.00		Lump Sum Dis (%)	0	
Final Spare Part Cost								1,869.18		Final Sur Total	149.40	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	-----------	-------------------------	-------------------------	---------

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH PORTION	845.00	400	
Total:		845.00	400.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY REAR FENDER RH	378.00	200	
Total:		756.00	400.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	NN
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
3	TO WASH AND VACUUM	60.00	0	NN
4	TO REPLACE SUNDRY PARTS	100.00	0	NN
5	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	NN
6	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	NN
7	TO REMOVE / REFIT SEAT	120.00	0	NN
Total:		705.00	40.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,869.18	149.40
Total Labour Cost	845.00	400.00
Total Spray Painting	756.00	400.00
Other	705.00	40.00
Overall Total	4,175.18	989.40
Lump Sum Repair Option	☒	☒

10/2/2018

<https://vacswb.smrt.com.sg/Estimation.aspx>

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Lump Sum Total	4,200.00	1,000.00
Surveyor Approved Amount		1,000.00
No of Repair Days*	5	3
Remarks	-	LUMP SUM REPAIR 3 DAYS AFTER REPAIR PHOTOS
Surveyor Name		Naz
Signature		 Save Clear
Survey Date	02/10/2018	