

15/2010

INS. CASE OWNER:

Lutheria

CCY ASM AXA1801

7744, Gubbs

LKK:

IDAC:

Surveyor:

xh2

DOI:

ASSIGNMENT

1/10/18

Date / Time:

1/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHO 9401B

Name of Insured:

Trans-LAB SERVICES INC

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A:

27/9/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MI position

Driver Tel No.:

(VIA YES / NO)

Claim No.:

88000XAD/72646

Policy No.:

VX/1660320

Make / Model:

MERCEDES

Place of Accident:

DIE

OI GIA REPORT (YES / NO):

YES / NO

TP GIA REPORT (YES / NO)

Insured Liability:

%

Final ? Yes / No

SHO 9401B

SJB 74119

SLU 7387

SKF 7164



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

AH um TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
1/10/18	Non-Reporting ltr (1st):	
TH	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler	Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

RECEIVED 17 OCT 2018

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm by:
FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$5	(days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	If NO or B 28, Ass. Lia:	
Repair Cost:	\$5			
Loss of Rental (LOR):	\$5	(days)		
Loss of Use (LOU):	\$5	(S x days)		
Loss of Income (LOI):	\$5	(S x days)		
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LO ☐	[Tick only one]
GIA/LTA Search	\$5			
Medical:	\$5			
Disbursement:	\$5	(e.g. Tow/ Independent)		
Legal Cost	\$5			
Total:	\$5	Global Sum \$5:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	\$5	Name 1:		
Payee 2: (Strike if N.A.)	\$5	Name 2:		
Payee 3: (Strike if N.A.)	\$5	Name 3:		

COPY SENT 1/10/18

 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: W/P
 3) Survey fee: \$250

Surveyor

Xel.

REF:

AXA

V

~~15922~~ 12880

ASSIGNMENT

(C-222)

From:

Date:

Veh No:

STB1411Y

Yr Regn:

23 Jan 2008

Estimated Cost:

Type: M/Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Toyota Vios

C.C.

1497

at Workshop m/s

Ah Lim Motor

Colour:

white

A/C:

Insured / Std / NI / NA

of

Eileen

Sp. Reading

20573

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

MROS 3HY 930 50 46438

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

185/60 R15

R:

11

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

\$26K

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

GIA / PR. Seen:

Consistent? : Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

Est. Repairs:

days

Res.:

Yes or No

D.O.A.

D.O.I.

01-10-18

Lum Sum:

%

3 Val.:

Yes or No

Survey held at

w/s

1:30 pm

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

02/10

Email Eileen Max repair limit \$7500

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) S + RS: \$

☐

Interview (\$

) Photos:

☐

Tech. Invs (\$

) Others:

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18017744/Gub3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 01-10-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 9401B	Veh. Inspected	SJB 7411Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	01/10/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/09/2018	Inspection Date		
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SURVEYOR COPY

Ah Lim Motor Company
10 Ang Mo Kio Industrial
Park 2A
#01-09 AMK Autopoint
Singapore 568047

Claim Reference: 3 PARTY CLAIM
Assessment Number: AH000940
Version: AHLIM001/1
Date Calculated: 29/09/2018 04:54

Full Report - V1
Registration: SJB7411Y
Printed: 29/09/2018 11:55

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Ahlim ahlim	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	3 PARTY CLAIM	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Vios
Sub Model:	J
Model Sheet Number:	YF3 04
Registration:	SJB7411Y
Registration Month:	January
Registration Year:	2008
VIN Number:	MRO53HY9305046438
Manufacture Year:	2007
Odometer:	Not Known
Colour:	
Engine Number:	1NZX688721
Fuel Level:	%



Model Specs

FROM 02/2008	BONNET INSULATION
HEADLAMP TRIM COLOUR	FOG LAMPS
1.5 LTR 80 KW	4-SPEED AUTOMATIC
TYRES 185/60 HR 15	WHEELS 5.5J X 15 ALU
EQUIPMENT "J" GRADE	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	29/09/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

Ah Lim Motor Company**Claim Reference: 3 PARTY CLAIM****Assessment Number: AH000940****Version: AHLIM001/1****Date Calculated: 29/09/2018 04:54****Full Report - V1****Registration: SJB7411Y****Printed: 29/09/2018 11:55**

Primary Impact
Secondary Impact

Addresses**Cost Summary**

Total Labour	\$3,753.00
Total Paint/Material	\$429.33
Total Parts	\$10,147.16
Total of Additional Costs	\$1,210.00
Excess:	TBA
Grand Total Exc GST:	\$15,539.49
7 % GST:	\$1,087.76
Grand Total Inc GST:	\$16,627.25

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
B040)	ADJUST HEADLAMPS	2.0	9.00
B100	R + R LEFT FRONT WING	4.0	18.00
	INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R		
	NOT INCLUDED: HEADLAMP AND R + R BUMPER		
B100	R + R RIGHT FRONT WING	4.0	18.00
	INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R		
	NOT INCLUDED: HEADLAMP AND R + R BUMPER		
B140	RENEW FRONT PANEL CPL	9.0	40.50
B110)	RENEW RIGHT FRONT WING	2.0	9.00
	INCLUDES: TRANSFER ATTACHED PARTS		
B010	R + R FRONT BUMPER	5.0	22.50
B020)	RENEW FRONT BUMPER (REMOVED)	4.0	18.00
NO NUMBER	R + R FRONT BUMPER DAMPER	1.0	4.50
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.00
B020)	RENEW FRONT BUMPER REINFORCEMENT	2.0	9.00
B040)	R + R LEFT HEADLAMP	1.0	4.50
	(BUMPER REMOVED)		
	DOES NOT INCLUDE: ADJUST HEADLAMP		
B040)	R + R RIGHT HEADLAMP	1.0	4.50
	(BUMPER REMOVED)		

Ah Lim Motor Company

Claim Reference: 3 PARTY CLAIM

Assessment Number: AH000940

Version: AHLIM001/1

Date Calculated: 29/09/2018 04:54

Full Report - V1

Registration: SJB7411Y

Printed: 29/09/2018 11:55

	DOES NOT INCLUDE: ADJUST HEADLAMP		
B100	R + R LEFT FRONT MUD FLAP	3.0	13.50
NO NUMBER	RENEW L/F WING BADGE	1.0	4.50
NO NUMBER	RENEW R/F WING BADGE	1.0	4.50
B100	R + R RIGHT FRONT MUD FLAP	3.0	13.50
B060	TRANSFER ATTACHED PARTS FROM BONNET	2.0	9.00
530051)	RENEW BONNET	1.0	4.50
	INCLUDES: R + R OR RENEW ATTACHED PARTS		
B080	R + R BONNET HINGE/S	1.0	4.50
530121	RENEW BONNET LOCK RELEASE CABLE	6.0	27.00
851091)	R + R WASHER RESERVOIR	1.0	4.50
B085)	RENEW AIR GRILLE (REMOVED)	2.0	9.00
B310)	RENEW R/R SIDE PANEL	54.0	243.00
	(COMPOSITE WORK FOR END PANEL)		
B420)	R + R REAR BUMPER REINFORCEMENT	1.0	4.50
B290	RENEW REAR END PANEL	35.0	157.50
	(BUMPER REMOVED)		
	INCLUDES: BOTH REAR LAMPS, FLOOR MAT		
	BOOT COMPARTMENT AND ALL TRIMS IN		
	REPAIR AREA REMOVE AND REFIT		
640201	R + R TAILGATE LOCK	4.0	18.00
G020	R + R REAR SCREEN	28.0	126.00
	INCLUDES: REAR PARCEL SHELF AND REQUIRED		
	TRIMS REMOVE AND REFIT		
750171	RENEW BADGE "TOYOTA"	2.0	9.00
B410	R + R REAR BUMPER	4.0	18.00
B420)	RENEW REAR BUMPER	1.0	4.50
NO NUMBER	R + R R/R BUMPER REFLECTOR	3.0	13.50
NO NUMBER	RENEW R/RR SIDE MEMBER CPL	25.0	112.50
NO NUMBER	RENEW CONDENSER-/COMPRESSOR HOSE	4.0	18.00
NO NUMBER	R + R COMPRESSOR-/EVAPORATOR HOSE	4.0	18.00
NO NUMBER	R + R EVAPORATOR/CONDENSER PIPE	4.0	18.00
B450)	R + R BOTH REAR SEAT RESTS	1.0	4.50
B450)	R + R COMPLETE REAR SEAT CUSHION	1.0	4.50
711511)	R + R LEFT REAR SEAT BELT	3.0	13.50
	INCLUDES: REAR PARCEL SHELF AND REQUIRED		
	TRIMS REMOVE AND REFIT		
M010	R + R RADIATOR/CONDENSER	15.0	67.50
M010)	RENEW RADIATOR (RADIATOR REMOVED)	2.0	9.00
160101)	R + R UPPER RADIATOR HOSE	2.0	9.00
160111)	R + R LOWER RADIATOR HOSE	2.0	9.00
NO NUMBER	R + R AIR FILTER INTAKE HOSE	1.0	4.50
170011)	R + R INTAKE MANIFOLD	8.0	36.00
NO NUMBER	R + R UPPER ENGINE COVER	1.0	4.50
280011	R + R STARTER	6.0	27.00
NO NUMBER	R + R REAR PROTECTION PANEL	1.0	4.50
M240)	R + R FRONT EXHAUST PIPE	2.0	9.00
420018)	R + R LEFT REAR WHEEL	1.0	4.50
420018)	R + R RIGHT REAR WHEEL	1.0	4.50
471551)	RENEW L/R BRAKE ANCHOR PLATE	8.0	36.00
	(WHEEL REMOVED)		
	INCLUDES: R + R BRAKE DRUM, WHEEL HUB		
	AND BRAKE SHOES		
471551)	RENEW R/R BRAKE ANCHOR PLATE	8.0	36.00

Ah Lim Motor Company

Claim Reference: 3 PARTY CLAIM

Assessment Number: AH000940

Version: AHLIM001/1

Date Calculated: 29/09/2018 04:54

Full Report - V1

Registration: SJB7411Y

Printed: 29/09/2018 11:55

	(WHEEL REMOVED)		
	INCLUDES: R + R BRAKE DRUM, WHEEL HUB AND BRAKE SHOES		
481251)	R + R LEFT REAR SHOCK ABSORBER	1.0	4.50
481251)	R + R RIGHT REAR SHOCK ABSORBER	1.0	4.50
NO NUMBER	R + R REAR AXLE CARRIER	16.0	72.00
004466)	BLEED REAR BRAKE SYSTEM	6.0	27.00
NN	REAR SILENCER R&R / NEW PARTS	10.0*	45.00
NN	H LAMP TOP PANAL LH R&R / NEW PARTS	10.0*	45.00
NN	H LMP TOP PANAL RH R&R / NEW PARTS	10.0*	45.00
NN	S TYRE SIDE PAL RH R&R / NEW PARTS	15.0*	67.50
NN	ENGINE MOUNING RH R&R / NEW PARTS	5.0*	22.50
NN	E MOUNING REAR R&R / NEW PARTS	5.0*	22.50
NN	GEAR BOX MOUNING LH R&R / NEW PARTS	5.0*	22.50
0741	REPAIR L/F WING	10.0*	45.00
1117	REPAIR L/F WHEELHOUSE CPL	20.0*	90.00
1118	REPAIR R/F WHEELHOUSE CPL	20.0*	90.00
1201	REPAIR L/F SIDE MEMBER	20.0*	90.00
1202	REPAIR R/F SIDE MEMBER	20.0*	90.00
1481	REPAIR LEFT FRONT DOOR	10.0*	45.00
1482	REPAIR RIGHT FRONT DOOR	10.0*	45.00
2931	REPAIR BOOTLID	10.0*	45.00
3901	REPAIR REAR FLOOR PANEL	20.0*	90.00
4162	REPAIR R/R OUTER WHEELHOUSE	60.0*	270.00
4166	REPAIR R/R INNER WHEELHOUSE	30.0*	135.00

LABOUR COST

Total Work Units

604.0

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.0HRS

0.00

Sub Total

60.4HRS

\$2,718.00

Paint Labour

23.0HRS

\$1,035.00

Total Labour

83.4HRS

\$3,753.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	BUMPER REINFORCEMENTSURFACE PAINT	6.0	
471	BONNET NEW PART PAINTING	12.0	
742	R/F WING NEW PART PAINTING	10.0	
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
2711	REAR PANEL NEW PART PAINTING	21.0	
3482	R/R SIDE PANEL NEW PART PAINTING	22.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
293	FRT TOWING EYE COVERNEW PART PAINT K1R	3.0	
2581	REAR BUMPER NEW PART PAINT K1R	10.0	
741	L/F WING REPAIR PAINTING <50%	11.0	
1481	LEFT FRONT DOOR REPAIR PAINTING <50%	16.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	16.0	
2931	BOOTLID REPAIR PAINTING <50%	16.0	
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	

Ah Lim Motor Company

Claim Reference: 3 PARTY CLAIM

Assessment Number: AH000940

Version: AHLIM001/1

Date Calculated: 29/09/2018 04:54

Full Report - V1

Registration: SJB7411Y

Printed: 29/09/2018 11:55

1201	L/F SIDE MEMBER SURFACE PAINT	5.0
1202	R/F SIDE MEMBER SURFACE PAINT	5.0
3901	REAR FLOOR PANEL SURFACE PAINT	7.0
4162	R/R OUTER WHEELHOUSE SURFACE PAINT	4.0
4166	R/R INNER WHEELHOUSE SURFACE PAINT	5.0

LABOUR COST - PAINT

TIME(PAINT)	200.0
Preparation Main Work Plastic	5.0
Preparation Main Work Metal	25.0
Preparation Work Multi Layer Paint	0.0
Total Work Units (10WU/HR)	230.0
Total Paintwork Labour	23.0HRS

\$1,035.00

MATERIAL COST - PAINT

New Part Painting	Cost Price
New Part Painting - Plastic K1R	\$101.34
Material-Constant Main Work Metal	\$112.18
Surface-/Blend Paint	\$28.60
Repair Painting	\$86.16
Material-Const Main Work Plastic	\$92.05
Total Excluding Pearlescent Uplift	\$9.00
Pearlescent Uplift @ 0.0%	\$429.33
Total Paint Material Cost	\$0.00
	\$429.33

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
253	1	L/LOWER GRILLE X <i>hmr</i>	52128 0D070		0%	45.00*
254	1	R/LOWER GRILLE X <i>hmr</i>	52127 0D150		0%	45.00*
281	1	FRONT BUMPER <i>re</i>	52119 0D996		0%	155.00*
293	1	FRT TOWING EYE COVER <i>at</i>	52721 0D902		0%	20.00*
317	1	L/F BUMPER BRACKET <i>SM</i>	53165 0D030		0%	38.00*
318	1	R/F BUMPER BRACKET <i>SM</i>	53164 0D030		0%	38.00*
333	1	FRT BUMPER ABSORBER <i>re</i>	52617 0D050		0%	40.00*
340	1	BUMPER REINFORCEMENT <i>BT</i>	52021 0D090		0%	110.00*
343	1	LOWER FRONT GRILLE <i>re</i>	53112 0D120		0%	38.00*
350	1	FRT BUMPER CLAMP KIT <i>re</i>	SEE GUIDE NO. 0351		0%	24.00*
410	1	GRILLE <i>CAF</i>	53111 0D901		0%	130.00*
431	1	FRONT MANUFACT BADGE <i>MC</i>	75301 0D010		0%	32.00*
471	1	BONNET <i>BT</i>	53301 0D100		0%	180.00*
475	1	L/F HINGE <i>BT</i>	53420 0D170		0%	30.00*
476	1	R/F HINGE <i>BT</i>	53410 0D170		0%	30.00*
493	1	BONNET LOCK <i>BT</i>	53510 0D181		0%	45.00*
500	1	BONNET CABLE X <i>nm</i>	53630 0D080		0%	32.00*
527	2	FRONT BONNET SEAL <i>twi</i>	53381 0D060		0%	30.00*
561	1	LEFT HEADLAMP ASSY ?	81150 0D700		0%	130.00*
562	1	RIGHT HEADLAMP ASSY <i>at</i>	81110 0D700		0%	130.00*
742	1	R/F WING X <i>re</i>	53811 52240		0%	130.00*
789	7	L/F WING MNTG KIT <i>re</i>	91621 40614		0%	20.00*
790	7	R/F WING MNTG KIT <i>re</i>	91621 40614		0%	20.00*
811	1	BADGE "VVT-I" L <i>re</i>	75443 06151		0%	16.31U
812	1	BADGE "VVT-I" R <i>re</i>	75443 06151		0%	16.31U
841	1	L/WHEELHOUSE SHELL X <i>nm</i>	53876 0D080		0%	50.00*
842	1	R/WHEELHOUSE SHELL X <i>nm</i>	53875 0D080		0%	50.00*

Ah Lim Motor Company

Claim Reference: 3 PARTY CLAIM

Assessment Number: AH000940

Version: AHLIM001/1

Date Calculated: 29/09/2018 04:54

Full Report - V1

Registration: SJB7411Y

Printed: 29/09/2018 11:55

1009	1	INNER FRT PANEL CPL <i>BT</i>	53201 0D130	0%	200.00*
1391	1	COWL PANEL GRILLE <i>?</i>	55708 0D130	0%	205.00*
1436	1	WASHER CONTAINER <i>ADA</i>	85315 0D101	0%	60.00*
2581	1	REAR BUMPER <i>Re</i>	52159 0D983	0%	160.00*
2619	1	L/R BUMPER BRACKET <i>X NN</i>	52576 0D070	0%	45.00*
2620	1	R/R BUMPER BRACKET <i>Re</i>	52575 0D070	0%	45.00*
2621	1	L/R OUT BUMPER BRKT <i>X</i>	52156 0D030	0%	55.00*
2622	1	R/R OUT BUMPER BRKT <i>X NN</i>	52155 0D030	0%	55.00*
2711	1	REAR PANEL <i>Buc</i>	58307 0D101	0%	210.00*
2944	1	BOOTLID SEAL <i>Tru</i>	64461 0D050	0%	55.00*
2977	1	BOOT/TAILGATE LOCK <i>?</i>	64610 0D030	0%	50.00*
3013	1	REAR MANUFACT BADGE <i>?</i>	90975 02063	0%	38.00*
3161	1	REAR WINDOW MOULDING <i>?</i>	55573 0D040	0%	55.00*
3163	1	REAR SCREEN FIX SET <i>X</i>	USE SINGLE PARTS	0%	0.00
3169	1	LWR REAR WINDOW MLDG <i>X NN</i>	64813 52080	0%	0.00
3171	2	CLIP FASTENING <i>?</i>	56116 22050	0%	3.96U
3172	2	CLIP FASTENING <i>?</i>	56115 30100	0%	4.04U
3282	1	R/R LAMP ASSY <i>ADA</i>	81550 0D220	0%	95.00*
3292	1	R/R REFLECTOR <i>Aut</i>	81910 0D010	0%	45.00*
3482	1	R/R SIDE PANEL <i>?</i>	61601 0D160	0%	350.00*
3572	1	R/R LAMP PANEL <i>?</i>	61063 0D010	0%	60.00*
3990	1	R/R SIDE MEMBER CPL <i>X NN</i>	57601 0D121	0%	110.00*
4448	1	CONDENSER FIX FRAME <i>?</i>	88891 0D080	0%	32.00*
4465	1	CONDENSER <i>?</i>	88460 0D130	0%	300.00*
4481	1	COMPRESSOR HOSE <i>?</i>	88704 0D050	0%	110.00*
4483	1	COND/EVAPORATOR HOSE <i>?</i>	88706 0D240	0%	140.00*
4485	1	PRESSURE HOSE COMPR <i>?</i>	88711 0D150	0%	140.00*
4978	1	LUGG COMPART CARPET <i>X NN</i>	64711 0D060C0	0%	65.00*
4985	1	END PANEL TRIM <i>Re</i>	58387 0D010	0%	95.00*
4992	1	R/BOOT TRIM COVER <i>Re</i>	64721 0D040C0	0%	135.00*
7751	1	L/RADIATOR STRUT <i>?</i>	16523 0M050	0%	10.00*
7752	1	R/RADIATOR STRUT <i>?</i>	16523 0M050	0%	10.00*
7753	1	L/RADIATOR RUBB MNTG <i>?</i>	90480 W0005	0%	10.00*
7754	1	R/RADIATOR RUBB MNTG <i>?</i>	90480 W0005	0%	10.00*
7761	1	RADIATOR CPL <i>?</i>	16400 0M070	0%	330.00*
7765	1	UPP FUEL HOSE FLANGE <i>?</i>	16502 21070	0%	32.00*
7767	1	RADIATOR SHROUD <i>?</i>	16711 0M030	0%	78.00*
7773	1	UPPER RADIATOR HOSE <i>?</i>	16573 0M010	0%	25.00*
7776	1	LWR RADIATOR HOSE <i>?</i>	16572 0M040	0%	25.00*
7789	1	FAN MOTOR <i>?</i>	16363 0M020	0%	110.00*
7793	1	COOLING FAN <i>?</i>	16361 0M050	0%	65.00*
8221	1	INTAKE MANIFOLD <i>?</i>	17101 0M030	0%	165.00*
8375	1	AIR INTAKE HOSE <i>?</i>	17751 0M020	0%	45.00*
8391	1	AIR FILTER ASSY <i>?</i>	17700 0M030	0%	255.00*
8501	1	STARTER MOTOR <i>?</i>	28100 0M051	0%	340.00*
8833	1	REAR SILENCER <i>BT</i>	17430 0M061	0%	200.00*
8846	1	REAR PROTECT PANEL <i>?</i>	58327 0D081	0%	0.00
8848	1	R/R EXHAUST RUBBER <i>Re</i>	17565 0M020	0%	105.00*
9081	1	REAR AXLE SUBFRAME <i>X NN</i>	42110 0D171	0%	700.00*
9182	1	R/R WHEEL HUB/BRG <i>Re</i>	42410 0D040	0%	230.00*
9646	1	HORN <i>?</i>	86520 52170	0%	80.00*
1000	1	F WIPER GAR COVER X2 <i>Renew</i>	Renew	0%	60.00*
1000	1	F WIPER GARH RUBBER <i>Renew</i>	Renew	0%	32.00*
1000	1	F BOT INER STOPER X2 <i>Renew</i>	Renew	0%	20.00*

Ah Lim Motor Company

Claim Reference: 3 PARTY CLAIM

Assessment Number: AH000940

Version: AHLIM001/1

Date Calculated: 29/09/2018 04:54

Full Report - V1

Registration: SJB7411Y

Printed: 29/09/2018 11:55

1000	1	H LAMP TOP PANAL LH <i>X</i>	Renew	0%	45.00*
1000	1	H LMP TOP PANAL RH <i>BT</i>	Renew	0%	45.00*
1000	1	H LAMP CLIPS X4 <i>mc</i>	Renew	0%	8.00*
1000	1	F REINFORMET BRT X2 <i>BT</i>	Renew	0%	170.00*
1000	1	E UNDER COVER RH <i>?</i>	Renew	0%	50.00*
1000	1	G BOX LOW COVER LH <i>?</i>	Renew	0%	60.00*
1000	1	R INER AIR GUIDE LH <i>?</i>	Renew	0%	38.00*
1000	1	R INER AIR GUIDE RH <i>?</i>	Renew	0%	38.00*
1000	1	R COOLING PIPE X2 <i>?</i>	Renew	0%	64.00*
1000	1	R BOT LOGO (VIOS) <i>-</i>	Renew	0%	35.00*
1000	1	R BOT LOGO (J) <i>-</i>	Renew	0%	35.00*
1000	1	TAIL LAMP CLIP X3 RH <i>-</i>	Renew	0%	9.00*
1000	1	R BUMBER CLPS X12 <i>-</i>	Renew	0%	24.00*
1000	1	TOOL BOX REAR <i>X</i>	Renew	0%	110.00*
1000	1	TOL BOX SIDE RH <i>CPA</i>	Renew	0%	115.00*
1000	1	S TYRE SIDE PAL RH <i>?</i>	Renew	0%	58.00*
1000	1	R FEN TRIM CLPX12 RH <i>mc</i>	Renew	0%	24.00*
1000	1	R FEN AIR VENT RH <i>-</i>	Renew	0%	58.00*
1000	1	R FEN COWLING RH <i>-</i>	Renew	0%	38.00*
1000	1	R EXHAUST CHROME RH <i>cut</i>	Renew	0%	55.00*
1000	1	ENGINE MOUNING RH <i>?</i>	Renew	0%	130.00*
1000	1	E MOUNING REAR <i>?</i>	Renew	0%	60.00*
1000	1	GEAR BOX MOUNING LH <i>?</i>	Renew	0%	75.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost (15 %)

Total Parts

\$8,823.62

\$1,323.54

\$10,147.16

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
COOLANT <i>mc</i> SPECIALIST	0%	\$35.00
F NUMBER PLATE <i>CPA</i> SPECIALIST		\$35.00
CECHK WIRING <i>CPA</i> SPECIALIST	0%	\$40.00 <i>20</i>
FRONT		
REFILL A/C GAS <i>mc</i> SPECIALIST		\$50.00
R SPORT RIM RH <i>repair</i> SPECIALIST <i>X</i>	0%	\$0.00
R TYRE 185/60/15 <i>TV</i> SPECIALIST	<i>50%</i>	\$0.00
REVERSE SENSORX2 <i>PM</i> SPECIALIST	0%	\$200.00
R WIND SEALANT <i>mc</i> SPECIALIST		\$60.00
R WIND INNER SEAL <i>mc</i> SPECIALIST	0%	\$40.00
CHECK WIRING REAR SPECIALIST		\$40.00 <i>20</i>
WHEEL ALIGMENT <i>mc</i> SPECIALIST	0%	\$80.00 <i>60</i>
REMOVE R SPECIALIST		\$100.00
WINDSCREEN <i>mc</i> SPECIALIST		
REPLACE RVER SPECIALIST	0%	\$80.00 <i>30</i>
SEOSOR <i>mc</i> SPECIALIST		
ANTI-RUST COATING <i>mc</i> SPECIALIST		\$200.00 <i>80</i>
RESET AL SPECIALIST	0%	\$250.00
DIAGNOSTIC <i>?</i> <i>(80)</i>		
Total Extras		\$1,210.00

Ah Lim Motor Company**Claim Reference: 3 PARTY CLAIM****Assessment Number: AH000940****Version: AHLIM001/1****Date Calculated: 29/09/2018 04:54****Full Report - V1****Registration: SJB7411Y****Printed: 29/09/2018 11:55****Final Calculation**

Total Parts		\$10,147.16
Labour		
Total Panel/Mechanical	\$2,718.00	
Total Paintwork	\$1,035.00	
Total Labour		\$3,753.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$1,210.00	
Total of Additional Costs		\$1,210.00
Total Paint/Material Costs		\$429.33
Grand Total Excludes GST		\$15,539.49
GST @ 7 %		\$1,087.76
Grand Total Includes GST		\$16,627.25

Assessment NotesLKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Summary Information**Vehicle**

Manufacturer & Model: TOYOTA Vios
 VIN Number: MRO53HY9305046438
 Build Date: 2008

Software

Calculation Date: 29/09/2018
 Software Version:
 Valid Part Price Date: 01/06/2015

Registration: SJB7411Y
 Type: YF3 04
 Signature:
 Date:

AudaDirect Version: 337
 Model Sheet Version:

Model Specification

A5 FROM 02/2008
 G1 BONNET INSULATION
 I1 HEADLAMP TRIM COLOUR
 I2 FOG LAMPS
 N3 1.5 LTR 80 KW
 P8 4-SPEED AUTOMATIC
 R1 TYRES 185/60 HR 15
 S7 WHEELS 5.5J X 15 ALU
 X4 EQUIPMENT "J" GRADE
 Y4 TWO COAT METALLIC
 Y7 PREPARE OFF VEHICLE

lumpsum Repairs.
After repair photos.

*Emo Qiaf**01/10/18.**12 Days.**2.00pm***Guide Numbers****Invalid Guide Numbers****H 471 F : Corrosion**

Service Request Details

Claim

S8M00X3D

Reference

None 

Loss Date

September 27, 2018

Request Date

October 1, 2018

Due Date

October 8, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SJB7411Y

Make

TPVD TOYOTA

01/10/2018 @ 10:53am
Filed veh in
GQ

Model

VIOS J AUTO

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM


(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : T/20180928/1008 Vehicle Registration No : SJB 7611Y
Name (as shown in NRIC) : NIRUBAMA MANIKANTAN NRIC/FIN/Passport No : S2661228 D
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : Blk 796, #03-3370, Vishnu Ring Road Singapore (760796)
Contact (Tel) : 62571394 Mobile No. : 96664 504
Email Address : niru_eai@yahoo.com
Date of Accident : 27-09-2018 Time of Accident : 8.10 am
Place of Accident : PIE Exit 35 to 34 towards PIE Tuas
Insurance Company : _____

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Revert to OD claim



Policyholder / Driver's Signature

Date: 04-10-2018

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Thin Thin (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Thursday, 4 October 2018 6:47 PM
To: muihong@ahlimmotor.com.sg
Cc: Admin - ALM AMK; Guo Qiang (LKKAUTO); Admin A; Thin Thin (LKKAUTO)
Subject: FW: Withdraw of Third party claim - SJB7411Y accident with AXA Insured - Audatex AH000940
Attachments: Addendum to revert to OD claim.pdf

Dear Sir / Madam,

Thank you for your email.

Dear Thin Thin,

Kindly take note.

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: muihong@ahlimmotor.com.sg <muihong@ahlimmotor.com.sg>
Sent: Thursday, 4 October 2018 3:03 PM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-B <admin-b@lkkauto.com>
Cc: Admin - ALM AMK <admin@ahlimmotor.com.sg>; Tomy Tun - Audatex <Tomy.Tun@audatex.com>; Tawffiek Yusoff - Audatex <Tawffiek.Yusoff@audatex.com>
Subject: Withdraw of Third party claim - SJB7411Y accident with AXA Insured - Audatex AH000940

Dear all,

Pls be informed that our client has decided to withdraw from Third party claim and revert to OD claim.

Pls see attached addendum report that she has signed and we will amend the report accordingly.

Pls update your records.

Aside to Tomy / Twffiek – Pls do not bill us for the Audatex usage fee for this case – AH000940

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18017744/Gub3s2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 05-11-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 9401B	Veh. Inspected	SJB 7411Y	
Policy No.	VPX/P1680520	Coverage (\$)	0.00	
Claim No.	S8M00X3D	Excess (\$)	0.00	
Assign From	CYNTHIA LOH	Assign Date	01/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053HY9305046438	Colour	WHITE	
Odometer	70573	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60R15	YOKOHAMA	5 mm	
L/H Front Tyre	185/60R15	YOKOHAMA	5 mm	
R/H Rear Tyre	185/60R15	YOKOHAMA	5 mm	
L/H Rear Tyre	185/60R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND REAR O/S PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2018	Inspection Date	01/10/2018	
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 7411Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	L/LOWER GRILLE (WCP) (CONSISTENT)	NOT NECESSARY	45.00	-
1	R/LOWER GRILLE (WCP) (CONSISTENT)	NOT NECESSARY	45.00	-
1	FRONT BUMPER (WCP) (CONSISTENT)	DEFORMED	155.00	155.00
1	FRT TOWING EYE COVER (WCP) (CONSISTENT)	CUT	20.00	20.00
1	L/F BUMPER BRACKET (WCP) (CONSISTENT)	BENT	38.00	38.00
1	R/F BUMPER BRACKET (WCP) (CONSISTENT)	BENT	38.00	38.00
1	FRT BUMPER ABSORBER (WCP) (CONSISTENT)	DEFORMED	40.00	40.00
1	BUMPER REINFORCEMENT (WCP) (CONSISTENT)	BENT	110.00	110.00
1	LOWER FRONT GRILLE (WCP) (CONSISTENT)	DEFORMED	38.00	38.00
1	FRT BUMPER CLAMP KIT (WCP) (CONSISTENT)	NECESSARY	24.00	24.00
1	GRILLE (WCP) (CONSISTENT)	CRACKED	130.00	130.00
1	FRONT MANUFACT BADGE (WCP) (CONSISTENT)	NECESSARY	32.00	32.00
1	BONNET (WCP) (CONSISTENT)	BENT	180.00	180.00
1	L/H HINGE (WCP) (CONSISTENT)	BENT	30.00	30.00
1	R/F HINGE (WCP) (CONSISTENT)	BENT	30.00	30.00
1	BONNET LOCK (WCP) (CONSISTENT)	BENT	45.00	45.00
1	BONNET CABLE (WCP) (CONSISTENT)	NOT NECESSARY	32.00	-
2	FRONT BONNET SEAL (WCP) (CONSISTENT)	TWISTED	30.00	30.00
1	LEFT HEADLAMP ASSY (WCP) (CONSISTENT)	* CHECK	130.00	-
1	RIGHT HEADLAMP ASSY (WCP) (CONSISTENT)	CUT	130.00	130.00
1	R/F WING (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	130.00	-
1	L/F WING MNTG KIT (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	R/F WING MNTG KIT (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	BADGE "VVT-I" L (WCP) (CONSISTENT)	NECESSARY	16.31	16.31
1	BADGE "VVT-I" R (WCP) (CONSISTENT)	NECESSARY	16.31	16.31
1	L/WHEELHOUSE SHELL (WCP) (CONSISTENT)	NOT NECESSARY	50.00	-
1	R/WHEELHOUSE SHELL (WCP) (CONSISTENT)	NOT NECESSARY	50.00	-
1	INNER FRT PANEL CPL (WCP) (CONSISTENT)	BENT	200.00	200.00
1	COWL PANEL GRILLE (WCP) (CONSISTENT)	* CHECK	205.00	-
1	WASHER CONTAINER (WCP) (CONSISTENT)	CRACKED	60.00	60.00

Report Ref No. CC4/ASM18017744/Gub3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER (WCP) (CONSISTENT)	DEFORMED	160.00	160.00
1	L/R BUMPER BRACKET (WCP) (CONSISTENT)	NOT NECESSARY	45.00	-
1	R/R BUMPER BRACKET (WCP) (CONSISTENT)	DEFORMED	45.00	45.00
1	L/R OUT BUMPER BRKT (WCP) (CONSISTENT)	NOT NECESSARY	55.00	-
1	R/R OUT BUMPER BRKT (WCP) (CONSISTENT)	NOT NECESSARY	55.00	-
1	REAR PANEL (WCP) (CONSISTENT)	BUCKLED	210.00	210.00
1	BOOTLID SEAL (WCP) (CONSISTENT)	TWISTED	55.00	55.00
1	BOOT / TAILGATE LOCK (WCP) (CONSISTENT)	* CHECK	50.00	-
1	REAR MANUFACT BADGE (WCP) (CONSISTENT)	NECESSARY	38.00	38.00
1	REAR WINDOW MOULDING (WCP) (CONSISTENT)	NECESSARY	55.00	55.00
1	REAR SCREEN FIX SET (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	LWR REAR WINDOW MLDG (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
2	CLIP FASTENING (WCP) (CONSISTENT)	NECESSARY	3.96	3.96
2	CLIP FASTENING (WCP) (CONSISTENT)	NECESSARY	4.04	4.04
1	R/R LAMP ASSY (WCP) (CONSISTENT)	CRACKED	95.00	95.00
1	R/R REFLECTOR (WCP) (CONSISTENT)	CUT	45.00	45.00
1	R/R SIDE PANEL (WCP) (CONSISTENT)	BUCKLED	350.00	350.00
1	R/R LAMP PANEL (WCP) (CONSISTENT)	BUCKLED	60.00	60.00
1	R/R SIDE MEMBER CPL (WCP) (CONSISTENT)	NOT NECESSARY	110.00	-
1	CONDENSER FIX FRAME (WCP) (CONSISTENT)	* CHECK	32.00	-
1	CONDENSER (WCP) (CONSISTENT)	* CHECK	300.00	-
1	COMPRESSOR HOSE (WCP) (CONSISTENT)	* CHECK	110.00	-
1	COND / EVAPORATOR HOSE (WCP) (CONSISTENT)	* CHECK	140.00	-
1	PRESSURE HOSE COMPRS (WCP) (CONSISTENT)	* CHECK	140.00	-
1	LUGG COMPART CARPET (WCP) (CONSISTENT)	NOT NECESSARY	65.00	-
1	END PANEL TRIM (WCP) (CONSISTENT)	DEFORMED	95.00	95.00
1	R/BOOT TRIM COVER (WCP) (CONSISTENT)	DEFORMED	135.00	135.00
1	L/RADIATOR STRUT (WCP) (CONSISTENT)	* CHECK	10.00	-
1	R/RADIATOR STRUT (WCP) (CONSISTENT)	* CHECK	10.00	-
1	L/RADIATOR RUBB MNTG (WCP) (CONSISTENT)	* CHECK	10.00	-
1	R/RADIATOR RUBB MTG (WCP) (CONSISTENT)	* CHECK	10.00	-
1	RADIATOR CPL (WCP) (CONSISTENT)	* CHECK	330.00	-
1	UPP FUEL HOSE FLANGE (WCP) (CONSISTENT)	* CHECK	32.00	-

Report Ref No. CC4/ASM18017744/Gub3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR SHROUD (WCP) (CONSISTENT)	* CHECK	78.00	-
1	UPPER RADIATOR HOSE (WCP) (CONSISTENT)	* CHECK	25.00	-
1	LWR RADIATOR HOSE (WCP) (CONSISTENT)	* CHECK	25.00	-
1	FAN MOTOR (WCP) (CONSISTENT)	* CHECK	110.00	-
1	COOLING FAN (WCP) (CONSISTENT)	* CHECK	65.00	-
1	INTAKE MANIFOLD (WCP) (CONSISTENT)	* CHECK	165.00	-
1	AIR INTAKE HOSE (WCP) (CONSISTENT)	* CHECK	45.00	-
1	AIR FIILTER ASSY (WCP) (CONSISTENT)	* CHECK	255.00	-
1	STARTER MOTOR (WCP) (CONSISTENT)	* CHECK	340.00	-
1	REAR SILENCER (WCP) (CONSISTENT)	BENT	200.00	200.00
1	REAR PROTECT PANEL (NPA) (WCP) (CONSISTENT)	* CHECK	-	-
1	R/R EXHAUST RUBBER (WCP) (CONSISTENT)	NECESSARY	105.00	105.00
1	REAR AXLE SUBFRAME (WCP) (CONSISTENT)	NOT NECESSARY	700.00	-
1	R/R WHEEL HUB/BRG (WCP) (CONSISTENT)	NECESSARY	230.00	230.00
1	HORN (WCP) (CONSISTENT)	* CHECK	80.00	-
2	F WIPER GAR COVER (WCP) (CONSISTENT)	O/S CUT / N/S NOT NECESSARY	60.00	30.00
1	F WIPER GARH RUBBER (WCP) (CONSISTENT)	NOT NECESSARY	32.00	-
2	F BOT INER STOPER (WCP) (CONSISTENT)	NOT NECESSARY	20.00	-
1	H LAMP TOP PANAL LH (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	45.00	-
1	H LMP TOP PANAL RH (WCP) (CONSISTENT)	BENT	45.00	45.00
4	H LAMP CLIPS (WCP) (CONSISTENT)	NECESSARY	8.00	8.00
2	F REINFORCEMENT BRT (WCP) (CONSISTENT)	BENT	170.00	170.00
1	E UNDER COVER RH (WCP) (CONSISTENT)	* CHECK	50.00	-
1	G BOX LOW COVER LH (WCP) (CONSISTENT)	* CHECK	60.00	-
1	R INER AIR GUIDE LH (WCP) (CONSISTENT)	* CHECK	38.00	-
1	R INER AIR GUIDE RH (WCP) (CONSISTENT)	* CHECK	38.00	-
2	R COOLING PIPE	* CHECK	64.00	-
1	R BOT LOGO (VIOS) (WCP) (CONSISTENT)	NECESSARY	35.00	35.00
1	R BOT LOGO (J) (WCP) (CONSISTENT)	NECESSARY	35.00	35.00
3	TAIL LAMP CLIP RH (WCP) (CONSISTENT)	NECESSARY	9.00	9.00
12	R BUMPER CLIPS (WCP) (CONSISTENT)	NECESSARY	24.00	24.00
1	TOOL BOX REAR (WCP) (CONSISTENT)	NOT NECESSARY	110.00	-

Report Ref No. CC4/ASM18017744/Gub3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TOL BOX SIDE RH (WCP) (CONSISTENT)	CRACKED	115.00	115.00
1	S TYRE SIDE PAL RH (WCP) (CONSISTENT)	* CHECK	58.00	-
12	R FEN TRIM RH (WCP) (CONSISTENT)	NECESSARY	24.00	24.00
1	R FEN AIR VENT RH (WCP) (CONSISTENT)	DEFORMED	58.00	58.00
1	R FEN COWLING RH (WCP) (CONSISTENT)	DEFORMED	38.00	38.00
1	R EXHAUST CHROME RH (WCP) (CONSISTENT)	CUT	55.00	55.00
1	ENGINE MOUNTING RH (WCP) (CONSISTENT)	* CHECK	130.00	-
1	E MOUNTING REAR (WCP) (CONSISTENT)	* CHECK	60.00	-
1	GEAR BOX MOUNTING LH (WCP) (CONSISTENT)	* CHECK	75.00	-
	COST PLUS 15%		1,323.54	590.19
			10,147.16	4,524.81
	<u>SPECIAL NETT ITEMS</u>			
1	COOLANT (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	F NUMBER PLATE (SN) (CONSISTENT)	CRACKED	35.00	35.00
1	R SPORT RIM RH (NPA) (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	R TYRE 185/60/15 RH (NPA) (SN) (CONSISTENT)	TORN	-	-
2	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	200.00	200.00
1	R WIND SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	R WIND INNER SEAL (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			370.00	370.00
	<u>LABOUR</u>			
	CHECK WIRING FRONT.		40.00	20.00
	REFILL A/C GAS.		50.00	50.00
	CHECK WIRING REAR.		40.00	20.00
	WHEEL ALIGNMENT.		80.00	60.00
	REMOVE R WINDSCREEN.		100.00	100.00
	REPLACE RVER SEOSOR.		80.00	30.00
	ANTI-RUST COATING.		200.00	80.00
	RESET AL DIAGNOSTIC. (\$180.00)	* CHECK	250.00	-
	TOTAL PANEL / MECHANICAL. INCLUSIVE OF THE REPAIR OF H LAMP TOP PANAL LH, R SPORT RIM RH AND R/F WING.		2,718.00	2,718.00

Report Ref No. CC4/ASM18017744/Gub3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOTAL PAINTWORK.		1,035.00	1,035.00
	TOTAL PAINT / MATERIAL COSTS.		429.33	429.33
			5,022.33	4,542.33
	GRAND TOTAL		15,539.49	9,437.14
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$3874.12 NETT)				7,550.00

Report Ref No. CC4/ASM18017744/Gub3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.