



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV No. AC2004583
INV Date 26/06/2020
Reference CC4/QBE18017760/Ges3q2
Code QBE



PROFESSIONAL SERVICE FEE

Vehicle No. YP 2473A
Insured Veh. GZ 5270J
Claim No. VC011895
Policy No. 8-V0010657-MVA-R003
Accident Date 24/09/2018
Inspection Date 02/10/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC4/QBE18017760/Ges3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 26-06-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 5270J	Veh. Inspected	YP 2473A
Policy No.	8-V0010657-MVA-R003	Coverage (\$)	0.00
Claim No.	VC011895	Excess (\$)	0.00
Assign From	JENNY	Assign Date	01/10/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI CANTER	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	FEB21EA20285	Colour	WHITE
Odometer	36796	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/85 R18	BRIDGESTONE	5 mm
L/H Front Tyre	195/85 R18	BRIDGESTONE	5 mm
R/H Rear Tyre	195/85 R18 (D)	BRIDGESTONE	5/5 mm
L/H Rear Tyre	195/85 R18 (D)	BRIDGESTONE	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/09/2018	Inspection Date	02/10/2018
Survey held at	BLK 5035# 01-345 AMK IND.PARK 2		
Repairer	GOLDBELL ENGINEERING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 2473A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER ASSY ,FRONT	BENT	929.76	929.76
1	COVER ,FR BMPR CORNER ,RH	MISSING	325.54	325.54
1	STAY ,FR BUMPER ,RH	BENT	186.95	186.95
1	BRKT ,FR BUMPER ,RH	NOT NECESSARY	155.80	-
1	GRILLE ,RADIATOR	NOT NECESSARY	1,053.14	-
1	PANEL ,CAB FR CORNER -RH	CUT	482.75	482.75
1	SEAL ,CORNER PANEL -RH	MISSING	35.07	35.07
1	PILLAR ,FR RH	BUCKLED	1,289.49	1,289.49
1	FENDER ,F/DR	BENT	63.59	63.59
1	W/STRIP ,F/DR FENDER	DEFORMED	27.00	27.00
1	STEP,FR SIDE ,RH	DISTORTED	285.00	285.00
1	PANEL ASSY ,FR DOOR,RH	DISTORTED	1,391.59	1,391.59
1	RUNCHANNEL ,F/DR WDO GLASS	NOT NECESSARY	265.93	-
2	HINGE ,FR DOOR 02TD DOM DX @\$154.89	BENT	309.78	309.78
1	CHECK ,FR DOOR	BENT	29.00	29.00
1	W/STRIP ,F/DR OPENING INR	NOT NECESSARY	266.23	-
1	W/STRIP ,F/DR OPENING OTR	TWISTED	340.01	340.01
1	ACTUATOR,F/DR LOCK RHS	NOT NECESSARY	492.80	-
1	LATCH ,F/DR POWER	NOT NECESSARY	639.41	-
1	STRIKER ,FR DOOR LOCK	NOT NECESSARY	12.00	-
1	REGULATOR ASSY ,F/DR PWR WD	BENT	1,254.47	1,254.47
1	HEADLAMP	CRACKED	461.45	461.45
1	SIGNAL LAMP ASSY -RH	CRACKED	245.15	245.15
1	GARNISH ,HEADLAMP	CRACKED	211.96	211.96
1	BEZEL ,HEADLAMP	CRACKED	13.83	13.83
1	TANK ASSY ,VACUUM	NOT NECESSARY	170.62	-
1	HOSE,VACUUM	NOT NECESSARY	34.34	-
1	SCUFF PLATE ,FR-RH	NOT NECESSARY	143.69	-
1	SILL ,FR FLOOR SIDE FR 02TD	BENT	299.20	299.20
1	SILL ,FR FLOOR SIDE RR 02TD	NOT NECESSARY	298.85	-
1	MIRROR OUTSIDE RR VIEW (ADDITIONAL)	CUT	93.59	93.59

Report Ref No. CC4/QBE18017760/Ges3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STAY ASSY ,O/S RR VIEW MIRR RH (ADDITIONAL)	BENT	418.19	418.19
1	CAP ,FR CORNER PANEL -RH (ADDITIONAL)	MISSING	38.61	38.61
	LESS 25% DISCOUNT		-3,066.20	-2,182.99
			9,198.59	6,548.99
	<u>SPECIAL NETT ITEMS</u>			
1	COMPANY STICKER (SN)	NECESSARY	300.00	150.00
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
			350.00	180.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT FRONT WINDSCREEN.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT FRONT DASHBOARD .	NOT NECESSARY	600.00	-
	TO REMOVE AND REFIX DAMAGED PARTS ,CUT ,WELD ,PANEL BEAT,STRAIGHTEN & REALIGN ,ETC.		4,200.00	3,000.00
	TO CHECK AND RECTIFY WIRING FAULTS ,TO CONDUCT DIAGNOSTIC CHECK.		280.00	250.00
	TO PUTTY,CLEAN ,SPRAY PAINT & POLISH ,ETC.		2,100.00	1,225.00
	TO REMOVE AND REFIT VACUUM TANK,TO CHECK FUNCTION.	NOT NECESSARY	500.00	-
	TO REMOVE AND REFIT DOOR COMPARTMENTS.		250.00	60.00
			8,110.00	4,535.00
GRAND TOTAL			17,658.59	11,263.99

RECOMMENDED COST OF REPAIRS			11,263.99
------------------------------------	--	--	------------------

Report Ref No. CC4/QBE18017760/Ges3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 2473A

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 2473A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 2473A

RE-INSPECTION

