



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18017826/Uvd3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-10-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 4873E	Veh. Inspected	GBH 7258L
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020957	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	02/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (A)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KDH2010230402	Colour	SILVER
Odometer	1763	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/80 R15	BRIDGESTONE	8 mm
L/H Front Tyre	195/80 R15	BRIDGESTONE	8 mm
R/H Rear Tyre	195/80 R15	BRIDGESTONE	8 mm
L/H Rear Tyre	195/80 R15	BRIDGESTONE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/09/2018	Inspection Date	02/10/2018
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**