

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 3383U

DATE 2/10/2018

AXA-4S

TS

1130

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet ✓			\$ 2,265.90
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Sponge ✓			\$ 99.20
	Front Bumper Reinforcement ✓			\$ 402.10
	Front Bumper Grille (RH) ✓			\$ 41.60
	Front Bumper Centre Grille Top Garnish .?			\$ 80.00
	Front Bumper Bracket Top (RH) ✓			\$ 22.40
	Front Bumper Bracket (RH) ✓			\$ 24.60
	Headlamp Support Panel Assy ✓			\$ 907.40
	Headlamp (RH) ✓			\$ 1,388.00
	Front Fender (RH) ✓			\$ 566.30
	Front Fender Apron Panel (RH) ✓			\$ 637.00
	Front Fender Shield (RH) ✓			\$ 175.90
	Front Fender Retainer ✓			\$ 24.60
	Wiper Container ?			\$ 61.90
	Wiper Container Motor ?			\$ 75.00
	Front Wheel Rim (RH) ?			\$ 325.30
	Front Wheel Hub Cap (RH) ✓			\$ 107.10
	SUB TOTAL			\$ 8,256.50
	LESS 20%			\$ 1,651.30
	DISCOUNTED TOTAL			\$ 6,605.20
	Frnt Fender Advertisement Logo (RH) ✓			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 660.00 400
	Spray Painting Charge			\$ 880.00 800
	Wiring			\$ 30.00 20
	Tuff Kote			\$ 50.00 20
	FRT Wheel Alignment			\$ 80.00 60
	Remove/Refix Aircon & Refill Gas			\$ 150.00 80
	Tow Charge			60 nett ✓
	TOTAL LABOUR			\$ 1,850.00
	ESTIMATE TOTAL			\$ 8,555.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary repairs must be resurveyed and is subject to final approval from Insurance Company

Ka hui (Ken)
 Signature: _____
 Date: 2/10/18 1550h.
 4 ps
 4s
 After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.