

ASS. REC. BY:

REF: CS/FCI18017835/ Urd 304 Special Instruction:

Surveyor: Marcus ASSIGNMENT (Office)From (Person): May chug of FCI Date/Time: 02/10/18 @ 12.47pm

Estimated Cost: Bill to:

OD ☒ TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBB 5608E Insured: SHD 3960Tat Workshop m/s Zoom Autowerks Tel: 9450 7920of 130 Bedok Reservoir Rd # 08-1339Policy No: Claim No: D18007160MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 28/09/18
(Client's Record)

CA / REV / REP. / REV 24 HRS

(wp)

Insp: 15 Kaki Bkt Rd 1 # 01-53

H.O.D. Endorsement:

Date/Time: 12.33pm @ 2/10/18Person Contacted: ElinVehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBB 5608E - NA / CFI 18017697/21 BOA: 28/9/18
	SHD 3960T - NA / CFI 18017697/21 BOA: 28/9/18
3/10/18	Informed FCI pending workshop est by email
9/10/18	Email preli revised to FCI

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / JNV / MV

To Inspect Vehicle No: AB356086at Workshop m/s noon

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 12k.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No 17026

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: AB356086Yr Regn: 7, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M.F. FB70C.C. 2977Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 229123

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FB70 B3A2 0034

Gen. Cond: Good / Fair / Poor / Burnt

Steering: border / Jammed / Leaked / Burnt orBrake: border / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 R15R: FS

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or h. flg

Front

Rear

R/Bal. 6 mmR/Bal. 6/6 mmL/Bal. 6 mmL/Bal. 6/6 mmD.O.A. 28/9/18D.O.I. 2/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

freer lorry LTA 9399/10/18 confirmed LTA 3000 with slip. (Red 14,667.61, 833)

Note:

MV: \$12K (EST) LTA: \$939 NV: \$11,061

RECEIVED 10 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

9/10 - typist

Report Format:

CWS

Lump Sum / I.B.I. (\$

3000/-)Days Of Repair: 4Resurvey No. of Trip: -

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

7x15=105

170+1055060385



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18007160MFSH

Our ref: CS/FCI18017835/Uvd3

DATE: 9/10/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. GBB 5608E


We thank for your instruction on 2/10/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 2/10/2018 at the premises of M/s ZOOM AUTOWERKS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$17,667.61
Revised Estimate Amount	: S\$3,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	01-10-2018	Our Ref No. D18007160MFSH
Accident Date	28-09-2018	Claim Type. Third Party
Insured Vehicle	SHD3960T	Third Party Vehicle. GBB5608E
Survey Location	130 BEDOK RESERVOIR ROAD#08-1339	
Contact Person.	ELIN CAI	
Contact No.	94507920/ 94507920	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZOOM AUTOWERKS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 9 October 2018 3:59 PM
To: 'Claim Workflow System'
Cc: 'MAYCHUA@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007160MFSH/1, GBB 5608E
Attachments: GBB 5608E PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBB 5608E
Date of survey: 2/10/2018
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 3 October 2018 12:07 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007160MFSH/1, GBB 5608E

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBB 5608E on 2/10/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 2 October 2018 12:45 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007160MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Tuesday, 2 October 2018 12:06 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18007160MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 3 October 2018 12:07 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007160MFSH/1, GBB 5608E

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBB 5608E on 2/10/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 2 October 2018 12:45 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007160MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 2 October 2018 12:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007160MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Article



Mitsubishi FB70

Price Range

Depreciation

2009

Vehicle Type

Home » Used Cars » Net Link Partners Pte Ltd » Mitsubishi Fuso Canter FB70

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Mitsubishi Fuso Canter FB70

Overview

Financial

Accessories

Similar

Research

Photos

Map

NETLINK

Specialized in New & Used Commercial Vehicles. Insurance. Hire P

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price	\$17,800	?
Depreciation	\$18,620 /yr View models with similar depreciation	?
Reg Date	18-Sep-2009 (11mths 14days COE left)	?
Manufactured	2009	?
Mileage	-	?
Transmission	Manual	?
Engine Cap	2,977 cc	?
Curb Weight	2,460 kg	?
Fuel type	Diesel	?
Features	-	?
Accessories	-	?
Description	Good Condition Maintained By Previous Owner. Cheap And Economical. Loan With Lowest Interest Rates. High Trade In. Call Now To View And Test Drive The Vehicle!	
COE	\$18,801	?
OMV	\$28,133	?
ARF	\$1,407	?
Dereg Value	\$1,798 as of today (change)	?



Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 1702E

Vehicle Details

Vehicle No.: GBB5608E
Vehicle to be Exported: No
Intended Deregistration Date: 02 Oct 2018
Vehicle Make: MITSUBISHI
Vehicle Model: FB70BB1SRDEA
Primary Colour: White
Manufacturing Year: 2009
Engine No.: 4M42A73440
Chassis No.: FB70BBA20034
Maximum Power Output: -
Open Market Value: \$28,133.00
Original Registration Date: 01 Jul 2009
First Registration Date: 01 Jul 2009
Transfer Count: 1
Actual ARF Paid: \$1,407.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2019
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$12,615.00
COE Rebate Amount: \$939.00
Total Rebate Amount: \$939.00

The information contained herein is correct as at 02 Oct 2018

OK



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

02 October 2018

REG NO.: GBB 5608 E
MAKE/MODEL: MITSUBISHI FUSO

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
LIST ITEMS		
1	Rear taillamp o/s 288.05	\$ Day/sea 381.50
1	Rear exhaust pipe 615.30	\$ 715.50
1	Rear exhaust mounting	\$ 27 42.50 X
1	Rear tow hook bracket	\$ 27 250.00 X
1	Rear wheel rim	\$ 27 280.00 X
1	Rear o/s leaf spring	\$ 17 1,656.00 X
1	Rear o/s mudguard - rear	\$ 335.20
1	Rear o/s mudflap	\$ 17 192.20 X
		\$ 3,852.90
Less 10% 2570		\$ 385.29
		\$ 3,467.61
SPECIAL NETT ITEMS		
1	Rear tyre (Depreciation)	\$ 17 300.00 X
1	Rear freezer box tailboard	\$ 17 2,200.00 X
1	Rear freezer box tailboard hinge - lower	\$ 17 120.00 X
1	Rear freezer box tailboard pillar frame	\$ 17 2,850.00 1700
1	Rear freezer box side board	\$ 17 2,500.00 X
1	Rear reverse sensor (1 set)	\$ 17 350.00 X
		\$ 8,320.00

S/N

LABOUR CHARGES

- | | | | | |
|---|--|----|-----------|------|
| 1 | To remove, replaced damaged lamps and check up rear wiring. | \$ | 80.00 | 20 |
| 2 | To remove and refit rear reverse sensor. | \$ | 11 150.00 | x |
| 3 | To remove, refit and replace exhaust silencer and mountings. | \$ | 150.00 | 60 |
| 4 | To apply undercoating. | \$ | 11 200.00 | x |
| 5 | Panel beating. | \$ | 2,800.00 | 1000 |
| 6 | To re-spray painting on the affected areas. | \$ | 2,500.00 | 500 |
| | | \$ | 5,880.00 | |

GRAND TOTAL :**\$ 17,667.61 ,**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To supply and part(s) during resurvey
- Repair estimate subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017835/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3960T	Veh. Inspected	GBB 5608E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007160MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	02/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FB70	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	FB70BBA20034	Colour	WHITE	
Odometer	229123	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	HIFLY	6 mm	
L/H Front Tyre	195 R15	HIFLY	6 mm	
R/H Rear Tyre	195 R15 (D)	FIRESTONE	6/6 mm	
L/H Rear Tyre	195 R15 (D)	FIRESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/09/2018	Inspection Date	02/10/2018	
Survey held at	15 KAKI BUKIT ROAD 4# 01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 5608E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILLAMP O/S	DAMAGED / SCRATCHED	381.50	288.05
1	REAR EXHAUST PIPE	DENTED	715.50	615.30
1	REAR EXHAUST MOUNTING	NOT NECESSARY	42.50	-
1	REAR TOW HOOK BRACKET	NOT NECESSARY	250.00	-
1	REAR WHEEL RIM	NOT NECESSARY	280.00	-
1	REAR O/S LEAF SPRING	NOT NECESSARY	1,656.00	-
1	REAR O/S MUDGUARD-REAR	DEFORMED / WARPED	335.20	335.20
1	REAR O/S MUDFLAP	NOT NECESSARY	192.20	-
	LESS 10% DISCOUNT		-385.29	-
	LESS 25% DISCOUNT		-	-309.64
			3,467.61	928.91
SPECIAL NETT ITEMS				
1	REAR TYRE (DEPRECIATION)(SN)	NOT NECESSARY	300.00	-
1	REAR FREEZER BOX TAILBOARD (SN)	NOT NECESSARY	2,200.00	-
1	REAR FREEZER BOX TAILBOARD HINGE-LOWER (SN)	NOT NECESSARY	120.00	-
1	REAR FREEZER BOX TAILBOARD PILLAR FRAME (SN)	DENTED	2,850.00	1,300.00
1	REAR FREEZER BOX SIDE BOARD (SN)	TO REPAIR SEE LABOUR	2,500.00	-
1	SET REAR REVERSE SENSOR (SN)	NOT NECESSARY	350.00	-
			8,320.00	1,300.00
LABOUR				
	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	20.00
	TO REMOVE AND REFIT REAR REVERSES ENSOR.	NOT NECESSARY	150.00	-
	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.		150.00	60.00
	TO APPLY UNDERCOATING.	NOT NECESSARY	200.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FREEZER BOX SIDE BOARD.		2,800.00	1,000.00

Report Ref No. CS/FCI18017835/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		2,500.00	500.00
			5,880.00	1,580.00
GRAND TOTAL			17,667.61	3,808.91
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/FCI18017835/Uvd3n2

MARKET VALUE: \$12,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$939.00=NETT VALUE: \$11,061.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.