

3/10/18  
 affirmed  
 with Man.

not allowed  
 take  
 d/s # 2000/c  
 3dy.  
 Take photo. Attached  
 2/10/18



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

AIGAsia Insured's Veh No : SKQ8220J  
 Date of Accident : 30 September 2018

51 Defu Lane 10 Singapore 539216  
 Tel : 68585151 ( 24 Hours ) Fax : 68580877  
 GST Regn. No. : M2-8922054-2

Messrs Begrand Pte Ltd

Date : 02 October 2018

Estimate To Repair SJZ1294G - KIA CERATO FORTE 1.6(M) EX ABS D/A  
 Chassis No : KNAFU411LA5288867

S/No	Quantity	Description	Amount
<b>LIST ITEMS</b>			
01	1 pc	bootlid cerato badge <i>nee</i>	\$ 27.00
02	1 pc	bootlid forte badge <i>nee</i>	\$ 27.00
03	1 pc	bootlid kia badge <i>nee</i>	\$ 27.00
04	1 pc	bootlid weatherstrip <i>11</i>	\$ 98.00
05	1 pc	bootlid lock <i>11</i>	\$ 113.00
06	1 pc	bootlid lock striker <i>11</i>	\$ 17.00
07	1 pc	rear end panel <i>R</i>	\$ 385.00
08	1 pc	rear end panel inner trim <i>11</i>	\$ 55.00
09	4 ps	rear end panel inner trim clip @ \$3.50 <i>11</i>	\$ 14.00
10	1 pc	rear bumper <i>do/pe</i>	\$ 607.00
11	1 pc	rear bumper reinforcement <i>one</i>	\$ 304.00
12	1 pc	rear bumper absorber foam <i>70.11</i>	\$ 165.00
13	2 ps	rear bumper side retainer @ \$22.00 <i>nee</i>	\$ 44.00
14	10 ps	rear bumper clip @ \$3.50 <i>nee</i>	\$ 35.00
15	2 ps	rear bumper bracket @ \$55.00 <i>11</i>	\$ 110.00
16	3 ps	rear bumper bottom bracket @ \$12.00 <i>11</i>	\$ 36.00
17	1 pc	rear bumper lower centre garnish / diffuser <i>De</i>	\$ 155.00
18	2 ps	rear lamp @ \$303.00 <i>11</i>	\$ 606.00
19	4 ps	rear lamp clip holder @ \$3.00 <i>11</i>	\$ 12.00
			\$ 2,837.00
Less 20 %			\$ 567.40
			\$ 2,269.60
<b>SPECIAL NETT ITEMS</b>			
20	1 pc	bootlid c/c accessory badge <i>nee</i>	\$ 20.00
21	1 set	rear bumper parking sensor <i>shield</i>	\$ 550.00
			\$ 570.00
<b>LABOUR &amp; MISC. CHARGES</b>			
01		To reinstall of rear bumper parking sensor.	\$ 150.00
02		To rust-proofing of the affected areas.	\$ 120.00
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 160.00
04		To check electrical lighting concerned.	\$ 60.00
05		To refit back power amplifier and fabricate wooden panel to resecure to calibrate and fine tune sound system.	\$ 500.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00

Handwritten marks on the right side of the table, including checkmarks, 'X' marks, and numbers: 1391, 200, 50, 2, 60, 20, 80, 400.



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKQ8220J  
Date of Accident : 30 September 2018

Messrs Begrand Pte Ltd

Date : 02 October 2018

Estimate To Repair SJZ1294G - KIA CERATO FORTE 1.6(M) EX ABS D/A  
Chassis No : KNAFU411LA5288867

S/No	Quantity	Description	Amount
07		<b>LABOUR &amp; MISC. CHARGES</b> Putty and spray painting of the affected portion.	\$ 800.00
			\$ 2,690.00
		<b>Total</b>	\$ 5,529.60

600  
120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

7-1391  
201  
1112.80

5.4 + 220  
labour + 1210  
2542.8