



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 4926H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LEFT FRONT DOOR (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	1,273.10	-
1	L/F DOOR SEAL (WCP) (CONSISTENT)	NOT NECESSARY	235.00	-
1	L/F LOWER DOOR MLDG (WCP) (CONSISTENT)	SCRATCHED	335.10	335.10
1	L/R DOOR (WCP) (CONSISTENT)	DEFORMED	1,084.90	1,084.90
1	L/R DOOR SEAL (WCP) (CONSISTENT)	NOT NECESSARY	245.70	-
1	L/R LOWER DOOR MLDG (WCP) (CONSISTENT)	SCRATCHED	321.70	321.70
1	L/R WING MOULDING (WCP) (CONSISTENT)	DEFORMED	278.50	278.50
1	FRT DOOR TAPE (WCP) (CONSISTENT)	NOT NECESSARY	110.00	-
1	REAR DOOR TAPE (WCP) (CONSISTENT)	NECESSARY	110.00	110.00
	COST PLUS 15%		599.10	319.53
			4,593.10	2,449.73
	<u>LABOUR</u>			
	WHEEL ALIGNMENT.		100.00	60.00
	PANEL/MECHANICAL.INCLUSIVE OF THE REPAIR OF LEFT FRONT DOOR.		499.50	499.50
	PAINTWORK.		355.50	355.50
	PAINT/MATERIAL COSTS.		105.24	105.24
			1,060.24	1,020.24
	GRAND TOTAL		5,653.34	3,469.97
	RECOMMENDED COST OF REPAIRS			3,469.97

Report Ref No. CC4/ASM18017871/Npa3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.