

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III18017876/DGA3Q2

**Date:** 17/04/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SFS4102S	<b>Insured Vehicle No :</b>	SHA7363G
Date of Loss: 21/09/2018	Nature of Claim: TP	Claim No: MCT18090573

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFS4102S		
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Engine No:	K24Z21301001
Reg. Date:	21/06/2010 (Man. Year: 2009)	Chassis No:	JHMRB38309C200995
Colour:	Blue	Odometer:	182746 km
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,630.40	2,568.80	1,061.60	29.24
Miscellaneous Items	10.00	11.00	-1.00	-10.00
Labour	1,990.00	1,440.00	550.00	27.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,630.40</b>	<b>4,019.80</b>	<b>1,610.60</b>	<b>28.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,200.00</b>		
<b>(S\$)</b>	5,630.40	3,200.00	2,430.40	43.17
<b>+ GST 7.00/7.00% (S\$)</b>	394.13	224.00	170.13	43.17
<b>Nett Amount (S\$)</b>	<b>6,024.53</b>	<b>3,424.00</b>	<b>2,600.53</b>	<b>43.17</b>
<b>+ Car Rental (4.0 x S\$160.00/day) (S\$)</b>		640.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,071.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,000.00</b>		

### INSPECTION

Date of Assignment:	03/10/2018 Present Location:	K Kim Hin Auto Pte Ltd (HQ)
Date Inspected:	08/10/2018 Inspected At:	K Kim Hin Auto Pte Ltd (HQ)
		160 Sin Ming Drive #02-20, Sin Ming
		AutoCity
		Singapore 575722

Estimated Period of Repair: 4.0 days

---

**Adjuster:** BRYAN TANI**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2020)
<b>Parts:</b>	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFS4102S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	714.00 F	*714.00 F
2	10		*REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 F
3	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Serviceable	60.00 F	*- F
4	1		*REAR BUMPER TOWING COVER	Dislodged	25.00 F	*25.00 F
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	110.00 F	*- F
6	1		*N/S REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	100.00 F	*- F
7	1		*N/S REAR BUMPER PARKING SENSOR-OUTER	Damaged	210.00 F	*210.00 F
8	1		*N/S REAR BUMPER PARKING SENSOR-INNER	Damaged	210.00 F	*210.00 F
9	1		*N/S REAR BUMPER REFLECTOR	Cracked	65.00 F	*65.00 F
10	1		*N/S TAILLAMP ASSY	Mtg Cracked	429.00 F	*429.00 F
11	1		*TAILGATE LOWER OUTER GARNISH	Distorted	548.00 F	*548.00 F
12	1		*TAILGATE LOWER OUTER GARNISH ODYSSEY EMBLEM	Necessary	40.00 F	*40.00 F
13	10		*TAILGATE LOWER OUTER GARNISH CLIPS	Necessary	70.00 F	*70.00 F
14	1		*N/S TAILGATE LAMP AND GASKET	Not Necessary	362.00 F	*- F
15	1		*N/S EXHAUST MUFFLER	Bent	680.00 F	*680.00 F
16	1		*N/S EXHAUST MUFFLER OUTER CHROME COVER	Bent	160.00 F	*160.00 F
17	1		*N/S EXHAUST MUFFLER HEAT SHIELD	Not Necessary	90.00 F	*- F
18	1		*N/S EXHAUST MUFFLER MOUNTING-FRONT	Not Necessary	60.00 F	*- F
19	1		*N/S EXHAUST MUFFLER MOUNTING-REAR	Not Necessary	60.00 F	*- F
20	1		*REAR END PANEL	Repair	485.00 F	*- F

F=Franchise part.

**Sub Total (\$\$)**    **4,538.00**    **3,211.00**  
**- Add. Disc. on L,N Items 20.00/20.00% (\$\$)**    907.60    642.20

**Total Parts (\$\$)**    **3,630.40**    **2,568.80**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	10.00	11.00
<b>Sub Total (\$\$)</b>			<b>10.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	120.00	80.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	800.00	600.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	800.00	600.00
4	TO APPLY UNDERSEALING.	New	80.00	40.00
5	TO REMOVE AND REFIT REVERSE SENSOR ASSY.	New	60.00	40.00
6	TO REMOVE AND RENEW EXHAUST SILENCER BOX.	New	100.00	60.00
7	TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	30.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,990.00</b>	<b>1,440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >