

Pre-assign / CCU / FTE

INSRS:
WSP:
Tel :
Liability :
RMKS:

328-Asa-Lia

REF:

AXA

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SHA64912

Yr Regn:

2016 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai / 40

C.C.

1685

Colour:

Yellow.

A/C:

Insured / Std / NI / NA

Sp Reading:

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM H154 / KM 64093622

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Triangle.

Front

6

mm

Rear

6

mm

R/Bal.

R/Bal.

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

3/10/18 E

Survey held at

Diy Auto.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Bakky neeh

10/11/18

(Confirm 2.P.)

20325.71

with 12 working days

(200-17569.69 46%)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

3)

Report Format :

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18017911/T1wb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 03-10-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 5876X	Veh. Inspected	SHA 649D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/10/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/10/2018	Inspection Date	03/10/2018	
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector 7
#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

03/10/2018 16:42

JOB-NO: 50111002

Page 1 of 3

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

VEHICLE DETAILS

LICENSE NO: SHA0649D

TRANS: AUTO

CHASSIS: KMHLB41UMGU093622

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU672446

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	2,500.00	0.00	2,500.00	Y		1600
2 R&R FRT WINDSCREEN & PILLAR GARNISH	1.00	180.00	0.00	180.00	Y		100
3 REMOVE & REFIT ENGINE & GEAR BOX & ENGINE MOUNTING	1.00	350.00	0.00	350.00	Y		200? photo
4 REMOVE & REFIT WIRE HARNESS & FUSE BOX	1.00	350.00	0.00	350.00	Y		200? photo
5 REMOVE & REFIT DASH BOARD ASSY	1.00	350.00	0.00	350.00	Y		200? photo
6 REMOVE & REFIT CONDENSER & RADIATOR & TURBO	1.00	250.00	0.00	250.00	Y		120
7 MOUNT WORKBENCH & ALIGNMENTS CHASSIS & REPLACE CHASSIS & SUPPORT PANEL	1.00	350.00	0.00	350.00	Y		250? photo
8 CONDUCT WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	Y		7.80x
9 TOP UP AIR-CON GAS 134A	1.00	160.00	0.00	160.00	Y		100
10 TOP UP RADIATOR COOLANT 4L & BLEEDING	1.00	180.00	0.00	180.00	Y		100
11 TOWING SERVICE	1.00	100.00	0.00	100.00	Y		80
12 RESPRAY FRT BUMPER	1.00	220.00	0.00	220.00	Y		200
13 RESPRAY FRT FENDER LHS	1.00	220.00	0.00	220.00	Y		200
14 RESPRAY FRT FENDER RHS	1.00	220.00	0.00	220.00	Y		200
15 RESPRAY FRT BONNET	1.00	220.00	0.00	220.00	Y		200
16 RESPRAY FRT CHASSIS	1.00	420.00	0.00	420.00	Y		300
17 RESPRAY FRT WHEEL HOUSE PANEL	1.00	420.00	0.00	420.00	Y		200
18 RESPRAY WINDSCREEN PILLAR & GARNISH	1.00	220.00	0.00	220.00	Y		150
19 DIAGNOSTIC & RESETTING FAULT CODE	1.00	250.00	0.00	250.00	Y		150
20 ADJUST HEAD LAMP AIM & RESETTING AUTOMATIC CONTROL	1.00	250.00	0.00	250.00	Y		150
21 RESPRAY SIDE SKIRT LHS	1.00	230.00	0.00	230.00	Y		200
TOTAL:		7,560.00	0.00	7,560.00			

MATERIALS

1 FRT BUMPER V3	1.00	599.68	119.94	479.74	L	Y	M/S
2 FRT BUMPER RETAINER LHS	1.00	48.32	9.66	38.66	L	Y	M/S
3 FRT BUMPER RETAINER RHS	1.00	48.32	9.66	38.66	L	Y	M/S
4 FRT BUMPER TOP SEAL	1.00	32.20	6.44	25.76	L	Y	M/S
5 FRT BUMPER TOWING CAP	1.00	21.92	4.38	17.54	L	Y	M/S
6 FRT BUMPER SENSOR COVER LHS	1.00	19.38	3.88	15.50	L	Y	M/S
7 FRT BUMPER SENSOR COVER RHS	1.00	19.38	3.88	15.50	L	Y	M/S

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
8 RADIATOR GRILLE	1.00	1,110.10	222.02	888.08	L	Y	mis ✓
9 RADIATOR GRILLE LOGO	1.00	142.84	28.57	114.27	L	Y	mis ✓
10 FRT BUMPER RADIATOR GRILLE CHROME	1.00	121.77	24.35	97.42	L	Y	mis ✓
11 FRT BUMPER HEAD LAMP BRACKET LHS	1.00	42.32	8.46	33.86	L	Y	ab ✓
12 FRT BUMPER HEAD LAMP BRACKET RHS	1.00	42.32	8.46	33.86	L	Y	ab ✓
13 FRT BUMPER FOG LAMP COVER LHS	1.00	178.55	35.71	142.84	L	Y	mis ✓
14 FRT BUMPER FOG LAMP COVER RHS	1.00	178.55	35.71	142.84	L	Y	mis ✓
15 FRT BUMPER AIR DUCT LHS	1.00	103.63	20.73	82.90	L	Y	mis ✓
16 FRT BUMPER AIR DUCT RHS	1.00	103.63	20.73	82.90	L	Y	mis ✓
17 FRT BUMPER LOWER LIP	1.00	82.63	16.53	66.10	L	Y	mis ✓
18 FRT BUMPER TOP GARNISH	1.00	105.83	21.17	84.66	L	Y	tu ✓
19 FRT ENGINE LOWER COVER	1.00	344.88	68.98	275.90	L	Y	tu ✓
20 FRT ENGINE SIDE COVER LHS	1.00	112.83	22.57	90.26	L	Y	X an ✓
21 FRT ENGINE SIDE COVER RHS	1.00	112.83	22.57	90.26	L	Y	de ✓
22 FRT BUMPER UPPER AIR DUCT	1.00	235.45	47.09	188.36	L	Y	X an ✓
23 FRT FENDER RHS	1.00	659.50	131.90	527.60	L	Y	bt ✓
24 FRT FENDER INNER SHIELD RHS	1.00	185.12	37.02	148.10	L	Y	mis ✓
25 FRONT WHEEL HOUSE PANEL RHS	1.00	678.55	135.71	542.84	L	Y	Rp ✓
26 FRONT FENDER BRACKET RHS	1.00	55.12	11.02	44.10	L	Y	X an ✓
27 HEAD LAMP LOWER PANEL RHS	1.00	189.88	37.98	151.90	L	Y	an ✓
28 WIPER TANK	1.00	108.76	21.75	87.01	L	Y	R ✓
29 WIPER TANK LEVER SENSOR	1.00	78.43	15.69	62.74	L	Y	X } ann ✓
30 WIPER TANK CAP	1.00	8.00	1.60	6.40	L	Y	X } ann ✓
31 FRONT FENDER LHS	1.00	659.50	131.90	527.60	L	Y	bt ✓
32 FRONT FENDER INNER SHIELD LHS	1.00	185.12	37.02	148.10	L	Y	tu ✓
33 FRT FENDER STAND GARNISH LHS	1.00	55.89	11.18	44.71	L	Y	X an ✓
34 FRT FENDER BRACKET LHS	1.00	55.12	11.02	44.10	L	Y	X an ✓
35 FRT HEAD LAMP LOWER LHS	1.00	189.88	37.98	151.90	L	Y	X an ✓
36 FRT FENDER UPPER RUBBER LHS	1.00	36.01	7.20	28.81	L	Y	de ✓
37 FRT FENDER QTR GARNISH LHS	1.00	113.55	22.71	90.84	L	Y	X an ✓
38 FRT WHEEL HOUSE PANEL LHS	1.00	678.55	135.71	542.84	L	Y	Rp ✓
39 FRT REINFORCEMENT	1.00	482.21	96.44	385.77	L	Y	bt ✓
40 FRT REINFORCEMENT SPONGE	1.00	99.86	19.97	79.89	L	Y	mis ✓
41 HORN LHS	1.00	123.83	24.77	99.06	L	Y	tu ✓
42 HORN RHS	1.00	123.83	24.77	99.06	L	Y	tu ✓
43 CONDENSER AIR GUARD LHS	1.00	74.58	14.92	59.66	L	Y	an ✓
44 CONDENSER AIR GUARD RHS	1.00	74.58	14.92	59.66	L	Y	an ✓
45 FRT SUPPORT PANEL	1.00	962.87	192.57	770.30	L	Y	an ✓
46 CONDENSER	1.00	927.55	185.51	742.04	L	Y	bt ✓
47 RADIATOR	1.00	1,140.60	228.12	912.48	L	Y	bt ✓
48 RADIATOR FAN COWLING	1.00	355.40	71.08	284.32	L	Y	an ✓
49 FAN BLADE	1.00	73.51	14.70	58.81	L	Y	X an ✓
50 TURBO INTERCOOLER	1.00	1,089.55	217.91	871.64	L	Y	X an ✓
51 TURBO TOP HOSE	1.00	343.20	68.64	274.56	L	Y	X an ✓
52 TURBO LOWER HOSE	1.00	277.29	55.46	221.83	L	Y	X an ✓
53 BONNET	1.00	1,912.68	382.54	1,530.14	L	Y	bt ✓
54 BONNET DAMPER LHS	1.00	76.45	15.29	61.16	L	Y	X an ✓
55 BONNET DAMPER RHS	1.00	76.45	15.29	61.16	L	Y	X an ✓
56 BONNET HINGE LHS	1.00	55.85	11.17	44.68	L	Y	bt ✓
57 BONNET HINGE RHS	1.00	55.85	11.17	44.68	L	Y	bt ✓
58 BONNET INSULATOR	1.00	196.50	39.30	157.20	L	Y	X an ✓
59 BONNET LOCK	1.00	79.90	15.98	63.92	L	Y	X an ✓
60 BONNET SENSOR LHS	1.00	63.55	12.71	50.84	L	Y	mis ✓
61 BONNET STRIP	1.00	33.88	6.78	27.10	L	Y	X ✓
62 BONNET STRIP LHS	1.00	23.97	4.79	19.18	L	Y	X } ann ✓
63 BONNET STRIP RHS	1.00	23.97	4.79	19.18	L	Y	X } ann ✓
64 BONNET STOPPER X2	1.00	25.19	5.04	20.15	L	Y	X ✓
65 HEAD LAMP LHS	1.00	1,808.10	361.62	1,446.48	L	Y	tu ✓

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
66 HEAD LAMP RHS	1.00	1,808.10	361.62	1,446.48	L	Y	OK
67 FRT WINDSCREEN	1.00	1,317.80	263.56	1,054.24	L	Y	OK
68 FRONT WINDSCREEN MOULDING	1.00	65.38	13.08	52.30	L	Y	OK
69 FRONT WINDSCREEN MOULDING LHS	1.00	57.21	11.44	45.77	L	Y	OK
70 FRONT WINDSCREEN MOULDING RHS	1.00	57.21	11.44	45.77	L	Y	OK
71 WIPER TOP GARNISH	1.00	222.60	44.52	178.08	L	Y	OK
72 WIPER TOP GARNISH SIDE COVER LHS	1.00	28.32	5.66	22.66	L	Y	X
73 WINDSCREEN PILLAR GARNISH LHS	1.00	183.30	36.66	146.64	L	Y	X
74 WINDSCREEN PILLAR GARNISH RHS	1.00	183.30	36.66	146.64	L	Y	X
75 AIR RESONATOR	1.00	181.60	36.32	145.28	L	Y	X
76 WINDSCREEN PILLAR LHS	1.00	1,745.50	349.10	1,396.40	L	Y	Rx
77 FRT CHASSIS LHS	1.00	1,260.70	252.14	1,008.56	L	Y	Rx
78 REPAIR CHASSIS RHS	1.00	0.00	0.00	0.00	L	Y	Xun
79 WATER PUMP pulley.	1.00	293.20	58.64	234.56	L	Y	bt
80 AIR-COND COMPRESSOR	1.00	2,578.00	515.60	2,062.40	L	Y	Xun.
81 TENSIONER PULLEY	1.00	103.88	20.78	83.10	L	Y	bt
82 FAN BELT	1.00	75.70	15.14	60.56	L	Y	bt
83 GROUNDING CABLE	1.00	32.88	6.58	26.30	L	Y	Xun
84 ENGINE MOUNTING (ENGINE SIDE)	1.00	456.30	91.26	365.04	L	Y	Xun.
85 SIDE SKIRT RHS	1.00	695.88	139.18	556.70	L	Y	bt
86 BATTERY	1.00	260.00	0.00	260.00	S	Y	Xun
87 RADIATOR LOWER HOSE	1.00	0.00	0.00	0.00	S	Y	Xun
88 RADIATOR TOP HOSE	1.00	0.00	0.00	0.00	S	Y	Xun.
89 FRT NUMBER PLATE	1.00	40.00	0.00	40.00	S	Y	OK
90 FRT NUMBER PLATE CASING	1.00	18.00	0.00	18.00	S	Y	OK
91 FRONT BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	OK
92 FRONT WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S	Y	OK
93 FRT WINDSCREEN COMFORT STICKER	1.00	85.00	0.00	85.00	S	Y	OK
94 FRT WINDSCREEN ERP & VIDEO RECORDER STICKER	1.00	55.00	0.00	55.00	S	Y	OK
95 FRONT FENDER INNER SHIELD CLIP LHS	1.00	35.00	0.00	35.00	S	Y	OK
96 FRONT FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	S	Y	OK
97 FRT BUMPER BOLT SET (MISSING)	1.00	60.00	0.00	60.00	S	Y	OK
TOTAL:		30,345.40	934.51	24,410.89			

TOTAL PARTS & LABOUR :

37,905.40

5,934.51

31,970.89

EXCESS/LOADING:SS 0.00

No. Of Day:

12

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: SS

DATE OF SURVEY:

3/10/18

SURVEYED BY:

Tanghan

CONTACT NO:

97498744

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ding Automotive Pte Ltd

Blk 10 Sin Ming Ind Est Sector C #01-20 Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

Parts Supplementary & Quotation Form

Attention:		Works Order Number:	
Vehicle Number: SHA 649 D		Our Reference Number:	
Make & Model: 740			

S/NO	PART NUMBER	PARTS DESCRIPTION	QTY	UNIT PRICE	SURVEYOR REMARK	W/S REMARK
1	Sw	Side Skirt (LHS) NOC	1	695.80		
2				-20%		
3				\$556.74		
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						



ESTIMATOR:

SURVEYOR:

Hsiao Tong (LKKAuto)

From: Dd hashim <dd.hashim@dingauto.sg>
Sent: Friday, 7 December 2018 5:30 PM
To: Taufikh (LKKAuto)
Cc: SUR; Admin A; CS A Team; taxiscs@stengg.com; Kenneth Ding; Kelly Ding; Accounts
Ding Auto; Ding Ding Auto
Subject: 50111002/SHA649D ON 02/10/2018-FINALIZE CONFIRMATION REMINDER
Attachments: Screenshot (18).png; ESTIMATE SHA649D.pdf

Dear Taufikh,

Kindly confirm this case finalize amount as soon as possible.

We are still pending for the finalize to submit our claim.

My clerk sent the finalize amount at P/P **\$20,355.68 with 12day** repairs as in the attachment below.

Sincerely appreciate your kindness to reply us as soon as possible.

HAVE A GREAT DAY TO YOU AHEAD..

SINCERELY

DD HASHIM

+6581160811

DING AUTO PTE LTD

DING AUTOMOTIVE PTE LTD (TAXI CC)

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

03/10/2018 16:42

JOB-NO: 50111002

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA0649D

TRANS: AUTO

CHASSIS: KMHLB41UMGU093622

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU672446

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	2,500.00	0.00	2,500.00	Y		1600
2 R&R FRT WINDSCREEN & PILLAR GARNISH	1.00	180.00	0.00	180.00	Y		100
3 REMOVE & REFIT ENGINE & GEAR BOX & ENGINE MOUNTING	1.00	350.00	0.00	350.00	Y		200? photo
4 REMOVE & REFIT WIRE HARNESS & FUSE BOX	1.00	350.00	0.00	350.00	Y		200? photo
5 REMOVE & REFIT DASH BOARD ASSY	1.00	350.00	0.00	350.00	X		20? photo
6 REMOVE & REFIT CONDENSER & RADIATOR & TURBO	1.00	250.00	0.00	250.00	Y		120
7 MOUNT WORKBENCH & ALIGNMENTS CHASSIS & REPLACE CHASSIS & SUPPORT PANEL	1.00	350.00	0.00	350.00	Y		250? photo
8 CONDUCT WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	Y		80 X
9 TOP UP AIR-CON GAS 134A	1.00	180.00	0.00	180.00	Y		100?
10 TOP UP RADIATOR COOLANT 4L & BLEEDING	1.00	180.00	0.00	180.00	Y		100
11 TOWING SERVICE	1.00	100.00	0.00	100.00	Y		80
12 RESPRAY FRT BUMPER	1.00	220.00	0.00	220.00	Y		200
13 RESPRAY FRT FENDER LHS	1.00	220.00	0.00	220.00	Y		200
14 RESPRAY FRT FENDER RHS	1.00	220.00	0.00	220.00	Y		200
15 RESPRAY FRT BONNET	1.00	220.00	0.00	220.00	Y		200
16 RESPRAY FRT CHASSIS	1.00	420.00	0.00	420.00	Y		200
17 RESPRAY FRT WHEEL HOUSE PANEL	1.00	420.00	0.00	420.00	Y		200
18 RESPRAY WINDSCREEN PILLAR & GARNISH	1.00	220.00	0.00	220.00	Y		150
19 DIAGNOSTIC & RESETTING FAULT CODE	1.00	250.00	0.00	250.00	Y		150
20 ADJUST HEAD LAMP AIM & RESETTING AUTOMATIC CONTROL	1.00	250.00	0.00	250.00	Y		150
21 RESPRAY SIDE SKIRT LHS	1.00	230.00	0.00	230.00	Y		250
TOTAL:		7,560.00	0.00	7,560.00			

MATERIALS

1 FRT BUMPER V3	1.00	598.68	119.94	478.74	L	Y	M/S
2 FRT BUMPER RETAINER LHS	1.00	48.32	9.66	38.66	L	Y	M/S
3 FRT BUMPER RETAINER RHS	1.00	48.32	9.66	38.66	L	Y	M/S
4 FRT BUMPER TOP SEAL	1.00	32.20	6.44	25.76	L	Y	M/S
5 FRT BUMPER TOWING CAP	1.00	21.92	4.38	17.54	L	Y	M/S
6 FRT BUMPER SENSOR COVER LHS	1.00	19.38	3.88	15.50	L	Y	M/S
7 FRT BUMPER SENSOR COVER RHS	1.00	19.38	3.88	15.50	L	Y	M/S

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
8 RADIATOR GRILLE	1.00	1,110.10	222.02	888.08	L	Y	ms
9 RADIATOR GRILLE LOGO	1.00	142.84	28.57	114.27	L	Y	ms
10 FRT BUMPER RADIATOR GRILLE CHROME	1.00	121.77	24.35	97.42	L	Y	ms
11 FRT BUMPER HEAD LAMP BRACKET LHS	1.00	42.32	8.46	33.86	L	Y	ms
12 FRT BUMPER HEAD LAMP BRACKET RHS	1.00	42.32	8.46	33.86	L	Y	ms
13 FRT BUMPER FOG LAMP COVER LHS	1.00	178.55	35.71	142.84	L	Y	ms
14 FRT BUMPER FOG LAMP COVER RHS	1.00	178.55	35.71	142.84	L	Y	ms
15 FRT BUMPER AIR DUCT LHS	1.00	103.63	20.73	82.90	L	Y	ms
16 FRT BUMPER AIR DUCT RHS	1.00	103.63	20.73	82.90	L	Y	ms
17 FRT BUMPER LOWER LIP	1.00	82.83	16.53	66.30	L	Y	ms
18 FRT BUMPER TOP GARNISH	1.00	105.83	21.17	84.66	L	Y	ms
19 FRT ENGINE LOWER COVER	1.00	344.88	68.98	275.90	L	Y	ms
20 FRT ENGINE SIDE COVER LHS	1.00	112.83	22.57	90.26	L	Y	X
21 FRT ENGINE SIDE COVER RHS	1.00	112.83	22.57	90.26	L	Y	X
22 FRT BUMPER UPPER AIR DUCT	1.00	235.45	47.09	188.36	L	Y	X
23 FRT FENDER RHS	1.00	659.50	131.90	527.60	L	Y	bt
24 FRT FENDER INNER SHIELD RHS	1.00	185.12	37.02	148.10	L	Y	ms
25 FRONT WHEEL HOUSE PANEL RHS	1.00	678.55	135.71	542.84	L	Y	Rp
26 FRONT FENDER BRACKET RHS	1.00	55.12	11.02	44.10	L	Y	X
27 HEAD LAMP LOWER PANEL RHS	1.00	189.88	37.98	151.90	L	Y	ms
28 WIPER TANK	1.00	108.76	21.75	87.01	L	Y	X
29 WIPER TANK LEVER SENSOR	1.00	78.43	15.69	62.74	L	Y	X
30 WIPER TANK CAP	1.00	8.00	1.60	6.40	L	Y	X
31 FRONT FENDER LHS	1.00	659.50	131.90	527.60	L	Y	bt
32 FRONT FENDER INNER SHIELD LHS	1.00	185.12	37.02	148.10	L	Y	ms
33 FRT FENDER STAND GARNISH LHS	1.00	55.89	11.18	44.71	L	Y	X
34 FRT FENDER BRACKET LHS	1.00	55.12	11.02	44.10	L	Y	X
35 FRT HEAD LAMP LOWER LHS	1.00	189.88	37.98	151.90	L	Y	ms
36 FRT FENDER UPPER RUBBER LHS	1.00	38.01	7.20	30.81	L	Y	X
37 FRT FENDER QTR GARNISH LHS	1.00	113.55	22.71	90.84	L	Y	X
38 FRT WHEEL HOUSE PANEL LHS	1.00	678.55	135.71	542.84	L	Y	Rp
39 FRT REINFORCEMENT	1.00	482.21	96.44	385.77	L	Y	bt
40 FRT REINFORCEMENT SPONGE	1.00	99.88	19.97	79.91	L	Y	ms
41 HORN LHS	1.00	123.83	24.77	99.06	L	Y	ms
42 HORN RHS	1.00	123.83	24.77	99.06	L	Y	ms
43 CONDENSER AIR GUARD LHS	1.00	74.58	14.92	59.66	L	Y	ms
44 CONDENSER AIR GUARD RHS	1.00	74.58	14.92	59.66	L	Y	ms
45 FRT SUPPORT PANEL	1.00	982.87	192.57	790.30	L	Y	ms
46 CONDENSER	1.00	927.55	185.51	742.04	L	Y	ms
47 RADIATOR	1.00	1,140.80	228.12	912.68	L	Y	ms
48 RADIATOR FAN COWLING	1.00	355.40	71.08	284.32	L	Y	ms
49 FAN BLADE	1.00	73.51	14.70	58.81	L	Y	X
50 TURBO INTERCOOLER	1.00	1,089.55	217.91	871.64	L	Y	X
51 TURBO TOP HOSE	1.00	343.20	68.64	274.56	L	Y	X
52 TURBO LOWER HOSE	1.00	277.29	55.46	221.83	L	Y	X
53 BONNET	1.00	1,912.88	382.54	1,530.34	L	Y	ms
54 BONNET DAMPER LHS	1.00	78.45	15.29	63.16	L	Y	X
55 BONNET DAMPER RHS	1.00	78.45	15.29	63.16	L	Y	X
56 BONNET HINGE LHS	1.00	55.85	11.17	44.68	L	Y	ms
57 BONNET HINGE RHS	1.00	55.85	11.17	44.68	L	Y	ms
58 BONNET INSULATOR	1.00	196.50	39.30	157.20	L	Y	X
59 BONNET LOCK	1.00	79.90	15.98	63.92	L	Y	X
60 BONNET SENSOR LHS	1.00	83.55	12.71	70.84	L	Y	ms
61 BONNET STRIP	1.00	33.88	6.78	27.10	L	Y	X
62 BONNET STRIP LHS	1.00	23.97	4.79	19.18	L	Y	X
63 BONNET STRIP RHS	1.00	23.97	4.79	19.18	L	Y	X
64 BONNET STOPPER X2	1.00	25.19	5.04	20.15	L	Y	X
65 HEAD LAMP LHS	1.00	1,808.10	361.62	1,446.48	L	Y	ms

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
66 HEAD LAMP RHS	1.00	1,808.10	361.62	1,446.48	L	Y	OK
67 FRT WINDSCREEN	1.00	1,317.80	263.56	1,054.24	L	Y	OK
68 FRONT WINDSCREEN MOULDING	1.00	85.38	13.08	52.30	L	Y	OK
69 FRONT WINDSCREEN MOULDING LHS	1.00	57.21	11.44	45.77	L	Y	OK
70 FRONT WINDSCREEN MOULDING RHS	1.00	57.21	11.44	45.77	L	Y	OK
71 WIPER TOP GARNISH	1.00	222.80	44.52	178.08	L	Y	OK
72 WIPER TOP GARNISH SIDE COVER LHS	1.00	28.32	5.66	22.66	L	Y	OK
73 WINDSCREEN PILLAR GARNISH LHS	1.00	183.30	36.66	146.64	L	Y	OK
74 WINDSCREEN PILLAR GARNISH RHS	1.00	183.30	36.66	146.64	L	Y	OK
75 AIR RESONATOR	1.00	181.60	36.32	145.28	L	Y	OK
76 WINDSCREEN PILLAR LHS	1.00	1,745.50	349.10	1,396.40	L	Y	OK
77 FRT CHASSIS LHS	1.00	1,260.70	252.14	1,008.56	L	Y	OK
78 REPAIR CHASSIS RHS	1.00	0.00	0.00	0.00	L	Y	OK
79 WATER PUMP pulley	1.00	293.20	58.64	234.56	L	Y	OK
80 AIR-COND COMPRESSOR	1.00	2,578.00	515.60	2,062.40	L	Y	OK
81 TENSIONER PULLEY	1.00	103.88	20.78	83.10	L	Y	OK
82 FAN BELT	1.00	75.70	15.14	60.56	L	Y	OK
83 GROUNDING CABLE	1.00	32.88	6.58	26.30	L	Y	OK
84 ENGINE MOUNTING (ENGINE SIDE)	1.00	456.30	91.26	365.04	L	Y	OK
85 SIDE SKIRT RHS	1.00	695.88	139.18	556.70	L	Y	OK
86 BATTERY	1.00	260.00	0.00	260.00	S	Y	OK
87 RADIATOR LOWER HOSE	1.00	0.00	0.00	0.00	S	Y	OK
88 RADIATOR TOP HOSE	1.00	0.00	0.00	0.00	S	Y	OK
89 FRT NUMBER PLATE	1.00	40.00	0.00	40.00	S	Y	OK
90 FRT NUMBER PLATE CASING	1.00	18.00	0.00	18.00	S	Y	OK
91 FRONT BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	OK
92 FRONT WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S	Y	OK
93 FRT WINDSCREEN COMFORT STICKER	1.00	65.00	0.00	65.00	S	Y	OK
94 FRT WINDSCREEN ERP & VIDEO RECORDER STICKER	1.00	55.00	0.00	55.00	S	Y	OK
95 FRONT FENDER INNER SHIELD CLIP LHS	1.00	35.00	0.00	35.00	S	Y	OK
96 FRONT FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	S	Y	OK
97 FRT BUMPER BOLT SET (MISSING)	1.00	60.00	0.00	60.00	S	Y	OK
TOTAL:		30,345.40	934.51	24,410.89			

TOTAL PARTS & LABOUR :

37,905.40

5,934.51

31,970.89

EXCESS/LOADING: \$5 0.00

No. Of Day:

12

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$5

DATE OF SURVEY:

9/10/18

SURVEYED BY:

Dangth

CONTACT NO:

97498744

FAX NO:

Side Skirt LHS

Labour \$4700

SIV \$413

Parts \$1522.68

LHS+P \$20335.58

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2839G
Vehicle Details	
Vehicle No.:	SHA649D
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Primary Colour:	Yellow
Manufacturing Year:	2016
Engine No.:	D4FDGU672446
Chassis No.:	KMHLB41UMGU093622
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$18,718.00
Original Registration Date:	15 Sep 2016
First Registration Date:	15 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$18,718.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2024
PARF Rebate Amount:	\$14,038.00
Intended COE Rebate Details	
COE Expiry Date:	14 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$42,672.00
COE Rebate Amount:	\$31,707.00
Total Rebate Amount:	\$45,745.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Oct 2018

OK

TP Veh	SHA 649D
Date of Reg	15.09.2016
DOA	02.10.2018
COE Expiry Date	14.09.2024

\$

(I) Estimated Book Value

Unit Cost	25,000.00
Import Duty	2,807.70
Registration Fee	140.00
PQP Paid	42,672.00
ARF Paid	18,718.00
Estimated Per Taxi Purchase Price	<u>89,337.70</u>
Estimated Per Taxi Purchase Price	89,337.70
Less 60% of ARF Paid	<u>11,230.80</u>
Estimated Full Lifespan Depreciation	<u>78,106.90</u>
Estimated Full Lifespan Depreciation	78,106.90
Times Balance Life (71/96 months)	<u>57,766.56</u>
Add 60% of ARF Paid	<u>11,230.80</u>
Estimated Book Value	<u><u>68,997.36</u></u>

(II) Adjusted LTA Rebate

PARF Rebate	
PQP Paid	
Times Balance Life (06/96 months)	<u> </u>
Adjusted COE Rebate	<u> </u>
PARF Rebate	
Add Adjusted COE Rebate	<u> </u>
Adjusted LTA Rebate	<u><u>45,745.00</u></u>

(Summary) Estimated Nett Value

Estimated Book Value	68,997.36
Less Adjusted LTA Rebate	45,745.00
Estimated Net Value	<u><u>23,252.36</u></u>



Service Request Details

Claim

S8M00XQ0

Reference

None 

Loss Date

October 2, 2018

Request Date

October 3, 2018

Due Date

October 10, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

03-10-2018 @ 9:55am

Alex veh in.

Taufik

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHA649D

Make

TPVD HYUNDAI

Model
I40-1.7 D

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE



SENT

10/3/18 9:51 AM

FROM

WANG Peter

SUBJECT

Liability not clear - conflicting version of stories

BODY

Liability not clear - the two drivers had conflict...



Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 11 March 2019 5:20 PM
To: 'Admin@Ding Automotive'
Cc: Admin A; CS A Team; 'taxiscs'; 'Kelly Ding'; 'Accounts Ding Auto'; 'Ding Ding Auto'; Denise Tay (LKKAUTO); 'Dd hashim'; Taufikh (LKKAUTO)
Subject: RE: 50111002/SHA649D ON 02/10/2018-FINALIZE CONFIRMATION REMINDER

Without Prejudice

Dear Kenneth,

Thank you for your patience.

As spoken, we would like to request a copy of your client video footage as per AXA instruction.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin@Ding Automotive <admin@dingautomotive.com.sg>
Sent: Monday, 11 March 2019 1:10 PM
To: 'Admin@Ding Automotive' <admin@dingautomotive.com.sg>; 'Dd hashim' <dd.hashim@dingauto.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; 'taxiscs' <taxiscs@stengg.com>; 'Kelly Ding' <kelly.ding@dingauto.sg>; 'Accounts Ding Auto' <accounts@dingauto.sg>; 'Ding Ding Auto' <ding@dingauto.sg>; Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: RE: 50111002/SHA649D ON 02/10/2018-FINALIZE CONFIRMATION REMINDER

Dear Hsiao Tong,

Good day to you.

Tried calling up LKK to look for you but could not reach you. As Vivian is on maternity leave, We would like to follow up on the finalization of this case.

Thank you and we sincerely look forward to hear from you as soon as possible.



RE: Pls request for TP video footage to ascertain liability

Type

🔔 Question

Message

Hi, we have uploaded a copy of third party video footage in Merimen. The video shows that traffic light was green in third party favour. Third party had the right of way. Kindly advise if we may proceed DS. Thank you.
Hsiao Tong - 20 March 2019

Reply

Please do not hesitate to contact us for further assistance.

Thank you so much.

~HAVE A GOOD DAY~

SINCERELY

DD HASHIM

MOTOR CLAIMS OFFICER

HP:+65 81160811

FAX:+65 64520614

On Fri, Dec 7, 2018 at 5:30 PM Dd hashim <dd.hashim@dingauto.sg> wrote:

Dear Taufikh,

Kindly confirm this case finalize amount as soon as possible.

We are still pending for the finalize to submit our claim.

My clerk sent the finalize amount at P/P \$20,355.68 with 12day repairs as in the attachment below.

Sincerely appreciate your kindness to reply us as soon as possible.

HAVE A GREAT DAY TO YOU AHEAD..

SINCERELY

DD HASHIM

+6581160811

DING AUTO PTE LTD

DING AUTOMOTIVE PTE LTD (TAXI CC)



Please proceed with proposed quantum

Type

🔗 Question

Message

Global sum of \$23,480.99 (all-in)

Reply



<MANDATE IA> - S8M00XQ0 [ACCIDENT INVOLVING SHC 5876X(OI) & SHA 649D(TP) ON 02/10/2018]

Type

 Question

Message

Liability: 100%. Third party video shows that the traffic light was green in third party favour. Inform OI about third party claim. Agreed to settle at best. We seek your mandate at \$23,480.99(all-in). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 04 April 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 04/04/2019

Survey Details:

Date of loss	2-Oct-18
Date of appointment	3-Oct-18
Date of survey	3-Oct-18
Location of survey	DING AUTO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHA 649D
Make and Model	HYUNDAI I40 1.7D CRDI A
Date of registration	15/9/2016
Excess	
Market Value/ Book Value	\$68,900 (est)
Parf Rebate	\$45,745 (est)
Nett Loss	\$23,155 (est)

Repair details:

Initial Estimate	\$ 31,970.89
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 15,079.01
Check items (estimate)	NIL
Labour	\$ 4,700.00
Total	\$ 19,779.01
Lump Sum(if applicable)	\$ -

Number of days for repair	12
---------------------------	----



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

12 recommended repair days + 2Sunday + 1PRS = 15days

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	21,163.54
Loss of use		NIL
Loss of rental	\$	1,560.00 (15days x \$130.00)
Loss of income	\$	750.00 (15days x \$50.00)
LTA search fees	\$	7.45
Others		NIL
Proposed Total	\$	23,480.99

Hsiao Tong (LKKAUTO)

From: Dd hashim <dd.hashim@dingauto.sg>
Sent: Thursday, 16 May 2019 3:28 PM
To: Hsiao Tong (LKKAUTO)
Cc: Taufikh (LKKAUTO); Admin A; Kelly Ding; Ding Ding Auto; claims; taxiscs; cst@axa.com.sg; Admin@Ding Automotive; Kenneth Ding
Subject: Re: 50111002/SHA649D ON 02/10/2018-FINALIZE CONFIRMATION REMINDER
//LKK REF: CC4/ASM18017911/T1pb3

Dear Hsiao Tong,

As spoken kindly help to seek the mandate to confirm the finalize amount.

We will follow up in 2 weeks time from today again.

Thank you.

~HAVE A GOOD DAY~

SINCERELY
DD HASHIM
MOTOR CLAIMS OFFICER
HP:+65 81160811
FAX:+65 64520614



Virus-free. www.avast.com

On Thu, May 16, 2019 at 3:06 PM Dd hashim <dd.hashim@dingauto.sg> wrote:

Dear Hsiao Tong,

As spoken kindly refer to the attachment for supplementary part.

After you add on the supplementary with part you can get the amount of **\$15,222.68**.

Thank you.

~HAVE A GOOD DAY~

SINCERELY
DD HASHIM
MOTOR CLAIMS OFFICER
HP:+65 81160811
FAX:+65 64520614



Virus-free. www.avast.com

On Thu, May 16, 2019 at 2:37 PM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Hashim,

As spoken, kindly refer to the attached.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Dd hashim <dd.hashim@dingauto.sg>

Sent: Thursday, 16 May 2019 2:25 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Kelly Ding <kelly.ding@dingauto.sg>; Ding Ding Auto <ding@dingauto.sg>; claims <claims@dingautomotive.com.sg>; taxiscs <taxiscs@stengg.com>; cst@axa.com.sg; Admin@Ding Automotive <admin@dingautomotive.com.sg>

Subject: Re: 50111002/SHA649D ON 02/10/2018-FINALIZE CONFIRMATION REMINDER //LKK REF: CC4/ASM18017911/T1pb3

Dear Hsiao Tong,

Kindly update us the finalize amount as per counter propose.

We will like to confirm the finalize amount and submit the LOD as soon as possible to this case.

Thank you.

~HAVE A GOOD DAY~

SINCERELY

DD HASHIM

MOTOR CLAIMS OFFICER

HP:+65 81160811

FAX:+65 64520614



Virus-free. www.avast.com

On Tue, May 14, 2019 at 4:10 PM Dd hashim <dd.hashim@dingauto.sg> wrote:

Dear Hsiao Tong,

Thank you for the previous finalize amount.

However we do not accept and would like to counter propose for **\$20,100.00** (before GST) to close thi finalize.

Kindly confirm the finalize amount to close this pending finalize since 2018 October.

Thank you.

~HAVE A GOOD DAY~

SINCERELY

DD HASHIM

MOTOR CLAIMS OFFICER

HP:+65 81160811

FAX:+65 64520614

On Sat, Apr 27, 2019 at 1:16 PM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

Thank you for your patience.

For COR, recommended amount at **P/P \$19,779.01(before GST)** with **12repair days**.

Kindly confirm.

** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



100

100

100

Hsiao Tong (LKKAUTO)

From: Dd hashim <dd.hashim@dingauto.sg>
Sent: Tuesday, 11 June 2019 3:27 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: SHA649D - Finalize Amount & After Repair Photo & Question Mark Item Photo .

Dear Hsiao Tong,

May I get the latest update for the COR amount?

Please do not hesitate to contact me for further assistance.

Thank you.

~Selamat Hari Raya~

SINCERELY
DD HASHIM
MOTOR CLAIMS OFFICER
HP: +65 81160811
FAX: +65 64520614

On Sat, Apr 6, 2019 at 1:55 PM Accounts Ding Auto <accounts@dingauto.sg> wrote:

----- Forwarded message -----

From: <taxiscs@stengg.com>
Date: Mon, Oct 15, 2018 at 6:06 PM
Subject: SHA649D - Finalize Amount & After Repair Photo & Question Mark Item Photo .
To: <taufikh@lkkauto.com>, <sur@lkkauto.com>
Cc: <ACCOUNTS@dingauto.sg>, <ADMIN@dingautomotive.com.sg>, <Carlur.chan@dingauto.sg>, <thinthin@lkkauto.com>, <vivianlau@lkkauto.com>, <AsherSng@lkkauto.com>, <cs-a@lkkauto.com>, <admin-a@lkkauto.com>

Dear Taufikh ,

Please see below for the finalize according to our conversion to finalize for SHA649D
AFTER PAINT PHOTO & ESTIMATE .

Finalize Amount
Total Repair - 12 Days
P/P
Labour - \$4700
Special Netts - \$413
Parts after 20% discount =\$15,222.68
Total L+P+S=\$20,355.68
Final Amount = \$20,355.68

Please help to close this case ASAP

Thanks

Best Regards
Ding Automotive Pte Ltd
Alex Khong
Hp : 62657130 / 83039588

NOTE !!!

All mailed letter & cheque payment is to be mailed to our main office address :

BLOCK 10 #01-20

SIN MING INDUSTRIAL EST. SEC C

SINGAPORE 575645

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]



Virus-free. www.avast.com

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

03/10/2018 16:42

OWNER'S PARTICULARS

JOB-NO: 50111002

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE

64739522

SINGAPORE 575717 0

VEHICLE DETAILS

LICENSE NO: SHA0649D

TRANS: AUTO

CHASSIS: KMHLB41UMGU093622

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU672446

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	2,500.00	0.00	2,500.00		Y	1600
2 R&R FRT WINDSCREEN & PILLAR GARNISH	1.00	180.00	0.00	180.00		Y	100
3 REMOVE & REFIT ENGINE & GEAR BOX & ENGINE MOUNTING	1.00	350.00	0.00	350.00		Y	200? photo
4 REMOVE & REFIT WIRE HARNESS & FUSE BOX	1.00	350.00	0.00	350.00		Y	200? photo
5 REMOVE & REFIT DASH BOARD ASSY	1.00	350.00	0.00	350.00		X	200? photo
6 REMOVE & REFIT CONDENSER & RADIATOR & TURBO	1.00	250.00	0.00	250.00		Y	120
7 MOUNT WORKBENCH & ALIGNMENTS CHASSIS & REPLACE CHASSIS & SUPPORT PANEL	1.00	350.00	0.00	350.00		Y	250? photo
8 CONDUCT WHEEL ALIGNMENT	1.00	120.00	0.00	120.00		Y	70. X
9 TOP UP AIR-CON GAS 134A	1.00	160.00	0.00	160.00		Y	100
10 TOP UP RADIATOR COOLANT 4L & BLEEDING	1.00	180.00	0.00	180.00		Y	100
11 TOWING SERVICE	1.00	100.00	0.00	100.00		Y	80
12 RESPRAY FRT BUMPER	1.00	220.00	0.00	220.00		Y	200
13 RESPRAY FRT FENDER LHS	1.00	220.00	0.00	220.00		Y	200
14 RESPRAY FRT FENDER RHS	1.00	220.00	0.00	220.00		Y	200
15 RESPRAY FRT BONNET	1.00	220.00	0.00	220.00		Y	200
16 RESPRAY FRT CHASSIS	1.00	420.00	0.00	420.00		Y	300
17 RESPRAY FRT WHEEL HOUSE PANEL	1.00	420.00	0.00	420.00		Y	200
18 RESPRAY WINDSCREEN PILLAR & GARNISH	1.00	220.00	0.00	220.00		Y	150
19 DIAGNOSTIC & RESETTING FAULT CODE	1.00	250.00	0.00	250.00		Y	150
20 ADJUST HEAD LAMP AIM & RESETTING AUTOMATIC CONTROL	1.00	250.00	0.00	250.00		Y	150
21 RESPRAY SIDE SKIRT LHS	1.00	230.00	0.00	230.00		Y	200
TOTAL:		7,560.00	0.00	7,560.00			
<u>MATERIALS</u>							
1 FRT BUMPER V3	1.00	599.68	119.94	479.74	L	Y	M/S
2 FRT BUMPER RETAINER LHS	1.00	48.32	9.66	38.66	L	Y	M/S
3 FRT BUMPER RETAINER RHS	1.00	48.32	9.66	38.66	L	Y	M/S
4 FRT BUMPER TOP SEAL	1.00	32.20	6.44	25.76	L	Y	M/S
5 FRT BUMPER TOWING CAP	1.00	21.92	4.38	17.54	L	Y	M/S
6 FRT BUMPER SENSOR COVER LHS	1.00	19.38	3.88	15.50	L	Y	M/S
7 FRT BUMPER SENSOR COVER RHS	1.00	19.38	3.88	15.50	L	Y	M/S

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
8 RADIATOR GRILLE	1.00	1,110.10	222.02	888.08	L	Y	mis/
9 RADIATOR GRILLE LOGO	1.00	142.84	28.57	114.27	L	Y	mis/
10 FRT BUMPER RADIATOR GRILLE CHROME	1.00	121.77	24.35	97.42	L	Y	mis/
11 FRT BUMPER HEAD LAMP BRACKET LHS	1.00	42.32	8.46	33.86	L	Y	ah/
12 FRT BUMPER HEAD LAMP BRACKET RHS	1.00	42.32	8.46	33.86	L	Y	ah/
13 FRT BUMPER FOG LAMP COVER LHS	1.00	178.55	35.71	142.84	L	Y	mis/
14 FRT BUMPER FOG LAMP COVER RHS	1.00	178.55	35.71	142.84	L	Y	mis/
15 FRT BUMPER AIR DUCT LHS	1.00	103.63	20.73	82.90	L	Y	mis/
16 FRT BUMPER AIR DUCT RHS	1.00	103.63	20.73	82.90	L	Y	mis/
17 FRT BUMPER LOWER LIP	1.00	82.63	16.53	66.10	L	Y	mis/
18 FRT BUMPER TOP GARNISH	1.00	105.83	21.17	84.66	L	Y	fn/
19 FRT ENGINE LOWER COVER	1.00	344.88	68.98	275.90	L	Y	fn/
20 FRT ENGINE SIDE COVER LHS	1.00	112.83	22.57	90.26	L	Y	X
21 FRT ENGINE SIDE COVER RHS	1.00	112.83	22.57	90.26	L	Y	de/
22 FRT BUMPER UPPER AIR DUCT	1.00	235.45	47.09	188.36	L	Y	X
23 FRT FENDER RHS	1.00	659.50	131.90	527.60	L	Y	bt/
24 FRT FENDER INNER SHIELD RHS	1.00	185.12	37.02	148.10	L	Y	mis/
25 FRONT WHEEL HOUSE PANEL RHS	1.00	678.55	135.71	542.84	L	Y	Rp
26 FRONT FENDER BRACKET RHS	1.00	55.12	11.02	44.10	L	Y	X
27 HEAD LAMP LOWER PANEL RHS	1.00	189.88	37.98	151.90	L	Y	ana/
28 WIPER TANK	1.00	108.76	21.75	87.01	L	Y	?
29 WIPER TANK LEVER SENSOR	1.00	78.43	15.69	62.74	L	Y	?
30 WIPER TANK CAP	1.00	8.00	1.60	6.40	L	Y	?
31 FRONT FENDER LHS	1.00	659.50	131.90	527.60	L	Y	bt/
32 FRONT FENDER INNER SHIELD LHS	1.00	185.12	37.02	148.10	L	Y	fn/
33 FRT FENDER STAND GARNISH LHS	1.00	55.89	11.18	44.71	L	Y	X
34 FRT FENDER BRACKET LHS	1.00	55.12	11.02	44.10	L	Y	X
35 FRT HEAD LAMP LOWER LHS	1.00	189.88	37.98	151.90	L	Y	de/
36 FRT FENDER UPPER RUBBER LHS	1.00	36.01	7.20	28.81	L	Y	de/
37 FRT FENDER QTR GARNISH LHS	1.00	113.55	22.71	90.84	L	Y	X
38 FRT WHEEL HOUSE PANEL LHS	1.00	678.55	135.71	542.84	L	Y	Rp
39 FRT REINFORCEMENT	1.00	482.21	96.44	385.77	L	Y	bt/
40 FRT REINFORCEMENT SPONGE	1.00	99.86	19.97	79.89	L	Y	mis/
41 HORN LHS	1.00	123.83	24.77	99.06	L	Y	lia/
42 HORN RHS	1.00	123.83	24.77	99.06	L	Y	ana/
43 CONDENSER AIR GUARD LHS	1.00	74.58	14.92	59.66	L	Y	mis/
44 CONDENSER AIR GUARD RHS	1.00	74.58	14.92	59.66	L	Y	mis/
45 FRT SUPPORT PANEL	1.00	962.87	192.57	770.30	L	Y	ana/
46 CONDENSER	1.00	927.55	185.51	742.04	L	Y	bt/
47 RADIATOR	1.00	1,140.60	228.12	912.48	L	Y	bt/
48 RADIATOR FAN COWLING	1.00	355.40	71.08	284.32	L	Y	ana/
49 FAN BLADE	1.00	73.51	14.70	58.81	L	Y	?
50 TURBO INTERCOOLER	1.00	1,089.55	217.91	871.64	L	Y	X
51 TURBO TOP HOSE	1.00	343.20	68.64	274.56	L	Y	X
52 TURBO LOWER HOSE	1.00	277.29	55.46	221.83	L	Y	X
53 BONNET	1.00	1,912.68	382.54	1,530.14	L	Y	bt/
54 BONNET DAMPER LHS	1.00	76.45	15.29	61.16	L	Y	?
55 BONNET DAMPER RHS	1.00	76.45	15.29	61.16	L	Y	?
56 BONNET HINGE LHS	1.00	55.85	11.17	44.68	L	Y	bt/
57 BONNET HINGE RHS	1.00	55.85	11.17	44.68	L	Y	bt/
58 BONNET INSULATOR	1.00	196.50	39.30	157.20	L	Y	X
59 BONNET LOCK	1.00	79.90	15.98	63.92	L	Y	?
60 BONNET SENSOR LHS	1.00	63.55	12.71	50.84	L	Y	mis/
61 BONNET STRIP	1.00	33.88	6.78	27.10	L	Y	X
62 BONNET STRIP LHS	1.00	23.97	4.79	19.18	L	Y	X
63 BONNET STRIP RHS	1.00	23.97	4.79	19.18	L	Y	X
64 BONNET STOPPER X2	1.00	25.19	5.04	20.15	L	Y	X
65 HEAD LAMP LHS	1.00	1,808.10	361.62	1,446.48	L	Y	ana/

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
66 HEAD LAMP RHS	1.00	1,808.10	361.62	1,446.48	L	Y	OK
67 FRT WINDSCREEN	1.00	1,317.80	263.56	1,054.24	L	Y	OK
68 FRONT WINDSCREEN MOULDING	1.00	65.38	13.08	52.30	L	Y	OK
69 FRONT WINDSCREEN MOULDING LHS	1.00	57.21	11.44	45.77	L	Y	OK
70 FRONT WINDSCREEN MOULDING RHS	1.00	57.21	11.44	45.77	L	Y	OK
71 WIPER TOP GARNISH	1.00	222.60	44.52	178.08	L	Y	OK
72 WIPER TOP GARNISH SIDE COVER LHS	1.00	28.32	5.66	22.66	L	Y	X
73 WINDSCREEN PILLAR GARNISH LHS	1.00	183.30	36.66	146.64	L	Y	X
74 WINDSCREEN PILLAR GARNISH RHS	1.00	183.30	36.66	146.64	L	Y	X
75 AIR RESONATOR	1.00	181.60	36.32	145.28	L	Y	X
76 WINDSCREEN PILLAR LHS	1.00	1,745.50	349.10	1,396.40	L	Y	RY
77 FRT CHASSIS LHS	1.00	1,260.70	252.14	1,008.56	L	Y	RY
78 REPAIR CHASSIS RHS	1.00	0.00	0.00	0.00	L	Y	
79 WATER PUMP pulley	1.00	293.20	58.64	234.56	L	Y	OK
80 AIR-COND COMPRESSOR	1.00	2,578.00	515.60	2,062.40	L	Y	?
81 TENSIONER PULLEY	1.00	103.88	20.78	83.10	L	Y	OK
82 FAN BELT	1.00	75.70	15.14	60.56	L	Y	OK
83 GROUNDING CABLE	1.00	32.88	6.58	26.30	L	Y	?
84 ENGINE MOUNTING (ENGINE SIDE)	1.00	456.30	91.26	365.04	L	Y	?
85 SIDE SKIRT RHS	1.00	695.88	139.18	556.70	L	Y	OK
86 BATTERY	1.00	260.00	0.00	260.00	S	Y	?
87 RADIATOR LOWER HOSE	1.00	0.00	0.00	0.00	S	Y	?
88 RADIATOR TOP HOSE	1.00	0.00	0.00	0.00	S	Y	?
89 FRT NUMBER PLATE	1.00	40.00	0.00	40.00	S	Y	OK
90 FRT NUMBER PLATE CASING	1.00	18.00	0.00	18.00	S	Y	OK
91 FRONT BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	OK
92 FRONT WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S	Y	OK
93 FRT WINDSCREEN COMFORT STICKER	1.00	85.00	0.00	85.00	S	Y	OK
94 FRT WINDSCREEN ERP & VIDEO RECORDER STICKER	1.00	55.00	0.00	55.00	S	Y	OK
95 FRONT FENDER INNER SHIELD CLIP LHS	1.00	35.00	0.00	35.00	S	Y	OK
96 FRONT FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	S	Y	OK
97 FRT BUMPER BOLT SET (MISSING)	1.00	60.00	0.00	60.00	S	Y	OK
TOTAL:		30,345.40	934.51	24,410.89			

TOTAL PARTS & LABOUR :

37,905.40

5,934.51

31,970.89

EXCESS/LOADING:\$ 0.00

No. Of Day:

12

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY:

9/16/18

SURVEYED BY:

Daphne

CONTACT NO:

97498766

FAX NO:

Side Skirt LHS

Labour \$4700

SN \$413

Parts \$15222.68

LHS+P \$20335.58

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:



Re:RE: Please proceed with proposed quantum

Type

🔗 Question

Message

In view of the supplementary , please proceed

Reply

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S0126280G



Name: MOHAMMAD YASIN BIN ABDUL
 محمد ياسين بن عبدول
 Race: MALAY
 Date of Birth: 18-05-1951 Sex: M NRIC: S0126280G
 Country of Birth: SINGAPORE



MOH S0126280G



Block Group: D+ Date of Issue: 10-04-1994
 Address: APT BLK 181, BUKIT BATOK STREET 11
 #03-76 SINGAPORE 2365

REPUBLIC OF SINGAPORE DRIVING LICENCE

DRIVER'S PHOTO

DRIVER'S NAME

DRIVER'S ADDRESS

DRIVER'S CATEGORY

DRIVER'S EXPIRY DATE

DRIVER'S CATEGORY

Class 1A	MOTORCYCLE NOT EXCEEDING 250 CC	11 Dec 1978
Class 1B	MOTORCYCLE BETWEEN 250 CC AND 400 CC	11 Dec 1978
Class 1	MOTORCYCLE EXCEEDING 400 CC	11 Dec 1978
Class 2	MOTOR CARS AND MOTOR TRACTORS THE WEIGHT OF WHICH UNLADEN DOES NOT EXCEED 2300 KILOGRAMS	28 Jan 1979

HP/ISSUED: S/No. 9000233074

REPUBLIC OF SINGAPORE DRIVING LICENCE

DRIVER'S PHOTO

DRIVER'S NAME

DRIVER'S ADDRESS

DRIVER'S CATEGORY

DRIVER'S EXPIRY DATE

DRIVER'S CATEGORY

1A	TAXI	03/12/1985
09	BUS	26/07/1989
09	BUS ATTENDANT	26/07/1989



Vehicle No: SHA 649 D (Hirer / Relief)

Reporting Date: 2/10/18 Time: (1:49 hrs)

Accident Date: 2/10/18 Time: 01:50 hrs

[OD: TPDWC / Cash] [PG: X] [SPD: 15 Km/H]

Mileage: 234439

[HP: 96649 H45] [Weather Condition: Clear / Raining / other:] [Road surface: Wet / Dry / Other:]

[Location: Jurong Gt Bt. Batok Central towards Bt. Batok West Ave 3]

TP1: Number Plate SHC 5876X Name: Ker Siong Lim NRIC: S1238792 Z HP:

TP2: Number Plate Name: NRIC: HP:

TP3: Number Plate Name: NRIC: HP:

[Witness:] [HP:] [Tow: Y/N]

**DING AUTOMOTIVE PTE LTD**

Blk 10 #01-20 Sin Ming
Industrial Est Sec C
Singapore 575645

OUR REF: 50111002/TP/SHA649D/AD/02/10/2019/DD
YOUR REF: SHC5876X/ CC4/ASM18017911/T1wb3

Without Prejudice
to our driver's Injury claim

6 August 2019
To: MOTOR CLAIMS DEPARTMENT
AXA INSURANCE
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ACCIDENT INVOLVING : SHA649D AGAINST SHC5876X ON 02/10/2019
LOCATION ALONG : JUNCTION OF BT BATOK CENTRAL&BT BATOK WEST AVE 3
We refer to the above matter:

	Rate Per Day	Repair/ Claims Day	Amount Before GST	GST 7%	Amount After GST
Cost of Repair	\$ -	11	\$ 20,355.68	\$ 1,424.90	\$ 21,780.58
Loss Of Rental	\$ 107.48	11	\$ 1,182.28	\$ -	\$ 1,182.28
Loss Of Income	\$ 80.00	11	\$ 880.00	\$ -	\$ 880.00
LTA/GIA Search Fee	\$ -	0	\$ 6.96	\$ 0.49	\$ 7.45
Towing Fee	\$ -	0	\$ -	\$ -	\$ -
Surveyor Fee	\$ -	0	\$ -	\$ -	\$ -
Total	\$ 187.48	11	\$ 22,424.92	\$ 1,425.38	\$ 23,850.30

The accident was caused solely by the negligence of your insured and as a results , We had incurred the following costs of repair and losses of our insurer:

Enclosed are copies of the following documents for your perusal:

☺	Repair Estimate	☺	Discharge Voucher
☺	GIA Report/Accident Police Report	☺	Certificate Of Insurance
☺	LTA 3 rd Party Search Fee	☺	Final Bill/Repair Tax Invoice
☺	Mileage Record	☺	Confirmation Finalize/Liability Email Copy
☺	Rental Invoice	☺	Letter Of Demand
☺	Letter Of Authority	☺	

Our insurer has authorized DING AUTOMOTIVE PTE LTD to deal with the claim in this accident case and also to receive and deal/negotiate with all payment as stated above.
Please look into our client's claim and revert soonest as possible.

Your Sincerely,
DD HASHIM
DING AUTOMOTIVE PTE LTD
HP:81160811
FAX:64520614

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18017911/T1wb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: PETER WANG

Date : 21-08-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5876X	Veh. Inspected	SHA 649D
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S8M00XQ0	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	03/10/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU093622	Colour	YELLOW
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TRIANGLE	6 mm
L/H Front Tyre	205/60 R16	TRIANGLE	6 mm
R/H Rear Tyre	205/60 R16	TRIANGLE	6 mm
L/H Rear Tyre	205/60 R16	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. THE CHASSIS FRAME AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/10/2018	Inspection Date	03/10/2018
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
--	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 649D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER V3 (CONSISTENT)	MISSING	599.68	599.68
1	FRT BUMPER RETAINER LHS (CONSISTENT)	NECESSARY	48.32	48.32
1	FRT BUMPER RETAINER RHS (CONSISTENT)	NECESSARY	48.32	48.32
1	FRT BUMPER TOP SEAL (CONSISTENT)	MISSING	32.20	32.20
1	FRT BUMPER TOWING CAP (CONSISTENT)	MISSING	21.92	21.92
1	FRT BUMPER SENSOR COVER LHS (CONSISTENT)	MISSING	19.38	19.38
1	FRT BUMPER SENSOR COVER RHS (CONSISTENT)	MISSING	19.38	19.38
1	RADIATOR GRILLE (CONSISTENT)	MISSING	1,110.10	1,110.10
1	RADIATOR GRILLE LOGO (CONSISTENT)	MISSING	142.84	142.84
1	FRT BUMPER RADIATOR GRILLE CHROME (CONSISTENT)	MISSING	121.77	121.77
1	FRT BUMPER HEAD LAMP BRACKET LHS (CONSISTENT)	NECESSARY	42.32	42.32
1	FRT BUMPER HEAD LAMP BRACKET RHS (CONSISTENT)	NECESSARY	42.32	42.32
1	FRT BUMPER FOG LAMP COVER LHS (CONSISTENT)	MISSING	178.55	178.55
1	FRT BUMPER FOG LAMP COVER RHS (CONSISTENT)	MISSING	178.55	178.55
1	FRT BUMPER AIR DUCT LHS (CONSISTENT)	MISSING	103.63	103.63
1	FRT BUMPER AIR DUCT RHS (CONSISTENT)	MISSING	103.63	103.63
1	FRT BUMPER LOWER LIP (CONSISTENT)	MISSING	82.63	82.63
1	FRT BUMPER TOP GARNISH (CONSISTENT)	TORN	105.83	105.83
1	FRT ENGINE LOWER COVER (CONSISTENT)	TORN	344.88	344.88
1	FRT ENGINE SIDE COVER LHS (CONSISTENT)	NOT NECESSARY	112.83	-
1	FRT ENGINE SIDE COVER RHS (CONSISTENT)	DEFORMED	112.83	112.83
1	FRT BUMPER UPPER AIR DUCT (CONSISTENT)	NOT NECESSARY	235.45	-
1	FRT FENDER RHS (CONSISTENT)	BENT	659.50	659.50
1	FRT FENDER INNER SHIELD RHS (CONSISTENT)	MISSING	185.12	185.12
1	FRONT WHEEL HOUSE PANEL RHS (CONSISTENT)	TO REPAIR SEE LABOUR	678.55	-
1	FRONT FENDER BRACKET RHS (CONSISTENT)	NOT NECESSARY	55.12	-
1	HEAD LAMP LOWER PANEL RHS (CONSISTENT)	CRACKED	189.88	189.88
1	WIPER TANK (CONSISTENT)	NOT NECESSARY	108.76	-
1	WIPER TANK LEVER SENSOR (CONSISTENT)	NOT NECESSARY	78.43	-

Report Ref No. CC4/ASM18017911/T1wb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WIPER TANK CAP (CONSISTENT)	NOT NECESSARY	8.00	-
1	FRONT FENDER LHS (CONSISTENT)	BENT	659.50	659.50
1	FRONT FENDER INNER SHIELD LHS (CONSISTENT)	TORN	185.12	185.12
1	FRT FENDER STAND GARNISH LHS (CONSISTENT)	NOT NECESSARY	55.89	-
1	FRT FENDER BRACKET LHS (CONSISTENT)	NOT NECESSARY	55.12	-
1	FRT HEADLAMP LOWER LHS (CONSISTENT)	NOT NECESSARY	189.88	-
1	FRT FENDER UPPER RUBBER LHS (CONSISTENT)	DEFORMED	36.01	36.01
1	FRT FENDER QTR GARNISH LHS (CONSISTENT)	NOT NECESSARY	113.55	-
1	FRT WHEEL HOUSE PANEL LHS (CONSISTENT)	TO REPAIR SEE LABOUR	678.55	-
1	FRT REINFORCEMENT (CONSISTENT)	BENT	482.21	482.21
1	FRT REINFORCEMENT SPONGE (CONSISTENT)	MISSING	99.86	99.86
1	HORN LHS (CONSISTENT)	CRACKED	123.83	123.83
1	HORN RHS (CONSISTENT)	CRACKED	123.83	123.83
1	CONDENSER AIR GUARD LHS (CONSISTENT)	CUT	74.58	74.58
1	CONDENSER AIR GUARD RHS (CONSISTENT)	CUT	74.58	74.58
1	FRT SUPPORT PANEL (CONSISTENT)	CRACKED	962.87	962.87
1	CONDENSER (CONSISTENT)	BENT	927.55	927.55
1	RADIATOR (CONSISTENT)	BENT	1,140.60	1,140.60
1	RADIATOR FAN COWLING (CONSISTENT)	CRACKED	355.40	355.40
1	FAN BLADE (CONSISTENT)	NOT NECESSARY	73.51	-
1	TURBO INTERCOOLER (CONSISTENT)	NOT NECESSARY	1,089.55	-
1	TURBO TOP HOSE (CONSISTENT)	NOT NECESSARY	343.20	-
1	TURBO LOWER HOSE (CONSISTENT)	NOT NECESSARY	277.29	-
1	BONNET (CONSISTENT)	BENT	1,912.68	1,912.68
1	BONNET DAMPER LHS (CONSISTENT)	NOT NECESSARY	76.45	-
1	BONNET DAMPER RHS (CONSISTENT)	NOT NECESSARY	76.45	-
1	BONNET HINGE LHS (CONSISTENT)	BENT	55.85	55.85
1	BONNET HINGE RHS (CONSISTENT)	BENT	55.85	55.85
1	BONNET INSULATOR (CONSISTENT)	NOT NECESSARY	196.50	-
1	BONNET LOCK (CONSISTENT)	NOT NECESSARY	79.90	-
1	BONNET SENSOR LHS (CONSISTENT)	MISSING	63.55	63.55
1	BONNET STRIP (CONSISTENT)	NOT NECESSARY	33.88	-

Report Ref No. CC4/ASM18017911/T1wb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET STRIP LHS (CONSISTENT)	NOT NECESSARY	23.97	-
1	BONNET STRIP RHS (CONSISTENT)	NOT NECESSARY	23.97	-
2	BONNET STOPPER (CONSISTENT)	NOT NECESSARY	25.19	-
1	HEAD LAMP LHS (CONSISTENT)	CRACKED	1,808.10	1,808.10
1	HEAD LAMP RHS (CONSISTENT)	CRACKED	1,808.10	1,808.10
1	FRT WINDSCREEN (CONSISTENT)	CRACKED	1,317.80	1,317.80
1	FRONT WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	65.38	65.38
1	FRONT WINDSCREEN MOULDING LHS (CONSISTENT)	NECESSARY	57.21	57.21
1	FRONT WINDSCREEN MOULDING RHS (CONSISTENT)	NECESSARY	57.21	57.21
1	WIPER TOP GARNISH (CONSISTENT)	CRACKED	222.60	222.60
1	WIPER TOP GARNISH SIDE COVER LHS (CONSISTENT)	NOT NECESSARY	28.32	-
1	WINDSCREEN PILLAR GARNISH LHS (CONSISTENT)	NOT NECESSARY	183.30	-
1	WINDSCREEN PILLAR GARNISH RHS (CONSISTENT)	NOT NECESSARY	183.30	-
1	AIR RESONATOR (CONSISTENT)	NOT NECESSARY	181.60	-
1	WINDSCREEN PILLAR LHS (CONSISTENT)	TO REPAIR SEE LABOUR	1,745.50	-
1	FRT CHASSIS LHS (CONSISTENT)	TO REPAIR SEE LABOUR	1,260.70	-
1	REPAIR CHASSIS RHS (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	WATER PUMP PULLEY (CONSISTENT)	BENT	293.20	293.20
1	AIR-COND COMPRESSOR (CONSISTENT)	NOT NECESSARY	2,578.00	-
1	TENSION PULLEY (CONSISTENT)	BENT	103.88	103.88
1	FAN BELT (CONSISTENT)	CUT	75.70	75.70
1	GROUNDING CABLE (CONSISTENT)	NOT NECESSARY	32.88	-
1	ENGINE MOUNTING (ENGINE SIDE) (CONSISTENT)	NOT NECESSARY	456.30	-
1	SIDE SKIRT RHS (CONSISTENT)	DEFORMED	695.88	695.88
1	SIDE SKIRT (LHS) (CONSISTENT) (ADDITIONAL)	NECESSARY	695.88	695.88
	LESS 20% DISCOUNT		-6,073.66	-3,805.68
			24,294.62	15,222.71
	SPECIAL NETT ITEMS			
1	BATTERY (SN) (CONSISTENT)	NOT NECESSARY	260.00	-
1	RADIATOR LOWER HOSE (NPA) (SN) (CONSISTENT)	NOT NECESSARY	-	-
1	RADIATOR TOP HOSE (NPA) (SN) (CONSISTENT)	NOT NECESSARY	-	-

Report Ref No. CC4/ASM18017911/T1wb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT NUMBER PLATE (SN) (CONSISTENT)	CRACKED	40.00	40.00
1	FRT NUMBER PLATE CASING (SN) (CONSISTENT)	DEFORMED	18.00	18.00
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	FRT WINDSCREEN COMFORT STICKER (SN) (CONSISTENT)	NECESSARY	85.00	85.00
1	FRT WINDSCREEN ERP & VIDEO RECORDER STICKER (SN) (CONSISTENT)	NECESSARY	55.00	55.00
1	FRONT FENDER INNER SHIELD CLIP LHS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT FENDER INNER SHIELD CLIP RHS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	SET FRT BUMPER BOLT (MISSING) (SN) (CONSISTENT)	NECESSARY	60.00	60.00
			673.00	413.00
	LABOUR			
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF FRONT WHEEL HOUSE PANEL RHS, FRT WHEEL HOUSE PANEL LHS, WINDSCREEN PILLAR LHS AND FRT CHASSIS LHS.		2,500.00	1,600.00
	R&R FRT WINDSCREEN & PILLAR GARNISH.		180.00	100.00
	REMOVE & REFIT ENGINE & GEAR BOX & ENGINE MOUNTING.		350.00	200.00
	REMOVE & REFIT WIRE HARNESS & FUSE BOX.		350.00	200.00
	REMOVE & REFIT DASHBOARD ASSY.	NOT NECESSARY	350.00	-
	REMOVE & REFIT CONDENSER & RADIATOR & TURBO.		250.00	120.00
	MOUNT WORKBENCH & ALIGNMENTS CHASSIS & REPLACE CHASSIS & SUPPORT PANEL.		350.00	250.00
	CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TOP UP AIR-CON GAS 134A.		160.00	100.00
	TOP UP RADIATOR COOLANT 4L & BLEEDING.		180.00	100.00
	TOWING SERVICE.		100.00	80.00
	RESPRAY FRT BUMPER.		220.00	200.00
	RESPRAY FRT FENDER LHS.		220.00	200.00
	RESPRAY FRT FENDER RHS.		220.00	200.00
	RESPRAY FRT BONNET.		220.00	200.00
	RESPRAY FRT CHASSIS.		420.00	300.00

Report Ref No. CC4/ASM18017911/T1wb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY FRT WHEEL HOUSE PANEL.		420.00	200.00
	RESPRAY WINDSCREEN PILLAR & GARNISH.		220.00	150.00
	DIAGNOSTIC & RESETTING FAULT CODE.		250.00	150.00
	ADJUST HEAD LAMP AIM & RESETTING AUTOMATIC CONTROL.		250.00	150.00
	RESPRAY SIDE SKIRT LHS.		230.00	200.00
			7,560.00	4,700.00
GRAND TOTAL			32,527.62	20,335.71

RECOMMENDED COST OF REPAIRS			20,355.71
-----------------------------	--	--	-----------

Report Ref No. CC4/ASM18017911/T1wb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.