



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18017915/T1jb3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 12-03-2019



ATTN: PETER WANG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLW 5939X	<b>Veh. Inspected</b>	SHC 7101K
<b>Policy No.</b>	VPA/P2090692	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S8M00XV2	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	PETER WANG	<b>Assign Date</b>	03/10/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI I40	<b>c.c</b>	1685
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	KMHLB41UMGU092440	<b>Colour</b>	YELLOW
<b>Odometer</b>	370576	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60R16	TRIANGLE	6 mm
<b>L/H Front Tyre</b>	205/60R16	TRIANGLE	6 mm
<b>R/H Rear Tyre</b>	205/60R16	TRIANGLE	6 mm
<b>L/H Rear Tyre</b>	205/60R16	TRIANGLE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	29/09/2018	<b>Inspection Date</b>	05/10/2018
<b>Survey held at</b>	31 CORPORATION RD		
<b>Repairer</b>	DING AUTOMOTIVE PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------