

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate  
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD

**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1810/001
Policy No:	8-V0017259-MVA	Date of Loss:	27/09/2018
Vehicle Reg. No.:	<b>SLM5281L</b>	Driveable?	yes
Driver Age:	0000-00-00	Third Party Vehicle No.:	GY6504J
Any Injuries?	no	Contact No:	
Insured/Claimant:	YEW TEE AUTOMOBILE TECH PTE LTD	Driver:	TOH SIEW TECK


Make/Model:	Mercedes-Benz, E200	Vehicle Reg. Date:	30-03-2017
Vehicle Colour:	GREY	Engine Number:	27492030778151
Chassis No:	WDD2130422A081705	Odometer:	
Total Loss?	<b>NO</b>	Est. Duration of Repair(Day)	

Description of Accident/loss: DAMAGED WHILST PARKED  
Remarks:  
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

**COST OF CLAIMS**

	Amount
Parts	3,484.80
Miscellaneous Items	139.00
Labour	810.00
Paintwork Labour	500.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>4,933.80</b>
<b>GST 7.00%(S\$):</b>	<b>345.37</b>
<b>Nett Amount(S\$):</b>	<b>5,279.17</b>

This claim is handled by: Sky Toh T C



*Not Authorized  
LKK  
w/cons  
Take photo before painting  
3/10/18  
3 day.  
P/P*

**REPAIR DETAILS****Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>deep cut</i>	690.00	690.00	+10.00	759.00 ✓
2	1	FRONT BUMPER SIDE RETAINER RH <i>new</i>	33.00	33.00	+10.00	36.30 ✓
3	1	FRONT FENDER RH <i>scr/line</i>	575.00	575.00	+10.00	632.50 X
4	1	FRONT HEADLAMP LED RH <i>scr/line</i>	1,870.00	1,870.00	+10.00	2,057.00 ✓
<b>Total Parts (\$\$)</b>						<b>3,484.80</b>

**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS <i>new</i>	35.00	35.00	0.00	35.00 ✓
2	1	FRONT BUMPER SENSOR RH	104.00	104.00	0.00	104.00 ?
<b>Sub Total (\$\$)</b>						<b>139.00</b>

**Estimates On Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Refit Front Bumper Sensor.	80.00	80.00	0.00 <i>40</i>	80.00
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00 <i>20</i>	30.00
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	700.00	700.00	0.00	700.00 <i>300</i>
<b>Gross Labour Cost (\$\$)</b>						<b>810.00</b>

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	30.00	30.00	0.00 <i>11</i>	30.00 X
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	20.00	20.00	0.00 <i>11</i>	20.00 X
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	450.00	450.00	0.00	450.00 <i>380</i>
<b>Gross Labour Cost (\$\$)</b>						<b>500.00</b>

&lt; END OF ESTIMATES &gt;