

ASS. REC. BY:

REF: es/fc/18018017/Dtd3

n2
Special Instruction:

Surveyor: 3mya

ASSIGNMENT (Office)

From (Person): Lurene juw

of fcf

Date/Time: 4/10/18 @ 10:08am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 2020Z

Insured: SHB 4518S

at Workshop m/s: Chunni Motor

Tel: 65425119

of AMK Autopoint # 01-05/06

Policy No:

Claim No: D18007181MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 28/09/18

CA / REV / REP. / REV 24 HRS (Ds)

H.O.D. Endorsement:

Date/Time: 10:15am @ 4/10/18

Person Contacted: Lynn

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 2020Z - NS/INC/18003/92/R/d3n2 DOA: 15/2/18
	SHB 4518S - EC3/AXA/110/4356/H/n/dq2 DOA: 18/7/2011
11/10/2018	Revised preli advise via email


REP:

ASSIGNMENT

COE 2022 August

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP REP. / OD REP. / VA / TRV / MV
 To inspect Vehicle No: _____
 at Make/Shop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Claim Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **SHB 2020 Z** Yr Reg: **August 2014**
 Type: Car / Cycle / Bus / Van / Lorry / Prime Mover /
 Truck / Trailer or
 Make: **Hyundai I40** cc: **1685**
 Color: **Yellow** ARC: Insured / Std / HI / HA
 Sp. Description: **695986** T/Taxi: Insured / Std / HI / HA
 Eng No: **D4FDEU463471**
 Ch No: **KMHLB41UMEU058015**
 Gen. Cond: Good / Fair / Poor / Ruined
 Steering: Normal / Jammed / Leaked / Burnt or
 Brake: Normal / Jammed / Leaked / Burnt or
 Mod: STD / S/Rtn / STD A/Rtn or



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: **205/60 R 16**
 R: **— " —**
 BS / DUH / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Westlake**
 Front: _____ Rear: _____
 R/Bal: **5** mm R/Bal: **5** mm
 L/Bal: **5** mm L/Bal: **5** mm
 D.O.A: **29/09/2018** D.O.I: **04/10/2018**
 Survey held at **Chunni AMK**

Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR. Book: _____ Consistent? : Yes or No
 Est. Repair: **108** days Res: Yes or No
 Lim Sum: **20** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Dir. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or
Front & Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	First copy SHB 45188
07/11/18	Jinapur 215 13500/- with 10 days jmv (Red: 7755.54 36%)

RECEIVED 08 NOV 2018

date of accident 28/9/2018
 dont need to upload GIA report.

Date/Time, File Print for
 : Prel. Report
 : Final Report

Days Of Repair: **10**
 Recurvey No. of Trip: **2**

11x15 = 165

1) **011 Typist**
 Date/Time, File Print for
 Report Format: **TP**
 Lump Sum / L.S.: **13,500/-**

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invt (\$)
 Weekend (\$)

Survey For	Transportation
1704 165	50
50 + 50	168
653	

550
 039
 8/11/18



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007181MFSH

Date: 11/10/2018

Our Ref: CS/FCI18018017/Dtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 2020Z

Please be informed that we had conducted the inspection of the abovementioned vehicle 11/10/2018 at the premises of M/s Chun Ni Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>21,255.54</u>
Revised Estimate Amount	: S\$ <u>17,086.94</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the Front and rear portion.



Comments/ Present Status:5

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	01-10-2018	Our Ref No. D18007181MFSH
Accident Date	28-09-2018	Claim Type. Third Party
Insured Vehicle	SHB4518S	Third Party Vehicle. SHB2020Z
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR,#01-05/06.	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65425119/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 11 October 2018 9:35 AM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007181MFSH/1
Attachments: PRELI ADVISED SHB 2020Z.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHB 2020Z**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 4 October 2018 10:31 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007181MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 4 October 2018 10:07 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007181MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

UK

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 2020Z

DATE : 1.10.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>crack</i>			\$ 251.00	✓
	Radiator Grille H Emblem <i>new</i>			\$ 27.50	✓
	Front Bumper Cover <i>crack</i>			\$ 544.50	✓
	Front Bumper Sponge <i>to be</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>is it</i>			\$ 402.10	✓
	Front Bumper Centre Grille <i>deformed</i>			\$ 178.60	✓
	Front Bumper Bracket Top (LH/RH) <i>new</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>new</i>	\$	24.60	\$ 49.20	X
	Headlamp Support Top Cover <i>svc</i>			\$ 222.60	X
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>mainly crack</i>	\$	1,388.00	\$ 2,776.00	✓
	Radiator <i>is it</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>new</i>			\$ 792.95	X
	Radiator Bracket (RH/LH) <i>new</i>	\$	6.50	\$ 13.00	X
	Radiator Guard <i>svc</i>	\$	20.00	\$ 40.00	X
	Horn Unit (LH/RH) <i>broken</i>	\$	73.80	\$ 147.60	✓
	Aircon Condenser <i>is it</i>			\$ 927.50	✓
	Inter Cooler <i>is it</i>			\$ 1,032.50	✓
	Inter Cooler Mounting (2 PCS) <i>new</i>			\$ 25.90	X
			<i>7992.20</i>		
			<i>6393.76</i>		
	SUB TOTAL			\$ 9,180.65	
	LESS 20%			\$ 1,836.13	
	DISCOUNTED TOTAL			\$ 7,344.52	
	Front Number Plate <i>crack</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>svc</i>			\$ 30.00	Nett X
			<i>25/-</i>	\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	<i>500/-</i>
	Spray Painting Charge			\$ 250.00	<i>200/-</i>
	Wiring Charge			\$ 50.00	<i>30/-</i>
	Towing Charge			\$ 50.00	<i>new</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00	<i>80/-</i>
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	<i>new</i>
	TOTAL LABOUR			\$ 1,980.00	
			<i>810/-</i>		

LKK Auto Consultants hence notify SHB 2020Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>bst</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>deformed</i>			\$ 96.50	✓
	Boot Lid Hinge (LH/RH) <i>run</i>		\$ 142.30	\$ 284.60	X
	Boot Lid Hinge Cover (LH/RH) <i>HH</i>		\$ 158.00	\$ 316.00	X
	Boot Lid Lock Upper <i>bst</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>run</i>			\$ 31.70	X
	Boot Lid 'H' Emblem <i>hlc</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>hlc</i>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <i>crack</i>		\$ 565.60	\$ 1,131.20	✓
	Boot Lid Trimboard <i>torn</i>			\$ 116.40	✓
	Boot Lid Trimboard Clips (10pcs) <i>hlc</i>			\$ 11.00	✓
	Bootlid Moulding <i>svl</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>svl</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>HH</i>			\$ 227.90	X
	Bootlid CR <i>HH</i>			\$ 56.30	X
	Rear Bumper <i>distorted</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>2 crack</i>			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>2 bst</i>		\$ 80.30	\$ 160.60	✓
	Rear Bumper Clip 10 pcs <i>hlc</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>HH</i>		\$ 35.60	\$ 71.20	X
	Rear Bumper Sponge <i>2 torn</i>			\$ 118.40	✓
	Rear Bumper Under Cover <i>distorted</i>			\$ 228.00	✓
	Tail Lamp (LH/RH) <i>crack</i>		\$ 697.80	\$ 1,395.60	✓
	Rear Panel <i>2 Dental</i>			\$ 526.70	✓
	Rear Panel Garnish <i>2 deformed mounting</i>			\$ 57.70	✓
	Rear Panel Lower Panel <i>2 Dental</i>			\$ 495.50	✓
	Exhaust Pipe Insulator <i>HH</i>		\$ 58.55	\$ 117.10	X
	Exhaust Silencer <i>2 bst</i>		\$ 967.70	\$ 1,935.40	✓
	Exhaust Pipe Hanger <i>HH</i>		\$ 58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>hlc dental</i>			\$ 730.10	✓
			<i>1035</i>		
			<i>10340.60</i>	\$ 11,675.40	
			<i>8272.48</i>	\$ 2,335.08	
				\$ 9,340.32	
				\$ 30.00	Nett ✓
			<i>215.70</i>	\$ 135.70	Nett ✓
				\$ 50.00	Nett ✓
				\$ 215.70	
	Labour Charge				
	Panel Beating	<i>04/10/2018 @ 1200m</i>		\$ 1,000.00	700/-
	Spray Painting Charge	<i>MA Antrol</i>		\$ 800.00	500/-
	Wiring Charge	<i>2/1 sum</i>	<i>10</i>	\$ 50.00	30/-
	Tuff Kote	<i>7 days</i>		\$ 50.00	40/-
	Remove/Refix Reverse Sensor	<i>LKK Antrol</i>		\$ 120.00	40/-
	Remove/Refix Exhaust Pipe			\$ 300.00	60/-
			<i>17086.94</i>		
			<i>4/13500/-</i>	\$ 2,320.00	
				\$ 21,255.54	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before final spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

04/10/2018 @ 1200m
MA Antrol
2/1 sum
10
7 days
LKK Antrol



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18018017/Dtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-11-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4518S	Veh. Inspected	SHB 2020Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18007181MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	04/10/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHLB41UMEU058015	Colour	YELLOW
Odometer	695986	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/09/2018	Inspection Date	04/10/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2020Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RADIATOR GRILLE	CRACKED	251.00	251.00
1	RADIATOR GRILLE H EMBLEM	NECESSARY	27.50	27.50
1	FRONT BUMPER COVER	CRACKED	544.50	544.50
1	FRONT BUMPER SPONGE	TORN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	BENT	402.10	402.10
1	FRONT BUMPER CENTRE GRILLE	DEFORMED	178.60	178.60
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	NOT NECESSARY	49.20	-
1	HEADLAMP SUPPORT TOP COVER	SERVICEABLE	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
2	HEADLAMP (LH/RH) @\$1388.00	MTG CRACKED	2,776.00	2,776.00
1	RADIATOR	BENT	698.30	698.30
1	RADIATOR FAN BLADE,COWLING,MOTOR ASSY	NOT NECESSARY	792.95	-
2	RADIATOR BRACKET (RH/LH) @\$6.50	NOT NECESSARY	13.00	-
2	RADIATOR GUARD @\$20.00	SERVICEABLE	40.00	-
2	HORN UNIT (LH/RH) @\$73.80	BROKEN	147.60	147.60
1	AIRCON CONDENSER	BENT	927.50	927.50
1	INTER COOLER	BENT	1,032.50	1,032.50
1	INTER COOLER MOUNTING (2 PCS)	NOT NECESSARY	25.90	-
1	BOOT LID	BENT	2,174.90	2,174.90
1	BOOT LID RUBBER	DEFORMED	96.50	96.50
2	BOOT LID HINGE (LH/RH) @\$142.30	TO REPAIR SEE LABOUR	284.60	-
2	BOOT LID HINGE COVER (LH/RH) @\$158.00	NOT NECESSARY	316.00	-
1	BOOT LID LOCK UPPER	BENT	102.60	102.60
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	31.70	-
1	BOOT LID "H" EMBLEM	NECESSARY	28.70	28.70
1	BOOT LID CRDI PLATE	NECESSARY	27.90	27.90
2	BOOT LID LAMP (LH/RH) @\$565.60	CRACKED	1,131.20	1,131.20
1	BOOT LID TRIMBOARD	TORN	116.40	116.40

Report Ref No. CS/FCI18018017/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	BOOTLID MOULDING	SERVICEABLE	85.00	-
1	BOOTLID I40 EMBLEM	SERVICEABLE	27.90	-
1	BOOTLID LOWER GARNISH	NOT NECESSARY	227.90	-
1	BOOTLID CR	NOT NECESSARY	56.30	-
1	REAR BUMPER	DISTORTED	553.00	553.00
1	REAR BUMPER REINFORCEMENT	CRACKED	428.40	428.40
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	BENT	160.60	160.60
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60	NOT NECESSARY	71.20	-
1	REAR BUMPER SPONGE	TORN	118.40	118.40
1	REAR BUMPER UNDER COVER	DISTORTED	228.00	228.00
2	TAIL LAMP (LH/RH) @\$697.80	CRACKED	1,395.60	1,395.60
1	REAR PANEL	DENTED	526.70	526.70
1	REAR PANEL GARNISH	MTG DEFORMED	57.70	57.70
1	REAR PANEL LOWER PANEL	DENTED	495.50	495.50
2	EXHAUST PIPE INSULATOR @\$58.55	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @\$967.70	BENT	1,935.40	1,935.40
2	EXHAUST PIPE HANGER @\$58.55	NOT NECESSARY	117.10	-
1	EXHAUST PIPE CENTRE LESS 20% DISCOUNT	DENTED	730.10	730.10
			-4,171.21	-3,666.56
			16,684.84	14,666.24
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	CRACKED	25.00	25.00
1	FRONT NO PLATE TRIM COVER (SN)	SERVICEABLE	30.00	-
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			270.70	240.70
	LABOUR			
	PANEL BEATING INCLUSIVE OF THE REPAIR OF BOOT LID HINGE (LH/RH) AND BOOT LID LOCK LOWER.		2,000.00	1,200.00

Report Ref No. CS/FCI18018017/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.		1,050.00	700.00
	WIRING CHARGE.		100.00	60.00
	TUFF KOTE.		50.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX EXHAUST PIPE.		300.00	60.00
			4,300.00	2,180.00
	GRAND TOTAL		21,255.54	17,086.94
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,500.00

Report Ref No. CS/FCI18018017/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.