



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD  
1 RAFFLES QUAY #29-10 SOUTH TOWER  
SINGAPORE 048583

INV No. AC2006038  
INV Date 03/09/2020  
Reference CC4/QBE18018047/Kba3q2  
Code QBE



#### PROFESSIONAL SERVICE FEE

Vehicle No. SJP 2921B  
Insured Veh. SKS 893J  
Claim No. VC011922  
Policy No. GA052501  
Accident Date 01/10/2018  
Inspection Date 11/10/2018

Description	Total
Survey Inspection	300.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>300.00</b>
<b>GST (7%)</b>	<b>21.00</b>
<b>Grand Total</b>	<b>321.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE18018047/Kba3q2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 03-09-2020		
		Code : QBE		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SKS 893J	<b>Veh. Inspected</b>	SJP 2921B
	<b>Policy No.</b>	GA052501	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	VC011922	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	Joyce Foo	<b>Assign Date</b>	11/10/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA CAMRY (A)	<b>c.c</b>	1998
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
	<b>Chassis No.</b>	MR053BK4107042121	<b>Colour</b>	METALLIC GREEN
	<b>Odometer</b>	262401	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	215/60 R16	YOKOHAMA	1 mm
	<b>L/H Front Tyre</b>	215/60 R16	YOKOHAMA	1 mm
	<b>R/H Rear Tyre</b>	215/60 R16	YOKOHAMA	7 mm
	<b>L/H Rear Tyre</b>	215/60 R16	YOKOHAMA	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	01/10/2018	<b>Inspection Date</b>	11/10/2018
	<b>Survey held at</b>	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 2921B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BOOTLID	TO REPAIR SEE LABOUR	960.00	-
1	BOOTLID EMBLEM	NECESSARY	65.00	65.00
1	BOOTLID LETTERING 'CAMRY'	NECESSARY	65.00	65.00
1	BOOTLID LETTERING '2.0'	NECESSARY	54.00	54.00
1	BOOTLID OUTER CHROME MOULDING	SERVICEABLE	360.00	-
1	BOOTID REFLECTOR LAMP LH	SERVICEABLE	465.00	-
1	BOOTID REFLECTOR LAMP RH	SERVICEABLE	465.00	-
1	BOOTLID LOCK ASSY	DENTED	405.00	349.70
1	BOOTLID STOPPER LH	SERVICEABLE	9.00	-
1	BOOTLID STOPPER RH	SERVICEABLE	9.00	-
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	525.00	-
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	150.00	-
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	150.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	150.00	-
1	REAR TAIL LAMP ASSY LH	SERVICEABLE	465.00	-
1	REAR TAIL LAMP ASSY RH	SERVICEABLE	465.00	-
1	REAR TAIL LAMP LOWER BRACKET LH	SERVICEABLE	36.00	-
1	REAR TAIL LAMP LOWER BRACKET RH	SERVICEABLE	36.00	-
1	REAR BUMPER	CRACKED	540.00	540.00
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	84.00	84.00
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	84.00	84.00
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	66.00	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	66.00	-
1	REAR BUMPER REINFORCEMENT	BENT	345.00	345.00
1	REAR END PANEL	BENT	535.00	535.00
1	REAR END PANEL LOCK STRIKER	TO REPAIR SEE LABOUR	36.00	-
1	REAR END PANEL TOP GARNISH	DENTED	450.00	339.10
1	REAR EXHAUST SILENCER BOX	TO REPAIR SEE LABOUR	695.00	-

Report Ref No. CC4/QBE18018047/Kba3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST SILENCER RUBBER	SERVICEABLE	66.00	-
1	REAR FENDER INNER SHIELD LH	SERVICEABLE	225.00	-
1	REAR FENDER INNER SHIELD RH	SERVICEABLE	225.00	-
	LESS 10% DISCOUNT		-825.10	-
	LESS 25% DISCOUNT		-	-615.20
			7,425.90	1,845.60
	<b><u>SPECIAL NETT ITEMS</u></b>			
10	REAR BUMPER CLIPS @\$3.00 (SN)	NECESSARY	30.00	30.00
10	REAR FENDER SHIELD CLIPS @\$4.50 (SN)	NOT NECESSARY	45.00	-
6	BOOTLID TRIM BOARD CLIPS @\$4.50 (SN)	NOT NECESSARY	27.00	-
6	REAR TAIL LAMP CLIPS @\$6.00 (SN)	NOT NECESSARY	36.00	-
1	SET REAR NUMBER SENSOR (SN)	SERVICEABLE	250.00	-
4	REAR END PANEL GARNISH CLIPS @\$4.50 (SN)	NECESSARY	18.00	18.00
1	REAR END PANEL SEAL (SN)	NECESSARY	100.00	30.00
1	REAR NUMBER PLATE WITH CASING (SN)	SERVICEABLE	80.00	-
			586.00	78.00
	<b><u>LABOUR</u></b>			
	ANTI-RUST COATING.		240.00	30.00
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED & NECESSARY PARTS ,TO PANEL BEAT ,CUT & WELD IF NECESSARY ,TO REALIGN ALL PANELS AND REINSTALL ALL REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID,BOOTLID HINGE LH,BOOTLID HINGE RH,REAR END PANEL LOCK STRIKER AND REAR EXHAUST SILENCER BOX .		1,250.00	600.00
	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL REPLACEMENT & REPAIRED PARTS ,TO RESPRAY USING 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES.		1,250.00	600.00
	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING.		80.00	20.00
	PROVIDE SKILL LABOUR TO DISMANTLE AND TRANSFER BOOTLID FITTING AND FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE REAR BUMPER SENSOR.		80.00	50.00
	PROVIDE SKILL LABOUR TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH .		120.00	60.00

Report Ref No. CC4/QBE18018047/Kba3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE EXHAUST PIPE/SYSTEM TO NEW .	NOT NECESSARY	100.00	-
	PROVIDE SKILL LABOUR TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH.	NOT NECESSARY	300.00	-
			3,570.00	1,360.00
<b>GRAND TOTAL</b>			<b>11,581.90</b>	<b>3,283.60</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,600.00</b>
---	--	--	--	-----------------

Report Ref No. CC4/QBE18018047/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SJP 2921B

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJP 2921B

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJP 2921B

RE-INSPECTION

