



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD	Ref : CC4/ASM18018066/Kga3s2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811	Date : 06-03-2020
ATTN: SAW THENG	Code : ASM



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 262U	Veh. Inspected	SLJ 7360U
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S8M00W28	Excess (\$)	0.00
Assign From	SAW THENG	Assign Date	03/10/2018

2. Vehicle Particulars & Condition

Make & Model	SUBARU XV (A)	c.c	1600
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JF1GP3KC5HG200688	Colour	METALLIC DARK GREY
Odometer	034360	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	YOKOHAMA	7 mm
L/H Front Tyre	225/55 R17	YOKOHAMA	7 mm
R/H Rear Tyre	225/55 R17	YOKOHAMA	7 mm
L/H Rear Tyre	225/55 R17	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/09/2018	Inspection Date	05/11/2018
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**