

OTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/1017/2018
DATE : 01-NOV-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : YEO ZONG RONG, KEYNES (YANG ZONGRONG, KEYNES)
ADDRESS : APT BLK 371 TAMPINES STREET 34
#10-10
S(520371)
TELEPHONE NO : 93854408

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : GA147814/1
VEHICLE NO : SLJ7360U
MODEL CODE : GP3FKDC
MODEL/YEAR : XV 1.6I-S AWD CVT
ENGINE NO : FB16Y444715
CHASSIS NO : JF1GP3KC5HG200688
MILEAGE : 1 KM
DATE IN : 01/11/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 01/11/2018

Print Date : 01/11/2018
Print Time : 15:06:44

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLJ7360U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	TO CONDUCT TP CLAIM AXA DATE:05/09/2018 TIME:2030 LOCATION:LENTOR AVE TWDS YIO CHU KANG		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER, FRT PANEL, FRT RH FENDER & BONNET	2240.00	8401
4	ZZ/003	RESPRAY FRT BUMPER, FRT PANEL, RH FRONT FENDER & BONNET	1680.00	8401
5	ZZ/004	TRANSFER/BALANCE TYRE/RIM BOTH FRONT	100.00	501
6	ZZ/005	REMOVE & REFLX AIRCON CONDENSER & RADIATOR TO FACILITATE REPAIR	nn 220.00	X
7	ZZ/006	WHEEL ALIGNMENT	200.00	1201
8	ZZ/007	TO CONDUCT FRONT LIGHTING TEST	50.00	301
9	ZZ/008	TO CONDUCT ANTI RUST COATING FRONT PORTION AFTER REPAIR	580.00	2901
10	ZZ/009	SUNDRIES	100.00	201
		TOTAL LABOUR CHARGES	5170.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ7360U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 VALVE TPMS ASSY	28103FJ003	360.00	?		
2 DISC WHEEL AL 17 C67	28111FJ170	3000.00	✓		
3 FENDER F XUV RH	57120FJ0509P	198.00	?		
4 HOOD COMPLETE-FRONT	57229FJ0009P	540.00	X		
5 BUMPER FACE F XUV	57704FJ070	414.00	✓		
6 ENR ABSORB FOAM XU	57705FJ010	79.20	X		
7 BRKT CORNER F RH	57707FJ001	43.20	?		
8 BRKT FLH BUMP CORN	57707FJ011	43.20	?		
9 BRKT BUMP FRH	57707FJ141	7.20	?		
10 BRKT SD F XUV LH	57707FJ151	7.20	X		
11 COVER FOG F XUV RH	57731FJ420	65.60	X		
12 MUD GUARD ASSY F RH	59110FJ040	108.00	X		
13 PNL AY DR FRH	60009FJ0019P	648.00	✓		
14 WSTR OUT DR F WRH	61280VA000	97.20	X		
15 LAMP ASSY HEAD EHR	84001FJ620	853.20	✓		
16 FOG DRL ASSY F	CBU-1.6 84503FJ000	425.00	X		
17 TAPE-FRONT DOOR RH	90422FJ001	9.00	X		
18 TAPE-FRONT DOOR SASH RH	90422FJ021	36.00	X		
19 TAPE-FRONT DOOR SASH-REAR RH	90422FJ041	23.40	X		
20 GARNISH-FRONT FENDER RH	91112FJ101	180.00	✓		
21 LH FRONT TYRE	T001FLH			500.00	X
22 RH FRONT TYRE	T001FRH			500.00	X
SUB TOTAL		7137.40	0.00	1000.00	0.00
LESS DISCOUNT (NETT-20 %)		1427.48	0.00	0.00	0.00
GRAND TOTAL		5709.92	0.00	1000.00	0.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ7360U

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
OVERALL TOTAL		6709.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLJ7360U

TOTAL LABOUR CHARGES	5170.00
TOTAL SPARE PARTS CHARGES	6709.92
GRAND TOTAL	11879.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

Not Notified
Resurvey B4 painting
4 days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: