

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG18018095/GKA3Q2**Date:** 08/04/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800069586
Claimant
Vehicle No : SJU1785H **Insured Vehicle No :** SMF618H
Date of Loss: 02/10/2018 Nature of Claim: TP Claim No: 7905693510SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU1785H**
Make & Model: HONDA CIVIC, 2.0 L (A) Engine No: K20Z24500863
Reg. Date: 23/11/2009 (Man. Year: 2008) Chassis No: JHMF26409S200864
Colour: White Odometer: 64800 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,377.44	312.48	2,064.96	86.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	650.00	1,140.00	63.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,167.44	962.48	3,204.96	76.90
+ Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$)		513.60		
		(S\$) 1,476.08		
Liabile Amount (50.00%) (S\$)		738.04		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		740.04		
Global Sum Settlement (S\$)		740.00		

INSPECTION

Date of Assignment: 04/10/2018
Date Inspected: 05/10/2018 Inspected At: Autoworx House - Sin Ming (HQ)
176 SIN MING DRIVE #02-01
Singapore 575721
Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Repair	578.60 FL	*- FL
2	1		*FRONT DOOR	Repair	978.10 FL	*- FL
3	1		*FRONT DOOR PROTECTOR	Cut	276.40 FL	*126.00 FL
4	1		*FRONT DOOR PROTECTOR MOULDING	Necessary	195.70 FL	*87.00 FL
5	1		*SIDE MIRROR ASSY	Repair	765.40 FL	*- FL
6	1		*SIDE MIRROR SIGNAL	Scratched	177.60 FL	*177.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,971.80	390.60
- List Item Discount on L Items 20.00/20.00% (S\$)	594.36	78.12
Total Parts (S\$)	2,377.44	312.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	800.00	200.00
2	TO CHECK WIRING SYSTEM	New	40.00	0.00
3	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	100.00	0.00
4	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	850.00	450.00
Gross Labour Cost (S\$)			1,790.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >