

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG18018192/R1CBS2**Date:** 31/10/2018REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100477162
<b>Claimant Vehicle No :</b>	SLH7759P	<b>Insured Vehicle No :</b>	SLE8128U
Date of Loss:	03/10/2018	Nature of Claim:	TP
		Claim No:	9505637377SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLH7759P</b>	Engine No:	CAX873155
Make & Model:	AUDI A3, 1.4 TFSI (A)	Chassis No:	WAUZZZ8P3CA031581
Reg. Date:	20/09/2011 (Man. Year: 2011)	Odometer:	18073 km
Colour:	Grey		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	16/10/2018	
Date Inspected:	17/10/2018	Inspected At: CarCrafters Singapore Pte Ltd (HQ) 48 Toh Guan Road East, #05-155 Enterprise Hub Singapore 608586
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Broken	0.00 F	*- F
2	1		*FRT BUMPER	Cut	0.00 F	*- F
3	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*FRT BUMPER SPONGE	*Check	0.00 F	*- F
7	1		*FRT LH BUMPER FOG LAMP COVER	*Check	0.00 F	*- F
8	1		*FRT RH BUMPER FOG LAMP COVER	*Check	0.00 F	*- F
9	1		*FRT LH BUMPER FOG LAMP	*Check	0.00 F	*- F
10	1		*FRT RH BUMPER FOG LAMP	*Check	0.00 F	*- F
11	1		*FRT GRILLE	Broken	0.00 F	*- F
12	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
13	1		*FRT SUPPORT PANEL	*Check	0.00 F	*- F
14	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
15	1		*FRT RH HEADLAMP ASSY	*Check	0.00 F	*- F
16	1		*BONNET	Bent	0.00 F	*- F
17	1		*BONNET LOCK	Bent	0.00 F	*- F
18	1		*AIR CON CONDENSER	*Check	0.00 F	*- F
19	1		*RADIATOR	*Check	0.00 F	*- F
20	1		*FRT LH FENDER	Dented	0.00 F	*- F
21	1		*REAR BUMPER	Dented	0.00 F	*- F
22	1		*REAR BUMPER LOWER	Dislodged	0.00 F	*- F
23	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
24	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
25	1		*REVERSE SENSOR	Cut	0.00 F	*- F
26	1		*REAR END PANEL	Repair	0.00 F	*- F
27	1		*REAR END PANEL TOP GARNISH	Dislodged	0.00 F	*- F
28	1		*REAR LH TAILLAMP	*Check	0.00 F	*- F
29	1		*REAR RH TAILLAMP	*Check	0.00 F	*- F
30	1		*BOOTLID RUBBER / WEATHERSTRIP	Cut	0.00 F	*- F
31	1		*TAILGATE	Dented	0.00 F	*- F
32	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
33	1		*TAILGATE LAMP N/S	Dislodged	0.00 F	*- F
34	1		*TAILGATE GLASS RUBBER	Necessary	0.00 F	*- F
35	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
36	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
37	1		*TAILGATE RUBBER	Bent	0.00 F	*- F
38	1		*TAILGATE INNER BOARD	*Check	0.00 F	*- F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >