



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004752
INV Date 06/07/2020
Reference CC4/LPC18018198/Kka3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. FBF 3126X
Insured Veh. GY 7797Z
Claim No. 18/18/18/VC05/020989
Policy No. Z18VC05000234
Accident Date 04/10/2018
Inspection Date 09/10/2018

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18018198/Kka3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 06-07-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 7797Z	Veh. Inspected	FBF 3126X
Policy No.	Z18VC05000234	Coverage (\$)	0.00
Claim No.	18/18/18/VC05/020989	Excess (\$)	0.00
Assign From	GERALD	Assign Date	08/10/2018

2. Vehicle Particulars & Condition

Make & Model	YAMAHA FZ	c.c	153
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	ME121605282028817	Colour	MULTI COLOUR
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80 R17	SUPERSPORT	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	130/70 R17	SUPERSPORT	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR, FRONT PORTION AND O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/10/2018	Inspection Date	09/10/2018
Survey held at	176 SIN MING DRIVE #03-21		
Repairer	AUTOWERKE AUTOMOTIVE PL		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 3126X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	TO REPAIR SEE LABOUR	450.00	-
1	FRONT RH SIDE FAIRING	NO SUCH PARTS	755.00	-
1	FRONT RH SIDE FAIRING LOWER GARNISH	SERVICEABLE	650.00	-
1	FRONT RH SIGNAL LAMP	CRACKED	65.00	65.00
1	FOOTREST RH	DENTED	294.00	294.00
1	FOOTREST GRIP RH	TORN	130.00	130.00
1	FOOTREST BRACKET	DISTORTED	259.00	259.00
1	FRONT HEADLAMP FAIRING	TO REPAIR SEE LABOUR	900.00	-
1	FRONT HEADLAMP	DENTED / CUT	1,249.00	1,249.00
1	HEADLAMP FAIRING BRACKET	TO REPAIR SEE LABOUR	210.00	-
1	BRAKE LEVER	BENT	240.00	240.00
1	HANDLE BAR	DISTORTED	690.00	690.00
1	HANDLE BAR BALANCE	DENTED	200.00	200.00
1	FRONT FORK LH	TWISTED	850.00	850.00
1	FRONT FORK RH	TWISTED	850.00	850.00
1	FRONT FORK BRACE	SERVICEABLE	450.00	-
1	STEERING CONE AND BEARING	NECESSARY	520.00	520.00
1	SET WING MIRROR	CRACKED	120.00	120.00
1	REAR RH FAIRING	CRACKED	690.00	690.00
1	REAR RH FAIRING INNER GARNISH	CRACKED	350.00	350.00
1	REAR RH SIGNAL LAMP	BROKEN	65.00	65.00
1	FUEL TANK	BENT	800.00	800.00
1	SWING ARM	SERVICEABLE	1,200.00	-
1	REAR SHOCK ABSORBER	SERVICEABLE	610.00	-
1	EXHAUST PIPE	DENTED	750.00	750.00
1	EXHAUST CHROME PROTECTOR COVER	BROKEN	450.00	450.00
	LESS 10% DISCOUNT		-1,379.70	-857.20
			12,417.30	7,714.80

Report Ref No. CC4/LPC18018198/Kka3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	GEAR SHIFT SHAFT OIL SEAL (SN) (50%)	NECESSARY	120.00	60.00
2	FORK OIL SEAL LH/RH (SN) (50%)	NECESSARY	90.00	45.00
2	FORK OIL SEAL LH/RH (SN) (50%)	NECESSARY	65.00	32.50
1	REAR BOX (SN)	MISSING	550.00	200.00
1	REAR BOX BRACKET (SN)	TO REPAIR SEE LABOUR	250.00	-
1	RIM (SN)	TO REPAIR SEE LABOUR	700.00	-
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	80.00	-
1	REAR NUMBER PLATE (SN)	DENTED	80.00	18.00
			1,935.00	355.50
	<u>LABOUR</u>			
	LABOUR .INCLUSIVE OF THE REPAIR OF FRONT FENDER,FRONT HEADLAMP FAIRING,HEADLAMP FAIRING BRACKET,REAR BOX BRACKET AND RIM .		800.00	200.00
	SPRAY PAINTING .	NOT NECESSARY	900.00	-
	BODY ALIGNMENT.		650.00	180.00
			2,350.00	380.00
GRAND TOTAL			16,702.30	8,450.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC4/LPC18018198/Kka3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 3126X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 3126X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 3126X

RE-INSPECTION

