

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18018214/KPA3Q2

Date: 15/04/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00003971-01

Claimant
Vehicle No : SLR9676D **Insured Vehicle No :** SJF5581G

Date of Loss: 04/10/2018 **Nature of Claim:** TP **Claim No:** 1201800012824

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR9676D		
Make & Model:	HONDA GRACE, 1.5 HYBRID DX CVT ABS D/AIRBAG (A)	Engine No:	HIDDEN
Reg. Date:	31/08/2017 (Man. Year: 2017)	Chassis No:	GM41105469
Colour:	Metallic Black	Odometer:	0 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Kumho 7 mm	Rear Left Side:	Achilles 9 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Achilles 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,333.96	3,032.48	301.48	9.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	1,960.00	1,180.00	37.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,473.96	4,992.48	1,481.48	22.88
+ GST 7.00/7.00% (S\$)	453.18	349.47	103.71	22.88
Nett Amount (S\$)	6,927.14	5,341.95	1,585.19	22.88
+ Loss of Use (8.0 x S\$75.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,943.95		

INSPECTION

Date of Assignment: 08/10/2018

Date Inspected: 09/10/2018 **Inspected At:** ComfortDelGro Engineering Pte Ltd
(Braddell)
205 Braddell Road
Singapore 579701

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Sep 2019)
Parts:	192	HONDA GRACE 1.5 HYBRID DX CVT ABS D/AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR9676D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE WITH CASING	Serviceable	45.00 FS	*- FS
2	1		*REAR BUMPER	Buckled	937.00 FL	*937.00 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Distorted	13.90 FL	*13.90 FL
4	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	13.90 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
6	1		*BOOTLID	Bent	675.20 FL	*675.20 FL
7	1		*BOOTLID HINGE LH (NPA)	Repair	0.00 FL	*- FL
8	1		*BOOTLID HINGE RH (NPA)	Repair	0.00 FL	*- FL
9	1		*BOOTLID LOCK (NPA)	Repair	0.00 FL	*- FL
10	1		*BOOTLID EMBLEM LOGO H	Necessary	27.10 FL	*27.10 FL
11	1		*BOOTLID EMBLEM GRACE	Necessary	45.00 FL	*45.00 FL
12	1		*BOOTLID EMBLEM HYBRID	Necessary	58.00 FL	*58.00 FL
13	1		*BOOTLID CHROME MOULDING	Dented	165.00 FL	*165.00 FL
14	1		*BOOTLID CHROME MOULDING CLIPS (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*BOOTLID LAMP LH	Dented	306.70 FL	*306.70 FL
16	1		*BOOTLID LAMP RH	Serviceable	306.70 FL	*- FL
17	1		*TAILLAMP LH	Cracked	381.70 FL	*381.70 FL
18	1		*TAILLAMP RH	Cracked	381.70 FL	*381.70 FL
19	1		*REAR END PANEL	Bent	323.90 FL	*323.90 FL
20	1		*REAR END PANEL TOP GARNISH	Cracked	86.40 FL	*86.40 FL
21	1		*REVERSE SENSOR	Shorted	280.00 FS	*280.00 FS
					Sub Total (S\$)	4,086.20 3,720.60
					- List Item Discount on L Items 20.00/20.00% (S\$)	752.24 688.12
					Total Parts (S\$)	3,333.96 3,032.48

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER BOOTLID PARTS AND MECHANISMS TO NEW BOOTLID	New	250.00	80.00
2	LABOR CHARGES TO REPAIR ,PANEL BEAT AND TO REPLACE REAR DAMAGED PARTS ,BOOTLID ,REAR BUMPER ,REAR END PANEL AND AFFECTED AREAS	New	1,200.00	720.00
3	TO CHECK WIRING FUNCTIONS	New	120.00	20.00
4	TO INSTALL REVERSE SENSOR	New	120.00	80.00
5	TO PUTTY AND SPRAY PAINT REAR BUMPER,BOOTLID ,REAR END PANEL AND AFFECTED AREAS	New	1,250.00	1,000.00
6	TO APPLY RUST PROOFING ON REPAIR AND REPLACE PANELS	New	200.00	60.00
Gross Labour Cost (\$\$)			3,140.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >