

and the second s

### 205 Braddell Road S(579701)

## ACCIDENT REPAIR ESTIMATE

Our Ref:			
Type of Claim:	TP	Vehicle No.	: SLR9676D
		Make & Model	: HONDA GRACE 1.5 HYB CV
		Year of Manufacture	: 2016
		Chassis No.	: <b>GM41105469</b>
Ins Company :	AIG / FWD	Engine No.	:
Excess :		Policy No.	
Date of Accident :		Time of Accident	:
Suggested Days of Repair :		In-house Vehicle Assesso	<u>or</u>
Repair Estimate		Case Owner	Andrew
Parts (a) Cost / List Price Items	<u>s</u> -	Signature  Contact No	:
Plus/Less 20%	<u> </u>	Frt Counter Operation 6383 7466 - Patrick Tia	
Total of Cost / List	<u>s</u>	6383 7730 - Brenda Ng	
(b) Nett Price Items	<u>s</u> -	6383 7890 – Rohani braddell_cr@sparkcarcare.c	<u>com</u>
Less	<u>s</u> -	Workshop Operation 63837656 - Ngo Toh Wee	
Total of Nett Item	<u> </u>	63837362 - Andrew Goh	
(c) Special Nett Items	<u>\$ 45.00</u>	63838115 - William Wang	
Total Parts Cost (Appendix A)	\$ 45.00	braddell operation@sparke	arcare.com
Labour (Appendix B)	\$ 3,140.00		
Total Repair Cost	\$ 3,185.00		
The above total will be subjected	to 7% G.S.T.		
Name of Surveyor	÷		
Company			
Survey conducted on			
Remarks By Surveyor			
(a) The repair of this vehicle is	s authorized / is not authoriz	ed until further notice.	
(b) Recommended Days of Re	-		
(c) Resurvey	: Required / Not	Required	
(d) Excess	:\$		
(e) Signature of surveyor	•	Dota	

ACCIDENT REPAIR ESTIMATES F3

## Spark Car Care

#### ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

#### Spare Parts

Vehicle No	: <u>SLR9676D</u>	Case Owner	: Andrew
Make & Model	: HONDA GRACE 1.5 HYB C	Year Manufacture	: 2016
Chassis No	: GM41105469	Engine No	: 0
Sales Order	:	Supplier	:
Order By	:	Type of Claim	: <b>TP</b>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing	1		·		\$ 45.00	<u> </u>
2	Rear bumper	1					
3	Rear bumper side retainer LH	1					
4	Rear bumper side retainer RH	1					
5	Rear bumper clips	10					
6	Bootlid	1					
7	Bootlid hinge LH	I					
8	Bootlid hinge RH	1					
9	Bootlid lock	1					
10	Bootlid emblem logo H	1					
11	Bootlid emblem GRACE	1					
12	Bootlid emblem HYRBID	1					
13	Bootlid chrome moulding	1					
14	Bootlid chrome moulding clips	4					
15	Bootlid lamp LH	1					
16	Bootlid lamp RH	1					
17	Taillamp LH	1					
18	Taillamp RH	1					
19	Rear end panel	1					
20	Rear end panel top garnish	1					
21	Reverse sensor	1					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

### ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour	Ľ	a	b	0	u	r
--------	---	---	---	---	---	---

Vehicle No.	:	SLR9676D	Case Owner	1	Andrew	
Make & Model	:	ONDA GRACE 1.5 HYB CVT	Year of Manufacture	:	2016	

	oc Flore : Stable of Flore of				
S/No	Labour Description	Esimated Price	Adjusted Price		
1	To transfer bootlid parts and mechanisms to new bootlid	\$ 250.00			
2	Labor charges to repair, panel beat and to replace rear damaged parts, bootlid, rear bumper, rear end panel and affected areas	\$ 1,200.00	***************************************		
3	To check wiring functions	\$ 120.00			
4	To install reverse sensor	\$ 120.00			
5	To putty and spray paint rear bumper, bootlid, rear end panel and affected areas	\$ 1,250.00			
6	To apply rust proofing on repair and replace panels	\$ 200.00			
			4		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.