23/03/2002 ASS. REC. BY:		REF: (93/	AU1180	18217/A	C ber Special	Instruction:	
Melimin From (Person)	Chin Lee Tin	ASSI of	GNMEN ALI	T (Office		e/Time: 08 (02018	1.15pm
Estimated Cos	/TP RES / OD R		E	Bill to:			
	nicle No:	And the second s				9LL 35707 6745 7367	(
of		BIK 1 Kakı	Bulcit		#07-34		
Policy No: Sum Insured:	2100503149	t			1234-82	23063.56	
Make of Veh: (Client's Record))				D.0	03-102 W	8
CA / REV /	REP. / REV 24 18-102018 1-351	HRS W// Person Con	tacted:	Arine	H. Vehic	O.D. Endorsement:	
Date/Fime	Action/Instruction	the same of the sa	timate				
		NA/AILHISOI				DuA: 03 10 2018	
		13/10/3018					
							19.

mit.

REF: AIG

Wir	MIC.		

anisyur:	17.0				
,	ASS	SIGNMENT			
From:	Date: 11 10 3018	Veh No:	SLQ137H.	Yr Regn: 201	6 Dec.
Estimated Cost:		Type M.Car M.	Cycle / Bus / Van / L	orry / Taxi / Prime Mo	ver /
OD I TP WS I TP RES I OD RE	S/EVA/INV/MV	Truck / Tra	ailer or		
To Inspect Vehicle No:	SLQ 137 H	Make:	Menedes Ben:	z A 200 c.c	1595
at Workshop m/s	Piccise Auto	Colour	Silver.	A/C: Insured /	Std / NI / NA
of Blk 1 Kaki B	skt Ave 6 # 02-34	Sp.Reading	6115	T/Radio: Insured /	Std / NI / NA
Insured:		Eng/No:			
Policy No.		C/No:	WOD17604	327489142	-
Claims No.		Gen. Cond:	d / Fair / Poor / Burn	t	
Sum Insured:	Excess:	Steering: Ingreen	r / Jammed / Leaked	/ Burnt or	
(Client's Record)	•	Brake: Incoder	/ Jammed / Leaked	/ Burnt or	•
Make of Veh:		Modi: Nil (S/I	Rim)/ STD A/Rim o	or	
		Tyre Size:		HSRIT.	
(Policy Condition)			R: 225/4	45R17.	
Remark: The veh had commen		- 1		/ MIC / OHTSU / PIR /	SUMI /
repair at the time of i	nspection.	ТОУО / УОКО	or		
Bal. or Market Value:		Front /		Rear	,
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. 06	, mm	R/Bal.	06 mm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal. 96	mm	L/Bal.	06 mm
Est. Repairs:	lays Res.: Yes or No	D.O.A.	- 0.	D.O.I. 11/1	10/18
Lum Sum: . 9	6 3 Val.: Yes or No	Survey held at	riec	ise.	
CA / REV / REP. / 24 F	irs lup		Frty Par 1 0/s	/ N/S / U/C / Rooft	op or
Date: Person C	Vehicle: IN / OU			y Structure affected of	due to collision.
Date / Time Action / Instru					
TP 416	PRS.				•
	DESCRIPTION OF	007 0010			
, W. ! !!	OK RECEIVED 15	OCT 2018			
	2K				
Nett : 47.	81C				
Date/Time, File Pass to?	Preli. Report	Days Of Repair	: 9		
1)	Final Report	Resurvey No. o	of Trip:	Survey Fee:	180
Date/Time, File Return to?				Transportation:	
2)	Add Fe)S +RS,SI	
		: Interview) Photos	22
Report Format: DR	R.	: Tech. In) Others	20
Lump Sum / I.B.I: (\$)	: Weeken	d (\$)	F2

200

TOTAL

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC... Page 1 of 1

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL3570X AND SLQ137H ON 03/10/2018

From

To

assignments@lkkauto.com, admin-a@lkkauto.com

Cc

Fong, Andy-SY

Sent

Monday, 8 October, 2018 1:15:17 PM

Attachments:

08102018095918.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG Claims | AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Singapore 079120 Tel +(65) 6419 1947 | Fax +(65) 6835 7416 Lee-Ying.Chin@aig.com |www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



ACRA NUMBER: 200911678H

GST REGISTRATION NUMBER: 200911678H

08/10/2018

Our Ref: SLQ 137H (V) PRECISE

Your Ref: SLL 3570X

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way Tower 2 #07-16 Singapore 079120

Attn: Motor Claims Department

RIAZ QAYYUM (LLB HONS) NUS

ABDUL HALIM BIN ROSALAN (LLB HONS) UTAS

MUHD RIDHWAN ABDUL RAHIM (LLB HONS) LEEDS (ASSOCIATE)

BY FAX (6415 3727) ONLY

NOTICE OF ACCIDENT

Dear Sir

TO:

We are instructed by our client to *notify* you of a road traffic accident on <u>03 October 2018</u> at about <u>1630</u> hours along <u>PIE towards Changi</u> involving our client's vehicle registration number <u>SLQ 137H</u> and vehicle registration number <u>SLL 3570X</u> driven by you or your authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop

PRECISE AUTO SERVICE

Address

1 Kaki Bukit Avenue 6

#02-34/36 Autobay @ Kaki Bukit

Singapore 417883

Telephone no.

6745 7367

Fax no.: 6841 3390

Please let us hear from you by the stipulated time.

Yours faithfully

encs

CC

1. Client

FOR SURVEYOR

Please initial here after completion of prerepair inspection. Thank you.

Appointed surveyor (Name & signature)

Date & time of inspection



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	6833J
Vehicle Details	
Vehicle No.:	SLQ137H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Oct 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	A200 FL STYLE (R17 HLG)
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	27091031022848
Chassis No.:	WDD1760432J489142
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$25,099,00
Original Registration Date:	28 Dec 2016
First Registration Date:	28 Dec 2016
Transfer Count:	2
Actual ARF Paid:	\$22,139.00
Intended PARE Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2026
PARF Rebate Amount:	\$16,604.00
Intended COE Rebate Details	· 医多种种种种 医克里斯特斯氏性病 医神经神经病 医二氏病 医二氏病 医二氏病 医二氏病 医二氏病 医二氏病 医二氏病 医二氏
COE Expiry Date:	27 Dec 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,010.00
COE Rebate Amount:	\$45,608.00
Total Rebate Amount:	\$62,212.00

The information contained herein is correct as at 11 Oct 2018

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?





Post an Advertisement Sell it yourself! Advertise it at just

\$58 until it's SOLD!

BMW 428i Coupe A/T Luxury Edition 241Bhp At \$128K.

August 2014, Very Low Mileage At 32,000 Km With 19" Forged Alloy Sports Rims.



wse by Category		Print			The second of	Sort by Date Pos	ted ▼ 20 r	esults/page
9 vehicles	→ Search a200		ofference of the property and		٩	Advanced Search	3 Search	View All
	Make ▼ Model •	Price 🔻 🗦	Depreciation ▼	Ĉ Reg Date ▼ 💲	Eng Cap ▼	Mileage ▼	Veh Type ▼	Status
earch Selection	a200	Any	Any	2017	Any	Any	Any	Available
	Mercedes-Benz A-Class A20 Style	\$113,800	\$12,460 /yr	09-Jan-2017	1,595 cc	21,338 km	Hatchback	Availabl
0.里	This Stunning Elbaitgreen Metallic Colo Year Mercedes-Benz Pre-Owned Vehic	or Will Certainly Help	You Stand Out In	Traffic. \$2000 Reput	blic Auto Warran	ty Workshop Cred	it! Additional 1	
	Republic Auto	te transity in bull,	**					PERMIT
	Posted: L1-Oct-2018 Tags: 2017 Marcades-B	Mercedes-Benz A200, enz. A200, a200, Used	2017 mercedes-cent Mercedes-Barc	a200, Mercentro-Bers	A200 mercepts			
	Mercedes-Benz A-Class A20 Style	0 \$111,800	\$12,210 /yr	10-Jan-2017	1,595 cc	26,000 km	Hatchback	Availabl
	The Newest Mercedes A-Class Continue Example Was Purchased And Maintaine	es The Success Of It	ts Predecessor Sett	ing Benchmarks For	Design, Quality	And Technology. 1	This Sleek Black	
-	Eurokars Pre Owned	so in ojeic a como	ge- 6					
	Posted: 31-Aug-2018 Tags: 2017 Mercedes-Br	Mercedes-Benz A200, enz, A200, a200, Used	2017 mercedes-ben Mercedes-Benz	z a200, Mercedies-Beni	A200, mercedes	benz a200,		
- Allendar	Mercedes-Benz A-Class A20 Style	0 \$109,800	\$11,960 /yr	11-Jan-2017	1,595 cc	13,000 km	Hatchback	Availabl
San	Style							***************************************
	Up To 90% Loan Available Or 30% Do	wn Payment \$33k. N	Monthly \$1110 x 84	Months. New Road	Tax Until 2019.	Comes With Bidde	d 2 Digit Numbers	
(Internal		wn Payment \$33k. N t Serviced, 3 Years V	Monthly \$1110 x 84 Warrant	Months. New Road	Tax Until 2019. (Comes With Bidde	d 2 Digit Numbers	
(INSERTED	Up To 90% Loan Available Or 30% Dot Plate SK5601 1 Owner, Fully C&C Agent In-Carz Credit Pte Ltd	wn Payment \$33k. M t Serviced, 3 Years V Mercedes-tienz A200, mz, A200, a200, Used	Varrant 2017 mercedes ben				d 2 Digit Numbers	
THI COLD	Up To 90% Loan Available Or 30% Dot Plate SK5601 1 Owner, Fully C&C Agent In-Carz Credit Pte Ltd	Mercedes-flenz A200, Used	Varrant 2017 mercedes ben				d 2 Digit Numbers Hatchback	FREMUM
INCOLUMN TO THE COLUMN TO THE	Up To 90% Loan Available Or 30% Dor Plate SKS60! 1 Owner, Fully C&C Agent In-Carz Credit Pte Ltd Posted: 30-Sep-2015 Tagis: 2017 Mercodes-Benz A-Class A20	Mercedes-Bonz A200, max A200, a200, Used 0 \$106,800	2017 mercodes-beny Mercodes-Beny \$11,520 /yr	01-Feb-2017	A200, mercedes- 1,595 cc	45,000 km	Hatchback	FREMUNA
means and a second	Up To 90% Loan Available Or 30% Dot Plate SK5601 1 Owner, Fully C&C Agent In-Carz Credit Pte Ltd Posted 30-Sep-2015 Tage: 2017 Mercoden-Bi Mercedes-Benz A-Class A20i Style The Merc A200, A Young, Trendy And 3 1.6L BlueEFFICIENCY Engine Coupled V	Mercedes-Bonz A200, max A200, a200, Used 0 \$106,800	2017 mercodes box Mercodes-Bery \$11,520 /yr ombination Of Style F 2017 inercodes-box.	01-Feb-2017 e And Image That Is	1,595 cc Superbly Built. S	45,000 km	Hatchback	FREMUNA
in can d	Up To 90% Loan Available Or 30% Dot Plate SK5601 1 Owner, Fully C&C Agent In-Carz Credit Pte Ltd Posted 30-Sep-2015 Tage: 2017 Mercoden-Bi Mercedes-Benz A-Class A20i Style The Merc A200, A Young, Trendy And 3 1.6L BlueEFFICIENCY Engine Coupled V	Mercedes-Benz A200, and A200, and A200, a200, Used Sporty Hatch With Country Hatch With Smooth 7G-DCI Mercedes-Benz A200, and A200, and A200, a200, Used	2017 mercodes box Mercodes-Bery \$11,520 /yr ombination Of Style F 2017 inercodes-box.	01-Feb-2017 e And Image That Is	1,595 cc Superbly Built. S	45,000 km	Hatchback	Available
THE CAMPA	Up To 90% Loan Available Or 30% Dor Plate SKS60! 1 Owner, Fully C&C Agent In-Carz Credit Pte Ltd Pasted: 30-Sep-2015 Tags: 2017 Mercodes-Bit Mercodes-Bit Mercodes-Bit Tags: 2017 Mercodes-Bit Tags: 2017 Mercodes-Bit Tags: 2017 Mercodes-Bit Tags: 2017 Mercodes-Bit M	Mercedes-Benz A200, and A200, a200, Used 5106,800 \$106,800 Sporty Hatch With Cillian Mith Smooth 7G-DCI Mercedes-Benz A200, and A200, and A200, a200, Used	\$2017 mercodes beau Mercodes-Berv \$11,520 /yr ombination Of Style F 2017 inercodes-beru Mercodes-Berz	01-Feb-2017 e And Image That Is	1,595 cc Superbly Built. S A200, mercedes-	45,000 km Sufficiently Powered	Hatchback	FREMIUM A
THE CONTRACT OF THE CONTRACT O	Up To 90% Loan Available Or 30% Dot Plate SK560! 1 Owner, Fully C&C Agent In-Carz Credit Pte Ltd Posted: 30-Sep-2015 Tags: 2017 Mercedes-Bit Style The Merc A200, A Young, Trendy And Style Mercedes-Benz launches the all	Mercedes-Benz A200, and A200, a200, Used 5106,800 \$106,800 Sporty Hatch With Cillian Mith Smooth 7G-DCI Mercedes-Benz A200, and A200, and A200, a200, Used	\$2017 mercodes beau Mercodes-Berv \$11,520 /yr ombination Of Style F 2017 inercodes-beru Mercodes-Berz	01-Feb-2017 e And Image That Is	1,595 cc Superbly Built. S A200, mercedes-	45,000 km Sufficiently Powered	Hatchback	FREMUNA
Micanz Micanz	Up To 90% Loan Available Or 30% Dot Plate SK5601 1 Owner, Fully C&C Agent In-Carz Credit Pte Ltd Posted 30-Sep-2015 Tags: 2017 Mercodes-Bit Mercedes-Benz A-Class A201 Style The Merc A200, A Young, Trendy And 1.6L BlueEFFICIENCY Engine Coupled Vigorian Coupled	Mercedes-Benz A200, and A200, are A2	\$2017 mercodes beau Mercodes-Berv \$11,520 /yr ombination Of Style F 2017 inercodes-beru Mercodes-Berz	01-Feb-2017 e And Image That Is	1,595 cc Superbly Built. S A200, mercedes-	45,000 km Sufficiently Powered	Hatchback	Available
NCADZ	Up To 90% Loan Available Or 30% Dot Plate SK5601 1 Owner, Fully C&C Agent In-Carz Credit Pte Ltd Posted: 30-Sep-2015 Tage: 2017 Mercodes-Be Mercedes-Benz A-Class A200 Style The Merc A200, A Young, Trendy And 1.6L BlueEFFICIENCY Engine Coupled Various 28-Aug-2018 Tages: 2017 Mercedes-Be Mercedes-Benz launches the all The all new Mercedes-Benz A-Class is at Read this article Mercedes-Benz A-Class A200 Mercedes-Benz A-Class A200 Mercedes-Benz A-Class Mercedes-Ben	Mercedes-Benz A200, and A200, a200, Used 5106,800 \$106,800 Sporty Hatch With Color Mith Smooth 7G-DCI Mercedes-Benz A200, and A200, and A200, a200, Used new A-Class s youthful and dynamic and dy	\$11,520 /yr \$11,520 /yr ombination Of Style r 2017 inercedes-beru Mercedes-Beru mic as ever, but gri \$11,790 /yr	01-Feb-2017 e And Image That Is a 200, Mercedes-Benz own-up and comforta	1,595 cc Superbly Built. S A200, mercedes-	45,000 km Sufficiently Powered benz a200, efore.	Hatchback ed With It's Punchy Hatchback	Available
N CANZ	Up To 90% Loan Available Or 30% Dot Plate SK5601 1 Owner, Fully C&C Agent In-Carz Credit Pte Ltd Posted: 30-Sep-2015 Tage: 2017 Mercodes-Benz A-Class A200 Style The Merc A200, A Young, Trendy And 1.6L BlueEFFICIENCY Engine Coupled Various Posted: 28-Aug-2018 Tages: 2017 Mercodes-Benz A-Class is at Read this article Mercedes-Benz A-Class A200 Style Lady Owner, C&C Warranty, Done 2500 & In House Loan Available.	Mercedes-Benz A200, and A200, a200, Used 5106,800 \$106,800 Sporty Hatch With Color Mith Smooth 7G-DCI Mercedes-Benz A200, and A200, and A200, a200, Used new A-Class s youthful and dynamic and dy	\$11,520 /yr \$11,520 /yr ombination Of Style f 2017 inercedes-beny Mercedes-Benz mic as ever, but gro \$11,790 /yr -Free, Upgraded Al 2017 mercedes-benz	01-Feb-2017 e And Image That Is a 200, Mercedes-Beru own-up and comforta 02-Feb-2017	1,595 cc Superbly Built. S A200, mercedes-	45,000 km Sufficiently Powered benz a200, efore. 25,000 km	Hatchback ed With It's Punchy Hatchback	FREMUNA



Republic Auto Posted: 09-Gct-2018 Tags: 2017 Mercedes-Benz A200, 2017 inercedes-benz a200, Mercedes-Benz A200, mercedes-benz a200, Mercedes-Benz A200, a200, tised Mercedes-Benz.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Control Market on the	ACCIDENT STATEMENT
Date Of Report	08/10/2018 10:02
Date Of Accident	03/10/2018 16:30
Exact Location Of Accident	ALONG PIE TWDS CHANGI ,NEAR POLICE ACADEMYEXIT17D
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLQ137H
Insured/Policyholder	
Name Of Registered Owner	TAN LIAN HIANG LILIAN
NRIC No	S0186833J

 Mobile Phone No
 (LOCAL) +65-98246320

 Alternative Phone No
 OFFICE-98246320

Vehicle Particulars

Email Address

Manufacturer MERCEDES-BENZ

Model A200

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

NOEMAIL

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company GREAT AMERICAN INSURANCE COMPANY

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number MT20181318

Cover Note Number

Driver

Name of Driver TAN LIAN HIANG LILIAN

 NRIC No
 S0186833J

 Date Of Birth
 31/08/1951

 Occupation
 INDOOR

 Date Of Driving Pass
 25/08/1981

Driving Experience 37 YEARS AND 1 MONTH

Gender FEMALE

Mobile Number (LOCAL) +65-98246320

Fax Number

Contact Number OFFICE-98246320

EMail Address NOEMAIL

Address

2C LANGSAT RD

Postcode

426790

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

YES

Was any body injured in the Accident?
Was any injured conveyed to hospital by

YES

ambulance?

LO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLL3570X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

WWJ7899

Vehicle Make/Model/Colour

1.

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKP308Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

82008343

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SLT7853L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number

SGS773U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

TAN LIAN HIANG LILIAN Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLQ137H

Were seat belts worn?

YES

Was this injured conveyed to hospital by

ambulance?

YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering processing, handling and/or dealing with my daims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers Tawyers/Taw firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore. for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - .10. to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

If for complying with requirements under any regulations, tawn or court circless

Followholde adaptation thate & I mie Driver's Signature

(Utriver is not the pull-violater)

thre & Time

Topporting Storing Theosomet's Signature

NEID ETCH

Sketch Plan #2

EXIT TO TO TO TO POLICE Academy Along P

(A) SLQ 137 H
(B) SLL 3570X
(C) WWJ 7899
(D) SKP 3082
(E) SLT 7853L
(F) SGS 793U.

Along PIE TOWARDS Changi

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03 Det 2019 @ about 1830hrs, locas driving my car (SLQ 137 H)
dong PIE Towards change (Hear Frit to Thoman Road, Ton Paych, Old Police
Academy). In extreme Fight lane . Whicle Inhorst of me has stopped, so i
Slow drawn a step in time too. Subjectly i felt an impact from behind, due
to the high impact, my car being peched furnard and collisted onto near ports
of wehicle infront of me, soon the next impact from behind and collidad onto
rear parties of my corr again I then come out to inspect my rar se i realized
that i was involving 6 tags chain adistan accident. My mobile phone was
smolled after the impact from this accident so I borrow a mobile phone
from vehicle D(Stp 308 2)'s driver to contact my son and try to capture
some necident scene photos. However, I was flamped after that and
conveyed to Tan Tack Sen Hospital by ambiliage I was discharge from
hospital on dated 05-10-2018 and was given 17 days MC. I hereto ladge
this report to dribe acquist behille BTS LL 35 to x)'s Insurance for my acciden
drawages telegino dismages, medical or punjes & logury. Here with attached my
mobile place I downed photos, hospital dischare amount & me how
Insurance claim purposo
PS: My car still inside T.P compand, pending for release

DECLARATION

Over declare the foregoing perticular, and thus in every respect

Function

Support Sensitive

University Sensitive

Case & Lime

Support Sensitive

Sup

Page 6 of 12

IVAC	INC	Item	CO	NIA	di
1001	991886	Frt Number Plate	DD		F)
1002	991887	Frt Number Plate Base	- 00	+	4
1003	991889	Frt Number Plate Garnish	BR	1	1
1004	991300	Frt Bumper	CRI		-
1005	992341	Frt Bumper Clips	NEC	· V	7
1006	991325	Frt Bumper Bracket	1100	1	+
1007	991462	Frt Bumper Side Retainer		+	+
1008	991433	Frt Bumper Reinforcement	RIT	9.7	+
1009	991318	Frt Bumper Beam	R.T	17	+
1010	991468	Frt Bumper Sponge	TN	Ť	+
1011	991427	Frt Bumper Protector	17.18	+	+
1012	991420	Frt Bumper Pad	+	+	+
1013	991363	Frt Bumper Grille	BR.	1	/
1014	991301	Frt Bumper Moulding	W.B.	+	+
1015	991407	Frt Bumper Lower Spoiler	1	+	+
1016	991438	Frt Bumper Sensor	+-	+	+
1017	995100	Frt LH Bumper Fog Lamp Cover	-	+	+
1018	991355	Frt RH Bumper Fog Lamp Cover	+	+	+
1019	995079	Frt LH Bumper Fog Lamp	-	+	+
1020	995080	Frt RH Bumper Fog Lamp	-	+-	+
1021	991793	Frt Grille	CO	1	+
1022	991328	Frt Grille Emblem	CRI	V	+
4. 77.77.74	991799	Frt Grille Chrome Moulding	NEC	W	1
1024	991222	Frt Apron Panel	CRA	V	1
1025	992013	Frt Support Panel		⊢	+
1026	992025	Frt Support Panel Top Garnish Cover	-	-	1
1027	992416	Home Cover	_	1	1
1027	001277	Frt Brace Panel		_	1
1020	005157	Frt LH Headlamp Assy		_	4
1030	001921	Ent PH Headlamp Assy	CUT	V	1
1030	005000	Frt RH Headlamp Assy Fr: LH Side Lamp			L
1031	005090	Fri RH Side Lamp			
1032	990248	Pri KH Side Lamp			
1033	990248	Bonnet			
1034	000202	Bonnet Emblem Bonnet Lock		L.	1
1033	000207	Bonnet Insulator			
1030	000272	Bonnet Insulator			
1037	990273	Bonnet Hinge Bonnet Damper		_	L
1030	000305	Bonnet Rubber			┖
1030	0000353	Bonnet Cable			L
1041	000211	Bonnet Cable			
042	990311	Bonnet Stand Air Con Condenser			
043			BT	V	1
044	990122	Air Con Fan Assy			
045	990134	Air Con Suction Pipe (Low Pressure)			
_	990118	Air Con Suction Hose			
046	990133	Air Con Discharge Pipe (High Pressure)			
047	000130	Air Con Discharge Hose			
048	990149	Air Con Liquid Pipe			
049	990066	Air Con Receiver Drier		*	
050	990111	Air Con Compressor Assy			
051	995294	Air Con Belt			
	995074		NN	X	
053	992/38	Radiator Cowling			
054	992742	Radiator Fan Assy	CRA	V	-
055	992745	Radiator Fan Clutch			
056	992758	Radiator Hose Top			
057	992757	Radiator Hose Bottom			
058	992741	Radiator Expansion Tank			-
059	990151	Air Duct			-
060	990070	Air Cleaner Assy .		-	-
061	990056	Air Cleaner Hose		-	-
		Air Cleaner Resonator			-
		Frt Exhaust Manifold		-	-
				_	_
065	001054	rt Exhaust Manifold Cover	BT.	R.	X
000	001714	rt Exhaust Manifold Sensor (Oxygen)			
066	991714	ront Exhaust Pipe	i		
067	990219 [Battery		-	
068	990224 E	Battery Cover			
3/23 1	990223 [1	Battery Bracket			
069 070 0		Battery Tray			

		Vehicle No: SLO	137	H	
NAC		Item	co	NA	clo
1071	992205	12 430 200		7	-
1072	994011	Relay Box	1	+	+
1073	995053	Wiper Washer Tank		+	+
1074	995052	Wiper Washer Tank Motor	_	+	+
1075	990159	Alternator Assy		+	+-
1076	990160	Alternator Belt	_	+-	+
1077		Power Steering Pump	+-	+	+
1078	992669	Power Steering Belt	-	-	+
1079	004431	Power Steering Belt	_	_	_
	002602	Power Steering Cooler Pipe	-	_	
1000	992092	Power Steering Hose		_	
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			1
1085	991011	Engine Under Cover	TN	10	
1086	.990946	Engine Mounting	11.0	1	+
1087	990949	Engine Mounting Frt	_	1	1
1088	. 990950	Engine Mounting LH	1	+-	-
1089	990952	Engine Mounting RH	_	-	1
1090-	990951	Engine Mounting Rear	+	+	-
1091	992234	Gear Box Mounting	+	+	-
1092	991520	Frt LH Chassis Member	-	+	-
1003	001520	Frt RH Chassis Member	-	-	_
1004	991320	Pet Vertical Country	-	+	_
1005	001042	Frt Vertical Cross Member	-	-	_
1095	331803	Frt Lower Cross Member	-		_
		Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147.	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
		Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover		1	
1104	995065	Frt LH Tyre			_
-1105	995071	Frt RH Fender	1		
		Frt RH Fender Inner Panel	1	\vdash	
1107	991744	Frt RH Fender Lamp	+-	-	
1108	991752	Frt RH Fender Protector	-	-	-
		Frt RH Fender Inner Shield	14	-	-
1110		Frt RH Mudflap	-	-	_
1111			-	_	
		Frt RH Wheel Rim	-	-	
1112	994025	Frt RH Rim Cover		_	
1113		Frt RH Tyre			
1114		Frt Windscreen Glass			
1115		Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding	= 1		
1117		Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119		ERP Unit			
1120		Frt Wiper Arm			
1121	992142	Frt Wiper Blade	1		
1122	995045	Wiper Panel Garnish	1		#
1123	991126	Firewall Panel	W	(V)	J.
1124		Dashboard Assy	1-17	~	-
1125		Glove Box Cover		-	_
1126			1-4	-	_
		Glove Box Compartment	1	1	-
		Steering Wheel Airbag	12	10	12
1128		Steering Wheel Airbag Sensor	13	1	1
1129		Dashboard Airbag			
1130		Dashboard Airbag Sensor			
1131		Airbag Control Unit			
		Frt Driver Seat	T		
-		Frt RH Seat Belt Assy	 	-	-
1134			-	-	
		Frt Passenger Sent			
		Frt LH Seat Belt Assy.			
		Sticker ·		_	
	Frt	tow hook cover	MJS	V	
	Er+_	bumper Emblem	NEC	V	a=10.5
	Inter	(BO lav	BT	1	STEP CO.
	1111111111	CERT THEY			

Mo of Items: 20

Agressor: _____

Tatim lim 15/10/18

MOTORCAR (Rear)


(1)Replace(√) (2)Repair() (3)Check €)
(4)Not Consistent ಔC)

Vehicle No: SLQ 1374

NAC	-INC	Item	CON	AC	Qt
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
		Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	J	
1142	993085	Rear Bumper Upper	-		
1143	993017	Rear Bumper Lower	CRA	V	\Box
		Rear Bumper Side	1	Ť	
		Rear Bumper Tow Cover	1	_	\vdash
		Rear Bumper Clips	1		
		Rear Bumper Bracket	-	-	\vdash
1148		Rear Bumper Side Retainer	BT	7	\vdash
	993045	Rear Bumper Reinforcement	DI	_	-
1150	002070	Rear Bumper Beam	-	-	-
1151	992970	Rear Bumper Sponge	ar	17	╌
1152	992999	Rear Bumper Damper	MI	V	\vdash
1153	003040	Rear Bumper Protector	-	-	-
1154	002026	Para Bulliper Frotector	-	-	-
		Rear Bumper Pad	-	-	-
		Rear Bumper Moulding	-	-	-
1156		Rear Bumper Reflector		_	_
1157		Rear Bumper Lower Spoiler		1	
1158		Reverse Sensor	MIS	1	1
1159		Rear End Panel		_	-
1160	993339	Rear End Panel Top Garnish		_	-
		Rear End Panel Inner Trim	-	_	1
	990333	Boot Compartment Inner Trim	-	<u> </u>	-
1163	993851	Rear LH Taillamp		_	_
1164	993853	Rear LH Taillamp Gamish			_
1165	993859	Rear LH Taillamp Panel			_
1166	995116	Rear RH Taillamp	_	Ļ	_
		Rear RH Taillamp Garnish			
		Rear RH Taillamp Panel			_
		Rear Apron Panel			_
	992895				_
		Bootlid Emblem			
		Bootlid Handle		_	1
		Bootlid Moulding	-	1	1
		Bootlid Reflector			_
		Bootlid Lamp LH		_	_
176		Bootlid Lamp RH			-
1177		Bootlid Lock	-	L	
1178		Bootlid Rubber 4	1		_
1179		Bootlid Hinge	_		_
1180	993877	Bootlid Spoiler	1		
1181		Tailgate	DD	V	T
1182	991328	Tailgate Emblem	NEC	V	3
1183		Tailgate Outer Handle			T
1184	994640	Tailgate Moulding		1	
1185		Tailgate Garnish		T	T
1186		Tailgate Reflector			T
1187		Tailgate Lamp		T	T
1188		Tailgate Protector			1
1189		Tailgate Wiper Aim		1	T
1190	994677	Tailgate Wiper Blade			T
1191		Tailgate Wiper Nozzle	1	+	+
1192		Tailgate Wiper Motor		1	+
1193		Tailgate Glass	-	+	+
			-	+	+
		Tailgate Glass Rubber	-	-	+
		Tailgate Glass Moulding	NEC	-	1
		Tailgate Glass Sealant	NE	V	1
		Tailgate Lock	BT	V	1
		Tailgate Rubber	cul	1/	1
1199		Tailgate Hinge		1	1
1200	994594	Tailgate Damper	di. n		
1201		Tailgate Inner Board			1

MAGI	INC	Ttom	CON	AC	Ot
			COL		X.
1202	993784	Spare Tyre Board	-		-
		Spare Tyre Panel			⊢
		Spare Tyre			<u> </u>
1205	994326	Spare Tyre Lock Screw		_	-
1206	993787	Spare Tyre Cover		_	_
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
		Antenna			
		Centre Exhaust Pipe Assy			
				-	-
		Centre Exhaust Mounting	_	-	-
		Rear Exhaust Pipe		_	<u> </u>
1213	993357	Rear Exhaust Chrome Pipe			_
1214	993361	Rear Exhaust Mounting		_	1
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
		Rear LH Fender Protector			Т
		Rear LH Fender Inner Panel			
					1
1441	993431	Rear LH Fender Inner Trim	-	-	-
1222	993415	Rear LH Fender Inner Garnish	_	-	-
1223	993425	Rear LH Fender Inner Shield	-	-	-
1224	993621	Rear LH Mudflap	-	-	\vdash
1225	993933	Rear LH Wheel Rim		\vdash	\vdash
1226	994025	Rear LH Rim Cover		-	⊢
1227	995065	Rear-LH Tyre	-	-	-
1228	993456	Rear RH Fender		_	1
1229	993450	Rear RH Fender Protector		_	_
1230	993420	Rear RH Fender Inner Panel			_
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			Γ
		Rear RH Fender Inner Shield			
		Rear RH Mudflap		Г	
		Rear RH Wheel Rim			
1236	004025	Rear RH Rim Cover		\vdash	1
1237	995065	Rear RH Tyre		T	1
1238	005162	Rear Fender Extension Panel LH	_	T	†
		Rear Fender Extension Panel RH		-	1
1239	993471	Rear Fender Inner Top Gamish	-	+	+
1240	993430	Rear Fender liner 100 Gamisi	-	+	╁
1241	993673	Rear Fender 1/4 Glass	-	+-	╁
1242	993452	Rear Fender 1/4 Glass Rubber		⊢	╀
1243	993453	Rear Fender 1/4 Glass Sealant	-	\vdash	╀
1244	993949	Rear Windscreen Glass	-	+	╀
1245	993976	Rear Windscreen Rubber	-	-	-
1246	993961	Rear Windscreen Moulding		_	_
1247	993955	Rear Windscreen Sealant	1_	_	1
1248	994729	Third Brake Light			1
		Rear Fender Air Grille	1		1
		Fuel Lid			
		Fuel Neck			T
		Fuel Tank		T	T
		Fuel Tank Bracket	1	1	1
1233	002101	Fuel Tank Float	1	T	T
			1	+	+
¥11/36)	990247		100	+	1
	TOW	haste tower	CUT	14	+
		_		1	1
		1 0 1			
		mich			T
		1 / X		T	T
		1 //	1	1	
		1 the tests	228	7	+
		12/10/2	411	-	+
		\	+-	+	+
	7		-	+	+
-				1	1

TGUM



...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Main	08 Oct 2018 Edit Reg		08 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estima	tes S\$0	ew Rpt		Pending for Report Cancel Case	1
,	Main	R	eference	Clair	n Details	\neg	Documents		Show All
CLAIM SU	BFOLDER DE	TAILS				[Created	by adjuster]		
Insured:	YEO CHE	KWANG, ID: S	8500765C			***************************************			
Main Claimant:	TAN LIAN	HIANG LILIAN,	ID: S0186833J						
Vehicle Reg No.:	SLQ137	н		Da	te of Loss:		3 16:00 - :59 s and 5 Days From	LTA Reg Date	(Man Yr)]
Claim Type:	TP / 123	4823063SG			licy/Cover te No.:	210050314	7 (Comprehensive	e)	
Vehicle Reg. No. (Insured):		SLL3570X							
				Ex	cess:				
Repairer:	_		No 1 Kaki Bukit Av		A STATE OF THE PARTY OF THE PAR	Control of the Contro	In the state of th		
Handling Insurer:	AIG Asia Yusoff@aig		e Pte. Ltd. (Expre	ss) - Tel: 65-64	19-3000	[Handled b	y Syed-Yusoff, S	ialiha] Saliha.S	yed-
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Ha	andled by X	ING GUO Q	IANG] [Final	Rpt due 18/	10/2018]
Claimant's Solicitor:	RIAZ LLC	- Tel: 65340110							
ASSOCIAT	ED MAIL RE	CEIVED					Viev	w All Compo	se Case Mail
AIG_SG	(10/10/2018)	Request to uplo	oad TP GIA Report	ta l					
ALL ASSO	CIATED TAS	sks⊟			,	View All S	Search Tasks C	reate New Task	Complete
Due Date No results.	Priority	Type Task	Group Subjec	t Handler	Assign	ned By	Completed On	Created C	n Done?

Claim Documents

*SLQ137H (1234823063SG)

[SLL3570X]

TP

TAN LIAN HIANG LILIAN

Oct 3 2018 4:00PM

[YEO CHEE KWANG]

Precise Auto Service

Pho	otos/Images		3 per	page 🔻	~
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
1	12/10/18 11:35	General View	0	Load JPG	V
2	12/10/18 11:35	General View	0	Load JPG	✓
3	12/10/18 11:35	General View	0	Load JPG	V
4	12/10/18 11:35	General View	0	Load JPG	V
5	12/10/18 11:35	General View	0	Load JPG	V
6	12/10/18 11:35	General View	0	Load JPG	~
7	12/10/18 11:35	General View	0	Load JPG	~
8	12/10/18 11:35	General View	0	Load JPG	4
9	12/10/18 11:35	General View	0	Load JPG	~
10	12/10/18 11:35	General View	0	Load JPG	V
11	12/10/18 11:35	General View	0	Load JPG	V
12	12/10/18 11:35	General View	0	Load JPG	~
13	12/10/18 11:35	General View	0	Load JPG	V
14	12/10/18 11:35	General View	0	Load JPG	~
15	12/10/18 11:35	General View	0	Load JPG	4
16	12/10/18 11:35	General View	0	Load JPG	~
17	12/10/18 11:35	General View	O	Load JPG	~
18	12/10/18 11:35	General View	0	Load JPG	V
19	12/10/18 11:35	General View	0	Load JPG	~
20	12/10/18 11:35	General View	0	Load JPG	V
21	12/10/18 11:35	General View	0	Load JPG	✓
22	12/10/18 11:35	General View	0	Load JPG	V
23	12/10/18 11:35	General View	0	Load JPG	✓
24	12/10/18 11:35	General View	0	Load JPG	~
25	12/10/18 11:35	General View	0	Load JPG	V
26	12/10/18 11:35	General View	0	Load JPG	✓
27	12/10/18 11:35	General View	0	Load JPG	V
28	12/10/18 11:35	General View	0	Load JPG	V
29	12/10/18 11:35	General View	0	Load JPG	V
30	12/10/18 11:35	General View	0	Load JPG	V
31	12/10/18 11:35	General View	0	Load JPG	~
32	12/10/18 11:35	General View	0	Load JPG	V
33	12/10/18 11:35	General View	0	Load JPG	✓
34	12/10/18 11:35	General View	0	Load JPG	V
35	12/10/18 11:35	General View	0	Load JPG	V
36	12/10/18 11:35	General View	0	Load JPG	~
37	12/10/18 11:35	General View	0	Load JPG	V

	tos/Images		3 per page	· \
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	-
38	12/10/18 11:35	General View	1 Load JPC	14
39	12/10/18 11:35	General View	1 Load JPC	¥
40	12/10/18 11:35	General View	1 Load JPC	₹
41	12/10/18 11:35	General View	1 Load JPC	₹
42	12/10/18 11:35	General View	1 Load JPC	
43	12/10/18 11:35	General View	1 Load JPC	V
44	12/10/18 11:35	General View	Load JPC	4
45	12/10/18 11:35	General View	1 Load JPC	₹
46	12/10/18 11:35	General View	1 Load JPC	V
47	12/10/18 11:35	General View	1 Load JPC	V
48	12/10/18 11:35	General View	Load JPG	V
49	12/10/18 11:35	General View	1 Load JPG	V
50	12/10/18 11:35	General View	1 Load JPG	
51	12/10/18 11:35	General View	1 Load JPG	-
52	12/10/18 11:35	General View	1 Load JPG	
53	12/10/18 11:35	General View	1 Load JPG	
54	12/10/18 11:35	General View	1 Load JPG	-
55	12/10/18 11:35	General View	1 Load JPG	
56	12/10/18 11:35	General View	1 Load JPG	
57	12/10/18 11:35	General View	■ Load JPG	
58				-
	12/10/18 11:35	General View	Load JPG	
59	12/10/18 11:35	General View	1 Load JPG	
50	12/10/18 11:35	General View	1 Load JPG	-
51	12/10/18 11:35	General View	1 Load JPG	-
52	12/10/18 11:35	General View	1 Load JPG	-
53	12/10/18 11:35	General View	1 Load JPG	
54	12/10/18 11:35	General View	1 Load JPG	
55	12/10/18 11:35	General View	1 Load JPG	- Beauti
66	12/10/18 11:35	General View	1 Load JPG	_
57	12/10/18 11:35	General View	1 Load JPG	V
58	12/10/18 11:35	General View	1 Load JPG	V
69	12/10/18 11:35	General View	1 Load JPG	V
70	12/10/18 11:35	General View	1 Load JPG	V
71	12/10/18 11:35	General View	Load JPG	V
72	12/10/18 11:35	General View	1 Load JPG	~
73	12/10/18 11:35	General View	1 Load JPG	V
74	12/10/18 11:35	General View	Load JPG	~
75	12/10/18 11:35	General View	1 Load JPG	V
76	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	V
77	15/10/18 14:08	Photographs of Damaged Parts	■ Load JPG	V
78	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	-
79	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	
30	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	-
31	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	-
32	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	
33	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	
34	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	
35	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	-
		Photographs of Damaged Parts	1 Load JPG	
36	15/10/18 14:08	Photographs of Damaged Parts Photographs of Damaged Parts	■ Load JPG	

Merimen e-Claims Page 3 of 6

Pho	hotos/Images 3			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	il Prir
88	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	V
89	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	V
90	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	V
91	15/10/18 14:08	Photographs of Damaged Parts	■ Load JPG	V
92	15/10/18 14:08	Photographs of Damaged Parts	♠ Load JPG	V
93	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	
94	15/10/18 14:08	Photographs of Damaged Parts	■ Load JPG	-
95	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	
96	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	-
97	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	
98	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	-
99	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	_
100	Investigation of the later of	Photographs of Damaged Parts	1 Load JPG	-
	15/10/18 14:08		1 Load JPG	-
101	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	
102	15/10/18 14:08	Photographs of Damaged Parts	The first of the second of the	-
103	15/10/18 14:08	Photographs of Damaged Parts		_
104	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	_
105	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	
106	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	-
107	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	- Factor
108	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	-
109	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	-
110	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	~
111	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	4
112	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	V
113	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	4
114	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	V
115	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	₩.
116	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	₩
117	15/10/18 14:08	Photographs of Damaged Parts	■ Load JPG	
118	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	- E
119	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	V
120	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	1
121	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	V
122	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	V
123	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	4
124	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	V
125	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	V
126	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	V
127	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	-
128	15/10/18 14:08	Photographs of Damaged Parts	■ Load JPG	V
129	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	-
130	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	1 =
131	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	
132	15/10/18 14:08	Photographs of Damaged Parts	Load JPG	
133	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	1 =
		Photographs of Damaged Parts	1 Load JPG	-
134	15/10/18 14:08		1 Load JPG	
135	15/10/18 14:08	Photographs of Damaged Parts	1 Load JPG	-
136	15/10/18 14:08	Photographs of Damaged Parts Photographs of Damaged Parts	1 Load JPG	

Merimen e-Claims Page 4 of 6

Photos/Images		3 per p	age 🗸	✓
No Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
138 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
139 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	4
140 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
141 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
142 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
143 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	~
144 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
145 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
146 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
147 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
148 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
149 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	7
		0	W. Tomosto at annual	1,700
150 15/10/18 14:08	Photographs of Damaged Parts		Load JPG	~
151 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	Z.
152 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	Z
153 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	~
154 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	<u>~</u>
155 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	~
156 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
157 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
158 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	4
159 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	4
160 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
161 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
162 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
163 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
164 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
165 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
166 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
167 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
168 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
169 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
170 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
171 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
		0		V
172 15/10/18 14:08	Photographs of Damaged Parts		Load JPG	-
173 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	Z.
174 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	~
175 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	Z.
176 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
177 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	~
178 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	Z
179 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	~
180 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	4
181 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
182 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
183 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
184 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	~
185 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
186 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
187 15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V

Pho	tos/Images		3 per	page 🗸	✓
No	Relabel/Reorder LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	
188	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
189	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
190	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
191	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
192	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
193	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	~
194	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
195	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
196	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	✓
197	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	✓
198	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	~
199	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	✓
200	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	✓
201	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
202	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
203	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
204	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	✓
205	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	✓
206	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
207	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
208	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
209	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
210	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
211	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
212	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
213	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
214	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
215	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	✓
216	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
217	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	✓
218	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
219	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
220	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
221	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	V
222	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	✓
223	15/10/18 14:08	Photographs of Damaged Parts	0	Load JPG	✓
Doc	umentation		1 222	page 🔽	V
	CONTRACTOR OF THE PROPERTY OF	AVC Asia Davidia Taranana Dec 144 (CC)	1 per		_
No 1	Finalized On 10/10/18 10:21	AIG Asia Pacific Insurance Pte. Ltd. (SG) OI GIA REPORT	0	Load PDF	Print
	10/10/10 10:21	OI GIA REPURI		LUGU FUF	

Documents Checklist

	Print
	^
	~

Merimen e-Claims Page 6 of 6

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_do... 17/10/2018

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG18018217/GCBE2

Date:

17/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100503147

Claimant Vehicle

SLQ137H

Insured Vehicle No:

SLL3570X

Date of Loss:

03/10/2018

Nature of Claim:

TP

Claim No: 1234823063SG

6115 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLQ137H

Make & Model:

MERCEDES-BENZ A200, 1.6 FL AMG LINE (A)

Engine No:

27091031022848

Reg. Date: Colour:

28/12/2016 (Man. Year: 2016)

Chassis No: Odometer:

WDD1760432J489142

Engine Capacity:

1595 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

08/10/2018

Date Inspected:

11/10/2018 Inspected At: Precise Auto Service (HQ)

No 1 Kaki Bukit Ave 6, #02-34/36

Singapore 417883

Estimated Period of Repair:

9.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommend	led	Part	S
-----------	-----	------	---

				Repairer's	Amount
1	1	*FRT NUMBER PLATE	Dented	0.00 F	*- F
2	1	*FRT NUMBER PLATE GARNISH	Broken	0.00 F	*- F
3	1	*FRT BUMPER	Cracked	0.00 F	*- F
4	1	*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1	*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1	*FRT BUMPER BEAM	Bent	0.00 F	*- F
7	1	*FRT BUMPER SPONGE	Torn	0.00 F	*- F
8	1	*FRT BUMPER GRILLE	Broken	0.00 F	*- F
9	1	*FRT GRILLE	Cracked	0.00 F	*- F
10	1	*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
11	1	*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*- F
12	1	*FRT LH HEADLAMP ASSY	Cut	0.00 F	*- F
13	1	*AIR CON CONDENSER	Bent	0.00 F	*- F
14	1	*RADIATOR	Not Necessary	0.00 F	*- F
15	1	*RADIATOR FAN ASSY	Cracked	0.00 F	*- F
16	1	*FRT EXHAUST MANIFOLD COVER	Repair	0.00 F	*- F
17	1	*ENGINE UNDER COVER	Torn	0.00 F	*- F
18	1	*FRT TOW HOOK COVER	Missing	0.00 F	*- F
19	1	*FRT BUMPER EMBLEM	Necessary	0.00 F	*- F
20	1	*INTER COOLER	Bent	0.00 F	*- F
21	1	*REAR BUMPER	Dented	0.00 F	*- F
22	1	*REAR BUMPER LOWER	Cracked	0.00 F	*- F
23	1	*REAR BUMPER SIDE RETAINER	Bent	0.00 F	*- F
24	1	*REAR BUMPER SPONGE	Cut	0.00 F	*-F
25	1	*REVERSE SENSOR	Missing	0.00 F	*- F
26	1	*TAILGATE	Dented	0.00 F	*- F
27	3	*TAILGATE EMBLEM	Necessary	0.00 F	*- F
28	1	*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
29	1	*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
30	1	*TAILGATE LOCK	Bent	0.00 F	*- F
31	1	*TAILGATE RUBBER	Cut	0.00 F	*- F
32	1	*TOW HOOK COVER	Cut	0.00 F	*- F
F=Fran	nchise part.		Market Surgician Control of Control	920218	TO HONAY
			Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >