

**CITY CAB PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHC 7253E

DATE 8/10/2018 9:04

*AKA*

MAKE :

*Chiung*

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X My car</i>			\$ 544.50
	Front Bumper Bracket Top (RH) <i>X car</i>			\$ 22.40
	Front Bumper Bracket (RH) <i>X car</i>			\$ 24.60
	Headlamp (RH) <i>cut</i>			\$ 1,388.00
	Front Fender (RH) <i>cut</i>			\$ 566.30
	Front Fender Shield (RH) <i>X car</i>			\$ 175.90
	Front Fender Retainer <i>X car</i>			\$ 24.60
	Frt Wheel Hub Cap, RH <i>changed.</i>			\$ 107.10
	<b>SUB TOTAL</b>			<b>\$ 2,853.40</b>
	<b>LESS 20%</b>			<b>\$ 570.68</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,282.72</b>
	Front Fender Advertisement Logo (RH) <i>—</i>			\$ 100.00 <i>Nett</i>
				<b>\$ 100.00</b>
	<b>Labour Charge</b>			<i>300</i>
	Panel Beating			\$ <del>440.00</del>
	Spray Painting Charge			\$ <del>440.00</del> <i>400</i>
	Wiring			\$ <del>30.00</del> <i>20</i>
	Tuff Kote			\$ <del>50.00</del> <i>20</i>
	Frt Wheel Alignment			\$ <del>80.00</del> <i>X 20</i>
	<b>TOTAL LABOUR</b>			<b>\$ 1,040.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 3,422.72</b>

*Kalvin (UK)*  
*M 1505 hrs*  
*3 days*  
*PIP*  
*Before Part photo*

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part during survey
- Parts prices are based on "market" basis
- Third party surveyors are not to be used
- No illegal work to be carried out
- Supplier and repairer must be approved by insurance company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.